Classifying the Entire Service Line When Ownership Is Split

Purpose of this worksheet *: To summarize EPA's requirements for classifying the entire service line when ownership is split.*

Introduction

In many cases, service line ownership is **split** meaning that the system owns a portion and the customer owns a portion of the service line. Exhibit 1 below is a diagram of a possible division in service line ownership between the water system and customer. While the LCRR requires the inventory to categorize each service line or portions of the service line where ownership is split, a single classification per service line is also needed to support various LCRR requirements, such as lead service line replacement (LSLR), tap sampling, and risk mitigation. Table 1 below indicates how to classify the material for the entire service line when ownership is split between the water system and customer. For more information, see EPA's, ***Guidance for Developing and Maintaining a Service Line Inventory*** (2022)***.***

Exhibit 1. Example of Service Line Ownership Distinction between the Water System and Customer



Source: Exhibit 2-2 of Guidance for Developing and Maintaining a Lead Service Line Inventory (USEPA, 2022).

Table 1: Classification of Entire Service Line When Ownership is Split

System-Owned Portion	Customer-Owned Portion	Classification for Entire Service Line
Lead	Lead	Lead
Lead	Galvanized Requiring Replacement	Lead
Lead	Non-lead	Lead
Lead	Lead Status Unknown	Lead
Non-lead	Lead	Lead
Non-lead and never previously lead	Non-lead, specifically galvanized pipe material	Non-lead
Non-lead	Non-lead, material other than galvanized	Non-lead
Non-lead	Lead Status Unknown	Lead Status Unknown
Non-lead, but system is unable to demonstrate it was not previously Lead	Galvanized Requiring Replacement	Galvanized Requiring Replacement
Lead Status Unknown	Lead	Lead
Lead Status Unknown	Galvanized Requiring Replacement	Galvanized Requiring Replacement
Lead Status Unknown	Non-lead	Lead Status Unknown
Lead Status Unknown	Lead Status Unknown	Lead Status Unknown

Source: *Exhibit 2-3 of Guidance for Developing and Maintaining a Service Line Inventory (USEPA, 2022).*

PWS Information

Purpose of this worksheet: *For water systems to document basic system information.*

Facility Information			
Water System Name:			
Bremerton City of			
PWSID:	Population Served (number of people):	Number of Service Connections:	PWS Type:
WA5308200	**72,504**	**29,192**	☑ CWS ☐ NTNCWS
If you are a CWS, do multi-family residences comprise at least 20% of the structures you serve?			*Yes*

Mailing Address		
Street or P.O. Box:		
100 Oyster Bay Ave N		
City or Town:	State:	Zip Code:
Bremerton	**WA**	**98312**

System Contact Person	
Name:	Title:
Cami Apfelbeck	**Water Utility Manager**
(360) 509-0746	cami.apfelbeck@ci.bremerton.wa.us

Person Who Prepared Inventory (if different from above)	
Name:	Title/Affiliation:
Chance W Berthiaume	**Utility Manager (Distribution)**
Telephone:	Email:
(360) 473-5929	chance.berthiaume@ci.bremerton.wa.us

Inventory Methodology

PWS Name: Bremerton City of
PWSID: WA5308200

Enter Date Last Updated:	**10/08/24**

Purpose of this worksheet: *For water systems to document the methods and resources they used to develop and update their inventory.*

Part 1: Historical Records Review

Type of Record	Describe the Records Reviewed for Your Inventory and Indicate Your Level of Confidence (*e.g.* , Low, Medium, or High)
1. Previous Materials Evaluation *Example: Locations of Tier 1 lead tap sampling locations that are served by a lead service line.*	The Federal Lead and Copper Rule (LCR) was promulgated in 1991. Bremerton took two sets of 60 Tier 1 samples for both lead and copper in 1992 and for lead only in 1993 with the following 90th%-ile lead results: 1992 A 14 ug/L, 1992 B 17 ug/L, 1993 12 ug/L. The second set of samples that exceeded the EPA action level of 15 ug/L triggered a requirement for Bremerton to conduct a Corrosion Control Study which was completed in 1995. The recommendation was to install pH adjustment using sodium hydroxide. The Corrosion Control Facility (CCF) went on line in early 1999 and has been fully operational since. Follow-up sampling of Tier 1 sites have verified that the corrosion control has been working and Bremerton is currently on reduced monitoring of 30 homes every three years. Bremerton routinely operates the CCF above the minimum entry point water quality parameter of pH 7.7 SU with an average pH adjustment to about 8.1 SU.
2. Construction Records and Plumbing Codes *Examples: Local ordinance adopting an international plumbing code. Permits for replacing lead service lines.*	Construction records were reviewed to see if lead service lines were ever used in the system as well as interviews with long time staff who have worked on the system for several decades. The search identified that lead goosenecks were still in place in areas close to the downtown core. Most of these have been removed from the system over the years.
3. Water System Records *Examples: Capital improvement plans. Standard operating procedures. Engineering standards.*	All of the records for the capital program, including inspections, as-built records, standards, and operating procedures were reviewed. Relevant information was recorded and used to determine where we needed to focus our efforts to remove lead goosenecks and galvanized service lines which is ongoing.
4. Distribution System Inspections and Records Examples: *Distribution system maps. Tap cards. Service line repair/replacement records. Inspection records. Meter installation records.*	System records were reviewed and updates made to the GIS system based on these reviews. Tap records, field inspection logs, pre-1980 aerial image maps, capital project records with main and service line replacement were review to provide baseline system information for potential areas to target. Inspection field logs from capital projects and service line taps provided information that generally showed taps/service lines from 1971 to present are plasitc, and from 1950 -1970 new service lines were copper.
5. Additional Records Required by Your State	
6. Other Records	

Part 2: Identifying Service Line Material During Normal Operations

1. During which normal operating activities are you collecting information on service line material? Check all that apply.

- ☑ Water meter reading
- ☑ Water meter repair or replacement
- ☑ Service line repair or replacement
- ☑ Water main repair or replacement
- ☑ Backflow prevention device inspection
- ☐ Other

If "Other", please explain:

2. Did you develop or revise standard operating procedures to collect service line material information during normal operation?	*Yes*

If "Yes", please describe:

SOP was created on 2/1/2017 that provides guidance and instructions for staff to conduct service line material inventories via records review, and field site checks. The SOP was deveoped as a colaborative effort between water system management and staff in Water Resources, Water Distribution, and Engineering and used during daily maintenance activities.

Part 3: Service Line Investigations

1. Identify the service line investigation methods your system used to prepare the inventory (check all that apply). If a water system chooses an investigation method not specified by the state under 40 CFR §141.84(a)(3)(iv), state approval is required. ***Note that investigations are not required by the LCRR but can be used by systems to assess accuracy of historical records and gather information when service line material is unknown.***

- ☑ Visual Inspection at the Meter Pit
- ☐ Customer Self-Identification
- ☐ CCTV Inspection at Curb Box - External
- ☐ CCTV Inspection at Curb Box - Internal
- ☐ Water Quality Sampling - Targeted
- ☐ Water Quality Sampling - Flushed
- ☐ Water Quality sampling - Sequential
- ☑ Water Quality Sampling - Other
- ☑ Mechanical Excavation
- ☑ Vacuum Excavation
- ☐ Predictive Modeling
- ☐ Other

If "Other", please explain:

N/A

2. If "Predictive Modeling", please briefly describe the model and inputs used:

N/A

3. How did you prioritize locations for service line materials investigations? For example, did you consider environmental justice and/or sensitive populations, did you use predictive modeling, and/or did you target areas with high number of unknowns?

We reviewed record drawings, engineering inspections, plan documents, field work/inspection records, and institutional knowledge from staff. It was determined that systems installed after 1950 would not have lead goosenecks and that areas built in 1949 and earlier were target for further investigation and visual inspection at the meter pits in the field. Areas where water mains were replaced had new service lines installed as part of the projects so those areas were removed from the initial effort but have been checked since.

Inventory Summary

PWS Name: Bremerton City of
PWSID: WA5308200

Enter Date Last Updated:	**10/15/24**

Purpose of this worksheet: *For water systems to provide a summary of their service line inventory, including information on ownership, inventory format, and the number of service lines for each of the four required materials classifications.*

Part 1. General Information

1. Is this the **Initial Inventory** or an **Inventory Update**?	*Initial Inventory*
2a. Who **owns the service lines** in your system? *If other, please explain below.*	*Ownership is split, meaning that the system owns and portion and the customer owns a portion*
2b. Is there documentation that defines service line ownership in your system, such as a local ordinance? *If yes, please describe below and explain where ownership is split (e.g., property line, curb stop).*	*Yes*

The city is responsible for service lines from the water main to the meter per Bremerton Municipal Code 15.02.140 Water System O and M - General

3a. Describe when lead service lines were generally installed in your system.

There are no lead city or customer service lines in Bremerton's system and most of the older customer water services in Bremerton were connected to the water main with copper or galvanized pipe.

3b. When were lead service lines banned in your system? Reference the state or local ordinance that banned the use of lead in your system.

Our records indacte that lead was not used for service lines. Both Seattle and Tacoma used 1939 as the end date of their concern about lead goosenecks and say this is a conservative date. This approach was used by Bremerton.

4. Do you have lead goosenecks, pigtails or connectors in your system?	*Yes*

5. What is your overall level of confidence in the inventory (*i.e.* , "Low", "Medium", or "High.") Please explain your rationale below.

Highly confidant that we have identified service line materials for all city owned services, and most customer locations. A thorough reviews of records and field inspections have identified that only older parts of downtown are likley to have a lead gooseneck and that lead services lines were not used in any portion of the system. Field inspections of customer side materials is ongoing and follows the SOP developed to identify these lines.

Part 2. Inventory Format

Describe your inventory format in the space provided below (*e.g.* , the **Detailed Inventory** worksheet, custom spreadsheet, GIS map). Provide the filename and/or web address if applicable. ***Note that the state may require you to submit your detailed inventory of each service line in your distribution system.***

The detailed inventory has the required information in an Excel spreadsheet format.

Part 3. Inventory Summary Table [1]

If you are using the ***Detailed Inventory*** *worksheet, the classifications you select in the Column "Entire Service Line Material Classification" (Column X) will be used to calculate the total number of service lines for each of the four material classifications below. Otherwise, enter the number of service lines in the aqua-colored cells.* ***Remember this is the classification for the entire service line.***

Service Line Material Classification	Definition	Total Number of Service Lines (REQUIRED to be reported under the LCRR)
Lead	Any portion of the service line is known to be made of lead.[2]	0
Galvanized Requiring Replacement (GRR)	The service line is not made of lead, but a portion is galvanized and the system is unable to demonstrate that the galvanized line was never downstream of a lead service line.	0
Non-Lead	All portions of the service line are known NOT to be lead or GRR through an evidence-based record, method, or technique.	20,315
Lead Status Unknown	The service line material is not known to be lead or GRR. For the entire service line or a portion of it (in cases of split ownership), there is not enough evidence to support material classification.	0

TOTAL	20,315

Notes

[1] This summary table is for reporting material for the entire service line connecting the water main to the customer's plumbing. See the **Classifying SLs** worksheet for additional guidance on assigning a materials classification to the entire service line when ownership is split. Remember that systems must track the system-owned and customer-owned portions separately in their inventory.

[2] A lead-lined galvanized service line is consistent with the definition of an LSL under the LCRR ("a portion of pipe that is made of lead, which connects the water main to the building inlet") (40 CFR §141.2) and must therefore be classified in the inventory as an LSL. Do NOT, however, count non-lead service lines with a lead gooseneck or pigtail as lead service lines unless required by your state.

Public Accessibility Documentation

PWS Name: Bremerton City of
PWSID: WA5308200

Enter Date Last Updated:	**10/16/24**

Purpose of this worksheet: For systems to provide documentation to states on how they met the public accessibility requirements of the LCRR.

1. Select the location identifiers that you use for your service line inventory. Check all that apply.

- ☑ Address
- ☑ Street
- ☐ Block
- ☐ Intersection
- ☐ Landmark
- ☐ GPS Coordinates
- ☐ Other

If "Other", please describe:

2. Does ***every service line*** have a location identifier? *Yes*

If "No", explain. Remember that location identifiers are required for service lines that are lead and galvanized requiring replacement.

3. How are you making your inventory publicly accessible? Check all that apply. *Remember that if your system serves > 50,000 people, you* ***must*** *provide the inventory online.*

- ☐ Interactive online map
- ☐ Static online map
- ☐ Online spreadsheet
- ☐ Printed service line map
- ☐ Printed tabular data
- ☐ Information on water utility mailings or newsletter
- ☐ Hard copy information available in water system office
- ☑ Other

If "Other", please describe:

A search feature for individual addresses is available on the City's website at: https://gis.bremertonwa.gov/apps/lead/search/ The search feature lets the searcher know if they potentially have a lead gooseneck. We don't have any lead service lines and are actively replacing galvanized water service lines. Notification will be sent to customers who have a galvanized service line in accordance with requirements.

State Checklist for Initial Inventory Submittal

PWS Name: Bremerton City of PWSID: WA5308200	
Enter Date Last Updated:	**10/8/2024**

Purpose of this worksheet: *For states to determine and document if water systems met all of the January 15, 2021 Lead and Copper Rule (LCRR) requirements for their* **Initial Inventory** *including timely submission, required elements, use of information sources, public accessibility, and public notification of service line materials.*

Part 1: Person Completing This Checklist	
Name:	Title:
Chance Berthiaume	**Utility Manager (Distribution)**
Telephone:	Email:
(360) 473-5929	chance.berthiaume@ci.bremerton.wa.us

Part 2: Review for Timely Submission	
1. Was the initial inventory submitted by the deadline of October 16, 2024?	*Yes*
Consider post-mark or date sent via email or reported into a state data system.	

Part 3: Review for Required Elements	
1. Does the inventory include ***all*** service lines connected to the distribution system?	*Yes*
Consider if the total number of service lines in the ***Inventory Summary*** *worksheet, Part 3, matches sanitary survey and monitoring data in the state's database (e.g., SDWIS /State) based on population served, number of service connections (including those for non-potable use), number of accounts, census data, or other information.*	
2. Does the inventory include portions owned by the water system and the customer?	*Yes*
Check the service line ownership type selected in the ***Inventory Summary*** *worksheet, Part 1, Question 2a. If the system selected "Ownership is Split" check that their inventory includes information for both the system-owned and customer-owned portions.*	
3. Did the system classify all service lines as either Lead, Galvanized Requiring Replacement (GRR), Non-Lead, or Lead Status Unknown?	*Yes*
Consider if the system completed each row of the inventory summary table in the ***Inventory Summary*** *worksheet, Part 3. Some rows may be zero.*	
4. In the space below, provide additional comments/documentation related to required elements of the system's initial inventory.	

Part 4: Review for Information Sources	
1. Did the system use the following historical records to prepare their initial inventory: previous materials evaluation, construction and plumbing codes/records, water system records, distribution system inspections and records.	*Yes*
Consider if the system identified historical records in each row of the ***Inventory Methods*** *worksheet, Part 1, Rows 1 through 4. Consider if the system completed Row 5 if additional records are required in your state.*	
2. Is the system collecting service line material information during normal operations?	*Yes*
Consider if the system checked one or more normal operations activities in the ***Inventory Methods*** *worksheet, Part 2. Consider asking the systems to submit updated or new standard operating procedures documenting service line material information collection.*	
3. Has the system conducted investigations to verify service line material?	*Yes*

This is not required by the LCRR but recommended by EPA to verify historical records and gather information where records do not exist to reduce the number of unknowns in the system as quickly as possible. Consider:

- *If the system checked one or more of the investigative methods on the* ***Inventory Methods*** *worksheet, Part 3.*
- *If in their inventory, the system indicated that the materials classification was based on investigations.*
- *The number of unknowns - EPA strongly discourages systems from submitting inventories with all unknowns. If all service line materials are lead status unknown, consider asking the water system to conduct investigations.*

4. In the space below, provide additional comments related to information sources used to develop the system's initial inventory.

We reviewed record drawings, engineering inspections, plan documents, field work/inspection records, and institutional knowledge from staff. It was determined that systems installed after 1950 would not have lead goosenecks and that areas built in 1949 and earlier were target for further investigation and visual inspection at the meter pits in the field. Areas where water mains were replaced had new service lines installed as part of

Part 5: Review for Public Accessibility

1. Does the inventory include location identifiers for each service line that is lead or galvanized requiring replacement? — *No*

Consider checking the inventory for location identifiers and reviewing the system's answers in the ***Public Accessibility Doc.*** *worksheet, Questions 1 and 2.*

2. Did the system make its inventory publicly accessible? — *Yes*

Consider reviewing the method by which the water system is making its inventory publicly accessible as identified in the ***Public Accessibility Doc.*** *worksheet, Question 3. Check that systems serving more than 50,000 people have posted their service line inventories online.*

3. In the space below, provide additional comments/documentation related to public accessibility of the system's initial inventory.

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier		Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previously	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material			Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field				Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
	Street Address	Other Location Identifier									Describe the Field Verification Method	Enter the Date of Field Verification	Notes						Describe the Field Verification Method	Enter the Date of Field Verification	Notes											
A Unique ID is recommended for each service line.	*Water systems must track addresses of all service lines in their internal inventory. For the publicly accessible version, location identifiers are required for lead and galvanized requiring replacement. If the system does not use addresses for their location identifier, other options could include GPS coordinates, landmark, intersection, block, or other details to specify service line locations.*		*Select Yes if sensitive subpopulation, e.g., day care, school, multifamily home. If Yes-Other, describe in the Notes field.*	*Does location meet state affordability guidelines or other measures?*	*Dropdown list includes recommended subclassifications. If "Non-Lead Other", describe in Notes field*	*Select Yes, No, or Don't know. Important for determining if downstream/ customer-owned galvanized service line requires replacement*	*Date, year, or estimated date range when the service line was installed or replaced*	*Diameter in inches*	*Select option from drop down list. If "Other," describe in the Notes field*	*Select Yes or No*	*Select option from drop down list. If "Other," describe in the Notes field*	*Enter approximate date of field verification or date that the record was updated*	*Can use this field for documenting additional relevant information, including when classification changes.*	*Dropdown list includes recommended subclassifications. If non-lead other, describe in Notes field.*	*Date, year, or estimate date range when the service line was installed or replaced*	*Diameter in inches*	*Select option from drop down list. If "Other," describe in the Notes field*	*Select Yes or No*	*Select option from drop down list. If "Other," describe in the Notes field*	*Enter approximate date of field verification or date that record was updated*	*Can use this field for documenting additional relevant information, including when classification changes.*	*Dropdown list includes four required service line classifications of Lead, Non-lead, Galvanized Requiring Replacement, or Unknown*	*For example, lead gooseneck or pigtail where the water main is connected to the service line*	*Select Yes, No, or Don't Know*	*For example, backflow preventer or meter containing lead*	*Note: This information may be helpful for identifying lead tap monitoring locations.*					
BremSLI-2400001		3775-000-032-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Galvanized		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown		
BremSLI-2400002		242401-2-014-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400003		242401-2-014-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400004		242401-2-012-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400005		242401-2-012-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400006		242401-2-016-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400007		242401-2-007-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050			2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400008		242401-2-007-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400009		242401-2-007-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400010		1100260	No	Not evaluated	Galvanized	No	Prior to 1966	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400011		1100260	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400012		1100270	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400013		132401-3-006-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400014		132401-3-005-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400015		132401-3-004-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400016		3712-003-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400017		3712-003-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400018		3712-003-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400019		3800-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400020		3713-002-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400021		3737-001-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400022		3737-001-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400023		3737-001-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400024		3737-001-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400025		3737-001-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400026		3737-001-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	New housing	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	New housing	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400027		3813-002-002-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400028		3813-002-002-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400029		132401-3-002-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	W226	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W226	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400030		132401-3-001-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W288			2016-2024		Non-Lead - Copper		0.75	W288	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400031		132401-2-045-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown		
BremSLI-2400032		132401-2-044-2006	No	Not evaluated	Non-Lead - Copper	No		0.75				2016-2024		Galvanized		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown		
BremSLI-2400033		132401-2-043-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Galvanized		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400034		132401-2-042-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown		
BremSLI-2400035		132401-2-041-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050			2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400036		132401-2-040-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	FC	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400037		132401-2-049-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400038		132401-2-048-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400039		132401-2-050-2007	No	Not evaluated	Non-Lead - Plastic	No		2.00		Abandon(couldn't find)		2016-2024		Unknown		2.00		Yes	Abandon(couldn't find)	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown		
BremSLI-2400040		132401-2-051-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400041		132401-2-039-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400042		132401-2-037-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400043		132401-2-035-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400044		3709-001-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400045		3709-001-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400046		3709-001-002-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 30	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400047		3709-002-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown		
BremSLI-2400048		3709-002-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400049		3709-002-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 41			2016-2024		<Null>		0.75	Book 6 Pg 41	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400050		3709-002-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 6	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 6	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400051		132401-2-036-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091			2016-2024		Non-Lead - Copper		0.75	BEDA 3091	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400052		132401-2-038-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2187			2016-2024		Non-Lead - Copper		0.75	BEDA 2187	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown		
BremSLI-2400053		132401-2-055-2002	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown		
BremSLI-2400054		132401-2-054-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400055		132401-3-025-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	W310	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	W310	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown		
BremSLI-2400056		132401-3-026-2006	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	W245	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W245	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown		
BremSLI-2400057		3725-001-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	W182	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	W182	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400058		3725-001-010-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81			2016-2024		Non-Lead - Copper		0.75	Tap log 81	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400059		3725-001-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log (1911.5)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log (1911.5)	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400060		3725-001-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400061		3737-004-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	No service			2016-2024		None		0.75	No service	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400062		3737-004-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400063		3737-004-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400064		3737-005-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400065		3737-005-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400066		3737-005-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400067		3737-005-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400068		3712-001-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400069		3712-001-023-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400070		3712-001-022-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400071		3712-001-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400072		3712-001-020-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400073		3712-001-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown		
BremSLI-2400074		3712-001-017-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400075		3712-001-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400076		3712-001-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400077		3712-001-014-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400078		3712-001-013-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400079		132401-3-029-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		
BremSLI-2400080		132401-3-029-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400081		3718-005-031-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400082		3718-005-030-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400083		3718-005-028-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400084		132401-3-010-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400085		132401-3-023-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400086		132401-3-024-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400087		132401-3-022-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400088		132401-3-021-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400089		132401-3-020-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400090		132401-3-019-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400091		3712-002-003-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400092		3712-002-003-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400093		3712-002-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400094		3712-002-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400095		3713-001-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400096		3713-001-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400097		3737-002-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400098		3737-002-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400099		3737-002-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400100		3737-002-001-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400101		3737-003-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400102		3737-003-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400103		3737-003-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400104		3737-003-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400105		3737-003-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400106		3813-001-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Index	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Index	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400107		3789-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 79	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400108		3789-000-001-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	W203	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W203	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400109		132401-3-211-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	W248	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	W248	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400110		3712-002-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400111		3712-002-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400112		132401-3-013-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400113		132401-3-011-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400114		132401-3-009-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400115		3718-006-018-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400116		3718-008-018-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400117		3718-008-017-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400118		3718-009-008-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400119		3718-009-008-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400120		3718-009-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400121		3718-009-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400122		3718-009-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400123		3718-009-021-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400124		3718-009-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400125		3718-009-023-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400126		3718-009-023-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400127		3718-009-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400128		3718-009-004-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400129		3718-008-001-0207	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400130		3718-007-016-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400131		3718-007-016-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400132		3718-007-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400133		3718-007-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400134		3718-007-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400135		3718-007-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400136		3718-007-037-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400137		3718-007-037-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400138		3718-007-036-0000	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year			2016-2024		<Null>		1.50	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400139		3718-007-034-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400140		3718-007-032-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400141		3718-007-030-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400142		3718-007-028-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400143		3718-006-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400144		3718-006-009-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400145		3718-006-009-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400146		3718-006-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400147		3718-006-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400148		3718-006-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400149		3718-006-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400150		3718-006-003-0001	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Service not in use		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Service not in use	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400151		3718-006-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400152		3718-006-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400153		3718-006-037-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400154		3718-006-029-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400155		3718-006-028-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400156		8149-000-000-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400157		3718-005-001-0302	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400158		132401-3-030-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400159		132401-3-030-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400160		3712-001-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400161		3712-001-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400162		3712-001-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400163		3712-001-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400164		3712-001-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400165		3712-001-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400166		3712-001-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400167		3712-001-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400168		3712-001-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400169		3712-001-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400170		3712-001-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400179		3737-004-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400180		3737-004-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400181		3737-004-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400182		3737-004-001-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	New housing	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	New housing	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400183		3725-001-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400184		3725-001-007-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400185		3725-001-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 76	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap log 76	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400186		3725-001-003-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	W224	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W224	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400187		3725-001-001-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Copper		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400188		1324013-037-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	W310	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W310	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400189		1324013-037-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	W311	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	W311	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400190		1324013-038-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Copper		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400191		1324013-039-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Plastic		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400192		1324013-042-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 77	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 77	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400193		1324013-043-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log (323)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Tap Log (323)	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400194		1324013-044-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400195		1324013-045-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Copper		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400196		1324013-046-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400197		1324013-050-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400198		1324013-051-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400199		1324013-051-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400200		1324013-053-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400201		1324013-054-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400202		1324013-055-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400203		1324013-203-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400204		1324013-059-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400205		1324013-060-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400206		3724-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400207		3724-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400208		3724-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400209		1324013-061-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400210		1324013-065-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400211		1324013-066-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400212		1324013-067-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400213		1324013-212-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400214		1324013-071-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400215		1324013-072-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400216		1324013-073-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400217		1324013-210-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400218		1324013-209-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew			2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400219		1324013-075-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400220		1324013-076-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400221		1324013-077-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400222		1324013-078-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400223		1324013-079-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 75	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 75	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400224		1324013-079-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 75	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 75	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400225		1324013-065-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400226		1324013-079-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400227		1324013-061-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400228		1324013-056-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400229		3714-000-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400230		3714-000-001-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400231		3709-003-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400232		3709-003-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400233		3788-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 16 Pg 50	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 16 Pg 50	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400234		3788-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 18 Pg 24	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 18 Pg 24	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400235		3788-000-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400236		3788-000-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400237		3788-000-005-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400238		3788-000-005-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400239		3788-000-005-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400240		1324012-064-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400241		1324012-063-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 Pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 Pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400242		3709-003-007-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400243		3709-005-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400244		3709-005-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400245		3709-005-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400246		3709-005-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400247		3803-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400248		3803-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23			2016-2024		Galvanized		0.75	Book 6 Pg 23	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400249		3803-000-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49			2016-2024		Unknown		0.75	Book 5 pg 49	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400250		3803-000-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400251		3803-000-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400252		3803-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 13 pg 33	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 13 pg 33	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400253		3803-000-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3091	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400254		3803-000-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400255		3803-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400256		3747-001-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400257		1324013-081-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400258		1324013-083-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400259		1324013-083-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400260		1324013-085-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400261		1324013-143-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400262		1324013-141-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400263		1324013-140-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400264		3738-001-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400265		3738-001-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400266		1324013-144-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400267		1324013-144-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400268		1324013-144-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400277		3718-014-001-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400278		3718-019-012-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400279		3718-019-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400280		3718-019-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400281		3718-019-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400282		3718-022-014-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400283		3718-022-014-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400284		3718-022-014-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400285		3718-022-011-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400286		3718-022-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400287		3718-022-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1555			2016-2024		Non-Lead - Copper		0.75	BEDA 1555	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400288		3718-022-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400289		3718-022-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Non-Lead - Copper		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400290		3718-022-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Galvanized		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400291		3718-022-002-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400292		3718-022-002-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400293		3718-022-033-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Galvanized		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400294		3718-022-032-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400295		3718-022-029-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400296		3718-022-029-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400297		3718-022-029-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400298		3718-022-028-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400299		3718-022-026-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400300		3718-022-025-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400301		3718-022-021-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400302		3718-019-037-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	Main Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	Main Year	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400303		3718-019-033-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400304		3718-019-026-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400305		3718-019-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400306		3718-019-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400307		3718-014-044-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400308		3718-014-039-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400309		3718-014-036-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400310		3718-014-035-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400311		3718-014-032-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400312		3718-014-026-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400313		3718-014-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400314		3718-015-019-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400315		3718-015-019-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400316		3718-015-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400317		3718-015-017-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400318		3718-015-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400319		3718-015-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400320		3718-015-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400321		3718-015-015-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400322		3718-015-040-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400323		3718-015-012-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400324		3718-015-012-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400325		3718-015-004-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400326		3718-015-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400327		3718-018-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit/ Abandon		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit/ A	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400328		3718-018-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400329		3718-023-014-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400330		3718-023-014-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400331		3718-023-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400332		3718-023-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Non-Lead - Copper		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400333		3718-023-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400334		3718-023-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400335		3718-023-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400336		3718-023-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1655	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400337		3718-023-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1724			2016-2024		Galvanized		0.75	BEDA 1724	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400338		3718-023-039-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1675	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1675	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400339		3718-023-038-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400340		3718-023-037-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Galvanized		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400341		3718-023-036-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400342		3718-023-034-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1555	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1555	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400343		3718-023-033-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Galvanized		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400344		3718-023-031-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400345		3718-023-030-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400346		3718-023-029-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400347		3718-023-028-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400348		3718-023-026-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400349		3718-023-026-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400350		3718-023-024-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400351		3718-023-023-0200	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400352		3718-023-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>			2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400353		3718-018-021-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400354		3718-018-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400355		3718-018-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400356		3718-018-021-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400357		3718-018-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400358		3718-015-033-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400359		3718-015-033-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400360		3718-016-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400361		3718-016-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400362		3718-016-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400363		3718-016-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400364		3718-016-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400365		3718-016-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400366		3718-016-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400367		3718-016-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400368		3718-016-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400369		3718-016-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400375		3718-024-014-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400376		3718-024-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400377		3718-024-011-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400378		3718-024-009-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400379		3718-024-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Galvanized		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400380		3718-024-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Galvanized		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400381		3718-024-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400382		3718-024-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400383		3718-024-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400384		3718-024-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400385		3718-024-040-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400386		3718-024-037-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 13 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400387		3718-024-035-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3031/3032	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3031/3032	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400388		3718-024-035-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3031/3032			2016-2024		Non-Lead - Copper		0.75	BEDA 3031/3032	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400389		3718-024-035-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3031/3032	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3031/3032	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400390		3718-024-033-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400391		3718-024-031-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400392		3718-024-027-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400393		3718-024-021-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400394		3718-024-021-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	<Null>			2016-2024		Galvanized		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400395		3718-017-037-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400396		3718-017-008-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400397		3718-017-008-0102	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400398		3718-017-008-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400399		3718-017-028-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400400		3718-017-028-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400401		3718-017-026-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400402		3718-017-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400403		3718-017-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400404		3718-016-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400405		3718-016-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400406		3718-016-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400407		3718-016-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400408		3718-016-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400409		3718-016-038-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400410		3718-016-035-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400411		3718-016-035-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400412		3718-016-032-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400413		3779-001-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400414		8187-000-000-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400415		8187-000-000-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400416		3779-001-027-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400417		3743-006-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2080	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2080	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400418		3743-006-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400419		3743-006-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400420		3743-006-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400421		3743-006-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400422		3743-006-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400423		3743-006-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400424		3743-006-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48			2016-2024		Galvanized		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400425		3743-006-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48			2016-2024		Galvanized		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400426		132401-3-178-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400427		132401-3-179-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400428		132401-3-180-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400429		132401-3-181-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400430		132401-3-189-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400431		132401-3-148-2009	Yes - Other	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400432		132401-3-151-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400433		132401-3-152-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400434		132401-3-155-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400435		132401-3-156-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400436		132401-3-159-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400437		132401-3-160-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400438		132401-3-161-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400439		132401-3-162-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400440		132401-3-132-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400441		3738-002-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400442		132401-3-157-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400443		132401-3-154-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400444		132401-3-153-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400445		3738-002-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400446		132401-3-150-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400447		132401-3-149-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400448		3738-001-010-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400449		3738-001-008-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400450		3738-002-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400451		3738-002-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400452		3738-002-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400453		3738-001-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400454		3738-002-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400455		3738-002-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400456		132401-3-137-2002	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Unknown Type			2016-2024		Non-Lead - Plastic		1.50	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400457		132401-3-128-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400458		132401-3-128-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400459		132401-3-127-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400460		132401-3-126-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400461		132401-3-135-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400462		132401-3-134-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400463		132401-3-133-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400464		132401-3-125-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400473		132401-3-089-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400474		132401-3-091-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400475		132401-3-091-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400476		132401-3-102-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400477		132401-3-101-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400478		132401-3-092-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400479		132401-3-093-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400480		132401-3-097-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400481		132401-3-096-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400482		3728-000-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Replaced			2016-2024		Non-Lead - Plastic		0.75	Replaced	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400483		3728-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400484		3728-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400485		132401-3-095-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400486		132401-3-095-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400487		132401-3-098-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400488		132401-3-100-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400489		3747-002-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400490		3747-002-006-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3090			2016-2024		Galvanized		0.75	BEDA 3090	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400491		3747-001-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400492		3747-001-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400493		3747-002-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400494		3747-002-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 25			2016-2024		Non-Lead - Plastic		0.75	Book 13 pg 25	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400495		3747-001-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 37	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 37	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400496		3747-001-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400497		3747-001-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400498		3747-002-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 27	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 27	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400499		3747-001-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400500		3747-002-015-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400501		3747-002-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 16			2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 16	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400502		3747-002-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 16			2016-2024		Non-Lead - Copper		0.75	Book 6 pg 16	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400503		3784-002-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400504		3747-001-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400505		3709-005-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400506		132401-2-024-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400507		3709-005-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400508		3784-001-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400509		3784-001-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400510		3784-002-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400511		3784-002-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400512		3784-002-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400513		3784-002-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400514		3784-002-004-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400515		3784-002-004-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400516		3784-001-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400517		3773-000-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 41			2016-2024		<Null>		0.75	Book 6 Pg 41	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400518		3773-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 20			2016-2024		Galvanized		0.75	Book 6 pg 20	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400519		3747-002-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400520		3747-002-014-0002	No	Not evaluated	Galvanized	No	Prior to 1959	0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400521		3747-002-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400522		3773-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49			2016-2024		<Null>		0.75	Book 5 pg 49	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400523		3773-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400524		3773-000-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 25			2016-2024		Galvanized		0.75	Book 13 pg 25	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400525		3747-002-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400526		3747-002-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400527		3773-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091			2016-2024		Galvanized		0.75	BEDA 3091	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400528		3747-002-009-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400529		3773-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 2187	Kc		2016-2024		Non-Lead - Copper		0.75	BEDA 2187	No	Kc	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400530		132401-3-109-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400531		132401-3-109-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400532		3815-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400533		3815-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400534		3815-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400535		3815-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400536		3796-000-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400537		132401-3-108-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400538		3705-001-001-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400539		3705-001-001-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400540		3705-002-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400541		3705-002-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400542		3705-001-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400543		3705-001-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400544		3705-003-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400545		3705-003-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400546		3705-003-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400547		3705-003-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400548		3705-004-001-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400549		132401-3-122-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400550		132401-3-118-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400551		132401-3-118-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400552		132401-3-119-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400553		132401-3-117-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400554		132401-3-117-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400555		132401-3-130-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400556		132401-3-130-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400557		132401-3-131-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400558		132401-3-167-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400559		132401-3-166-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400560		132401-3-165-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400561		132401-3-163-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400562		132401-3-163-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier					Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Other Potential Sources of: Is there a Lead Connector?	Other Potential Sources of: Is there Lead Solder in the Service Line?	Other Potential Sources of: Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400571		3768-000-037-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400572		132401-3-172-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400573		132401-3-171-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400574		132401-3-171-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400575		132401-3-171-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400576		132401-3-171-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400577		132401-3-171-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400578		132401-3-113-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400579		132401-3-113-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400580		3705-003-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400581		3705-003-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400582		3705-003-009-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400583		3705-003-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400584		3705-002-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400585		3705-002-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400586		3705-002-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400587		132401-3-110-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 79	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400588		3757-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400589		3757-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400590		3804-001-001-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400591		3804-001-001-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400592		3773-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400593		3773-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400594		3804-001-001-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485			2016-2024		Non-Lead - Plastic		0.75	BEDA 5485	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400595		3804-001-001-0108	No	Not evaluated	Galvanized	No	Prior to 1960	0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400596		3773-000-012-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486			2016-2024		Galvanized		0.75	BEDA 5486	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400597		3773-000-012-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400598		3773-000-012-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400599		3773-000-012-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 39	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 19 pg 39	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400600		3773-000-012-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 39	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 19 pg 39	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400601		3773-000-013-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400602		3731-004-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400603		3731-005-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400604		3784-001-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400605		3773-000-015-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400606		3773-000-015-0200	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400607		3784-001-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400608		3784-001-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400609		132401-2-075-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400610		132401-2-075-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400611		132401-2-026-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400612		3726-000-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400613		3726-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	Yes	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400614		3726-000-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400615		132401-2-025-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400616		132401-2-021-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400617		3726-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400618		132401-2-020-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400619		132401-2-019-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400620		3726-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400621		132401-2-080-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400622		132401-2-080-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400623		3726-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400624		3802-003-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400625		3802-003-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400626		3802-003-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400627		132401-2-014-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400628		3802-003-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400629		3802-003-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400630		3802-003-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400631		3802-003-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400632		3802-002-019-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400633		3802-002-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400634		3802-002-015-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400635		3802-002-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400636		3802-002-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400637		3802-002-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400638		3802-002-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400639		3802-002-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400640		3802-002-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400641		132401-2-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400642		132401-2-006-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400643		132401-2-008-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400644		132401-2-009-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400645		132401-2-010-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400646		132401-2-011-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400647		132401-2-011-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400648		132401-2-012-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400649		3802-002-005-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400650		3802-002-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400651		3802-002-003-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400652		3802-002-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400653		8068-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400654		3802-001-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400655		132401-2-002-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400656		3802-001-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400657		132401-2-076-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400658		132401-2-076-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400659		132401-2-013-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400660		3802-001-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400661		8037-000-000-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400669		3802-002-036-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400670		3802-002-031-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400671		3802-002-029-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400672		3802-002-028-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400673		3802-002-025-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400674		3802-002-025-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400675		3802-002-024-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400676		3802-002-022-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400677		3802-002-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400678		3802-003-023-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400679		3802-003-020-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400680		3802-003-020-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400681		3802-003-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400682		3802-003-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400683		3802-003-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400684		3802-003-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400685		3802-003-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400686		3726-000-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400687		3726-000-014-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400688		3726-000-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400689		3726-000-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400690		3726-000-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400691		3726-000-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400692		3731-004-001-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400693		3731-004-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400694		3731-004-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400695		3731-004-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400696		3731-004-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400697		3731-004-010-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400698		142401-4-001-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400699		3731-003-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400700		3731-003-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3091	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400701		3731-003-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400702		3731-003-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400703		3731-003-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Abandon service/ live service?		2016-2024		<Null>		0.75	Book 5 pg 28	No	Abandon service/ live service?	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400704		3731-003-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 49	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400705		3731-003-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 18			2016-2024		Galvanized		0.75	Book 6 Pg 18	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400706		3731-002-007-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400707		3731-002-006-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400708		3731-002-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400709		3731-002-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400710		3731-002-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400711		3731-002-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400712		3731-001-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400713		3731-001-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400714		3731-001-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400715		3731-001-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400716		3731-001-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400717		3731-001-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400718		3731-001-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400719		3763-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400720		3763-000-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400721		3763-000-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400722		3763-000-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400723		3764-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400724		3764-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400725		3764-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400726		3764-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Asbuilt		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Asbuilt	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400727		3764-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400728		3804-003-010-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400729		3804-003-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400730		3804-003-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400731		3804-003-009-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400732		3804-003-009-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400733		3804-003-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400734		3804-003-008-0404	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400735		3804-003-008-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400736		3804-003-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400737		3804-003-007-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400738		3804-003-007-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400739		3804-003-007-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400740		3804-003-007-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400741		3804-003-007-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400742		3804-003-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400743		3804-004-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400744		3804-004-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400745		3804-004-006-0206	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400746		3804-004-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400747		3804-004-005-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400748		3804-004-005-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400749		3804-004-006-0404	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400750		3804-003-006-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400751		3804-003-006-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400752		3804-003-008-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400753		3804-003-008-0206	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400754		3804-003-009-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400755		3804-003-009-0403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400756		3804-003-009-0502	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400757		3804-003-010-0400	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400758		3804-003-010-0509	No	Not evaluated	Non-Lead - Plastic	No		2.00	Pipe Diameter	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Pipe Diameter	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400759		3804-003-010-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400760		3804-003-010-0608	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400767		3764-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400768		3764-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400769		3763-000-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400770		3763-000-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400771		3763-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400772		3763-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400773		8186-000-000-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400774		8186-000-000-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400775		8186-000-000-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400776		3763-000-009-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400777		3763-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400778		3731-001-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400779		3731-001-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400780		3731-001-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400781		3731-001-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400782		3731-001-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400783		3731-001-012-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400784		3731-001-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400785		3731-001-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400786		3731-001-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400787		3731-001-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400788		3731-001-008-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400789		3731-001-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400790		3731-001-006-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400791		3731-002-001-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400792		3731-002-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400793		3731-002-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400794		3731-002-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400795		3731-002-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400796		3731-002-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400797		3731-003-017-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 17			2016-2024		Galvanized		0.75	Book 6 pg 17	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400798		3731-003-016-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 6	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 6	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400799		3731-003-015-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 27	Visual inspection at the meter pit/Abandon		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 27	No	Visual inspection at the meter pit/A	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400800		3731-003-014-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 20 Pg 73	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 20 Pg 73	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400801		3731-003-013-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 Pg 15	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 13 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400802		3731-003-012-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3031/3032	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3031/3032	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400803		3731-003-012-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3031/3032	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3031/3032	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400804		142401-4-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log (1227.5)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log (1227.5)	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400805		142401-4-005-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400806		142401-4-006-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400807		142401-4-007-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400808		142401-4-008-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND			2016-2024		Galvanized		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400809		142401-4-009-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400810		142401-4-010-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400811		3756-000-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400812		142401-4-011-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400813		3756-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400814		3769-001-002-0001	No	Not evaluated	Galvanized	No	Prior to 1997	0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400815		3769-001-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400816		3769-001-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400817		3760-000-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400818		3760-000-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400819		3760-000-001-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400820		3760-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400821		3760-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400822		3780-002-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400823		3780-002-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400824		3780-001-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400825		3780-001-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400826		3760-000-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400827		3760-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400828		3760-000-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400829		3760-000-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400830		3760-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400831		3769-001-005-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400832		3769-001-005-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400833		3769-001-005-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400834		3769-001-005-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400835		3769-001-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400836		3769-001-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400837		3756-000-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400838		3756-000-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400839		3756-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400840		3779-001-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400841		3779-001-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400842		3779-001-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400843		3779-001-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400844		3779-001-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400845		3779-001-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400846		3779-001-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400847		3779-001-018-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400848		3779-001-018-0100	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400849		3779-001-019-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400850		3743-001-013-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400851		3743-002-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400852		3743-002-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400853		3743-002-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400854		3743-002-025-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400855		3743-002-025-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400856		3743-002-024-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400857		3743-002-024-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400865		3743-002-016-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400866		3743-005-020-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400867		3743-005-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400868		3743-005-024-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400869		3743-002-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400870		3743-005-025-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400871		3743-005-026-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400872		3743-002-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400873		3743-002-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400874		3743-005-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400875		3743-002-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400876		3743-002-008-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400877		3743-002-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		<Null>		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400878		3743-002-005-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400879		3743-002-003-0108	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400880		3743-002-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.50	<Null>			2016-2024		Non-Lead - Plastic		1.50		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400881		3743-001-020-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400882		3743-001-020-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400883		3743-001-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400884		3743-006-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400885		3743-006-022-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400886		3743-006-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400887		3743-001-013-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400888		3743-006-026-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400889		3743-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400890		3743-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400891		3743-006-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400892		3743-006-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400893		3743-006-008-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400894		3743-005-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2082	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2082	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400895		3743-005-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Abandon		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Abandon	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400896		3743-005-006-0009	No	Not evaluated	Galvanized	No	Prior to 2017	0.75	Book 19 pg 3	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 19 pg 3	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400897		3743-005-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400898		3743-005-008-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400899		3743-005-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400900		3743-005-010-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400901		3743-005-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400902		3743-005-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400903		3743-005-015-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400904		3743-005-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400905		3743-004-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 20 Pg73	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 20 Pg73	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400906		3743-004-014-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400907		3743-004-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400908		3743-004-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400909		3743-004-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 30	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400910		3743-004-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48			2016-2024		Non-Lead - Copper		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400911		3743-004-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400912		3743-005-020-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400913		142401-4-017-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400914		3743-003-008-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400915		3743-003-007-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400916		3743-003-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400917		3743-003-005-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400918		3743-003-003-0007	No	Not evaluated	Non-Lead - Other	No		8.00	<Null>			2016-2024		Unknown		8.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400919		3743-003-001-0009	Yes - Schoo	Not evaluated	Non-Lead - Other	No		4.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		4.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400920		142401-4-015-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400921		142401-4-014-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400922		142401-4-016-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND	Visual inspection at the meter pit		2016-2024		None		0.75	ABAND	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400923		142401-4-012-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400924		142401-4-017-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400925		142401-4-017-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400926		3804-008-001-0905	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400927		3804-008-002-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400928		3754-000-017-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400929		3754-000-021-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400930		3754-000-017-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400931		3754-000-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400932		3754-000-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400933		3754-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400934		3804-007-004-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400935		3804-007-004-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400936		3804-007-004-0508	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400937		3804-007-004-0508	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400938		3754-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400939		3754-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400940		3754-000-007-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400941		3754-000-007-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400942		3754-000-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400943		3754-000-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400944		3754-000-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400945		3754-000-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400946		3804-008-002-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400947		3804-008-002-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400948		3804-008-002-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400949		3804-008-002-0300	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400950		3804-008-003-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400951		3804-008-003-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400952		3804-008-004-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400953		3804-008-004-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060			2016-2024		Galvanized		0.75	BEDA 2060	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400954		3804-008-009-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400955		3740-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400956		3740-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2400963		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400964		3804-007-005-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400965		3798-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400966		3798-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400967		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400968		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400969		3804-005-005-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400970		3804-005-005-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2400971		3804-005-004-0205	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400972		3804-005-004-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400973		3804-005-006-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400974		3804-005-007-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074			2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400975		3804-005-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2080	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2080	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400976		3804-005-006-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2082	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2082	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400977		3804-005-007-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400978		3804-005-006-0500	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2400979		3804-005-006-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400980		3804-005-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400981		142401-1-043-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400982		142401-1-043-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400983		142401-1-002-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400984		142401-1-002-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400985		142401-1-002-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400986		142401-1-003-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400987		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400988		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400989		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2400990		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400991		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400992		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400993		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400994		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400995		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400996		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400997		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400998		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2400999		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401000		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401001		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401002		3804-008-009-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401003		3797-007-006-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401004		3797-007-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401005		3797-007-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401006		3797-016-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48			2016-2024		Galvanized		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401007		3797-016-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401008		3797-016-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)			2016-2024		Galvanized		0.75	BEDA 3771 (FM)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401009		3804-008-005-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401010		3797-016-007-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401011		3797-016-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401012		3797-016-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401013		3797-016-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401014		3797-015-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401015		3797-016-015-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401016		3797-016-015-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401017		3797-016-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401018		3797-016-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401019		3797-007-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401020		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401021		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401022		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401023		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401024		3797-002-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401025		3797-002-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401026		3797-002-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401027		3797-005-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401028		3797-005-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401029		3797-005-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401030		3797-005-004-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401031		3797-005-010-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401032		3797-005-010-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401033		3797-005-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401034		3708-002-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401035		3708-002-013-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401036		3708-002-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401037		3708-002-010-0003	No	Not evaluated	Galvanized	No	Prior to 1990	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401038		3708-002-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401039		3708-002-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401040		3708-002-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401041		3708-002-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401042		3708-002-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401043		3708-002-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401044		3708-002-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401045		3708-002-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401046		3708-001-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401047		3708-001-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401048		142401-1-009-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401049		142401-1-015-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401050		142401-1-027-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401051		142401-1-027-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401052		3797-009-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401053		3797-009-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401054		3797-009-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401055		3797

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401061		3797-014-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3091	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401062		3797-014-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401063		3797-014-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401064		3797-014-017-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401065		3797-014-017-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401066		3797-009-010-0000	No	Not evaluated	Galvanized	No	Prior to 1977	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401067		3797-009-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401068		3797-009-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401069		3797-009-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401070		3797-010-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401071		3797-010-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401072		3797-013-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401073		3797-013-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401074		3797-013-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401075		3797-013-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401076		3797-013-010-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401077		3797-013-012-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401078		3797-013-015-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 20 Pg 73	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 20 Pg 73	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401079		3797-013-015-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 20 Pg 73			2016-2024		Galvanized		0.75	Book 20 Pg 73	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401080		3797-010-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401081		3797-010-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401082		3797-010-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401083		3797-012-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401084		3797-012-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401085		3797-012-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401086		3797-012-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401087		3797-012-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401088		3797-012-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401089		3797-012-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401090		3797-012-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401091		3797-012-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401092		3797-011-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401093		3797-011-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401094		142401-1-028-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401095		142401-1-035-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401096		142401-1-041-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401097		142401-1-034-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401098		142401-1-033-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401099		142401-1-032-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401100		142401-1-032-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401101		142401-1-031-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401102		142401-1-031-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401103		142401-1-030-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401104		142401-1-026-2009	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401105		142401-1-023-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401106		142401-1-021-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401107		142401-1-040-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401108		142401-1-020-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401109		3782-002-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401110		3782-002-005-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401111		3782-002-004-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401112		3782-002-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401113		3782-002-003-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401114		3782-002-003-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401115		3782-002-002-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401116		3782-002-002-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401117		3782-002-001-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401118		3782-002-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401119		142401-1-048-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401120		142401-1-049-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401121		142401-1-049-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401122		142401-1-016-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401123		142401-1-014-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401124		142401-1-011-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401125		142401-1-011-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401126		142401-1-012-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401127		3782-001-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401128		3782-001-002-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401129		3782-001-002-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401130		3782-001-002-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401131		3782-001-002-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401132		3782-001-003-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401133		3782-001-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401134		3782-001-003-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401135		3782-001-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401136		3782-001-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401137		3782-001-005-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401138		3782-001-005-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401139		142401-2-001-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401140		142401-2-002-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401141		142401-2-003-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401142		142401-2-004-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401143		142401-2-005-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401144		142401-2-006-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401145		142401-2-007-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401146		142401-2-008-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401147		142401-2-009-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401148		142401-2-010-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401149		142401-2-011-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401150		142401-2-012-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401151		142401-2-013-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401152		142401-2-014-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401153		142401-2-015-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401159		3741-000-011-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401160		3741-000-010-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401161		3741-000-009-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401162		3741-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401163		3741-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401164		3741-000-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401165		3741-000-005-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401166		3741-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401167		3741-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401168		3741-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401169		3741-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401170		3741-000-003-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401171		3741-000-002-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401172		3741-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401173		3711-000-001-0607	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401174		3741-000-016-0307	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401175		3741-000-016-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401176		3741-000-018-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401177		3741-000-017-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401178		3741-000-017-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401179		3741-000-016-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401180		3741-000-015-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401181		3741-000-014-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401182		3741-000-014-0507	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401183		3741-000-014-0408	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401184		3741-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401185		3741-000-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401186		3741-000-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401187		3741-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401188		142401-2-025-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401189		3711-000-001-0607	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401190		3711-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401191		3711-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401192		3710-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401193		3710-000-007-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401194		3710-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401195		142401-2-024-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401196		3739-000-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401197		3739-000-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401198		3739-000-007-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401199		3739-000-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401200		3775-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401201		3775-000-004-0300	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401202		3775-000-004-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401203		3775-000-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401204		3775-000-003-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401205		3775-000-002-0609	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401206		3775-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401207		3775-000-002-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401208		3775-000-002-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401209		3775-000-002-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401210		3775-000-001-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401211		3775-000-001-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401212		3775-000-001-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401213		3775-000-001-0303	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401214		3775-000-002-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401215		3775-000-002-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401216		3775-000-002-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401217		3775-000-003-0400	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401218		3775-000-003-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401219		3775-000-004-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401220		3775-000-004-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401221		3775-000-005-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401222		3775-000-005-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401223		3775-000-019-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401224		3775-000-019-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401225		3742-000-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401226		3742-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401227		3742-000-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401228		3742-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401229		3746-001-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401230		3746-001-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401231		3746-001-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401232		3746-001-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401233		3746-001-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401234		3746-001-019-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401235		3775-000-040-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401236		3775-000-040-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401237		3775-000-040-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2187	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2187	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401238		3775-000-040-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401239		3746-006-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401240		3746-006-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401241		3746-006-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401242		3746-006-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 4 Pg 63			2016-2024		Non-Lead - Plastic		0.75	Book 4 Pg 63	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401243		3746-006-001-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401244		3746-006-001-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Book 6 pg 16			2016-2024		Non-Lead - Plastic		1.00	Book 6 pg 16	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401245		3746-001-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 63	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 63	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401246		3746-001-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	E435	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401247		3746-001-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	E474	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E474	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401248		3746-001-015-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401249		3746-001-016-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
B

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401257		3706-000-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401258		3706-000-003-0008	No	Not evaluated	Galvanized	No	Prior to 1962	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401259		3706-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401260		3706-000-023-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401261		3706-000-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401262		3706-000-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401263		3706-000-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401264		3746-002-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401265		3746-002-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401266		3746-002-004-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401267		3746-002-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	E428			2016-2024		Non-Lead - Plastic		0.75	E428	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401268		3746-002-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71			2016-2024		Non-Lead - Plastic		0.75	Book 7 Pg 71	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401269		3746-002-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401270		3746-002-019-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401271		3746-005-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401272		3746-005-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401273		3746-005-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401274		3746-005-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3091	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401275		3746-005-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752			2016-2024		Non-Lead - Plastic		0.75	BEDA 2752	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401276		3746-005-008-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401277		3746-005-008-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401278		3746-005-008-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401279		3746-005-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401280		3746-005-010-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401281		3746-005-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2080	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2080	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401282		3746-005-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401283		3746-005-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401284		3746-005-015-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401285		3746-005-018-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401286		3746-002-020-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6			2016-2024		Galvanized		0.75	Book 6	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401287		3746-002-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401288		3746-002-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435			2016-2024		Non-Lead - Plastic		0.75	E435	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401289		3746-002-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401290		3746-002-015-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401291		3746-002-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401292		3706-000-013-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401293		3706-000-013-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401294		3706-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401295		3775-000-016-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401296		3775-000-016-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401297		3775-000-016-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401298		3749-001-007-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401299		3749-001-007-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401300		3746-003-016-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401301		3746-003-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401302		3746-003-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401303		3746-003-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401304		3746-003-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401305		3746-003-006-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401306		3746-003-007-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401307		3746-003-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401308		3746-003-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 20			2016-2024		Non-Lead - Copper		0.75	Book 6 pg 20	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401309		3746-004-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 6	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 6	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401310		3746-004-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401311		3746-004-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401312		3746-004-007-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401313		3746-004-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401314		3746-004-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401315		3746-004-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085			2016-2024		Non-Lead - Plastic		0.75	BEDA 2085	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401316		3746-004-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401317		3746-004-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401318		3746-004-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401319		3746-004-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401320		3746-004-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401321		3746-004-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401322		3746-003-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 16	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 16	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401323		3746-003-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401324		3746-003-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401325		3746-003-015-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401326		3749-001-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401327		3749-001-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401328		3749-001-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401329		3749-001-001-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401330		3775-000-006-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401331		3775-000-006-0407	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401332		3775-000-006-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401333		3775-000-006-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401334		3775-000-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401335		142401-2-027-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401336		142401-2-028-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401337		142401-2-029-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401338		142401-2-030-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401339		142401-2-031-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401340		142401-2-032-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401341		142401-2-033-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401342		142401-2-034-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401343		142401-2-035-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401344		142401-2-036-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401345		142401-2-037-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401346		142401-2-038-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401347		142401-2-039-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter p

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401355		142401-2-049-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401356		142401-2-050-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401357		142401-2-051-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401358		142401-2-052-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401359		142401-2-053-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401360		142401-2-054-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401361		142401-2-055-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401362		142401-2-056-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401363		142401-2-145-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401364		142401-2-057-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401365		142401-2-058-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401366		142401-2-059-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401367		142401-2-060-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401368		142401-2-061-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401369		142401-2-062-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401370		142401-2-063-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401371		142401-2-064-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401372		3775-000-009-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401373		3775-000-009-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401374		3775-000-009-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401375		3775-000-009-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401376		3809-000-009-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401377		3809-000-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401378		3809-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401379		3809-000-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401380		3809-000-013-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401381		3809-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401382		3809-000-001-0006	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401383		3809-000-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401384		3809-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401385		3809-000-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401386		3749-002-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401387		3749-002-014-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401388		3749-002-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401389		3749-002-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401390		3775-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401391		3775-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401392		3775-000-029-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401393		3775-000-029-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401394		3775-000-028-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401395		3775-000-028-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401396		3775-000-028-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401397		3775-000-027-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401398		3775-000-027-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401399		3775-000-027-0402	No	Not evaluated	Non-Lead - Plastic	No		0.75	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401400		3775-000-027-0204	No	Not evaluated	Non-Lead - Copper	No		2.00	fc	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401401		3775-000-027-0303	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401402		3775-000-027-0600	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401403		3775-000-034-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49			2016-2024		<Null>		0.75	Book 5 pg 49	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401404		3775-000-034-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 28	Live Service not in use		2016-2024		<Null>		0.75	Book 5 pg 28	No	Live Service not in use	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401405		3775-000-034-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485			2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401406		3775-000-034-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091			2016-2024		Non-Lead - Copper		0.75	BEDA 3091	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401407		3775-000-034-0403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401408		3775-000-034-0502	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401409		3775-000-033-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401410		3775-000-032-0801	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401411		3775-000-032-0801	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401412		3775-000-033-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401413		3775-000-033-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401414		3775-000-032-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401415		3775-000-032-0207	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401416		3775-000-032-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401417		3775-000-031-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401418		3775-000-031-0406	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401419		3775-000-031-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401420		3775-000-031-0505	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 63	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 63	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401421		3775-000-031-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401422		3775-000-032-0405	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401423		3775-000-029-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401424		3775-000-030-0209	No	Not evaluated	Galvanized	No	Prior to 1991	0.75	Book 6 Pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401425		3775-000-030-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 30	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401426		3775-000-030-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401427		3775-000-030-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401428		3775-000-030-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401429		3775-000-030-0605	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401430		3775-000-030-0704	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401431		3816-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401432		3816-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401433		3816-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401434		3816-000-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401435		3816-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401436		3775-000-010-0203	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401437		3775-000-010-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401438		3775-000-010-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401439		3775-000-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401440		142401-2-065-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401441		142401-2-066-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401442		142401-2-067-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401443		142401-2-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401444		142401-2-069-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401445		142401-2-070-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401446		142401-2-071-2001	No	Not evaluated	Non-Lead

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401453		142401-2-077-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401454		142401-2-201-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401455		142401-2-081-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401456		8027-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401457		142401-2-085-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401458		142401-2-088-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401459		142401-2-090-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401460		142401-2-093-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401461		142401-2-094-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401462		142401-2-096-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401463		142401-2-099-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401464		142401-2-100-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401465		142401-2-101-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401466		142401-2-102-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401467		142401-2-102-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401468		142401-2-103-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401469		142401-2-104-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401470		3817-001-004-0407	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401471		3817-001-004-0506	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401472		3817-001-004-0209	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401473		3817-001-004-0308	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401474		3817-001-004-0308	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401475		3817-001-003-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401476		3817-001-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401477		3817-001-003-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401478		3817-001-003-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401479		3817-001-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401480		3817-001-002-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401481		3817-001-001-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2082	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2082	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401482		3817-001-001-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401483		3817-001-001-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401484		3817-001-001-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401485		3817-001-001-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401486		3817-001-001-0608	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401487		3817-001-001-0707	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401488		142401-2-188-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401489		142401-2-189-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401490		142401-2-190-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401491		142401-2-191-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401492		142401-2-192-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401493		142401-2-193-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401494		142401-2-186-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 Pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 Pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401495		142401-2-185-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401496		142401-2-184-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 30	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401497		142401-2-183-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401498		3767-003-001-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401499		3767-003-003-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401500		3767-003-004-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401501		3767-003-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401502		3767-003-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401503		3767-003-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401504		3767-003-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 49	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401505		3767-003-014-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401506		3767-003-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401507		3767-003-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401508		3767-003-019-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401509		3767-003-021-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401510		3767-003-023-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401511		3767-003-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401512		3767-003-025-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401513		3767-003-028-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401514		3767-003-029-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401515		3767-003-032-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401516		3767-003-034-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401517		3767-003-036-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401518		3767-003-039-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401519		3755-001-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401520		3755-001-006-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401521		3755-001-006-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401522		3755-001-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401523		3755-001-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401524		3755-001-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401525		3755-001-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401526		3755-001-001-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401527		3755-001-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401528		3755-002-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401529		3755-002-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401530		3755-002-001-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401531		3755-002-001-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401532		3755-002-001-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401533		3755-002-001-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401534		3755-002-002-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401535		3755-002-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401536		3755-002-003-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401537		3755-002-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401538		3755-002-005-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401539		3755-002-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401540		3755-002-007-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401541		3755-002-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401542		3767-002-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401543		3767-002-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401551		3767-002-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401552		3767-002-019-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401553		3718-021-017-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401554		3718-021-017-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401555		3718-021-013-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401556		3718-021-003-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401557		3718-021-003-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401558		3785-001-003-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401559		3785-001-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401560		3785-001-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401561		3785-001-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401562		3785-001-009-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401563		3785-001-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401564		3785-001-012-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401565		3785-001-011-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401566		3785-006-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Galvanized		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401567		3785-006-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401568		3785-006-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401569		3785-006-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401570		3785-006-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401571		3785-006-010-0000	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401572		3785-006-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401573		3785-006-012-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401574		3785-007-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401575		3785-007-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401576		3785-007-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401577		3785-007-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401578		3785-007-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401579		3785-007-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401580		3785-007-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401581		3717-009-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401582		3717-009-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401583		3717-009-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401584		3717-009-006-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401585		3717-009-008-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401586		3717-009-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401587		3717-009-010-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401588		3717-009-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401589		3717-009-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401590		3717-009-017-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401591		3717-009-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401592		3717-009-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401593		3717-009-018-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401594		3717-010-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401595		3717-010-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401596		3717-010-002-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401597		3717-010-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401598		3717-010-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401599		3717-010-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401600		3717-010-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401601		3717-010-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401602		3717-010-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401603		3717-010-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401604		3717-010-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401605		3717-010-014-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401606		3717-010-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401607		3717-010-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401608		3717-010-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401609		3717-007-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401610		3717-007-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401611		3717-007-024-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401612		3717-007-025-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401613		3717-007-026-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401614		3717-007-027-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401615		3717-007-029-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401616		3717-007-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401617		3717-007-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401618		3717-007-032-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401619		3717-007-033-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401620		3717-007-034-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401621		3717-007-035-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401622		3717-007-037-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401623		3717-007-038-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401624		3717-007-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401625		3717-008-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401626		3717-008-021-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401627		3717-008-022-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401628		3717-008-024-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401629		3717-008-025-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401630		3717-008-027-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401631		3717-008-028-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401632		3717-008-031-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401633		3717-008-033-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401634		3717-008-034-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401635		3717-008-035-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401636		3717-008-035-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401637		3717-008-035-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401638		3717-008-037-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401639		3717-008-039-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401640		3717-008-039-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401641		3785-008-013-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401642		3785-008-013-0102	No	Not

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401649		3785-008-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401650		3785-008-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401651		3785-008-001-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401652		3785-008-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401653		3785-005-012-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401654		3785-005-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401655		3785-005-012-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401656		3785-005-010-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401657		3785-005-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401658		3785-005-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401659		3785-005-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401660		3785-005-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401661		3785-005-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401662		3785-002-012-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401663		3785-002-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401664		3785-002-009-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401665		3785-002-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401666		3785-002-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401667		3785-002-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401668		3785-002-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401669		3785-002-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401670		3785-002-003-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401671		3785-002-001-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401672		3785-002-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401673		3785-002-020-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401674		3785-002-018-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401675		3785-002-018-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401676		3785-002-018-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401677		3785-002-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401678		3785-002-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401679		3785-002-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401680		3785-002-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401681		3785-002-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401682		3785-002-014-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401683		3785-005-023-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401684		3785-005-021-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401685		3785-005-019-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401686		3785-005-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401687		3785-005-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401688		3785-005-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401689		3785-005-014-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401690		3785-008-023-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401691		3785-008-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401692		3785-008-021-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401693		3785-008-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401694		3785-008-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401695		3785-008-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401696		3785-008-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401697		3785-008-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401698		3785-008-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401699		3717-008-001-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401700		3717-008-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401701		3717-008-002-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401702		3717-008-002-0009	No	Not evaluated	Galvanized	No	Prior to 1992	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401703		3717-008-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401704		3717-008-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401705		3717-008-009-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401706		3717-008-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401707		3717-008-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401708		3717-008-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401709		3717-008-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401710		3717-008-015-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401711		3717-008-016-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401712		3717-008-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401713		3717-008-019-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401714		3717-007-001-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401715		3717-007-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401716		3717-007-003-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401717		3717-007-005-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401718		3717-007-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401719		3717-007-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401720		3717-007-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401721		3717-007-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401722		3717-007-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401723		3717-007-015-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401724		3717-007-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401725		3717-007-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401726		3717-007-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401727		3717-007-019-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401728		3717-006-021-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401729		3717-006-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401730		3717-006-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401731		3717-006-027-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401732		3717-006-029-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401733		3717-006-031-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401734		3717-006-032-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401735		3717-006-033-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401736		3717-006-035-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401737		3717-006-039-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401738		3717-005-021-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401739		3717-005-023-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401740		3717-005-024-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401747		3717-005-034-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401748		3717-005-036-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401749		3717-005-037-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401750		3717-005-038-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401751		3785-009-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401752		3785-009-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401753		3785-009-005-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401754		3785-009-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401755		3785-009-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401756		3785-009-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401757		3785-004-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401758		3785-004-012-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401759		3785-004-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401760		3785-004-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401761		3785-004-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401762		3785-004-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401763		3785-004-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401764		3785-004-001-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401765		3785-004-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401766		3785-003-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401767		3785-003-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401768		3785-003-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401769		3785-003-008-0001	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401770		3785-003-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401771		3785-003-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401772		3785-003-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401773		3785-003-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401774		3795-003-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401775		3795-003-001-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401776		3795-003-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401777		3795-003-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401778		3795-003-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401779		3795-003-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401780		3795-003-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401781		3795-003-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401782		3795-003-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401783		3795-003-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401784		3795-004-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401785		3751-003-001-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401786		3751-004-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401787		3751-004-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401788		3751-004-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401789		3751-004-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401790		3717-005-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401791		3717-005-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401792		3717-005-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401793		3717-005-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401794		3717-005-007-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401795		3717-005-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401796		3717-005-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401797		3717-005-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401798		3717-005-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401799		3717-005-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401800		3717-005-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401801		3717-005-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401802		3717-005-018-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401803		3717-005-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401804		3717-006-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401805		3717-006-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401806		3717-006-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401807		3717-006-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401808		3717-006-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401809		3717-006-009-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401810		3717-006-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401811		3717-006-012-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401812		3717-006-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401813		3717-006-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401814		3717-006-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401815		3717-003-021-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401816		3717-003-023-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401817		3717-003-024-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401818		3717-003-025-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401819		3717-003-026-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401820		3717-003-028-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401821		3717-003-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401822		3717-003-031-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401823		3717-003-032-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401824		3717-003-034-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401825		3717-003-037-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401826		3717-004-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401827		3717-004-022-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401828		3717-004-023-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401829		3717-004-025-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401830		3717-004-028-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401831		3717-004-028-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401832		3717-004-029-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401833		3751-002-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401834		3751-002-011-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401835		3795-002-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401836		3795-002-017-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401837		3795-002-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401838		3795-002-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024	

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier					Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Other Potential Sources of: Is there a Lead Connector?	Other Potential Sources of: Is there Lead Solder in the Service Line?	Other Potential Sources of: Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401845		3795-002-026-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401846		3795-002-027-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401847		3795-002-028-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401848		3795-002-029-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401849		3795-002-029-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401850		3795-002-029-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401851		3795-002-001-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401852		3795-002-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401853		3795-002-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401854		3795-002-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401855		3795-002-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401856		3795-002-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401857		3795-002-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401858		3795-002-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401859		3795-002-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401860		3795-002-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401861		3795-002-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401862		3795-002-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401863		3795-002-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401864		3795-002-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401865		3795-002-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401866		3795-002-014-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401867		3751-002-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401868		3751-002-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401869		3751-002-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401870		3751-002-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401871		3751-002-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401872		142401-4-018-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401873		3717-004-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401874		3717-004-013-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401875		3717-004-014-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401876		3717-004-015-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401877		3717-004-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401878		3717-004-018-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401879		3717-004-019-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401880		3717-004-019-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401881		3717-003-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401882		3717-003-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401883		3717-003-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401884		3717-003-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401885		3717-003-005-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401886		3717-003-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401887		3717-003-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401888		3717-003-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401889		3717-003-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401890		3717-003-013-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401891		3717-003-014-0006	No	Not evaluated	Non-Lead - Copper	No		1.50	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401892		3717-003-015-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401893		3717-003-016-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401894		3717-003-017-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401895		3717-003-018-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401896		3717-003-019-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401897		3717-003-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401898		3717-002-021-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401899		3717-002-024-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401900		3717-002-025-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401901		3717-002-027-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401902		3717-002-029-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401903		3717-002-030-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401904		3717-002-031-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401905		3717-002-033-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401906		3717-002-034-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401907		3717-002-035-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401908		3717-002-036-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401909		3717-002-037-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401910		3717-002-038-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401911		3717-002-039-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401912		3717-001-021-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401913		3717-001-021-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401914		3717-001-023-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401915		3717-001-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401916		3717-001-026-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401917		3717-001-027-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401918		3717-001-029-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401919		3717-001-030-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401920		3717-001-031-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401921		3717-001-032-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401922		3717-001-034-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401923		3717-001-034-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401924		3717-001-036-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401925		3717-001-037-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401926		3717-001-038-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401927		3717-001-039-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401928		3751-001-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401929		3751-001-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401930		3751-001-012-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401931		3751-001-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401932		3751-001-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401933		3751-001-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401934		3751-001-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401935		3751-001-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401936		3751-001-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown		

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2401943		3795-001-025-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401944		3795-001-026-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401945		3795-001-026-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401946		3795-001-027-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401947		3795-001-029-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401948		3795-001-030-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401949		3795-001-001-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401950		3795-001-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401951		3795-001-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401952		3795-001-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401953		3795-001-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401954		3795-001-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401955		3751-001-001-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401956		3751-001-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401957		3751-001-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401958		3751-001-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401959		3751-001-008-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401960		3751-001-008-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401961		3751-001-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401962		3751-001-008-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401963		3717-001-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401964		3717-001-001-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401965		3717-001-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401966		3717-001-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401967		3717-001-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401968		3717-001-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2401969		3717-001-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401970		3717-001-011-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401971		3717-001-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401972		3717-001-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401973		3717-001-015-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2401974		3717-001-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401975		3717-001-019-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401976		3717-001-019-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401977		3717-002-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401978		3717-002-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401979		3717-002-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401980		3717-002-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401981		3717-002-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401982		3717-002-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401983		3717-002-010-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401984		3717-002-011-0001	No	Not evaluated	Galvanized	No	Prior to 2007	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401985		3717-002-013-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401986		3807-009-005-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401987		3807-009-005-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401988		3807-010-019-0007	No	Not evaluated	Galvanized	No	Prior to 2004	0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401989		3807-010-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401990		3807-010-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401991		3807-010-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401992		3807-010-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401993		3797-026-008-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401994		3797-027-010-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401995		3797-027-010-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2401996		3797-027-008-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401997		3797-027-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401998		3797-028-007-0203	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2401999		3797-028-007-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402000		3811-002-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402001		3811-002-020-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402002		3811-002-020-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402003		3811-002-020-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402004		3811-002-025-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402005		3811-002-028-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402006		3811-002-029-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402007		3811-001-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402008		3811-001-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402009		3811-001-019-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402010		3811-001-020-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402011		3811-001-021-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402012		3811-001-022-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402013		3811-001-023-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402014		3811-001-023-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402015		3811-001-024-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402016		3811-001-025-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402017		3811-001-027-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402018		3811-001-028-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402019		3811-001-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402020		3811-001-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402021		3811-001-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402022		3811-001-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402023		3811-001-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402024		3811-001-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402025		3811-001-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402026		3811-001-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402027		3811-001-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402028		3811-001-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402029		3811-001-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402030		3811-001-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402031		3811-001-014-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402032		3811-001-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402033		3811-002-029-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402034		3811-002-001-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402041		3811-002-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402042		3811-002-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402043		3811-002-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402044		3811-002-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402045		3811-002-013-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402046		3811-002-013-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402047		3811-002-013-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402048		3797-028-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402049		3797-028-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402050		3797-023-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402051		3811-003-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402052		3811-003-016-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402053		3811-003-016-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402054		3811-003-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402055		3811-003-020-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402056		3811-003-020-0003	No	Not evaluated	Non-Lead - Other	No		4.00	Field Check			2016-2024		Non-Lead - Plastic		4.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402057		3811-003-021-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402058		3811-003-023-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402059		3811-003-023-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402060		3811-003-025-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402061		3811-003-026-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402062		3811-003-028-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402063		3811-003-029-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402064		3811-003-029-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402065		3811-004-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402066		3811-004-017-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402067		3811-004-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402068		3811-004-019-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402069		3811-004-020-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402070		3811-004-021-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402071		3811-004-022-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402072		3811-004-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402073		3811-004-024-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402074		3811-004-025-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402075		3811-004-026-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402076		3811-004-027-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402077		3811-004-028-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402078		3811-004-029-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402079		3811-004-030-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402080		3811-004-029-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402081		3811-004-029-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402082		3811-004-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402083		3811-004-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402084		3811-004-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402085		3811-004-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402086		3811-004-003-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402087		3811-004-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402088		3811-004-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402089		3811-004-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402090		3811-004-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402091		3811-004-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402092		3811-004-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402093		3811-004-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402094		3811-004-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402095		3811-004-014-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402096		3811-004-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402097		3811-003-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402098		3811-003-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402099		3811-003-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402100		3811-003-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402101		3811-003-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402102		3811-003-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402103		3811-003-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402104		3811-003-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402105		3811-003-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402106		3811-003-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402107		3811-003-011-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402108		3811-003-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402109		3811-003-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402110		3811-003-014-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402111		3797-023-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402112		3797-023-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402113		3797-023-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402114		3811-006-013-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402115		3811-006-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402116		3811-006-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402117		3811-006-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402118		3811-006-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402119		3811-006-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402120		3811-006-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402121		3811-006-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402122		3811-006-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402123		3811-006-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402124		3811-006-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402125		3811-006-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402126		3811-006-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402127		3811-005-015-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402128		3811-005-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402129		3811-005-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402130		3811-005-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402131		3811-005-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402132		3811-005-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402139		3811-005-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402140		3799-008-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402141		3799-008-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402142		3799-008-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402143		3799-008-002-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402144		3799-008-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402145		3799-008-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402146		3799-008-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402147		3799-008-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402148		3799-008-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402149		3799-008-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402150		3799-008-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402151		3799-008-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402152		3799-008-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402153		3799-008-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402154		3799-008-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402155		3799-008-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402156		3799-008-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402157		3799-008-015-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402158		3799-008-015-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402159		3799-007-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402160		3799-007-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402161		3799-007-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402162		3799-007-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402163		3799-007-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402164		3799-007-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402165		3799-007-008-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402166		3799-007-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402167		3799-007-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402168		3797-022-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402169		3797-022-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402170		3797-022-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402171		3797-022-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402172		3797-022-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402173		142401-4-021-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402174		142401-4-022-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402175		3799-010-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402176		3799-010-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402177		3799-010-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402178		3799-010-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402179		3799-010-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402180		3799-010-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402181		3799-010-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402182		3799-010-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402183		3799-010-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402184		3799-010-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402185		3799-010-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402186		3799-009-022-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402187		3799-009-027-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402188		3799-009-029-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402189		3799-009-031-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402190		3799-009-034-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402191		3799-009-034-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402192		3799-009-037-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402193		3799-009-038-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402194		3799-009-040-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402195		3799-009-040-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402196		3799-009-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402197		3799-009-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402198		3799-009-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402199		3799-009-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402200		3799-009-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402201		3799-009-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402202		3799-009-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402203		3799-009-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402204		3799-009-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402205		3799-009-014-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402206		3758-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		<Null>		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402207		3758-000-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402208		3758-000-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402209		3758-000-020-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402210		3758-000-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402211		3758-000-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402212		3758-000-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402213		3758-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402214		3758-000-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402215		3758-000-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402216		3758-000-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402217		3797-017-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	<Null>			2016-2024		Galvanized		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402218		3797-017-007-0008	No	Not evaluated	Non-Lead - Plastic	No		1.50	<Null>			2016-2024		Non-Lead - Plastic		1.50		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402219		3797-017-006-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402220		3797-017-005-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402221		3797-017-003-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402222		3797-017-001-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402223		142401-4-019-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402224		142401-4-020-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402225		3758-000-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402226		3758-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402227		3758-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402228		3758-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402229		3758-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402230		3758-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402231		3758-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402232		3758-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402237		3799-012-020-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402238		3799-012-022-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402239		3799-012-022-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402240		3799-012-024-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402241		3799-012-025-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402242		3799-012-027-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402243		3799-012-029-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402244		3799-012-030-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402245		3799-012-032-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402246		3799-012-033-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402247		3799-012-035-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402248		3799-012-037-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402249		3799-012-039-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402250		3799-012-041-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402251		3799-012-041-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402252		3799-012-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402253		3799-012-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402254		3799-012-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402255		3799-012-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402256		3799-012-012-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402257		3799-012-014-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402258		3799-012-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402259		3799-012-017-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402260		3799-011-015-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402261		3797-017-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402262		3797-017-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND			2016-2024		None		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402263		3797-017-013-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402264		3797-017-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402265		3797-017-010-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402266		3797-022-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402267		3797-022-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402268		3797-022-013-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402269		3797-022-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402270		3797-022-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402271		3797-022-010-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402272		3797-022-010-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402273		3797-023-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402274		3797-023-001-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402275		3797-023-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402276		3797-023-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402277		3797-023-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402278		3797-023-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402279		3797-023-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402280		3797-023-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402281		3797-023-008-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402282		3797-028-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402283		3797-028-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402284		3797-028-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402285		3797-027-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402286		3797-024-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402287		3797-024-006-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402288		3797-024-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402289		3797-024-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402290		3797-024-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402291		3797-021-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402292		3797-021-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402293		3797-021-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402294		3797-021-003-0004	No	Not evaluated	Galvanized	No	Prior to 1995	0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402295		3797-021-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402296		3797-021-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402297		3797-018-008-0005	No	Not evaluated	Non-Lead - Other	No		2.00	<Null>			2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402298		3797-018-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402299		3797-018-004-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402300		3797-018-001-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402301		3797-018-015-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402302		3797-018-015-0204	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402303		3797-018-015-0204	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402304		3797-018-014-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402305		3797-018-010-0001	Yes - Schoo	Not evaluated	Non-Lead - Copper	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402306		3797-021-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402307		3797-021-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402308		3797-021-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402309		3797-021-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402310		3797-021-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402311		3797-021-010-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402312		3797-021-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402313		3797-021-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402314		3797-024-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402315		3797-024-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402316		3797-024-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402317		3797-024-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402318		3797-024-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402319		3797-027-017-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402320		3797-027-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402321		3797-027-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402322		3797-027-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402323		3797-026-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402324		3797-026-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402325		3797-025-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402326		3797-020-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402327		3797-020-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Un

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402335		3807-002-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402336		3807-002-005-0000	No	Not evaluated	Galvanized	No	Prior to 2002	0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402337		3807-002-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402338		3807-002-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402339		3807-002-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402340		3807-002-019-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402341		3807-002-019-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Galvanized		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402342		3807-002-018-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402343		3807-002-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402344		3807-002-014-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402345		3807-002-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402346		3807-002-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402347		3807-004-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402348		3807-004-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402349		3807-004-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402350		3807-004-004-0007	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402351		3807-004-002-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402352		3807-004-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew			2016-2024		Galvanized		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402353		3807-004-019-0000	No	Not evaluated	Galvanized	No	Prior to 2005	0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402354		3807-004-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402355		3807-004-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402356		3807-004-014-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402357		3807-004-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402358		3807-004-011-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402359		3797-020-007-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402360		3807-006-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402361		3807-006-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402362		3807-006-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402363		3807-006-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402364		3807-006-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402365		3807-006-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402366		3807-006-002-0004	No	Not evaluated	Galvanized	No	Prior to 2003	0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402367		3807-006-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402368		3807-006-019-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402369		3807-006-018-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402370		3807-006-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402371		3807-006-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402372		3807-006-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402373		3797-025-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402374		3797-025-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402375		3797-025-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402376		3797-025-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402377		3807-008-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402378		3807-008-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402379		3807-008-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402380		3807-008-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402381		3807-008-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402382		3807-008-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402383		3807-008-019-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402384		3807-008-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402385		3807-008-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402386		3807-008-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402387		3807-008-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402388		3797-025-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402389		3797-025-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402390		3797-026-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402391		3807-010-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402392		3807-010-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402393		3807-010-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402394		3807-010-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402395		3807-010-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402396		3807-009-001-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402397		3807-009-001-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402398		3807-007-017-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402399		3807-007-016-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402400		3807-007-015-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402401		3807-007-014-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402402		3807-007-012-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402403		3807-007-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402404		3807-007-008-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402405		3807-007-008-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402406		3807-007-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402407		3807-007-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402408		3807-007-004-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402409		3807-007-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402410		3807-005-017-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402411		3807-005-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402412		3807-005-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402413		3807-005-010-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402414		3807-005-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402415		3807-005-008-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402416		3807-005-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402417		3807-005-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402418		3807-005-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402419		3807-005-001-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402420		3807-003-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402421		3807-003-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402422		3807-003-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402423		3807-003-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402424		3807-003-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402425		3807-003-012-0009	No	Not evaluated	Galvanized	No	Prior to 2008	0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Y

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402433		3807-001-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402434		3807-001-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402435		3807-001-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402436		3807-001-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402437		3807-001-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402438		3807-001-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402439		3807-001-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402440		3807-001-001-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402441		3807-001-017-0008	No	Not evaluated	Non-Lead - Copper	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402442		3807-003-001-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402443		3807-003-016-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	No CUSTOMER service line		2016-2024		Galvanized		0.75	Meter Crew	Yes	No CUSTOMER service line	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402444		3807-005-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402445		3807-007-001-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402446		3752-003-017-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402447		3752-003-017-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402448		3752-002-021-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402449		3752-002-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402450		3752-002-019-0108	No	Not evaluated	Non-Lead - Other	No		3.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		3.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402451		3752-002-019-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402452		142401-3-038-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402453		142401-3-037-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>			2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402454		142401-3-036-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402455		142401-3-039-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402456		142401-3-040-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402457		142401-3-041-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402458		142401-3-070-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402459		3766-001-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402460		3766-001-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402461		3766-001-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402462		3766-001-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402463		3766-001-001-0005	No	Not evaluated	Non-Lead - Plastic	No		6.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		6.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402464		3805-004-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402465		3805-004-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402466		3805-004-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402467		3805-004-013-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402468		3805-004-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402469		3805-004-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402470		3805-004-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402471		3805-004-017-0004	No	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402472		3805-004-018-0003	No	Not evaluated	UNK	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402473		3805-001-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402474		3805-001-011-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402475		3805-001-010-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402476		3805-001-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402477		3805-004-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402478		3805-001-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W131			2016-2024		Non-Lead - Plastic		0.75	W131	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402479		3805-004-002-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402480		3805-004-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402481		3805-004-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402482		3805-004-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402483		3805-004-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402484		3805-004-007-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402485		3805-004-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402486		3805-004-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402487		3766-001-018-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402488		3766-001-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402489		3766-001-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402490		3766-001-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402491		3766-001-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402492		142401-3-044-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402493		142401-3-045-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402494		142401-3-046-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402495		142401-3-047-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402496		142401-3-048-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402497		142401-3-048-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402498		3805-003-010-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402499		3805-003-011-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402500		3805-003-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402501		3805-003-013-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402502		3805-003-014-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402503		3805-003-015-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402504		3805-003-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402505		3805-003-017-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402506		3805-001-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 77	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Tap log 77	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402507		3805-003-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402508		3805-001-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Non-Lead - Plastic	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Non-Lead - Plasti	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402509		3805-001-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402510		3805-001-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402511		3805-001-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402512		3805-001-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402513		3805-003-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402514		3805-003-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402515		3805-003-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402516		3805-003-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402517		3805-003-006-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402518		3805-003-007-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402519		3805-003-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402520		3805-002-009-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402521		3805-002-008-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402522		3805-002-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402523		3805-002-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402524		3805-002-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402531		3810-001-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402532		3810-001-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402533		3810-002-001-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402534		3810-002-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402535		3810-002-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402536		3810-002-006-0004	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402537		3810-002-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402538		3810-002-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402539		3810-002-010-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402540		3810-002-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402541		3810-002-013-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402542		3810-002-015-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402543		3752-002-017-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402544		3752-002-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402545		3752-002-015-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402546		3752-002-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402547		3752-002-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402548		3752-002-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402549		3752-002-009-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402550		3752-002-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402551		3752-002-005-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402552		3752-002-003-0007	No	Not evaluated	Galvanized	No	Prior to 2014	0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402553		3752-002-001-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402554		3810-003-014-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402555		3810-003-013-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402556		3810-003-011-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402557		3810-003-010-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402558		3810-003-008-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402559		3810-003-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402560		3810-003-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402561		3810-003-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402562		3810-003-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402563		3810-001-003-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402564		3810-001-003-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402565		3810-001-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402566		3810-001-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402567		3810-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402568		3810-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402569		3810-003-029-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402570		3810-003-027-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402571		3810-003-026-0008	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402572		3810-003-024-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402573		3810-003-022-0002	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402574		3810-003-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402575		3810-003-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402576		3810-003-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402577		3810-003-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402578		3752-002-039-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402579		3752-002-037-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402580		3752-002-035-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402581		3752-002-033-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402582		3752-002-031-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402583		3752-002-030-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402584		3752-002-029-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402585		3752-002-027-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402586		3752-002-026-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402587		3752-002-025-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402588		3752-002-025-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402589		3752-002-024-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402590		3752-002-023-0003	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402591		3752-003-018-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402592		3752-003-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402593		3752-003-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402594		3752-003-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402595		3752-003-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402596		3752-003-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402597		3752-003-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402598		3752-003-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402599		3752-003-002-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402600		3752-003-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402601		3810-004-014-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402602		3810-004-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402603		3810-004-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402604		3810-004-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402605		3810-004-009-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402606		3810-004-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402607		3810-004-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402608		3810-004-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402609		3810-004-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402610		3810-004-001-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402611		3810-001-016-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402612		3810-004-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402613		3810-004-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402614		3810-004-016-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402615		3752-003-036-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402616		3752-003-031-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402617		3752-003-029-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402618		3752-003-025-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402619		3752-003-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402620		142401-3-065-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402629		3723-000-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402630		3723-000-014-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402631		3723-000-024-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402632		3723-000-015-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402633		3723-000-017-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402634		3723-000-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402635		3723-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402636		3723-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402637		3723-000-023-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402638		3723-000-020-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402639		3808-002-001-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402640		3723-000-022-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402641		3808-002-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402642		3723-000-021-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402643		3808-002-006-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402644		3808-002-008-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402645		3808-002-009-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402646		3723-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402647		3723-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402648		3723-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402649		3723-000-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402650		3723-000-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402651		3723-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402652		3723-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402653		3723-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402654		3723-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402655		3722-001-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402656		3722-001-006-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402657		3722-001-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402658		3722-001-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402659		3722-001-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402660		3722-001-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402661		3722-001-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402662		142401-3-012-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402663		3753-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402664		3753-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402665		3753-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402666		3753-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402667		142401-3-016-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402668		142401-3-015-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402669		142401-3-014-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402670		142401-3-013-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402671		3722-002-007-0109	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402672		3722-002-006-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402673		3722-002-005-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402674		3722-002-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402675		3722-002-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402676		3722-002-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402677		3727-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402678		3727-000-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402679		3727-000-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402680		3727-000-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402681		3727-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402682		3727-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402683		3727-000-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402684		3727-000-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402685		142401-3-018-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402686		142401-3-018-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402687		142401-3-019-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402688		142401-3-019-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402689		142401-3-021-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402690		142401-3-022-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402691		142401-3-023-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402692		3808-003-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402693		142401-3-025-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402694		142401-3-024-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402695		142401-3-027-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402696		142401-3-028-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402697		142401-3-029-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402698		142401-3-029-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402699		142401-3-030-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402700		142401-3-059-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402701		142401-3-031-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402702		142401-3-032-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402703		142401-3-033-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402704		3727-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402705		3778-005-020-0108	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402706		3727-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402707		3727-000-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402708		3778-005-020-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402709		3727-000-015-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402710		3727-000-015-0108	No	Not evaluated	Galvanized	No	Prior to 1970	0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402711		3778-005-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402712		3778-005-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402713		3778-005-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402714		3778-005-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402715		3778-005-007-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402716		3778-005-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402717		3778-005-009-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402718		3778-005-010-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402727		3778-005-015-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402728		3778-005-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402729		3778-005-017-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402730		3778-005-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402731		3778-004-003-0003	Yes - Schoo	Not evaluated	Non-Lead - Other	No		4.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		4.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402732		3778-004-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402733		3778-004-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402734		3778-004-005-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402735		3778-004-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402736		3778-004-007-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402737		3778-004-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402738		3778-004-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402739		3778-004-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402740		3778-004-011-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402741		3778-004-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402742		3778-004-012-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402743		3778-004-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Fc	Abandon		2016-2024		None		0.75	Field Check	Yes	Abandon	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2402744		3778-004-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402745		3778-004-014-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402746		3778-004-015-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402747		3778-004-016-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402748		3778-004-016-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402749		3778-004-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402750		3778-004-018-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402751		3778-004-019-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402752		3778-003-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402753		3778-003-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402754		3778-003-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402755		3778-003-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402756		3778-003-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402757		3778-003-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402758		3778-003-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402759		3778-003-008-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402760		3778-003-008-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402761		3778-003-010-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402762		3778-003-011-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402763		3778-003-011-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402764		3778-003-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1916	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1916	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402765		3778-003-013-0003	No	Not evaluated	Galvanized	No	Prior to 2031	0.75	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402766		3778-002-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402767		3778-003-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402768		3778-003-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402769		3778-003-014-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402770		3778-003-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402771		3778-003-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402772		3778-003-017-0009	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402773		3778-003-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402774		3778-003-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402775		3778-003-019-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402776		3778-002-020-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402777		3778-002-019-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402778		3778-001-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402779		3778-001-002-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402780		3778-001-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402781		3778-002-018-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402782		3778-001-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402783		3778-002-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402784		3778-002-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402785		3778-002-015-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402786		8189-000-125-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402787		3778-001-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402788		3778-002-014-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402789		3778-002-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 31	Service not in use		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 31	No	Service not in use	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402790		3778-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402791		3778-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402792		3778-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Non-Lead - Plastic		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402793		3778-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402794		3778-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402795		3778-001-008-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402796		3778-002-011-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402797		3778-002-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402798		3778-001-010-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402799		3806-006-017-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402800		3806-006-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402801		3806-006-016-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 2050			2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402802		3806-006-015-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402803		3806-006-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402804		3806-006-012-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402805		3806-006-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402806		3806-006-011-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402807		3806-006-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other		Unknown			
BremSLI-2402808		3806-006-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402809		3806-006-001-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402810		142401-3-068-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402811		142401-3-069-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402812		142401-3-066-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402813		142401-3-066-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402814		142401-3-067-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402815		142401-3-067-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402816		142401-3-067-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402817		142401-3-066-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402818		3734-009-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402825		3734-009-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402826		3734-009-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402827		3734-009-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402828		3735-024-019-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402829		3735-024-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402830		3735-024-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402831		3735-024-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402832		3735-024-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402833		3735-024-011-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402834		3735-024-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402835		3735-024-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W353	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W353	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402836		3735-024-005-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Year Built	Year Built		2016-2024		Non-Lead - Plastic		1.00	Year Built	Yes	Year Built	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402837		3735-024-003-0003	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402838		3735-024-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402839		3735-023-021-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402840		3734-010-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402841		3734-010-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402842		3734-010-005-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402843		3734-010-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402844		3734-010-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402845		3733-007-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402846		3733-007-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402847		3733-007-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402848		3733-007-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402849		3733-007-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402850		3806-005-035-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402851		3806-005-035-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402852		3806-005-033-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402853		3806-005-032-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402854		3806-005-030-0003	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402855		3806-005-029-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402856		3806-005-028-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402857		3806-005-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402858		3806-005-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402859		3806-005-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402860		3806-005-021-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts			2016-2024		Non-Lead - Copper		1.00	As-builts	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402861		3806-005-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402862		3806-005-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402863		3806-005-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402864		3806-005-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402865		3806-005-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402866		3806-005-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402867		3806-005-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402868		3733-007-021-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402869		3733-007-021-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402870		3733-007-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402871		3733-007-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402872		3733-007-025-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402873		3733-007-025-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402874		3733-007-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402875		3733-007-029-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402876		3733-007-029-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402877		3733-007-029-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402878		3733-007-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402879		3733-007-033-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402880		3733-007-035-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402881		3733-007-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402882		3733-007-037-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402883		3733-007-037-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402884		3734-010-021-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402885		3734-010-024-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402886		3734-010-027-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402887		3734-010-027-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402888		3734-010-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402889		3734-010-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402890		3734-010-031-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402891		3734-010-031-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402892		3734-010-031-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402893		3734-010-034-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402894		3734-010-034-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402895		3734-010-036-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402896		3735-022-001-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402897		3734-011-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402898		3734-011-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402899		3734-011-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402900		3734-011-012-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402901		3734-011-016-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402902		3733-006-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402903		3733-006-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402904		3733-006-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402905		3733-006-006-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402906		3733-006-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402907		3733-006-008-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402908		3733-006-008-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402909		3733-006-008-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402910		3733-006-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402911		3733-006-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402912		3733-006-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402913		3733-006-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402914		3733-006-017-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402915		3733-006-021-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2402923		3806-004-027-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402924		3806-004-025-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402925		232401-1-001-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402926		3732-004-015-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402927		3732-004-015-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402928		232401-1-001-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402929		3806-004-022-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402930		3806-004-020-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1916	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1916	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402931		3806-004-017-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402932		3806-004-017-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	FC	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402933		3806-004-016-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	No service		2016-2024		<Null>		0.75	Field Check	Yes	No service	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402934		3806-004-013-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402935		3806-004-011-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402936		3806-004-008-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402937		3806-004-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402938		3806-004-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402939		3806-004-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402940		3806-004-004-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402941		3733-006-021-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402942		8099-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402943		8099-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402944		8099-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402945		8099-000-003-0002	No	Not evaluated	Non-Lead - Other	No		8.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		8.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402946		8099-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402947		8099-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402948		8099-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402949		3733-006-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402950		3733-006-030-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402951		3733-006-032-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402952		3733-006-034-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402953		3733-006-034-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402954		3733-006-039-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402955		3734-012-018-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402956		3733-005-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402957		3733-005-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402958		3733-005-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402959		3733-005-011-0004	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402960		3733-005-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402961		3733-005-016-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402962		3733-005-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402963		3733-005-018-0007	Yes - Other	Not evaluated	Non-Lead - Copper	No		1.50	GIS Mains Year			2016-2024		Galvanized		1.50	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402964		3733-005-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402965		3806-003-039-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402966		3806-003-036-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402967		3806-003-036-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402968		3806-003-032-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402969		3806-003-031-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402970		3806-003-029-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402971		3806-003-027-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402972		3806-003-025-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402973		3806-003-023-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402974		3806-003-021-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402975		3806-003-018-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402976		3732-003-043-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402977		3732-003-041-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402978		3732-003-040-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402979		3732-003-038-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402980		3732-003-036-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402981		3732-003-034-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402982		3732-003-032-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402983		3732-010-018-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402984		3732-010-018-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402985		3732-010-018-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402986		3732-010-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402987		3732-010-014-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402988		3732-010-012-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402989		3732-010-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2402990		3732-010-010-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402991		3732-010-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402992		3732-010-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402993		3732-010-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402994		3732-010-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2402995		3732-010-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402996		3732-010-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402997		3732-010-002-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402998		3732-010-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2402999		3732-003-019-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403000		3732-003-019-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403001		3732-003-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403002		3732-003-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403003		3732-003-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403004		3732-003-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403005		3732-003-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403006		3806-003-018-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403007		3806-003-014-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403008		3806-003-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403009		3806-003-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403010		3806-003-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403011		3806-003-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403012		3806-003-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403013		3733-004-020-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403021		3734-014-016-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403022		3733-003-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403023		3733-003-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403024		3733-003-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403025		3733-003-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403026		3733-003-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403027		3733-003-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403028		3733-003-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403029		3733-003-017-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403030		3733-003-019-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403031		3733-002-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403032		3733-002-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403033		8156-010-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403034		8156-010-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403035		8156-009-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403036		8156-009-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403037		3733-002-020-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403038		8156-008-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403039		8156-008-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403040		8156-008-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403041		8156-007-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403042		3733-001-009-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403043		8156-006-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403044		8156-006-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403045		8156-005-011-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403046		8156-005-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403047		8156-005-012-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403048		3733-001-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403049		8156-004-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403050		8156-004-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403051		8156-003-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403052		8156-003-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403053		3806-002-006-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403054		8156-002-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403055		8156-002-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403056		8156-002-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403057		8156-002-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403058		3806-002-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403059		3806-002-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403060		3806-002-039-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403061		3806-002-037-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403062		3806-002-035-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403063		3806-002-033-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403064		3806-002-031-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403065		3806-002-029-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403066		3732-002-037-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403067		3732-002-035-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403068		3732-002-033-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2403069		3732-002-031-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403070		3732-002-028-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403071		3732-002-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403072		3732-002-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403073		3732-011-039-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403074		3732-011-037-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403075		3732-011-034-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403076		3732-011-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403077		3732-011-027-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403078		3732-011-025-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403079		3732-011-024-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403080		3732-011-021-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403081		3732-014-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403082		3732-014-014-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403083		3732-014-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403084		3732-014-009-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403085		3732-014-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403086		3732-014-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403087		3732-014-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403088		3732-014-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403089		3732-014-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403090		3732-014-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403091		3732-011-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403092		3732-011-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403093		3732-011-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403094		3732-011-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403095		3732-011-010-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403096		3732-011-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403097		3732-011-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403098		3732-011-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403099		3732-002-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403100		3732-002-011-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403101		3732-002-006-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403102		3732-002-006-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 31	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 31	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403103		3732-002-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403104		3732-002-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403105		3732-002-001-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403106		3732-001-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403107		3732-001-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403108		3732-001-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403109		3732-001-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403110		3732-001-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403119		3732-012-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403120		3732-012-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403121		3732-012-011-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403122		3732-012-012-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403123		3732-012-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403124		3732-012-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year		Visual inspection at the meter pit	2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403125		3732-012-016-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403126		3732-013-001-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403127		3732-013-001-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403128		3732-013-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403129		3732-013-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403130		3732-013-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403131		3732-013-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403132		142401-2-098-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403133		142401-2-095-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403134		142401-2-092-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403135		142401-2-091-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403136		142401-2-113-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403137		142401-2-210-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403138		142401-2-210-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403139		5265-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403140		5265-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403141		5265-000-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403142		5265-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403143		5265-000-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403144		5265-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403145		5265-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403146		5265-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403147		5265-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403148		5265-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403149		5265-000-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403150		142401-2-105-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403151		142401-2-105-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403152		142401-2-106-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403153		142401-2-107-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403154		142401-2-108-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403155		142401-2-109-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403156		142401-2-110-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403157		142401-2-111-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403158		3703-004-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403159		3703-004-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403160		3703-004-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403161		3703-004-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403162		3703-004-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403163		3703-004-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403164		3703-004-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403165		3703-004-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403166		3703-004-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403167		3703-004-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403168		3703-004-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403169		3703-004-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403170		3703-004-004-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403171		3703-005-001-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403172		3703-005-002-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403173		3703-005-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403174		3703-005-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403175		3703-005-004-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403176		3703-005-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403177		3703-005-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403178		3703-004-003-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403179		3703-004-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403180		3703-004-002-0301	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403181		3703-004-002-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403182		3703-004-002-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403183		3703-004-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403184		3702-003-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403185		3702-003-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403186		3702-003-005-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403187		3703-003-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403188		3703-003-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403189		3703-003-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403190		3703-003-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403191		3703-003-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403192		142401-2-114-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403193		142401-2-197-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403194		142401-2-118-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403195		142401-2-119-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403196		142401-2-122-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403197		142401-2-206-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403198		142401-2-205-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403199		142401-2-121-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2403200		142401-2-120-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403201		142401-2-198-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403202		142401-2-115-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403203		3703-003-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403204		3703-003-006-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403205		3703-003-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403206		3703-003-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check		Visual inspection at the meter pit	2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403207		3703-006-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403208		3703-006-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403209		3702-003-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403210		3702-003-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check		Visual inspection at the meter pit	2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403211		3702-003-008-0001

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403217		3702-002-005-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403218		3702-002-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403219		3703-002-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403220		3703-002-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403221		3703-002-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403222		3703-002-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403223		3703-002-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403224		3703-002-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403225		142401-2-136-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403226		142401-2-135-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403227		142401-2-134-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403228		142401-2-131-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403229		142401-2-131-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403230		142401-2-130-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403231		142401-2-124-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403232		142401-2-125-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403233		142401-2-126-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403234		142401-2-127-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403235		3755-002-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403236		3755-002-013-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403237		3755-002-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403238		3755-002-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403239		3755-002-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403240		3755-002-010-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403241		3755-002-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403242		3755-002-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403243		3767-002-039-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403244		3767-002-037-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403245		3767-002-035-0002	No	Not evaluated	Non-Lead - Other	No		4.00	FC	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		4.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403246		3767-002-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	E475	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E475	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403247		3767-002-032-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403248		3767-002-030-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 38			2016-2024		Galvanized		0.75	Book 6 Pg 38	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403249		3767-002-028-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48			2016-2024		Galvanized		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403250		3767-002-026-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 8550			2016-2024		<Null>		0.75	BEDA 8550	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403251		3767-002-026-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 13 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403252		3767-002-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403253		3767-001-019-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403254		3767-001-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403255		3767-001-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403256		3767-001-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403257		3767-001-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403258		3767-001-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	E428			2016-2024		Non-Lead - Plastic		0.75	E428	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403259		3767-001-004-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403260		3767-001-002-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403261		3767-001-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403262		3755-003-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403263		3755-003-006-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403264		3755-003-006-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403265		3755-003-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403266		3755-003-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403267		3755-003-003-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403268		3755-003-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403269		3755-003-002-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403270		3755-003-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403271		3755-003-001-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403272		3755-003-001-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403273		3755-003-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403274		142401-2-128-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403275		142401-2-129-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403276		142401-2-129-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403277		142401-2-132-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403278		142401-2-133-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403279		142401-2-133-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403280		142401-2-137-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403281		142401-2-137-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403282		3703-002-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403283		3703-002-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403284		3703-002-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403285		3703-002-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403286		3703-002-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403287		3703-002-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403288		3703-002-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403289		3702-002-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403290		3702-002-007-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403291		3702-002-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403292		3702-002-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403293		3702-002-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403294		3702-002-011-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403295		3702-002-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403296		3702-002-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403297		112401-3-107-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403298		112401-3-108-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403299		112401-3-079-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403300		112401-3-078-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403301		112401-3-110-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403302		112401-3-100-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403303		112401-3-057-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403304		112401-3-058-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403305		112401-3-058-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403306		112401-3-056-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403307		112401-3-055-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403308		112401-3-054-2003	No	Not evaluated	Non-

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403315		112401-3-036-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403316		112401-3-035-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403317		112401-3-032-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403318		112401-3-034-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403319		112401-3-033-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403320		112401-3-016-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403321		112401-3-031-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403322		112401-3-029-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403323		112401-3-017-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403324		112401-3-009-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403325		112401-3-008-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403326		112401-3-008-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403327		112401-3-006-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403328		112401-3-010-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403329		112401-3-010-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403330		112401-3-013-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403331		112401-3-018-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403332		112401-3-018-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403333		112401-3-019-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403334		112401-3-020-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403335		112401-3-094-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403336		112401-3-093-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403337		112401-3-095-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403338		112401-3-026-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403339		112401-3-027-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403340		112401-3-028-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403341		112401-3-025-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403342		112401-3-042-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403343		112401-3-043-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403344		112401-3-046-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403345		112401-3-046-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403346		112401-3-044-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403347		112401-3-053-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403348		112401-3-053-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403349		112401-3-092-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403350		112401-3-052-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403351		112401-3-062-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403352		112401-3-061-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403353		112401-3-059-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403354		112401-3-060-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403355		112401-3-068-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403356		112401-3-068-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403357		112401-3-070-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403358		112401-3-083-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403359		112401-3-082-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403360		112401-3-081-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403361		112401-3-084-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403362		3702-001-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403363		3702-001-001-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403364		3702-001-002-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403365		3702-001-003-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403366		3702-001-004-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403367		3703-001-001-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403368		3703-001-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403369		3703-001-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403370		3703-001-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403371		3703-001-003-0009	No	Not evaluated	Non-Lead - Plastic	No		6.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		6.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403372		3703-001-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403373		3703-001-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403374		3703-001-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403375		3703-001-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403376		3703-001-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403377		3703-001-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403378		3703-001-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403379		3703-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403380		3703-001-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403381		3703-001-010-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403382		3703-001-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403383		3702-001-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403384		3702-001-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403385		3702-001-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403386		112401-3-096-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403387		112401-3-088-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403388		142401-2-180-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403389		142401-2-179-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403390		142401-2-178-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403391		142401-2-174-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403392		142401-2-207-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403393		142401-2-169-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403394		142401-2-168-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403395		142401-2-167-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403396		142401-2-162-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403397		142401-2-161-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403398		142401-2-157-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403399		142401-2-152-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403400		142401-2-149-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403401		142401-2-146-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403402		142401-2-138-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403403		142401-2-139-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403404		142401-2-140-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403405		142401-2-141-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403413		142401-2-164-2009	No	Not evaluated	Galvanized	No	Prior to 1993	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403414		142401-2-165-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403415		142401-2-166-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403416		142401-2-170-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403417		142401-2-171-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403418		142401-2-175-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403419		142401-2-176-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403420		142401-2-177-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403421		142401-2-177-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403422		142401-2-181-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403423		112401-3-087-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403424		112401-3-067-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403425		112401-3-066-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403426		112401-3-064-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403427		112401-3-063-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403428		112401-3-063-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403429		112401-3-049-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403430		112401-3-049-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403431		112401-3-047-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403432		112401-3-048-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403433		112401-3-024-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403434		112401-3-023-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403435		112401-3-022-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403436		112401-3-021-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403437		112401-3-012-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403438		112401-3-011-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403439		112401-3-003-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403440		112401-3-003-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403441		112401-3-105-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403442		3814-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403443		3814-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403444		3814-000-007-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403445		3814-000-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403446		3814-000-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403447		3814-000-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403448		3814-000-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403449		3814-000-001-0504	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403450		3814-000-001-0405	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403451		102401-4-031-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403452		102401-4-108-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403453		102401-4-107-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403454		102401-4-121-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403455		102401-4-122-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403456		102401-4-037-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403457		102401-4-037-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403458		102401-4-130-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403459		102401-4-130-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403460		102401-4-130-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403461		102401-4-130-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403462		102401-4-109-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403463		102401-4-109-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403464		102401-4-109-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403465		102401-4-047-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403466		102401-4-048-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403467		102401-4-004-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403468		102401-4-051-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403469		102401-4-049-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403470		102401-4-050-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403471		102401-4-057-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403472		102401-4-058-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403473		102401-4-115-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403474		3771-001-009-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403475		3771-001-009-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403476		3771-001-009-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403477		3771-001-008-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403478		3771-001-007-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403479		3771-001-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403480		3771-001-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403481		3771-001-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403482		3771-001-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403483		3771-001-004-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403484		3771-001-003-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403485		3771-001-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403486		3771-001-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403487		3771-001-002-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403488		3771-001-002-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403489		102401-4-093-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403490		102401-4-094-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403491		102401-4-095-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403492		102401-4-096-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403493		102401-4-097-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403494		102401-4-089-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403495		152401-1-003-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403496		152401-1-001-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403497		152401-1-002-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403498		152401-1-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403499		152401-1-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403500		152401-1-006-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403501		152401-1-008-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403502		152401-1-009-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403503		152401-1-009-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403504		152401-1-010-2006	No	Not evaluated	Non-Lead - Plastic	No

Location Information					System-Owned Portion								Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403511		152401-1-017-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403512		152401-1-018-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403513		152401-1-021-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403514		152401-1-084-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403515		152401-1-085-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403516		152401-1-086-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403517		152401-1-087-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403518		152401-1-088-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403519		152401-1-089-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403520		152401-1-090-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403521		152401-1-092-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403522		152401-1-093-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403523		152401-1-094-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403524		152401-1-096-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2403525		152401-1-097-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403526		152401-1-098-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403527		152401-1-099-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403528		152401-1-100-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435			2016-2024		Galvanized		0.75	E435	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403529		152401-1-101-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 6 Pg 63	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 6 Pg 63	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403530		152401-1-102-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403531		152401-1-103-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48			2016-2024		Galvanized		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403532		152401-1-104-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403533		152401-1-105-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486			2016-2024		Galvanized		0.75	BEDA 5486	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403534		152401-1-106-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403535		152401-1-108-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403536		152401-1-108-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403537		152401-1-109-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403538		152401-1-110-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 2187	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2187	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403539		152401-1-111-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091			2016-2024		Non-Lead - Copper		0.75	BEDA 3091	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403540		152401-1-112-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403541		152401-1-113-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403542		152401-1-114-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49			2016-2024		Galvanized		0.75	Book 5 pg 49	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403543		152401-1-115-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66			2016-2024		Galvanized		0.75	Book 5 pg 66	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403544		152401-1-116-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403545		152401-1-117-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	E311			2016-2024		Galvanized		0.75	E311	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403546		152401-1-117-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	E424			2016-2024		Galvanized		0.75	E424	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403547		152401-1-119-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403548		152401-1-120-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403549		152401-1-121-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403550		152401-1-223-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403551		152401-1-124-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2403552		152401-1-125-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403553		152401-1-126-2007	Yes - Schoo	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403554		152401-1-127-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403555		152401-1-128-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403556		152401-1-129-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403557		152401-1-130-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403558		152401-1-131-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403559		152401-1-132-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403560		152401-1-133-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403561		152401-1-022-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403562		152401-1-020-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403563		152401-1-019-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403564		152401-1-036-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403565		152401-1-041-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403566		152401-1-040-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403567		152401-1-039-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403568		152401-1-038-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403569		152401-1-037-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403570		152401-1-035-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403571		152401-1-033-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403572		152401-1-209-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403573		152401-1-011-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403574		152401-1-029-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403575		152401-1-028-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403576		152401-1-027-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403577		152401-1-025-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403578		102401-4-088-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403579		102401-4-090-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403580		102401-4-091-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403581		102401-4-092-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403582		3771-001-018-0108	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403583		3771-001-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403584		3771-001-017-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403585		3771-001-017-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403586		3771-001-016-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403587		3771-001-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403588		3771-001-015-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403589		3771-001-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403590		3771-001-014-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403591		3771-001-013-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403592		3771-001-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403593		3771-001-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403594		3771-001-011-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403595		3771-001-011-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403596		3771-001-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403597		3771-001-010-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403598		3771-001-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403599		102401-4-113-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403600		102401-4-112-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403601		3771-002-009-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403602		3771-002-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403603		3771-002-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403609		3771-002-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403610		3771-002-003-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403611		3771-002-003-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403612		3771-002-002-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403613		102401-4-002-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403614		102401-4-075-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403615		102401-4-076-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403616		102401-4-077-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403617		102401-4-081-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403618		102401-4-082-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403619		102401-4-085-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403620		102401-4-087-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403621		102401-4-083-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403622		102401-4-084-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403623		102401-4-086-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403624		152401-1-043-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2403625		152401-1-042-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2403626		152401-1-042-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403627		152401-1-042-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403628		152401-1-183-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403629		152401-1-045-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403630		152401-1-045-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403631		152401-1-034-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403632		152401-1-046-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403633		152401-1-047-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403634		152401-1-207-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403635		152401-1-208-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403636		152401-1-049-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403637		152401-1-049-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403638		152401-1-050-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403639		152401-1-051-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403640		152401-1-051-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403641		152401-1-051-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403642		152401-1-052-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403643		152401-1-053-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403644		152401-1-054-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403645		152401-1-055-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403646		152401-1-056-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403647		152401-1-057-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403648		152401-1-058-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403649		152401-1-059-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403650		152401-1-060-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403651		152401-1-061-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403652		152401-1-062-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403653		152401-1-062-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403654		152401-1-134-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403655		152401-1-135-2006	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403656		152401-1-136-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403657		152401-1-137-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403658		152401-1-138-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403659		152401-1-140-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403660		152401-1-141-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403661		152401-1-142-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403662		152401-1-145-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403663		152401-1-146-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403664		152401-1-147-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403665		152401-1-148-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403666		152401-1-150-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403667		152401-1-150-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403668		152401-1-150-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403669		152401-1-150-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 30	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403670		152401-1-152-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 63	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 63	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403671		152401-1-153-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403672		152401-1-044-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3734 (CTS)			2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403673		152401-1-044-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403674		152401-1-219-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403675		152401-1-166-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403676		152401-1-167-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403677		152401-1-167-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403678		152401-1-168-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403679		152401-1-170-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403680		152401-1-171-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403681		152401-1-172-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403682		152401-1-064-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Work			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403683		152401-1-065-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403684		152401-1-066-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403685		152401-1-067-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403686		152401-1-068-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403687		152401-1-069-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403688		152401-1-070-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403689		152401-1-071-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403690		152401-1-072-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403691		152401-1-073-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403692		152401-1-074-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403693		152401-1-075-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403694		152401-1-076-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403695		152401-1-078-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403696		152401-1-079-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403697		152401-1-080-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403698		152401-1-081-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403699		152401-1-083-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403700		102401-4-079-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403707		3771-002-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403708		3771-002-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403709		3771-002-011-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403710		3771-002-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2403711		3771-002-010-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403712		3771-002-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403713		102401-4-055-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403714		102401-4-054-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403715		102401-4-052-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403716		102401-4-045-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403717		102401-4-043-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403718		102401-4-042-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403719		102401-4-036-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403720		102401-4-035-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403721		102401-4-034-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403722		102401-4-027-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403723		102401-4-028-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403724		102401-4-119-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403725		102401-4-119-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403726		102401-1-070-2008	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check			2016-2024		Non-Lead - Copper		2.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2403727		102401-1-039-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403728		3720-001-002-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403729		3720-001-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403730		3720-001-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403731		3720-001-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403732		3720-001-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403733		3720-001-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403734		3720-001-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403735		3720-001-010-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403736		3720-001-010-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403737		3720-001-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403738		3720-003-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403739		3720-003-002-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403740		3720-003-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403741		3720-003-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403742		3720-003-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403743		3720-003-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403744		3720-003-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403745		3720-003-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403746		3720-003-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403747		3720-003-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403748		3720-003-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403749		3720-003-014-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403750		102401-4-060-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403751		102401-4-073-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403752		102401-4-072-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403753		102401-4-071-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403754		102401-4-070-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403755		102401-4-069-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403756		3744-000-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403757		3744-000-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403758		3744-000-016-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403759		3794-003-019-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403760		3794-003-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403761		3794-002-019-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403762		3794-002-019-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403763		3794-001-021-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403764		3774-001-004-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403765		3774-001-005-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403766		3774-001-006-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403767		3774-001-007-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403768		3774-001-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403769		3774-001-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403770		3774-001-011-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403771		3774-001-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403772		3774-001-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403773		3774-001-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403774		3774-001-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403775		3774-006-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403776		3774-006-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403777		3774-006-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403778		3774-006-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403779		3774-006-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403780		3774-006-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403781		3774-006-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403782		3774-006-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403783		3774-006-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403784		3774-006-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403785		3774-006-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403786		3774-006-013-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403787		152401-1-175-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403788		152401-1-177-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403789		152401-1-176-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403790		152401-1-178-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403791		152401-1-179-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403792		152401-1-180-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403793		152401-1-181-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403794		152401-1-182-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403795		152401-1-163-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403796		152401-1-163-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403797		152401-1-159-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Un

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403805		3735-022-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403806		3734-011-021-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403807		3734-012-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403808		3734-012-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403809		3734-012-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403810		3734-012-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403811		3734-012-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403812		3734-012-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403813		3735-020-017-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403814		3735-020-016-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403815		3735-019-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403816		3735-020-013-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403817		3735-020-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Non-Lead - Plastic	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Non-Lead - Plasti	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403818		3735-020-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 74	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 74	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403819		3735-020-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 75	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap log 75	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403820		3735-020-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 75	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 75	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403821		3735-019-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log (208A)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log (208A)	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403822		3735-021-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403823		3735-021-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403824		3735-021-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Non-Lead - Plastic	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Non-Lead - Plasti	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403825		3735-021-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403826		3774-012-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403827		3774-012-012-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403828		3774-012-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403829		3774-012-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403830		3774-012-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403831		3774-007-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403832		3774-007-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403833		3774-007-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403834		3774-007-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403835		3774-007-011-0000	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403836		3774-007-010-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403837		3774-007-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403838		3774-007-007-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403839		3774-007-005-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403840		3774-007-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403841		3774-007-002-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403842		3774-007-001-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403843		3774-006-019-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403844		3774-006-022-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403845		3774-006-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403846		3774-006-024-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403847		3774-006-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403848		3774-006-026-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403849		3774-006-027-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403850		3774-006-028-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403851		3774-006-029-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403852		3774-001-016-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403853		3774-001-016-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403854		3774-001-018-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403855		3774-001-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403856		3774-001-020-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403857		3774-001-022-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403858		3774-001-023-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403859		3774-001-025-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403860		3774-001-026-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403861		3774-001-028-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403862		3774-001-028-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403863		3774-001-001-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403864		3774-001-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403865		3794-001-025-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403866		3794-001-031-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403867		3794-001-033-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403868		3794-001-013-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403869		3794-001-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403870		3794-001-017-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403871		3794-002-025-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403872		3794-002-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403873		3794-002-031-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403874		3794-002-013-0203	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403875		3794-002-006-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403876		3794-002-006-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403877		3794-002-006-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403878		3794-003-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403879		3794-003-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403880		3744-000-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403881		3744-000-013-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403882		102401-4-068-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403883		102401-4-067-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403884		102401-4-066-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403885		102401-4-062-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403886		102401-4-061-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403887		3720-003-016-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403888		3720-003-016-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403889		3720-003-018-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403890		3720-003-020-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403891		3720-003-021-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403892		3720-003-022-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403893		3720-003-023-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403894		3720-003-024-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2403903		3720-001-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403904		3720-001-016-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403905		3720-001-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403906		3720-001-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403907		3720-001-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403908		102401-1-038-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403909		1024001-1-027-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403910		1024001-1-020-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403911		1024001-1-019-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403912		1024001-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403913		1024001-1-005-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403914		1024001-1-006-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403915		1024001-1-018-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403916		1024001-1-072-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403917		1024001-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403918		1024001-1-029-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403919		1024001-1-029-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403920		1024001-1-049-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403921		1024001-1-037-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403922		1024001-1-037-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403923		1024001-1-036-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403924		1024001-1-035-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403925		3720-002-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403926		3720-002-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403927		3720-002-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403928		3720-002-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403929		3720-002-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403930		3720-002-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403931		3720-002-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403932		3720-002-008-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403933		3720-002-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403934		3720-002-021-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403935		3720-004-001-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403936		3720-004-002-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403937		3720-004-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403938		3720-004-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403939		3720-004-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403940		3720-004-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403941		3720-004-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403942		3720-004-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403943		3720-004-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403944		3720-004-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403945		3720-004-013-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403946		3720-004-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403947		3720-004-016-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403948		3720-004-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403949		3720-004-020-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403950		3720-004-021-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403951		3720-004-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403952		3720-004-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403953		3720-004-027-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403954		3720-004-030-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403955		3720-004-030-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403956		3720-002-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403957		3720-002-011-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403958		3720-002-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403959		3720-002-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403960		3720-002-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403961		3720-002-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403962		3720-002-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403963		3720-002-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403964		1024001-1-034-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403965		1024001-1-033-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403966		1024001-1-064-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403967		1024001-1-060-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403968		1024001-1-060-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403969		1024001-1-032-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403970		1024001-1-032-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403971		1024001-1-058-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403972		1024001-1-058-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403973		1024001-1-063-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403974		1024001-1-063-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403975		1024001-1-008-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403976		1024001-1-008-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2403977		1024001-1-007-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403978		1024001-1-009-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403979		1024001-1-067-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403980		1024001-1-054-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check (Blue Non-Lead - Plastic)			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403981		3701-003-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403982		3701-003-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403983		3701-003-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403984		3701-003-001-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403985		3701-003-001-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403986		1024001-1-013-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403987		1024001-1-014-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2403988		1024001-1-015-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403989		1024001-1-016-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403990		3812-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403991		3812-000-001-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403992		3812-000-001-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403993		3812-000-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403994		3812-000-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2403995		3812-000-005-0007	No	Not

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404001		3701-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404002		3720-005-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404003		3720-005-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404004		102401-4-059-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404005		102401-4-063-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404006		102401-4-064-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404007		3744-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404008		3744-000-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404009		3744-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404010		3744-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404011		3744-000-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404012		3744-000-011-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404013		3744-000-001-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404014		3744-000-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404015		3744-000-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404016		3744-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404017		3744-000-006-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404018		3786-000-007-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404019		3786-000-007-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404020		3786-000-007-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404021		3786-000-007-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404022		3794-003-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404023		3794-002-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404024		3794-001-001-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404025		3794-001-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404026		3794-001-045-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404027		3786-000-009-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404028		3774-002-029-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404029		3774-002-029-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404030		3794-001-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404031		3794-001-037-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404032		3794-001-006-0303	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404033		3794-001-006-0402	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404034		3794-002-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404035		3794-002-009-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404036		3794-002-006-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404037		3794-002-006-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404038		3794-002-006-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404039		3794-002-006-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404040		3794-003-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404041		3774-002-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404042		3774-002-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404043		3774-002-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404044		3774-002-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404045		3774-002-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404046		3774-002-008-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404047		3774-002-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404048		3774-002-010-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404049		3774-002-011-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404050		3774-002-013-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404051		3774-002-014-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404052		3774-002-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404053		3774-002-016-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404054		3774-002-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404055		3774-002-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404056		3774-002-019-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404057		3774-002-021-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404058		3774-002-023-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404059		3774-002-024-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404060		3774-002-027-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404061		3774-003-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404062		3774-003-004-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404063		3774-003-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404064		3774-003-012-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404065		3774-003-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404066		3774-003-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404067		3774-003-014-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404068		3759-000-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404069		3759-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404070		3759-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404071		3759-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404072		3759-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404073		3759-000-019-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404074		3759-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404075		3759-000-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404076		3759-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404077		3759-000-014-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404078		3774-004-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404079		3774-005-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404080		3774-005-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404081		3774-005-021-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404082		3774-005-022-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404083		3774-005-023-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404084		3774-005-025-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404085		3774-005-026-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404086		3774-005-028-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404087		3774-005-029-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404088		3774-005-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404089		3774-005-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404090		3774-005-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404091		3774-005-004-0102	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Un

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier					Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Other Potential Sources of: Is there a Lead Connector?	Other Potential Sources of: Is there Lead Solder in the Service Line?	Other Potential Sources of: Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404099		3774-005-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404100		3774-005-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404101		3774-005-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404102		3774-005-016-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404103		3774-008-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404104		3774-007-028-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404105		3774-008-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404106		3774-008-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404107		3774-007-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404108		3774-007-026-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404109		3774-008-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404110		3774-007-025-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404111		3774-008-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404112		3774-007-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404113		3774-008-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404114		3774-007-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404115		3774-007-020-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404116		3774-008-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404117		3774-007-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404118		3774-007-018-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404119		3774-007-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404120		3774-008-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404121		3774-008-015-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404122		3774-008-015-0004	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown			
BremSLI-2404123		3774-007-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404124		3774-012-029-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404125		3774-012-029-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404126		3774-011-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404127		3774-011-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404128		3774-011-003-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404129		3774-012-027-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404130		3774-011-004-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404131		3774-011-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404132		3774-012-025-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404133		3774-011-006-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404134		3774-012-024-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 16			2016-2024		Non-Lead - Copper		0.75	Book 6 pg 16	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404135		3774-011-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 6	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 6	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404136		3774-012-023-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown			
BremSLI-2404137		3774-012-022-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 4 Pg 63	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 63	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404138		3774-011-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49			2016-2024		<Null>		0.75	Book 5 pg 49	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404139		3774-011-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404140		3774-012-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 38	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 19 pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404141		3774-012-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404142		3774-012-018-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752			2016-2024		Non-Lead - Plastic		0.75	BEDA 2752	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404143		3774-011-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 25			2016-2024		Galvanized		0.75	Book 13 pg 25	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404144		3774-012-016-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404145		3774-012-016-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2080	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2080	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404146		3774-011-014-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404147		3735-018-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404148		3735-018-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404149		3774-011-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404150		3774-010-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404151		3774-011-016-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404152		3774-010-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404153		3774-011-017-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404154		3774-011-019-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486			2016-2024		Galvanized		0.75	BEDA 5486	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404155		3774-011-020-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 4 Pg 63			2016-2024		Galvanized		0.75	Book 4 Pg 63	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404156		3774-010-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404157		3774-010-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 41			2016-2024		<Null>		0.75	Book 6 Pg 41	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404158		3774-011-022-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown			
BremSLI-2404159		3774-011-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404160		3774-010-007-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404161		3774-011-025-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404162		3774-010-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404163		3774-011-026-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	FC	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404164		3787-000-013-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	E480	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E480	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404165		3774-010-003-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404166		3774-011-028-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404167		3774-011-028-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404168		3774-010-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404169		3774-011-029-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404170		3774-009-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404171		3774-008-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404172		3774-008-019-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404173		3774-008-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404174		3774-008-022-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404175		3774-008-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404176		3774-009-005-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404177		3774-009-004-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404178		3774-008-026-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404179		3774-009-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404180		3774-009-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404181		3787-000-009-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404182		3787-000-009-0301	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404183		3787-000-009-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404184		3787-000-010-0704	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404185		3787-000-009-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404186		3787-000-010-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404187		3787-000-010-0902	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404188		3774-009-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404189		3787-000-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404190		3774-009-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404197		3787-000-013-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404198		3787-000-011-0802	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404199		3787-000-013-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404200		3787-000-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404201		3787-000-013-0503	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404202		3787-000-012-0603	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404203		3787-000-013-0701	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404204		3787-000-013-0602	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404205		3787-000-012-0306	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404206		3787-000-013-1402	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404207		3787-000-013-1204	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404208		3787-000-013-1709	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404209		3787-000-022-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404210		3787-000-022-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404211		3787-000-014-0403	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 37	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 37	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404212		3787-000-021-0404	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48			2016-2024		Non-Lead - Copper		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404213		3787-000-020-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404214		3787-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404215		3787-000-012-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404216		3787-000-012-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404217		3787-000-012-0504	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404218		3787-000-020-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404219		3787-000-011-0604	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404220		3787-000-011-0604	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404221		3787-000-019-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404222		3787-000-019-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404223		3787-000-018-0201	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404224		3787-000-009-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404225		3787-000-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404226		3787-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404227		3787-000-008-0609	No	Not evaluated	Galvanized	No	Prior to 1978	0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404228		3787-000-008-0609	No	Not evaluated	Galvanized	No	Prior to 1979	0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404229		152401-1-204-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404230		152401-1-204-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404231		152401-1-203-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404232		3787-000-007-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404233		152401-1-201-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404234		3787-000-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404235		3787-000-006-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404236		152401-1-200-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404237		152401-1-195-2003	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404238		3787-000-006-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404239		3787-000-006-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404240		3787-000-007-0303	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404241		3787-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404242		3787-000-008-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404243		3787-000-008-0401	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404244		3787-000-008-0500	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404245		3759-000-022-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404246		3759-000-022-0100	No	Not evaluated	Galvanized	No	Prior to 1981	0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404247		3759-000-023-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404248		152401-1-205-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404249		3759-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404250		3787-000-003-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404251		3787-000-003-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404252		3787-000-002-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404253		152401-1-187-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404254		152401-1-188-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404255		3787-000-002-0209	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404256		3787-000-002-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404257		152401-1-189-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404258		3787-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404259		3787-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404260		152401-1-212-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404261		152401-1-211-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404262		3787-000-001-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404263		3787-000-001-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404264		3787-000-001-0408	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404265		3787-000-001-0507	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404266		3786-000-009-0500	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404267		3786-000-009-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404268		3786-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404269		3786-000-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404270		3786-000-009-0203	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404271		3786-000-010-0606	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404272		3786-000-009-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404273		3786-000-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404274		3786-000-010-0705	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404275		3786-000-010-0408	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404276		3786-000-007-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404277		3786-000-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404278		3786-000-007-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404279		3786-000-008-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404280		3786-000-007-0403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404281		3786-000-004-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404282		3786-000-003-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404283		3786-000-003-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404284		3786-000-003-0407	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404285		3786-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404286		102401-4-105-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404287		3720-005-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404288		3720-005-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404295		3701-001-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404296		3812-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404297		3812-000-007-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404298		3812-000-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404299		3812-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404300		3812-000-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404301		102401-1-042-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404302		3701-003-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404303		3701-003-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404304		3701-003-001-0702	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404305		3701-003-001-0504	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404306		3701-003-001-0603	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404307		3701-003-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404308		3701-003-002-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404309		3701-003-002-0404	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404310		3812-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404311		3812-000-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404312		3812-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404313		3812-000-014-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404314		102401-4-104-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404315		102401-4-104-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404316		3812-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404317		3812-000-020-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404318		3812-000-020-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404319		3812-000-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404320		3812-000-017-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404321		3812-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404322		3701-002-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404323		3701-002-008-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404324		3701-002-006-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404325		3701-002-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404326		3701-002-004-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404327		3701-002-004-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404328		3701-002-004-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404329		3701-002-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404330		102401-4-102-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404331		102401-4-103-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404332		102401-4-001-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404333		102401-4-101-2005	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2404334		3786-000-001-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404335		3786-000-001-0300	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404336		3786-000-002-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404337		3786-000-002-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404338		3786-000-002-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404339		3786-000-003-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404340		3786-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404341		3786-000-004-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404342		3786-000-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404343		3786-000-005-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404344		3786-000-006-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404345		3786-000-010-0507	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404346		3207601	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404347		3786-000-011-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404348		3786-000-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404349		3786-000-012-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404350		3786-000-013-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404351		3786-000-014-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404352		3786-000-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404353		4511-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404354		102401-3-110-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404355		102401-3-131-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404356		102401-3-132-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404357		102401-3-130-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404358		4683-000-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404359		102401-3-129-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404360		102401-3-215-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404361		4683-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404362		4683-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404363		4683-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404364		102401-3-126-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404365		102401-3-026-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404366		4683-000-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404367		102401-3-025-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404368		102401-3-024-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404369		102401-3-023-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404370		102401-3-023-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404371		102401-3-023-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404372		102401-3-021-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404373		102401-3-022-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404374		102401-3-062-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404375		102401-3-063-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404376		102401-3-061-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404377		102401-3-059-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404378		102401-3-060-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404379		102401-3-064-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404380		4683-000-004-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404381		102401-3-065-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404382		102401-3-069-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404383		102401-3-070-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404384		102401-3-072-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404385		102401-3-076-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404393		102401-3-176-2007	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404394		102401-3-139-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404395		4683-000-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404396		102401-3-137-2005	No	Not evaluated	Galvanized	No	Prior to 2016	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404397		102401-3-138-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404398		4683-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404399		4683-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404400		4511-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404401		4511-000-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404402		4511-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404403		4511-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404404		4511-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404405		4511-000-014-0503	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404406		102401-3-197-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404407		4511-000-014-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404408		4511-000-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404409		4511-000-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404410		4511-000-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404411		102401-3-170-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404412		102401-3-140-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404413		102401-3-141-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404414		102401-3-217-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404415		4511-000-010-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404416		4511-000-011-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404417		102401-3-144-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404418		102401-3-136-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404419		102401-3-136-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404420		102401-3-181-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404421		102401-3-146-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404422		102401-3-136-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404423		102401-3-194-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404424		102401-3-194-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404425		102401-3-194-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404426		102401-3-135-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404427		102401-3-135-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404428		102401-3-135-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404429		152401-2-011-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404430		152401-2-011-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404431		152401-2-012-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404432		102401-3-149-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404433		152401-2-013-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404434		152401-2-013-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404435		152401-2-121-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404436		152401-2-014-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404437		152401-2-015-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404438		152401-2-009-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404439		152401-2-017-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404440		152401-2-019-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404441		152401-2-031-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404442		152401-2-032-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404443		152401-2-034-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404444		152401-2-004-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404445		152401-2-220-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404446		152401-2-220-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404447		152401-2-003-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404448		152401-2-035-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404449		152401-2-036-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404450		152401-2-003-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404451		152401-2-037-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404452		152401-2-056-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404453		152401-2-057-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404454		152401-2-059-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404455		152401-2-060-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404456		152401-2-061-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404457		152401-2-062-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404458		152401-2-063-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404459		152401-1-194-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404460		152401-2-064-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404461		152401-1-196-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404462		152401-1-197-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404463		152401-2-065-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404464		152401-2-066-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404465		152401-1-198-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404466		152401-2-067-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404467		152401-2-068-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404468		152401-2-069-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404469		152401-2-235-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404470		152401-2-071-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404471		3787-000-017-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404472		3787-000-017-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404473		3787-000-017-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404474		152401-2-072-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404475		152401-2-073-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404476		152401-2-074-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404477		152401-2-075-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404478		3787-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404479		152401-2-076-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404480		152401-2-077-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404481		3787-000-018-0300	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404482		152401-2-078-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404483		3787-000-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404491		3787-000-021-0701	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404492		3787-000-021-0701	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404493		3787-000-021-1303	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404494		3787-000-021-0602	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404495		3787-000-021-0503	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404496		152401-2-084-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404497		152401-2-085-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404498		3787-000-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404499		152401-2-086-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg. 54			2016-2024		Galvanized		0.75	Book 6 Pg. 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404500		152401-2-087-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 20			2016-2024		Galvanized		0.75	Book 6 pg 20	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404501		152401-2-087-2002	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404502		152401-2-088-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404503		152401-2-088-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404504		152401-2-088-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404505		3787-000-023-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404506		3787-000-023-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404507		3787-000-023-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404508		3787-000-021-0909	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404509		3787-000-022-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404510		3787-000-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404511		3787-000-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404512		152401-2-088-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404513		152401-2-088-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404514		152401-2-090-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404515		152401-2-091-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404516		152401-2-097-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404517		152401-2-097-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404518		152401-2-094-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404519		152401-2-094-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404520		152401-2-095-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404521		152401-2-208-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404522		152401-2-209-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404523		152401-2-049-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404524		152401-2-050-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404525		152401-2-051-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404526		152401-2-058-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404527		152401-2-052-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404528		152401-2-052-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404529		152401-2-053-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404530		152401-2-054-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404531		152401-2-055-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2404532		152401-2-055-2000	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404533		152401-2-039-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404534		152401-2-040-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404535		152401-2-042-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404536		152401-2-043-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404537		152401-2-239-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404538		152401-2-239-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404539		152401-2-027-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404540		152401-2-027-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404541		152401-2-103-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404542		152401-2-098-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404543		152401-2-098-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404544		152401-2-213-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404545		152401-2-212-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404546		152401-2-175-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404547		152401-2-106-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404548		152401-2-241-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404549		152401-2-112-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404550		152401-2-119-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404551		152401-2-113-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404552		152401-2-227-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404553		152401-2-229-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404554		152401-2-230-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404555		152401-2-228-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404556		152401-2-168-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404557		152401-2-167-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404558		152401-2-167-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404559		152401-2-115-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404560		152401-2-116-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404561		152401-2-166-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404562		152401-2-116-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404563		5461-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404564		5461-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404565		5461-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404566		5461-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404567		5461-000-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404568		5461-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404569		5461-000-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404570		152401-2-024-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404571		152401-2-023-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404572		152401-2-237-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404573		152401-2-236-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404574		152401-2-016-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404575		152401-2-120-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404576		102401-3-092-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404577		102401-3-047-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404578		102401-3-088-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404579		102401-3-086-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404580		102401-3-085-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404581		102401-3-081-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404582		102401-3-080-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404583		102401-3-077-2007	No	Not evaluated	Non-Lead - Pl

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404589		102401-3-066-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404590		102401-3-020-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404591		102401-3-020-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404592		102401-3-188-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404593		102401-3-188-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404594		102401-3-188-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404595		102401-3-188-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404596		102401-3-014-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404597		102401-3-014-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404598		102401-3-015-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404599		102401-3-010-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404600		102401-3-011-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404601		102401-3-011-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404602		102401-3-009-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404603		102401-3-006-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404604		102401-3-003-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404605		102401-3-004-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404606		102401-3-005-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404607		102401-3-001-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404608		102401-3-001-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404609		4554-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404610		4554-000-012-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2404611		4554-000-012-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404612		4554-000-012-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404613		4554-000-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404614		4554-000-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404615		4554-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404616		5516-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404617		5516-000-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404618		5516-000-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404619		5516-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404620		5516-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404621		5516-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404622		5516-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404623		4554-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404624		4670-001-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404625		4670-001-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404626		4670-001-006-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404627		4670-001-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404628		4670-001-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404629		4670-001-004-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404630		4670-001-003-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404631		4670-001-002-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404632		4670-001-001-0008	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404633		4670-001-001-0404	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404634		4670-001-001-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404635		4670-001-001-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404636		4670-001-001-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404637		4670-001-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404638		4670-001-003-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2404639		4670-002-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404640		4670-002-008-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404641		4670-002-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404642		4670-002-007-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404643		4670-002-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2404644		4670-002-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404645		4670-002-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404646		4670-002-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404647		4670-003-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404648		4670-003-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404649		4670-003-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404650		4670-003-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404651		4670-003-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404652		102401-2-047-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404653		102401-2-046-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404654		102401-2-095-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404655		102401-2-094-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404656		102401-2-042-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404657		102401-2-041-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404658		102401-2-040-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404659		102401-2-039-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404660		102401-2-036-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404661		102401-2-036-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404662		102401-2-036-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404663		102401-2-038-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404664		102401-2-032-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404665		102401-2-033-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404666		102401-2-031-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404667		102401-2-030-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404668		102401-2-117-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404669		102401-2-104-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404670		102401-2-025-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404671		102401-2-023-2004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404672		102401-2-022-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404673		102401-2-021-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404674		102401-2-020-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404675		102401-2-019-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404676		102401-2-018-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404677		102401-2-017-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404678		102401-2-011-2008	No	Not evaluated	Non-Lead - Copper	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404687		102401-2-007-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404688		102401-2-008-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404689		102401-2-009-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404690		102401-2-010-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404691		102401-2-004-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404692		0324013-090-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404693		0324013-087-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404694		0324013-089-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404695		0324013-135-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown	Yes		
BremSLI-2404696		0324013-086-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404697		0324013-085-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404698		0324013-136-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Non-Lead - Copper		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404699		0324013-136-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Non-Lead - Plastic		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404700		0324013-136-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Galvanized		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404701		0324013-108-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404702		0324013-083-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404703		0324013-096-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 25			2016-2024		Galvanized		0.75	Book 13 pg 25	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404704		0324013-141-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404705		0324013-097-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404706		0324013-138-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404707		0324013-142-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb5 pg 52	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb5 pg 52	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404708		0324013-142-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb5 pg 52	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb5 pg 52	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404709		0324013-080-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404710		0324013-100-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404711		0324013-101-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1724	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1724	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404712		0324013-102-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404713		0324013-102-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404714		0324013-104-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404715		0324013-139-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404716		0324013-139-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404717		0324013-139-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404718		0324013-139-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404719		0324013-139-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404720		0324013-139-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404721		0324013-139-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404722		0324013-103-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404723		0324013-076-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404724		0324013-075-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404725		0324013-106-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404726		0324013-020-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404727		0324013-019-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404728		0324013-131-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404729		0324013-014-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404730		0324013-015-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404731		0324013-016-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404732		0324013-130-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404733		0324013-010-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404734		0324013-017-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404735		0324013-008-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404736		0324013-018-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404737		0324013-127-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404738		4630-002-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404739		4630-002-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404740		4630-002-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404741		4630-002-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404742		4630-002-006-0000	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404743		4630-001-012-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404744		4630-001-020-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404745		4630-001-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404746		4630-001-001-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404747		4630-001-003-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404748		4630-001-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404749		4630-001-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404750		4630-001-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404751		4630-001-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404752		4630-001-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404753		4630-001-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404754		4635-000-067-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404755		4635-000-082-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404756		4635-000-081-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404757		4635-000-079-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404758		4635-000-079-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404759		4635-000-078-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404760		4635-000-076-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404761		4635-000-076-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404762		4635-000-075-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404763		4635-000-074-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404764		4635-000-073-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404765		4635-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404766		4635-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404767		4635-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404768		4635-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404769		4635-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404770		4635-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404771		4635-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404772		4635-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404773		4635-000-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404774		4635-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404775		4635-000-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404776		4635-000-015-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404777		4635-000-017-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404785		4635-000-026-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404786		4635-000-027-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404787		4635-000-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404788		4635-000-031-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404789		4635-000-031-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404790		4635-000-051-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404791		4635-000-033-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404792		4635-000-035-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404793		4635-000-036-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404794		4635-000-039-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404795		4635-000-042-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404796		4635-000-046-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404797		4635-000-047-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404798		4635-000-047-0109	No	Not evaluated	Galvanized	No	Prior to 1987	0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404799		4630-006-011-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404800		4630-006-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404801		4630-006-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404802		4630-004-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404803		4630-006-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404804		4630-006-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404805		4630-005-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404806		4630-006-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404807		032401-3-001-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404808		032401-3-001-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404809		032401-3-001-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404810		032401-3-001-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404811		032401-3-007-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404812		4630-002-019-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404813		4630-003-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404814		4630-004-004-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404815		4635-000-057-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404816		4635-000-059-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404817		4635-000-084-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404818		4635-000-088-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404819		4635-000-088-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404820		4635-000-006-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404821		4635-000-006-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404822		4635-000-070-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404823		4635-000-069-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404824		4635-000-068-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404825		032401-3-035-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404826		032401-3-034-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404827		032401-3-033-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404828		032401-3-032-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404829		032401-3-031-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404830		032401-3-030-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404831		032401-3-028-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404832		032401-3-036-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404833		032401-3-037-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404834		032401-3-038-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404835		032401-3-039-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404836		032401-3-040-2000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404837		032401-3-042-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404838		032401-3-150-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404839		032401-3-043-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404840		032401-3-025-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404841		032401-3-044-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404842		032401-3-065-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404843		032401-3-045-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404844		032401-3-074-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404845		032401-3-047-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404846		032401-3-047-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404847		032401-3-048-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404848		032401-3-072-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404849		032401-3-071-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404850		032401-3-050-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404851		032401-3-049-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404852		032401-3-069-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404853		032401-3-070-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404854		032401-3-070-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404855		032401-3-051-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404856		032401-3-052-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404857		032401-3-133-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404858		032401-3-134-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404859		5509-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404860		5509-000-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404861		032401-3-063-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404862		032401-3-053-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404863		032401-3-147-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404864		032401-3-147-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404865		032401-3-147-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404866		032401-3-149-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404867		032401-3-062-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404868		032401-3-061-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404869		032401-3-060-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404870		032401-3-060-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404871		102401-2-099-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404872		102401-2-099-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404873		102401-2-099-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404883		102401-2-056-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404884		102401-2-078-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404885		102401-2-078-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404886		102401-2-058-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404887		102401-2-059-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404888		102401-2-076-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404889		102401-2-060-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404890		102401-2-077-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2404891		4595-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404892		4595-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404893		4595-000-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404894		4595-000-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404895		4595-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404896		4595-000-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404897		4595-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404898		4595-000-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404899		4595-000-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404900		4595-000-005-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404901		4595-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404902		4595-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404903		4595-000-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404904		4530-000-001-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404905		4530-000-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404906		4530-000-001-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404907		4530-000-002-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404908		4530-000-002-0108	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2404909		4530-000-003-0602	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404910		4530-000-003-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404911		4530-000-004-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404912		4530-000-004-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404913		4530-000-005-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404914		4530-000-005-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404915		4530-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404916		4530-000-005-0303	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404917		4530-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404918		4530-000-007-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check blue	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404919		4530-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404920		4530-000-008-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404921		4530-000-009-0507	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404922		4530-000-008-0201	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2404923		4530-000-009-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404924		4530-000-009-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404925		4530-000-010-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404926		102401-2-061-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404927		102401-2-062-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404928		102401-2-063-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404929		102401-2-064-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404930		102401-2-065-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404931		102401-2-066-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404932		102401-2-103-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404933		102401-3-210-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404934		102401-3-027-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404935		102401-3-030-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404936		102401-3-030-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404937		102401-3-031-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404938		102401-3-083-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404939		102401-3-033-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404940		102401-3-168-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404941		102401-3-223-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404942		102401-3-036-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404943		102401-3-091-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404944		102401-3-037-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404945		102401-3-040-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404946		102401-3-039-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404947		102401-3-042-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404948		102401-3-044-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404949		102401-3-201-2006	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404950		102401-3-200-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404951		102401-3-048-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404952		102401-3-046-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404953		102401-3-052-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404954		102401-3-053-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404955		102401-3-054-2004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404956		102401-3-058-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404957		102401-3-056-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404958		102401-3-056-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404959		102401-3-055-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404960		102401-3-206-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404961		102401-3-095-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404962		102401-3-156-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404963		102401-3-155-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404964		102401-3-159-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404965		102401-3-094-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404966		102401-3-160-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404967		102401-3-114-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404968		102401-3-163-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404969		102401-3-162-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404970		102401-3-166-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404971		102401-3-165-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404972		102401-3-167-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404973		102401-3-153-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2404981		3776-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404982		3776-000-018-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404983		3776-000-016-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404984		3776-000-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404985		3776-000-015-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404986		3776-000-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404987		3776-000-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404988		3776-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404989		3776-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404990		3776-000-009-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2404991		3776-000-007-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404992		3776-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404993		3776-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404994		3776-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404995		3776-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404996		3776-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404997		3776-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2404998		3776-000-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2404999		3750-001-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405000		3750-001-004-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405001		3750-002-004-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405002		3750-002-005-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405003		152401-2-138-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405004		152401-2-139-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405005		152401-2-140-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405006		152401-2-142-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405007		152401-2-146-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405008		3750-002-006-0303	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405009		3750-002-006-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405010		3750-002-006-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405011		3750-002-007-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405012		3750-002-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405013		152401-2-131-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405014		152401-2-130-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405015		102401-3-161-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405016		102401-3-118-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405017		102401-3-116-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405018		102401-3-111-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405019		102401-3-113-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405020		102401-3-108-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405021		102401-3-106-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405022		102401-3-198-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405023		102401-3-101-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405024		102401-3-199-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405025		102401-3-097-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405026		102401-3-193-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405027		102401-3-098-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405028		102401-3-192-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405029		102401-3-100-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405030		102401-3-225-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405031		102401-3-125-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405032		102401-3-124-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405033		102401-3-123-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405034		102401-3-122-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405035		102401-3-119-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405036		102401-3-120-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405037		102401-3-212-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405038		3793-000-024-0205	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405039		3793-000-024-0601	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405040		3793-000-022-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405041		3793-000-022-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405042		3793-000-022-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405043		3793-000-021-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405044		3793-000-021-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405045		3793-000-021-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405046		3793-000-020-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405047		3793-000-020-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405048		3793-000-019-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405049		3793-000-019-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405050		3793-000-018-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405051		3793-000-017-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405052		3793-000-017-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405053		3793-000-016-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405054		3793-000-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405055		3793-000-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405056		3793-000-014-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405057		3730-000-015-0004	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405058		3730-000-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405059		3730-000-019-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405060		3730-000-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405061		3730-000-017-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405062		3730-000-015-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405063		3730-000-013-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405064		3730-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405065		3730-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405066		3730-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405067		3730-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405068		3730-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405069		3730-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405070		3730-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405071		3730-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405079		3730-000-026-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405080		3730-000-024-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405081		3730-000-023-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405082		3730-000-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405083		3730-000-021-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405084		3730-000-023-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405085		3730-000-024-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405086		3730-000-025-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405087		3730-000-026-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405088		3730-000-026-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405089		3791-000-019-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405090		3791-000-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405091		3791-000-018-0403	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405092		3791-000-017-0800	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405093		3791-000-017-0503	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405094		3791-000-017-0503	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405095		3791-000-016-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405096		3791-000-016-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405097		3791-000-015-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405098		3792-000-028-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405099		3792-000-027-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405100		3792-000-026-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405101		3792-000-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405102		3792-000-024-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405103		3792-000-023-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405104		3792-000-022-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405105		3792-000-022-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405106		3792-000-021-0407	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405107		3792-000-021-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405108		3792-000-020-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405109		3792-000-019-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405110		3792-000-017-0502	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405111		3792-000-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405112		3792-000-017-0601	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405113		3792-000-017-0700	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405114		3792-000-015-0702	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405115		3792-000-015-0603	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405116		3792-000-015-0504	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405117		3792-000-015-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405118		3792-000-015-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405119		3792-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405120		092401-1-049-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405121		092401-1-011-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405122		092401-1-010-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405123		092401-1-007-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405124		092401-1-038-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405125		092401-1-040-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405126		092401-1-006-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405127		092401-1-052-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405128		092401-1-051-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405129		092401-1-004-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405130		092401-1-004-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405131		092401-1-044-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405132		092401-1-043-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405133		092401-1-042-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405134		092401-1-045-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405135		092401-1-035-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405136		3761-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405137		3761-000-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405138		3761-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405139		3761-000-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405140		3761-000-005-0008	No	Not evaluated	Galvanized	No	Prior to 1971	0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405141		3761-000-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405142		3761-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405143		3761-000-008-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405144		3761-000-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405145		3761-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405146		3761-000-012-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405147		3761-000-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405148		3761-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405149		3761-000-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405150		3761-000-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405151		3761-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405152		3761-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405153		3761-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405154		3761-000-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405155		3761-000-022-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405156		3761-000-022-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405157		3761-000-022-0205	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405158		3761-000-022-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405159		3761-000-022-0403	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405160		3761-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405161		3761-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405162		3761-000-021-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405163		092401-1-034-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405164		092401-1-033-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405165		092401-1-031-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405166		092401-1-032-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405167		092401-1-032-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405168		092401-1-037-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405169		092401-1-030-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the me

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405177		092401-1-023-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405178		092401-1-022-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405179		092401-1-041-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405180		092401-1-020-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405181		092401-1-018-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405182		092401-1-019-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405183		092401-1-017-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405184		092401-1-016-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405185		092401-1-014-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405186		092401-1-015-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405187		3792-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405188		3792-000-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check (AB)			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405189		3792-000-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405190		3792-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405191		3792-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405192		3792-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405193		3792-000-005-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405194		3792-000-005-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405195		3792-000-006-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405196		3792-000-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405197		3792-000-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405198		3792-000-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405199		3792-000-009-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405200		3792-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405201		3792-000-010-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405202		3792-000-010-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405203		3792-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405204		3792-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405205		3792-000-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405206		3792-000-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405207		3791-000-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405208		3791-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405209		3791-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405210		3791-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405211		3791-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405212		3791-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405213		3791-000-006-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405214		3791-000-007-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405215		3791-000-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405216		3791-000-009-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405217		3791-000-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405218		3791-000-010-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405219		3791-000-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405220		3791-000-011-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405221		3791-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405222		3791-000-013-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405223		3791-000-013-0408	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405224		3791-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405225		3793-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405226		3793-000-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405227		3793-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405228		3793-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405229		3793-000-004-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405230		3793-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405231		3793-000-007-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405232		3772-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405233		3772-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405234		3772-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405235		3772-000-004-0006	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405236		3772-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405237		3772-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405238		3772-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405239		3793-000-010-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405240		3793-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405241		3793-000-010-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405242		3793-000-011-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405243		3793-000-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405244		3793-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405245		3793-000-012-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405246		3793-000-013-0406	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405247		3793-000-013-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405248		3793-000-013-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405249		162401-1-031-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405250		162401-1-137-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405251		162401-1-136-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405252		162401-1-029-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405253		162401-1-028-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405254		162401-1-027-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405255		162401-1-027-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405256		162401-1-026-2007	No	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405257		162401-1-025-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405258		162401-1-025-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405259		162401-1-023-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405260		162401-1-022-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405261		162401-1-021-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405262		162401-1-020-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405263		162401-1-019-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405264		162401-1-018-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405265		162401-1-017-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405266		162401-1-016-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405267		162401-1-016-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405275		162401-1-007-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405276		162401-1-005-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405277		162401-1-004-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405278		162401-1-035-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405279		3750-003-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405280		3750-003-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405281		3750-003-002-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405282		3750-003-003-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405283		3750-003-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405284		3750-003-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405285		152401-2-135-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405286		152401-2-133-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405287		152401-2-134-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405288		152401-2-145-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405289		152401-2-207-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405290		152401-2-148-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405291		152401-2-149-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405292		152401-2-151-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405293		152401-2-026-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405294		152401-2-026-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405295		152401-2-198-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405296		152401-2-155-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405297		152401-2-157-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405298		152401-2-156-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405299		152401-2-233-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405300		152401-2-158-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405301		152401-2-160-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405302		152401-2-162-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb 5 pg 62			2016-2024		Galvanized		0.75	Fb 5 pg 62	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405303		152401-2-163-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405304		152401-2-164-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405305		5296-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405306		5296-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405307		5296-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405308		5296-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405309		5296-000-005-0007	Yes - Schoo	Not evaluated	Non-Lead - Copper	No		2.00		Visual inspection at the meter pit		2016-2024		Galvanized		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405310		5296-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405311		5296-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405312		5296-000-008-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405313		5296-000-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405314		5296-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405315		152401-3-175-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405316		152401-3-175-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405317		152401-3-175-2003	No	Not evaluated	Non-Lead - Plastic	No		2.00				2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405318		152401-2-196-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405319		152401-2-196-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405320		152401-2-205-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 16	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 16	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405321		152401-2-205-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 16			2016-2024		Non-Lead - Plastic		0.75	Book 6 Pg 16	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405322		152401-2-169-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405323		152401-2-179-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405324		152401-2-181-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405325		152401-2-181-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405326		152401-2-182-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405327		152401-2-178-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405328		152401-2-178-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405329		152401-2-178-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405330		152401-2-177-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405331		152401-2-176-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 49	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405332		152401-2-186-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405333		152401-2-186-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405334		152401-2-174-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405335		152401-2-188-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405336		152401-2-190-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405337		152401-2-193-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405338		152401-2-218-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405339		152401-2-218-2004	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405340		152401-2-173-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405341		152401-2-173-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405342		152401-2-191-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405343		152401-2-192-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405344		152401-2-194-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 2187	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2187	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405345		152401-2-197-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405346		3783-001-001-0400	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405347		3783-001-001-0400	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405348		3783-001-001-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405349		152401-3-177-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405350		152401-3-173-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405351		152401-3-172-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405352		152401-3-172-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405353		3783-008-001-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405354		3783-009-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405355		3777-008-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405356		3777-008-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405357		8014-000-000-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Non-Lead - Plastic	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Non-Lead - Plasti	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405358		8014-000-000-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405359		8014-000-000-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405360		152401-3-095-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405361		152401-3-094-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405362		152401-3-100-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405363		152401-3-092-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405364		152401-3-093-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405365		152401-3-099-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405366		3748-002-003-0103	No	Not evaluated	Non-Lead - Plastic	No		0

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405373		162401-4-052-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405374		162401-4-052-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405375		162401-4-052-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405376		162401-4-048-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405377		162401-4-049-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	W164			2016-2024		Non-Lead - Plastic		0.75	W164	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405378		162401-4-047-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W248	Live service/ abandon		2016-2024		Unknown		0.75	W248	Yes	Live service/ abandon	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405379		162401-4-046-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	W312			2016-2024		Non-Lead - Plastic		0.75	W312	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405380		162401-4-043-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405381		162401-4-042-2001	Yes - Schoo	Not evaluated	Non-Lead - Other	No		4.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		4.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405382		162401-4-041-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		<Null>		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405383		162401-4-041-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405384		162401-4-039-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405385		162401-4-038-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405386		162401-4-037-2008	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405387		162401-4-084-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405388		162401-4-084-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405389		162401-4-033-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405390		162401-4-031-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Tap log 79	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405391		162401-4-030-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 76	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap log 76	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405392		162401-4-028-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 77			2016-2024		Non-Lead - Plastic		0.75	Tap log 77	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405393		162401-4-027-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405394		162401-4-017-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405395		162401-4-022-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405396		162401-4-026-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405397		162401-4-074-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405398		162401-4-075-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405399		162401-4-020-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405400		162401-4-018-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405401		162401-4-029-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405402		162401-4-016-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405403		8005-000-000-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405404		162401-1-159-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405405		162401-1-153-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405406		162401-1-037-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405407		162401-1-037-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405408		162401-1-036-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 13 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405409		162401-1-036-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 13 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405410		162401-1-108-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 20 Pg 73			2016-2024		Galvanized		0.75	Book 20 Pg 73	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405411		162401-1-105-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 11	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 11	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405412		162401-1-104-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 38			2016-2024		Galvanized		0.75	Book 6 Pg 38	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405413		162401-1-140-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405414		162401-1-123-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405415		162401-1-123-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405416		162401-1-094-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405417		162401-1-092-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405418		162401-1-089-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405419		162401-1-089-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405420		162401-1-088-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405421		162401-1-086-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405422		162401-1-164-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405423		162401-1-097-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405424		162401-1-156-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	E475	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E475	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405425		162401-1-098-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405426		162401-1-161-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	E467	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E467	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405427		162401-1-102-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405428		162401-1-116-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405429		162401-1-106-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405430		162401-1-107-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3734	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405431		162401-1-111-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405432		162401-4-012-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405433		162401-4-012-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405434		162401-1-095-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405435		162401-1-133-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405436		162401-1-087-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405437		162401-1-078-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405438		162401-1-077-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405439		162401-1-076-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405440		162401-1-075-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405441		162401-1-073-2009	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405442		162401-1-072-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405443		162401-1-056-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405444		162401-1-055-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405445		162401-1-054-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405446		162401-1-048-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405447		162401-1-047-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405448		162401-1-046-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405449		162401-1-045-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405450		162401-1-042-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405451		162401-1-041-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405452		162401-1-039-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405453		162401-1-135-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405454		162401-1-134-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405455		162401-1-033-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405456		3762-000-009-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405457		3762-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405458		3762-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405459		3762-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405460		162401-1-006-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405461		3762-000-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405462		3762-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405463		3762-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405464		3762-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Vis

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405471		3770-000-046-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405472		3770-000-045-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405473		3770-000-044-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405474		3770-000-043-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405475		3770-000-042-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405476		3770-000-040-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405477		3770-000-039-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405478		3770-000-037-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405479		3770-000-036-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405480		3770-000-035-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405481		3770-000-035-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405482		3770-000-033-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405483		3770-000-032-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405484		3770-000-032-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405485		3770-000-029-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405486		3770-000-029-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405487		3770-000-027-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405488		3770-000-025-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405489		3770-000-022-0006	No	Not evaluated	Galvanized	No	Prior to 2015	0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405490		3770-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405491		3770-000-019-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405492		3770-000-015-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405493		3770-000-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405494		3770-000-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405495		3770-000-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405496		3770-000-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405497		3770-000-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405498		3770-000-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405499		3770-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405500		3770-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405501		3770-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405502		3762-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405503		3762-000-017-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405504		162401-1-120-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405505		3762-000-016-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405506		3762-000-016-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405507		3762-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405508		162401-1-032-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405509		162401-1-038-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405510		162401-1-044-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405511		162401-1-051-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405512		162401-1-050-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405513		162401-1-049-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405514		162401-1-052-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405515		162401-1-053-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405516		162401-1-057-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405517		162401-1-058-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405518		162401-1-059-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405519		162401-1-063-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405520		162401-1-071-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405521		162401-1-144-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405522		162401-1-060-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405523		162401-1-145-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405524		162401-1-069-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405525		162401-1-070-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405526		162401-1-117-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405527		162401-1-064-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405528		162401-1-113-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405529		162401-1-113-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405530		162401-1-061-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405531		3719-001-015-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405532		3719-001-014-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405533		3719-001-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405534		3719-001-011-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405535		3719-001-010-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405536		3719-001-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405537		3719-001-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405538		3719-001-003-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405539		092401-3-007-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405540		3719-001-001-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405541		3719-001-004-0307	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405542		3719-001-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405543		3719-001-007-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405544		3719-001-008-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405545		3719-001-010-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405546		3719-001-012-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405547		5262-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405548		5262-000-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405549		5262-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405550		5262-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405551		5262-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405552		5262-000-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405553		5262-000-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405554		5262-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405555		5262-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405556		5262-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405557		3719-001-018-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405558		3719-001-018-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405559		3719-001-019-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405560		3719-001-019-0300	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405561		3719-001-018-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405569		162401-1-148-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405570		162401-1-149-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405571		162401-1-083-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405572		162401-1-084-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405573		3821-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405574		3821-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405575		3821-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405576		3821-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405577		3821-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405578		3821-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405579		3821-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405580		162401-2-001-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405581		162401-2-007-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405582		3719-001-036-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405583		3719-001-035-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 18			2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 18	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405584		3719-001-035-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48			2016-2024		Galvanized		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405585		3719-001-035-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 27	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 27	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405586		3719-001-035-0300	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405587		3719-001-034-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 20 Pg73	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 20 Pg73	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405588		3719-001-034-0202	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 15	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 13 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405589		3719-001-034-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3031/3032			2016-2024		Galvanized		0.75	BEDA 3031/3032	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405590		3719-001-034-0400	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405591		3719-001-033-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405592		162401-1-124-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2080	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2080	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405593		162401-1-125-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752			2016-2024		Non-Lead - Plastic		0.75	BEDA 2752	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405594		162401-1-126-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486			2016-2024		Galvanized		0.75	BEDA 5486	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405595		162401-4-010-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405596		162401-4-014-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405597		162401-4-087-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405598		162401-4-087-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405599		3748-001-001-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405600		3748-001-001-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405601		3748-001-001-0107	Yes - School	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405602		3748-001-001-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405603		3748-001-019-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405604		3748-001-019-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405605		3748-001-019-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405606		3748-001-019-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405607		3748-001-019-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405608		3748-001-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405609		3748-001-015-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405610		3748-001-015-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405611		152401-3-195-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405612		152401-3-195-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405613		152401-3-195-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405614		152401-3-196-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405615		152401-3-196-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405616		152401-3-196-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405617		3777-005-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405618		3783-001-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405619		3783-001-018-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405620		3783-001-014-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405621		3783-007-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405622		3783-006-038-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405623		3783-006-036-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405624		3783-007-003-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405625		3783-006-035-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405626		3783-007-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405627		3783-006-033-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405628		3783-007-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405629		3783-006-031-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405630		3783-007-010-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405631		3783-006-029-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405632		3783-006-027-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405633		3783-007-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405634		3783-007-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405635		3783-006-024-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405636		3783-007-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405637		3783-007-017-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405638		3783-006-022-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405639		152401-3-165-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405640		152401-3-138-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405641		152401-3-139-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405642		3783-007-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405643		3783-007-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405644		3783-007-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405645		3783-007-034-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405646		3783-007-037-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405647		3783-008-008-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405648		152401-3-140-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405649		152401-3-161-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405650		152401-3-141-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405651		152401-3-160-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405652		152401-3-142-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405653		152401-3-159-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405654		152401-3-189-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405655		152401-3-158-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405656		152401-3-157-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405657		152401-3-145-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405658		152401-3-156-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405659		152401-3-155-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405660		152401-3-146-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405667		152401-3-150-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405668		152401-3-151-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405669		152401-3-164-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405670		152401-3-048-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405671		152401-3-047-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405672		152401-3-040-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405673		152401-3-041-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405674		152401-3-038-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405675		152401-3-180-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405676		152401-3-035-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405677		152401-3-034-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405678		152401-3-033-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405679		152401-3-032-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405680		152401-3-030-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405681		4596-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405682		152401-3-027-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405683		152401-3-025-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405684		152401-3-024-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1916	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1916	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405685		152401-3-023-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405686		152401-3-021-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405687		152401-3-019-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405688		152401-3-015-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405689		152401-3-014-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405690		152401-3-013-2009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405691		152401-3-012-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405692		152401-3-011-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405693		152401-3-128-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405694		152401-3-010-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405695		152401-3-009-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405696		152401-3-126-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405697		152401-3-008-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405698		152401-3-006-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405699		152401-3-006-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405700		152401-3-006-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405701		152401-3-007-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405702		152401-3-125-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405703		152401-3-183-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405704		152401-3-184-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405705		152401-3-124-2005	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405706		152401-3-129-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405707		152401-3-131-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405708		152401-3-046-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405709		152401-3-046-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405710		152401-3-120-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405711		152401-3-133-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405712		152401-3-135-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405713		152401-3-135-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405714		152401-3-135-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405715		152401-3-118-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405716		152401-3-118-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405717		152401-3-137-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405718		152401-3-117-2004	No	Not evaluated	Non-Lead - Other	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405719		152401-3-116-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405720		152401-3-115-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405721		3783-006-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405722		3783-005-021-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405723		3783-005-024-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405724		3783-006-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405725		3783-005-026-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405726		3783-005-026-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405727		3783-006-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405728		3783-005-028-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405729		3783-005-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405730		3783-006-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405731		3783-006-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405732		3783-005-032-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405733		3783-006-006-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405734		3783-005-034-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405735		3783-005-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405736		3783-006-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405737		3783-006-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405738		3783-005-039-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405739		3783-002-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405740		3783-002-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405741		3783-002-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405742		3783-002-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405743		3783-002-016-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405744		3783-005-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405745		3783-005-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405746		3783-005-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405747		3783-005-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405748		3783-005-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405749		3783-005-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405750		3783-005-018-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405751		152401-3-114-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405752		152401-3-114-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405753		152401-3-114-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405754		152401-3-114-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405755		152401-3-113-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405756		152401-3-113-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No

Location Information					System-Owned Portion								Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405765		3783-004-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405766		3783-004-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405767		3783-004-001-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405768		3783-003-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405769		3783-003-005-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	Tap log 78			2016-2024		Non-Lead - Plastic		2.00	Tap log 78	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405770		3783-003-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405771		152401-4-023-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405772		152401-4-005-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405773		152401-4-003-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405774		152401-4-002-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405775		152401-4-001-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405776		152401-4-016-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405777		3787-000-016-0401	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405778		3787-000-016-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405779		3783-003-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405780		3787-000-016-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405781		3787-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405782		3787-000-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405783		3787-000-015-0303	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405784		3787-000-015-0303	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405785		3787-000-015-0402	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405786		3729-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405787		3787-000-015-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405788		3729-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405789		3729-000-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405790		3729-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405791		3729-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405792		3729-000-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405793		3729-000-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405794		3729-000-054-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405795		3729-000-055-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	W181			2016-2024		Galvanized		0.75	W181	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405796		3735-017-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W202	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W202	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405797		3729-000-057-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	No service			2016-2024		Unknown		0.75	No service	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405798		3735-017-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Replaced			2016-2024		Galvanized		0.75	Replaced	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405799		3729-000-058-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405800		3729-000-059-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405801		3735-017-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405802		3735-017-014-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405803		3729-000-060-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405804		3735-017-016-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405805		3729-000-061-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405806		3729-000-062-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	C		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	C	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405807		3729-000-063-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405808		3735-017-018-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405809		3735-018-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405810		3734-015-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405811		3734-015-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405812		3734-015-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405813		3734-015-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405814		3734-015-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405815		3734-015-009-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405816		3734-015-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405817		3734-015-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405818		3734-015-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405819		3734-014-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405820		3734-015-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405821		3734-015-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405822		3733-001-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405823		3733-001-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405824		3734-016-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405825		3734-016-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405826		3734-016-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405827		3734-016-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405828		3734-016-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405829		3734-016-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405830		3734-016-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405831		3734-016-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405832		3734-016-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405833		3781-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405834		3781-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405835		3781-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405836		3781-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405837		3781-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405838		3781-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405839		3781-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405840		3781-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405841		3781-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405842		3781-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405843		3781-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405844		3781-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405845		3781-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405846		3781-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405847		3781-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405848		3781-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405849		3781-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405850		3781-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405851		3781-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405852		3781-000-020-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405853		3781-000-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405854		3781-000-022-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405855		3781-000-023-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non

Location Information					System-Owned Portion									Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier						Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Other Potential Sources of: Is there a Lead Connector?	Other Potential Sources of: Is there Lead Solder in the Service Line?	Other Potential Sources of: Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405863		3729-000-050-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		<Null>		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405864		3729-000-051-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 77			2016-2024		Galvanized		0.75	Tap log 77	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405865		3729-000-052-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Copper		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405866		3729-000-034-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405867		3729-000-035-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	W247	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W247	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405868		3729-000-036-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81			2016-2024		Non-Lead - Copper		0.75	Tap log 81	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405869		3729-000-037-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log (3118)			2016-2024		Galvanized		0.75	Tap Log (3118)	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405870		3781-000-025-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405871		3781-000-026-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405872		3781-000-027-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405873		3781-000-028-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405874		3781-000-029-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405875		3781-000-030-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405876		3781-000-031-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405877		3781-000-032-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405878		3781-000-033-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405879		3781-000-034-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405880		3781-000-035-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405881		3781-000-035-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405882		3781-000-036-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405883		3781-000-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405884		3781-000-038-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405885		3781-000-039-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405886		3781-000-040-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405887		3781-000-041-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405888		3781-000-042-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405889		3781-000-043-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405890		3781-000-044-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405891		3781-000-045-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405892		3781-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405893		3781-000-047-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405894		3781-000-048-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405895		3729-000-024-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405896		3729-000-026-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405897		3729-000-027-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405898		3729-000-028-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Copper		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405899		3729-000-029-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 76	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 76	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405900		3729-000-029-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79 2005			2016-2024		Non-Lead - Plastic		0.75	Tap log 79 2005	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405901		3729-000-032-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W226	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W226	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405902		3729-000-033-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405903		3729-000-014-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405904		3729-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	W247	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	W247	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405905		3729-000-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W131			2016-2024		Non-Lead - Plastic		0.75	W131	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405906		3729-000-017-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 71 3518	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 71 3518	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405907		3729-000-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405908		3729-000-019-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	NULL			2016-2024		Non-Lead - Plastic		0.75	NULL	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405909		3729-000-021-0009	No	Not evaluated	Galvanized	No	Prior to 1994	2.00	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405910		3729-000-022-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405911		3729-000-023-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405912		3781-000-049-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405913		3781-000-051-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405914		3781-000-053-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405915		3781-000-054-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405916		3781-000-055-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405917		3781-000-056-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405918		3781-000-057-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405919		3781-000-059-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405920		3715-000-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405921		3715-000-005-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405922		3715-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405923		3715-000-004-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405924		3715-000-003-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405925		3715-000-003-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405926		3715-000-003-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405927		3715-000-002-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405928		3715-000-002-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405929		3715-000-002-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405930		3715-000-002-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405931		3715-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405932		3715-000-001-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405933		3715-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405934		3715-000-001-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405935		152401-4-014-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405936		152401-4-013-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405937		152401-4-013-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405938		3715-000-011-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405939		3715-000-006-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405940		3715-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405941		3715-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405942		3715-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405943		3715-000-008-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405944		3715-000-009-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405945		3715-000-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405946		3715-000-009-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405947		3715-000-009-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405948		3715-000-014-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405949		3715-000-014-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405950		3715-000-014-0400	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405951		3715-000-013-0302	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405952		3715-000-012-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405953		3715-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405954		3715-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405955		3715-000-011-0205	No	Not evaluated	Non-Lead -

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2405961		3715-000-017-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405962		3715-000-018-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405963		3715-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405964		3715-000-019-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405965		222401-1-011-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405966		222401-1-010-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405967		222401-1-009-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405968		222401-1-008-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405969		222401-1-033-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405970		3707-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405971		3707-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405972		222401-1-006-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405973		222401-1-006-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405974		222401-1-005-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405975		222401-1-005-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2405976		222401-1-004-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405977		222401-1-004-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405978		222401-1-054-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405979		222401-1-054-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405980		222401-1-054-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405981		222401-1-054-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405982		222401-1-054-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405983		152401-4-017-2003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2405984		152401-4-017-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405985		152401-4-017-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405986		152401-3-103-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405987		152401-3-104-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405988		152401-3-105-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405989		152401-3-106-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405990		152401-3-107-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405991		152401-3-108-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405992		152401-3-108-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405993		152401-3-109-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405994		152401-3-110-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405995		152401-3-197-2007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2405996		152401-3-197-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405997		152401-3-186-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405998		152401-3-002-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2405999		152401-3-192-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406000		222401-2-001-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406001		222401-2-001-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406002		222401-2-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406003		222401-2-003-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406004		222401-2-004-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406005		222401-2-005-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406006		222401-2-006-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406007		222401-2-035-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406008		222401-2-036-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406009		222401-2-109-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406010		222401-2-109-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406011		222401-2-032-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406012		222401-2-032-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406013		222401-2-032-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406014		222401-2-031-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406015		222401-2-009-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406016		222401-2-030-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406017		222401-2-028-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406018		222401-2-020-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406019		222401-2-018-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406020		222401-2-018-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406021		222401-2-025-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406022		222401-2-015-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406023		222401-2-015-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406024		4596-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406025		4596-000-003-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406026		4596-000-003-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406027		4596-000-003-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406028		222401-2-014-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406029		222401-2-014-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406030		222401-2-010-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406031		152401-3-036-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1916	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1916	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406032		152401-3-039-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406033		3777-003-015-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406034		4502-002-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406035		4502-002-024-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406036		4502-002-022-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406037		4502-002-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406038		4502-006-028-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406039		4502-006-033-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406040		4502-006-037-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406041		4502-006-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406042		4502-006-004-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406043		4502-006-001-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406044		4502-006-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406045		4502-006-005-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406046		4502-006-007-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406047		4502-003-019-0008	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406048		4502-003-019-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406049		4502-003-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406050		4502-003-017-0208	No	Not evaluated	Galvanized	No	Prior to 2011	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406059		4502-003-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406060		4502-003-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406061		4502-002-012-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406062		4502-002-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406063		4502-002-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406064		4502-002-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406065		4502-002-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406066		4502-002-027-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406067		4502-002-027-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406068		4502-002-026-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406069		4502-001-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406070		4502-001-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406071		4502-001-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406072		4502-001-024-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406073		4502-001-026-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406074		4502-001-022-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406075		4502-001-029-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406076		4502-001-029-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406077		4502-004-007-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406078		4502-004-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406079		4502-004-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406080		4502-004-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406081		4502-004-014-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406082		4502-004-016-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406083		4502-004-018-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406084		4502-004-020-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406085		4502-004-024-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406086		4502-005-011-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406087		4502-005-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406088		4502-005-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406089		4502-005-021-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406090		4502-005-024-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406091		4502-005-020-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406092		4502-005-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406093		4502-005-031-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406094		4502-005-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406095		4502-005-035-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406096		4502-005-046-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406097		4502-004-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406098		4502-004-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406099		4502-001-001-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406100		4502-001-001-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 31	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 31	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406101		3745-000-028-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406102		4502-008-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406103		4502-008-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406104		4502-008-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406105		4502-008-014-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406106		4502-008-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406107		4502-008-030-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406108		4502-008-020-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406109		4502-007-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406110		4502-007-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406111		4502-007-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406112		4502-007-010-0206	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406113		4502-007-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406114		4502-007-018-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406115		4502-007-024-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406116		4502-007-026-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406117		4502-011-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406118		4502-011-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406119		4502-011-011-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406120		4502-011-009-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406121		4502-007-032-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406122		4502-011-011-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406123		4502-011-009-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406124		4502-007-034-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406125		4502-011-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406126		4502-011-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406127		4502-007-038-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406128		4502-007-040-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406129		4502-008-024-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406130		4502-010-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406131		4502-011-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406132		4502-011-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406133		4502-010-019-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406134		4502-010-020-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406135		4502-011-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406136		4502-011-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406137		4502-012-001-0009	No	Not evaluated	Non-Lead - Other	No		3.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		3.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406138		4502-012-039-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406139		4502-012-036-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406140		4502-012-035-0009	No	Not evaluated	Non-Lead - Other	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406141		4502-012-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406142		4502-012-028-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406143		4502-011-020-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406144		4502-012-011-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406145		4502-016-034-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406146		4502-016-032-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown	Yes		
BremSLI-2406147		4502-016-032-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406148		4502-016-031-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406149		4502-016-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406157		4502-016-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406158		4502-016-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406159		4502-017-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406160		4502-017-032-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406161		4502-016-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406162		4502-017-034-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406163		4502-016-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406164		4502-017-036-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406165		4502-016-009-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406166		4502-017-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406167		4502-017-039-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406168		4502-016-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406169		4502-016-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406170		4502-016-005-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406171		4502-017-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406172		4502-017-005-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406173		4502-017-005-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406174		4502-018-001-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406175		4502-018-001-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406176		4502-018-038-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406177		4502-017-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406178		4502-018-036-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406179		4502-018-034-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406180		4502-017-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406181		4502-017-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406182		4502-018-031-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406183		4502-018-030-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406184		4502-018-028-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406185		4502-017-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406186		4502-017-020-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406187		4502-017-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406188		4502-018-024-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406189		4502-018-024-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406190		4502-018-022-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Galvanized		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406191		4502-018-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406192		4502-018-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406193		4502-018-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406194		4502-018-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406195		4502-018-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406196		4502-018-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406197		4502-019-039-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406198		4502-019-037-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406199		4502-019-037-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406200		4502-019-035-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406201		4502-019-035-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406202		4502-019-035-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406203		4502-019-026-0005	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406204		4502-019-026-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406205		4502-019-024-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406206		4502-019-024-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406207		4502-019-024-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406208		4502-019-022-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406209		4502-022-024-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406210		4502-022-024-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406211		4502-019-020-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406212		4502-022-026-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406213		4502-019-019-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406214		4502-019-019-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406215		4502-019-019-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406216		4502-019-017-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406217		4502-022-030-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406218		4502-019-015-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406219		4502-019-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406220		4502-019-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406221		4502-019-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406222		4502-019-011-0002	No	Not evaluated	Galvanized	No	Prior to 2010	0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406223		4502-019-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406224		4502-022-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406225		4502-019-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406226		4502-019-007-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406227		4502-022-039-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406228		4502-022-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406229		4502-022-001-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406230		4502-019-005-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406231		4502-019-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406232		4502-019-003-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406233		4502-023-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406234		4502-019-006-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406235		4502-022-004-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Other		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406236		4502-023-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406237		4502-023-040-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406238		4502-023-040-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406239		4502-022-004-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406240		4502-022-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406241		4502-022-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406242		4502-022-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406243		4502-022-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406244		4502-023-032-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406245		4502-022-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406246		4502-023-029-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406247		4502-022-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406255		4502-026-001-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406256		4502-026-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406257		4502-026-037-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406258		4502-026-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406259		4502-026-015-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406260		4502-026-013-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406261		4502-026-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406262		4502-026-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406263		4502-026-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406264		4502-027-039-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406265		4502-027-037-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406266		4502-027-034-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406267		4502-027-032-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406268		4502-027-030-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406269		4502-027-028-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406270		4502-027-026-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406271		4502-027-024-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406272		4502-027-021-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406273		4502-027-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406274		4502-027-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406275		4502-027-015-0001	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406276		4502-027-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406277		4502-027-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406278		4502-027-001-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406279		4600-014-036-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406280		4600-014-032-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406281		4600-014-030-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 18			2016-2024		Galvanized		0.75	Book 6 Pg 18	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406282		4600-014-028-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406283		4600-014-026-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	E436	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	E436	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406284		4600-014-024-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406285		4600-014-021-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406286		4600-014-021-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406287		4600-013-002-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406288		4600-013-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406289		4600-013-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406290		4600-013-030-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406291		4600-013-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406292		4600-013-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406293		4600-013-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406294		4600-013-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406295		4600-013-025-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406296		4600-013-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406297		4600-013-021-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406298		4600-013-023-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406299		4600-012-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406300		4600-012-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406301		4600-013-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406302		4600-012-017-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406303		4600-011-021-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406304		4600-014-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406305		4600-011-023-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406306		4600-014-017-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406307		4600-014-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	E479	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E479	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406308		4600-014-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406309		4600-011-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	E428	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	E428	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406310		4600-011-029-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 30	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406311		4600-014-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 18			2016-2024		Galvanized		0.75	Book 6 Pg 18	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406312		4600-011-031-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406313		4600-011-031-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406314		4600-011-033-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 57	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 57	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406315		4600-014-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406316		4600-014-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406317		4600-011-035-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406318		4600-011-037-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752			2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406319		4600-014-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2187	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2187	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406320		4600-014-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406321		4600-011-039-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074			2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406322		4600-011-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406323		4600-011-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406324		4600-011-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406325		4600-011-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 24	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 24	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406326		4600-011-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	E428			2016-2024		Non-Lead - Plastic		0.75	E428	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406327		4600-011-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406328		4600-011-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406329		4600-011-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406330		4600-012-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406331		4600-012-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406332		4600-012-006-0005	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406333		4600-012-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406334		4600-012-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406335		4600-012-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406336		4600-012-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406337		4600-012-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406338		4600-027-012-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406339		4600-027-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406340		4600-027-008-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406341		4600-027-007-0408	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406342		4600-027-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406343		4600-026-057-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406344		4600-026-052-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406345		4600-025-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406353		4600-023-031-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406354		4600-023-029-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406355		4600-023-027-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406356		4600-023-026-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406357		4600-025-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406358		4600-023-024-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406359		4600-023-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406360		4600-025-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406361		4600-025-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406362		4600-023-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	E475	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E475	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406363		4600-023-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406364		4600-022-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406365		4600-023-013-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406366		4600-022-026-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406367		4600-022-029-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406368		4600-022-031-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406369		4600-023-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406370		4600-023-002-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406371		4600-022-036-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406372		4600-023-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406373		4600-023-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406374		4600-023-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406375		4600-023-039-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406376		4600-023-037-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406377		4600-026-034-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406378		4600-026-032-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406379		4600-026-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406380		4600-026-025-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406381		4600-026-025-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406382		4600-026-022-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406383		4600-026-016-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406384		4600-026-013-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406385		4600-026-011-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406386		4600-026-011-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406387		4600-024-008-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406388		4600-024-006-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406389		4600-024-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406390		4600-024-006-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406391		4600-024-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406392		4600-024-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406393		4600-024-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406394		4600-024-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406395		4600-021-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406396		4600-021-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406397		4600-021-020-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406398		4600-021-017-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406399		4600-022-039-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406400		4600-021-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074			2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406401		4600-021-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406402		4600-021-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406403		4600-021-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406404		4600-009-029-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406405		4600-009-026-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406406		4600-009-025-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406407		4600-009-023-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406408		4600-009-021-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Non-Lead - Plastic		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406409		4600-010-039-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406410		4600-022-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406411		4600-010-037-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406412		4600-022-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406413		4600-010-033-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406414		4600-022-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406415		4600-022-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406416		4600-010-031-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406417		4600-010-029-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406418		4600-010-027-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406419		4600-022-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406420		4600-010-025-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406421		4600-022-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406422		4600-022-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406423		4600-010-021-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406424		4600-022-019-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406425		4600-022-019-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406426		4600-010-021-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406427		4600-010-016-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406428		4600-010-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406429		4600-010-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406430		4600-010-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406431		4600-010-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406432		4600-010-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406433		4600-010-001-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406434		4600-010-001-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406435		4600-009-019-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Galvanized		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406436		4600-009-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406437		4600-009-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406438		4600-009-013-0002	No	Not evaluated	Non-Lead - Copper	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406439		4600-009-011-0004	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406440		4600-009-007-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406441		4600-009-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406451		4600-007-038-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406452		4600-007-035-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406453		4600-007-033-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406454		4600-007-030-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406455		4600-007-028-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406456		4600-007-026-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406457		4600-007-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406458		4600-007-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406459		4600-007-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406460		4600-007-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406461		4600-006-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406462		4600-006-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406463		4600-007-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406464		4600-007-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406465		4600-006-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406466		4600-006-025-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406467		4600-007-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406468		4600-007-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406469		4600-006-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406470		4600-006-029-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406471		4600-007-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406472		4600-006-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406473		4600-007-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406474		4600-006-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406475		4600-007-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406476		4600-007-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406477		4600-006-037-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406478		4600-006-038-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406479		4600-007-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406480		4600-007-040-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406481		4600-008-018-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406482		4600-005-021-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406483		4600-005-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406484		4600-008-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406485		4600-005-025-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406486		4600-005-026-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406487		4600-008-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406488		4600-008-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406489		4600-005-027-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406490		4600-005-029-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406491		4600-005-030-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406492		4600-005-034-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406493		4600-008-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406494		4600-005-036-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406495		4600-008-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406496		222401-4-063-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406497		222401-4-063-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406498		222401-4-060-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406499		222401-4-057-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406500		4600-005-039-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406501		222401-4-056-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406502		222401-4-056-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406503		4600-005-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406504		222401-4-052-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406505		4600-005-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406506		4600-004-036-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406507		4600-005-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406508		4600-004-032-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406509		4600-005-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406510		4600-004-027-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406511		4600-005-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406512		4600-005-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406513		4600-005-020-0209	No	Not evaluated	UNK	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406514		4600-003-035-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406515		4600-003-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406516		4600-003-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406517		4600-003-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406518		4600-006-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406519		4600-003-031-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406520		4600-006-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406521		4600-003-030-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406522		4600-003-027-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406523		4600-006-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406524		4600-003-025-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406525		4600-003-025-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406526		4600-006-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406527		4600-003-023-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406528		4600-003-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406529		4600-006-019-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406530		4600-002-021-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406531		4600-002-021-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406532		4600-003-019-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406533		4600-002-025-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406534		4600-002-025-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406535		4600-003-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406536		4600-003-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406537		4600-003-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406538		4600-002-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406539		4600-002-030-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			litional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406549		4600-004-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406550		4600-001-026-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406551		4600-001-026-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406552		4600-001-028-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406553		4600-004-008-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406554		4600-001-031-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406555		4600-004-006-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406556		4600-004-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406557		4600-001-035-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406558		4600-001-037-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406559		4600-004-002-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406560		4600-004-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406561		4600-004-038-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406562		4600-004-038-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406563		222401-4-044-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406564		222401-4-042-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406565		4600-001-039-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406566		4600-001-039-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406567		222401-4-041-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406568		4600-001-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406569		4600-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406570		4600-001-005-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406571		4600-001-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406572		222401-2-077-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406573		4600-001-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406574		4600-001-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406575		222401-2-079-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406576		222401-2-079-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406577		4600-001-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406578		4600-001-012-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406579		4600-001-018-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406580		222401-2-110-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406581		222401-2-110-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406582		222401-2-110-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406583		4600-001-020-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406584		4600-002-037-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406585		4600-002-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406586		4600-002-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406587		4600-002-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406588		4600-002-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406589		4600-002-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406590		4600-002-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406591		4600-002-016-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406592		4600-002-018-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406593		222401-2-070-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406594		222401-2-070-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406595		222401-2-046-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406596		222401-2-055-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406597		222401-2-095-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406598		222401-2-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406599		222401-2-066-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406600		222401-2-065-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406601		222401-2-065-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406602		222401-2-063-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406603		222401-2-071-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406604		222401-2-062-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406605		222401-2-062-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406606		222401-2-060-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406607		222401-2-060-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406608		222401-2-060-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406609		222401-2-061-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406610		222401-2-061-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406611		222401-2-059-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406612		222401-2-058-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406613		222401-2-051-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406614		222401-2-052-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406615		222401-2-057-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406616		222401-2-093-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406617		222401-2-084-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406618		222401-2-047-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406619		222401-2-048-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406620		222401-2-049-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406621		222401-2-049-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406622		222401-2-050-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406623		3736-003-032-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406624		3736-003-038-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406625		3736-003-040-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406626		222401-1-044-2007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		<Null>		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406627		222401-1-043-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406628		222401-1-046-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406629		3736-003-046-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406630		152401-4-021-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406631		152401-4-021-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406632		152401-4-021-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406633		3736-002-037-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406634		3736-002-037-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406635		3736-001-001-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406636		3736-002-001-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406637		3736-

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406647		3736-002-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406648		3736-001-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406649		3736-001-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406650		3736-002-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406651		3736-002-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406652		3736-001-018-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406653		3736-002-019-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406654		3736-002-021-0303	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406655		3736-004-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406656		3736-004-008-0108	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406657		3736-004-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406658		3736-005-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406659		3736-004-001-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406660		3736-005-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406661		3736-005-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406662		3736-004-002-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406663		3736-004-004-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406664		3736-005-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406665		3736-004-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406666		3736-005-006-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406667		3736-005-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406668		3736-004-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406669		3736-004-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406670		3736-002-023-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406671		3736-002-027-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406672		3736-002-029-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406673		3736-002-031-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406674		3736-002-033-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406675		3736-002-033-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406676		3736-003-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406677		3736-003-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406678		3736-003-014-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406679		3736-003-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406680		3736-003-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406681		224401-1-032-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406682		224401-1-034-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406683		224401-1-035-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406684		3822-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406685		3822-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406686		222401-1-014-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406687		222401-1-013-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406688		222401-1-015-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406689		222401-1-015-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406690		222401-1-017-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406691		222401-1-018-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406692		222401-2-044-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406693		222401-2-042-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406694		3790-015-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406695		3790-006-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406696		3790-006-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406697		3790-006-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406698		3790-006-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406699		3790-006-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406700		3790-006-001-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406701		3790-005-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406702		3790-005-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406703		3790-005-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406704		3790-005-010-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406705		3790-005-010-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406706		3790-005-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406707		3790-005-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406708		3790-005-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406709		3790-005-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406710		3790-005-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406711		222401-4-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406712		222401-4-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406713		222401-4-039-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406714		222401-4-038-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406715		222401-4-034-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406716		222401-4-032-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406717		222401-4-030-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406718		222401-4-029-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406719		222401-4-028-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406720		222401-4-028-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406721		3790-004-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406722		3790-004-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406723		3790-004-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406724		3790-004-023-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406725		3790-004-022-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406726		3790-004-018-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406727		3790-007-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406728		3790-007-021-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406729		3790-007-018-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406730		3790-014-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406731		3790-014-025-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406732		3790-014-020-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406733		222401-1-019-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406734		3790-014-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406735		3790-014-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406736		3822-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter p

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406745		3790-014-011-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406746		3790-014-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406747		3790-014-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406748		3790-007-013-0008	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406749		3790-007-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406750		3790-007-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406751		3790-004-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406752		3790-004-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406753		3790-004-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406754		3790-004-011-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406755		3790-004-009-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406756		222401-4-027-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406757		222401-4-027-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406758		222401-4-003-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406759		222401-4-002-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406760		222401-4-122-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406761		3790-003-003-0306	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406762		3790-003-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406763		3790-008-025-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406764		3790-008-023-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406765		3790-008-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406766		3790-008-020-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406767		3790-008-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406768		3790-013-001-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406769		3790-013-025-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406770		3790-013-023-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406771		3790-013-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406772		3790-013-020-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406773		222401-1-030-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406774		222401-1-029-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406775		3790-013-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406776		222401-1-028-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406777		222401-1-027-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406778		222401-1-026-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406779		222401-1-025-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406780		222401-1-024-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406781		3736-008-019-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406782		3736-008-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406783		3736-008-015-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406784		3736-008-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406785		3736-008-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406786		3790-013-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406787		3790-013-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406788		3790-013-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406789		3790-013-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406790		3790-013-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406791		3790-013-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406792		3790-013-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406793		3790-013-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406794		3790-013-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406795		3790-008-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406796		3790-008-014-0005	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406797		3790-008-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406798		3790-008-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406799		3790-008-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406800		3790-008-005-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406801		3790-003-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406802		3790-003-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406803		3790-003-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406804		3790-003-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406805		3790-003-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406806		3790-003-025-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406807		3790-003-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406808		222401-4-006-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406809		3704-003-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406810		3790-002-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406811		3790-002-025-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406812		3790-002-022-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406813		3790-002-022-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406814		3790-002-021-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406815		3790-002-019-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406816		3790-002-018-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406817		3790-009-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406818		3790-009-023-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406819		3790-009-023-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406820		3790-009-023-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406821		3790-009-023-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406822		3790-009-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406823		3790-009-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406824		3790-012-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406825		3790-012-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406826		3790-012-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406827		3790-012-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406828		3790-012-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406829		3790-012-018-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406830		3736-008-009-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406831		3736-008-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406832		3736-008-005-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406833

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406843		3790-012-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406844		3790-012-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406845		3790-012-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406846		3790-012-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406847		3790-009-013-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406848		3790-011-026-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406849		3790-011-024-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406850		3790-011-022-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406851		3790-011-020-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406852		3736-007-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406853		3736-006-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406854		3736-006-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406855		3736-006-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406856		3736-006-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406857		3790-011-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406858		3736-006-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406859		3790-011-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406860		3732-013-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406861		3732-013-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406862		3790-011-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406863		3790-011-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406864		3790-011-010-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406865		3790-011-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406866		3790-011-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406867		3790-011-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406868		3790-011-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406869		3790-011-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406870		3790-010-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406871		3790-010-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406872		3790-010-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406873		3790-009-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406874		3790-002-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406875		3790-002-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406876		3790-002-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406877		3790-002-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406878		3790-002-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406879		3790-002-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406880		3790-002-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406881		3790-002-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406882		3790-002-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406883		3704-003-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406884		3704-003-005-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406885		3704-003-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406886		3790-001-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406887		3790-001-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406888		3790-001-023-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406889		3790-001-021-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406890		3790-001-020-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406891		3790-001-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406892		3790-001-018-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406893		3790-001-014-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406894		3790-001-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406895		3790-001-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406896		3790-001-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406897		3790-001-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406898		3790-001-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406899		3790-001-010-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406900		3790-001-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406901		3790-001-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406902		3790-001-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406903		3790-001-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406904		3704-003-022-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406905		3704-003-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406906		3704-003-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406907		3704-003-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406908		3704-003-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406909		3704-003-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406910		3704-003-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406911		3704-003-014-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406912		3704-003-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406913		3704-003-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406914		222401-4-013-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406915		222401-4-015-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406916		222401-4-014-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406917		222401-4-014-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406918		222401-4-011-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406919		222401-4-010-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406920		222401-4-009-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406921		222401-4-008-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406922		222401-4-119-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406923		222401-4-024-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406924		222401-4-021-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406925		222401-4-019-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406926		222401-4-017-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406927		222401-4-018-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406928		222401-4-020-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406929		222401-4-022-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406930		222401-4-023-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406931		222401-4-037-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2406941		222401-4-062-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406942		222401-4-064-2006	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Unknown Type			2016-2024		Non-Lead - Copper		2.00	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406943		222401-4-066-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406944		222401-4-066-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		<Null>		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406945		222401-4-066-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406946		222401-4-065-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406947		222401-4-105-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406948		222401-4-106-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406949		222401-4-110-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406950		222401-4-112-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406951		222401-4-112-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406952		222401-4-113-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406953		222401-4-115-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406954		3704-004-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406955		3704-004-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406956		3704-004-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406957		3704-004-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406958		3704-004-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406959		3704-004-013-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406960		3704-004-013-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406961		3704-004-015-0008	No	Not evaluated	Galvanized	No	Prior to 1968	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406962		3732-025-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406963		3732-025-001-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406964		3732-024-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406965		3732-024-013-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2406966		3732-024-001-0008	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406967		3732-024-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406968		3732-024-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406969		3732-024-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406970		3732-024-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406971		3732-024-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406972		3732-024-010-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406973		3732-024-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406974		3732-025-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406975		3732-026-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406976		3732-026-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406977		3732-026-003-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406978		3732-026-003-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406979		3732-023-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406980		3732-023-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406981		3732-023-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406982		3732-023-002-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406983		3732-023-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406984		4501500	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406985		4501550	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406986		3732-026-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406987		3732-026-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406988		3704-005-000-0903	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406989		222401-4-092-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406990		8175-000-000-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406991		222401-4-071-2007	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2406992		222401-4-073-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406993		222401-4-073-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406994		222401-4-073-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406995		4600-026-039-0204	No	Not evaluated	Galvanized	No	Prior to 1989	0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406996		4600-026-039-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406997		4600-026-044-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2406998		4600-026-048-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2406999		4600-026-050-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407000		4600-026-052-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407001		4600-026-054-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407002		4600-026-054-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407003		4600-026-046-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407004		4600-027-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407005		4600-027-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407006		4600-027-004-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407007		4600-027-004-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407008		4600-027-007-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407009		4600-027-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407010		282401-1-079-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407011		282401-1-017-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407012		282401-1-018-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407013		282401-1-063-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407014		8035-012-101-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407015		8035-010-101-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407016		8035-009-101-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407017		8035-002-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407018		8035-008-101-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407019		8035-007-101-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407020		8035-005-101-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407021		8035-005-101-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407022		8035-005-101-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407023		282401-1-091-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407024		282401-1-091-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407025		282401-1-091-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407026		282401-1-048-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407027		282401-1-048-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407028		4624-008-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407029		4624-008-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407030		4624-008-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407031		4624-008-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407039		4624-007-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407040		4624-008-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407041		4624-007-009-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407042		4624-012-011-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407043		4624-012-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407044		4624-012-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407045		8092-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407046		8092-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407047		8092-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407048		8092-000-000-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407049		8092-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407050		8092-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407051		8092-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407052		8092-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407053		8092-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407054		4624-013-009-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407055		4624-012-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407056		4624-012-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407057		4624-012-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407058		4624-012-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407059		4624-012-015-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407060		4624-007-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407061		4624-007-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407062		4624-006-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407063		4624-006-013-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407064		4624-006-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407065		4624-006-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407066		4624-006-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407067		4624-007-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407068		4624-007-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407069		282401-1-025-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407070		282401-1-024-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407071		282401-1-026-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407072		4624-006-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407073		4624-006-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407074		4624-006-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407075		4624-006-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407076		4624-006-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407077		4624-006-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407078		4624-006-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407079		4624-006-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407080		4624-006-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407081		4624-006-006-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407082		4624-006-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407083		4624-013-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407084		4624-013-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407085		4624-013-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407086		4624-013-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407087		4624-013-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407088		4624-014-010-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407089		4624-014-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407090		4624-014-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407091		4624-014-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407092		4624-005-009-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407093		4624-005-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407094		4624-005-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407095		4624-005-001-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407096		4624-014-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407097		4624-014-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407098		4624-014-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407099		4624-014-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407100		4624-014-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407101		4624-014-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407102		4624-014-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407103		4624-023-002-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407104		4624-023-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407105		4624-022-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407106		4624-022-013-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407107		4624-015-009-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407108		4624-015-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407109		4624-015-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407110		4624-015-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407111		4624-004-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407112		4624-004-003-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407113		4624-004-003-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407114		4624-032-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407115		4624-032-001-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407116		4624-032-001-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407117		4624-021-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407118		4624-021-007-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407119		4624-021-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407120		4624-021-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407121		4624-020-015-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407122		4624-020-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407123		4624-020-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407124		4624-033-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407125		4624-033-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407126		4624-037-001-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407127		4624-036-013-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407128		4624-036-013-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407129		4624-036-005-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407137		282401-4-009-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407138		282401-4-011-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407139		282401-4-012-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407140		4624-043-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407141		282401-4-014-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407142		282401-4-037-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407143		282401-4-038-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407144		282401-4-039-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407145		4624-039-011-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407146		4624-039-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407147		4624-037-015-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407148		4624-037-015-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407149		4624-037-011-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407150		282401-4-003-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407151		282401-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407152		4624-022-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407153		4624-015-001-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407154		4624-015-001-0302	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407155		282401-1-057-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407156		4624-061-001-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407157		4624-061-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407158		4624-068-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407159		282401-4-021-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407160		282401-3-036-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407161		282401-3-036-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407162		282401-3-036-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407163		282401-3-037-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407164		4640-005-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407165		282401-3-038-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407166		332401-2-017-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407167		332401-2-017-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407168		332401-2-024-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407169		332401-2-024-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407170		4640-005-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407171		4640-004-025-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407172		4640-004-024-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407173		4640-004-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407174		282401-3-027-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407175		282401-3-069-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Unknown		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407176		282401-3-081-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407177		282401-3-072-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Work			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407178		282401-3-016-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407179		332401-2-006-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407180		332401-2-019-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407181		332401-2-019-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407182		322401-1-005-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407183		322401-1-005-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407184		322401-1-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407185		322401-1-094-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407186		322401-1-095-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407187		322401-1-096-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407188		322401-1-126-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407189		322401-1-138-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407190		322401-1-104-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407191		322401-1-027-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407192		322401-1-028-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407193		322401-1-111-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407194		322401-1-111-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407195		322401-1-031-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407196		322401-1-018-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407197		322401-1-113-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407198		322401-1-041-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407199		322401-1-042-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407200		322401-1-038-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407201		322401-1-038-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407202		4504-000-006-0700	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407203		4504-000-006-0700	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407204		4504-000-006-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407205		4504-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407206		4504-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407207		4504-000-005-0404	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407208		4504-000-001-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407209		322401-3-049-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407210		322401-3-049-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407211		352401-3-001-1001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407212		362401-1-001-1004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407213		362401-1-001-1004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407214		362401-1-001-1004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407215		362401-1-001-1004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407216		362401-1-001-1004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407217		362401-1-001-1004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407218		362401-1-001-1004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407219		4505-000-036-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407220		4504-000-012-0306	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407221		4504-000-012-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407222		4504-000-012-0405	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407223		4504-000-012-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407224		4504-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407225		4504-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407226		4504-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407235		3224O1-1-054-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407236		3224O1-1-103-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407237		3224O1-1-103-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407238		3224O1-1-103-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407239		3224O1-1-103-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407240		3224O1-1-103-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407241		3224O1-1-103-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407242		3224O1-1-061-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407243		3224O1-1-127-2005	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407244		3224O1-1-065-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407245		3224O1-1-067-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407246		3224O1-1-115-2009	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407247		4539-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407248		3224O1-4-075-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407249		4539-000-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407250		4539-000-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407251		4539-000-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407252		3224O1-4-071-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407253		3224O1-4-084-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407254		3224O1-3-001-2002	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407255		3224O1-3-045-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407256		3224O1-3-003-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407257		3224O1-3-004-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407258		3224O1-3-005-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407259		4504-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407260		4505-000-032-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407261		4505-000-033-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407262		4505-000-033-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407263		4505-000-033-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407264		4505-000-033-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407265		4505-000-033-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407266		4505-000-033-0607	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407267		4505-000-033-0508	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407268		4505-000-034-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407269		4505-000-034-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407270		4505-000-035-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown	Yes		
BremSLI-2407271		4505-000-035-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407272		4505-000-040-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407273		4505-000-040-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407274		4505-000-030-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407275		4505-000-030-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407276		4505-000-040-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407277		4505-000-040-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407278		4505-000-029-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407279		4505-000-040-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407280		4505-000-039-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407281		4505-000-039-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407282		4504-000-015-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407283		4505-000-021-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407284		4505-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407285		4505-000-020-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407286		4505-000-020-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407287		4505-000-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407288		4505-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407289		4505-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407290		4505-000-017-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407291		4505-000-017-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407292		4505-000-016-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407293		4505-000-016-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407294		4505-000-016-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407295		4505-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407296		4505-000-014-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407297		4505-000-014-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407298		4505-000-015-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407299		4505-000-015-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407300		4505-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407301		4505-000-001-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407302		4505-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407303		4505-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407304		4505-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407305		4505-000-005-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407306		4505-000-005-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407307		4505-000-007-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407308		4505-000-007-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407309		4505-000-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407310		4505-000-008-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407311		3224O1-3-007-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407312		3224O1-3-007-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407313		3224O1-3-022-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407314		3224O1-3-021-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407315		4505-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	No meter		2016-2024		<Null>		0.75	GIS Mains Year	No	No meter	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407316		3224O1-3-025-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407317		3224O1-3-023-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407318		4505-000-028-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407319		4505-000-027-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407320		4505-000-026-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407321		4505-000-025-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407322		4505-000-025-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407323		4505-000-025-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS M

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407333		322401-3-014-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407334		322401-3-014-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407335		322401-3-014-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407336		322401-3-010-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407337		322401-3-009-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407338		322401-3-009-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407339		322401-3-013-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407340		322401-3-011-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407341		4505-000-031-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407342		4505-000-032-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407343		4505-000-032-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407344		322401-3-028-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407345		322401-3-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407346		322401-3-027-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407347		322401-3-008-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407348		322401-3-006-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407349		4607-002-007-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407350		4607-002-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407351		4607-002-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407352		4607-002-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407353		4607-002-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407354		4607-002-012-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407355		4607-002-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407356		4607-002-002-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407357		4607-002-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407358		4607-001-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407359		4607-001-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407360		4607-001-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407361		4607-001-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407362		4607-001-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407363		4607-001-003-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407364		4607-001-003-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407365		4607-001-012-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407366		1223O1-2-010-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407367		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407368		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407369		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407370		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407371		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407372		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407373		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407374		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407375		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407376		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407377		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407378		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407379		1123O1-2-001-1002	No	Not evaluated	Non-Lead - Copper	No		0.75	Tap log 80			2016-2024		Non-Lead - Plastic		0.75	Tap log 80	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407380		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unkown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unkown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407381		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407382		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407383		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407384		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407385		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Unknown		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407386		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407387		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407388		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407389		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407390		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407391		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407392		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407393		1123O1-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407394		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407395		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407396		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407397		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407398		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407399		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407400		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Abandoned		2016-2024		Unknown		0.75	GIS Unknown Type	Yes	Abandoned	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407401		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407402		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407403		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407404		1223O1-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407405		4608-007-004-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407406		4608-007-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407407		4608-007-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407408		4608-007-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407409		4608-007-007-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407410		4608-008-003-0008	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407411		4608-008-003-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407412		4608-008-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407413		4608-008-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407414		4608-008-008-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407415		4608-010-001-0105	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407416		322401-3-042-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407417		4608-010-008-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407418		4608-010-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407419		4608-011-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407420		322401-3-030-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407421		322401-3-031-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GI

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407431		4608-006-013-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407432		4608-006-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407433		4608-006-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407434		4608-006-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407435		4608-005-008-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407436		4608-006-008-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407437		4608-006-006-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407438		4608-005-007-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407439		4608-005-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407440		4608-006-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407441		4608-006-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407442		4608-006-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407443		4608-006-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407444		4608-005-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407445		4608-006-002-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407446		4608-006-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407447		322401-3-035-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407448		322401-3-052-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407449		4608-005-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407450		322401-3-037-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407451		322401-4-063-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407452		322401-4-062-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407453		322401-4-079-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407454		322401-4-061-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407455		322401-4-061-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407456		322401-4-060-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407457		322401-4-059-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407458		322401-4-058-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407459		322401-4-055-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407460		322401-4-056-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407461		322401-4-054-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407462		322401-4-053-2007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407463		322401-4-050-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407464		322401-4-050-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407465		322401-4-050-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407466		322401-4-086-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407467		322401-4-088-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407468		322401-4-088-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407469		322401-4-087-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407470		322401-4-047-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407471		322401-4-033-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407472		322401-4-033-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407473		322401-4-029-2008	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407474		4642-000-002-0004	No	Not evaluated	Galvanized	No	Prior to 2018	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407475		322401-4-034-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407476		322401-4-046-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407477		322401-4-042-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407478		322401-4-041-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407479		322401-4-039-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407480		322401-4-044-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407481		322401-4-036-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407482		322401-4-045-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407483		322401-4-037-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407484		4539-000-005-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407485		322401-4-023-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407486		322401-4-023-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407487		322401-4-106-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407488		322401-4-080-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407489		322401-4-080-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407490		332401-3-011-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407491		332401-3-008-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407492		332401-4-037-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407493		332401-4-033-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407494		332401-4-038-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407495		332401-4-039-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407496		332401-4-036-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407497		332401-4-032-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407498		332401-4-031-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407499		332401-4-029-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407500		332401-4-073-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407501		332401-4-027-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407502		332401-4-010-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407503		332401-4-013-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407504		332401-4-013-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407505		332401-4-015-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407506		332401-4-023-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407507		332401-4-024-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407508		332401-4-021-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407509		332401-4-020-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407510		332401-4-019-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407511		332401-4-017-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407512		332401-4-016-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407513		332401-4-016-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407514		332401-4-014-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407515		332401-4-012-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407516		332401-4-011-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407517		332401-4-008-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407518		332401-4-007-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407519		332401-4-003-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407520		342401-2-035-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407529		332401-1-028-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407530		332401-1-028-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407531		332401-3-001-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407532		332401-3-001-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407533		332401-3-020-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407534		322401-4-118-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407535		322401-4-118-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407536		322401-4-008-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407537		322401-4-008-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407538		322401-4-091-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407539		322401-4-091-2001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407540		322401-4-110-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407541		322401-4-110-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407542		322401-1-128-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407543		232401-1-001-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407544		282401-1-089-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407545		282401-1-001-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407546		4546-001-001-0307	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407547		4546-001-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407548		4546-001-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407549		4546-002-023-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407550		4546-001-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407551		4546-001-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407552		4546-001-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407553		4546-001-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407554		4546-001-010-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407555		4546-001-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407556		4546-010-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407557		4546-010-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407558		4546-010-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407559		4546-010-007-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407560		4546-002-019-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407561		4546-002-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407562		4546-002-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407563		4546-002-017-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407564		4546-002-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407565		4546-002-014-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407566		4546-002-013-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407567		4546-009-001-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407568		4546-009-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407569		4546-009-002-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407570		4546-009-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407571		4546-009-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407572		4546-008-009-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407573		4546-013-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407574		4546-013-001-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407575		4546-013-001-0302	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407576		4546-013-001-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407577		4546-013-020-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407578		4546-012-010-0709	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407579		4546-012-010-0600	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407580		4546-012-010-0501	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407581		4546-012-009-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407582		4546-012-008-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407583		4546-012-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407584		4546-012-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407585		4546-012-006-0507	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407586		4546-012-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407587		4546-012-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407588		4546-012-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407589		4546-012-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407590		4546-012-002-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407591		4546-012-001-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407592		4546-008-004-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407593		4546-008-005-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407594		4546-008-005-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407595		4546-008-006-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407596		4546-008-007-0108	No	Not evaluated	Galvanized	No	Prior to 1956	0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407597		4546-008-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407598		4546-008-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407599		4546-008-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407600		4546-008-005-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407601		4546-008-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407602		4546-008-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407603		4546-008-008-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407604		4546-008-011-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407605		4546-003-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407606		4546-003-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407607		4546-003-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407608		4546-003-019-0006	No	Not evaluated	Non-Lead - Other	No		6.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		6.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407609		4546-002-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407610		4546-002-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407611		4546-003-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407612		222401-3-003-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407613		4502-014-007-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407614		4502-014-007-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407615		4502-014-007-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407616		4502-014-007-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407617		4502-014-007-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407618		4502-014-007-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407619		4546-003-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407620		4546-003-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407627		162401-4-057-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407628		162401-4-057-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407629		162401-4-056-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407630		162401-4-058-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407631		162401-4-058-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407632		3719-002-047-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407633		3719-002-047-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407634		3719-002-047-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407635		3719-002-047-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407636		4681-000-043-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407637		4681-000-043-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407638		3719-002-046-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 71 2451	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 71 2451	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407639		162401-3-047-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407640		3719-002-047-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407641		162401-3-117-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407642		162401-3-091-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407643		162401-3-090-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407644		162401-3-089-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407645		162401-3-087-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407646		162401-3-086-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407647		162401-3-085-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	No meter		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	No meter	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407648		162401-3-046-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407649		162401-3-044-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407650		162401-3-045-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407651		162401-3-043-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407652		162401-3-050-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407653		162401-3-050-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407654		162401-3-051-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407655		162401-3-051-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407656		162401-3-051-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407657		3820-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407658		3820-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407659		3820-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407660		162401-3-058-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407661		162401-3-148-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407662		162401-3-059-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407663		162401-3-057-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407664		162401-3-056-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407665		162401-3-069-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407666		162401-3-066-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407667		162401-3-065-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407668		162401-3-131-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407669		162401-3-139-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1916	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1916	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407670		162401-3-127-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407671		162401-3-143-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407672		162401-3-144-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407673		162401-3-146-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407674		162401-3-145-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407675		162401-3-136-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407676		162401-3-136-2000	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407677		162401-3-136-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407678		162401-3-092-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407679		162401-3-093-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407680		162401-3-151-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407681		162401-3-095-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407682		162401-3-096-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407683		162401-3-097-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407684		162401-3-097-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407685		162401-4-078-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407686		162401-4-078-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407687		162401-4-078-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407688		162401-4-066-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407689		162401-4-066-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407690		162401-4-006-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407691		162401-4-077-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407692		162401-4-077-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407693		162401-4-076-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407694		162401-4-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407695		162401-4-068-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407696		162401-4-068-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407697		162401-4-068-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407698		162401-3-103-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407699		162401-3-104-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407700		162401-3-141-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407701		162401-3-153-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407702		162401-3-154-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407703		3826-000-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407704		162401-4-070-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407705		162401-3-154-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407706		212401-1-005-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	No meter		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	No meter	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407707		212401-1-005-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407708		212401-1-005-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407709		3826-000-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407710		3826-000-001-0005	No	Not evaluated	Non-Lead - Other	No		4.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		4.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407711		212401-1-005-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407712		162401-4-067-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407713		162401-4-067-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407714		212401-1-085-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407715		212401-1-111-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407725		3745-000-034-0400	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407726		3745-000-034-0400	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407727		3745-000-034-0400	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407728		3745-000-031-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407729		3745-000-031-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407730		3745-000-031-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407731		3745-000-031-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407732		212401-1-029-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407733		212401-1-028-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407734		212401-1-019-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407735		212401-1-009-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407736		212401-1-020-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407737		212401-1-109-2000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407738		212401-1-109-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407739		212401-1-132-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407740		212401-1-132-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407741		212401-1-132-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407742		212401-1-132-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407743		212401-1-126-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407744		212401-1-126-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407745		212401-1-126-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407746		212401-1-124-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407747		212401-1-125-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407748		212401-1-125-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407749		212401-1-035-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407750		212401-1-035-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407751		212401-1-034-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407752		212401-1-002-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407753		3823-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407754		3823-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407755		3823-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407756		3823-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407757		3823-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407758		212401-1-092-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407759		212401-1-106-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407760		212401-1-086-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407761		212401-1-087-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407762		212401-1-088-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407763		212401-2-094-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407764		212401-2-084-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407765		212401-1-129-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407766		212401-1-129-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407767		212401-1-129-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407768		212401-1-112-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407769		212401-1-112-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407770		212401-1-112-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407771		212401-1-112-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407772		212401-1-081-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407773		212401-1-081-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407774		212401-1-080-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407775		212401-1-079-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407776		212401-1-078-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407777		4564-001-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407778		4564-001-019-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407779		4564-001-019-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407780		212401-1-118-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407781		212401-1-118-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407782		4546-007-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407783		4546-007-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407784		4546-007-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407785		4546-005-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407786		4546-005-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407787		4546-024-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>			2016-2024		Unknown		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407788		4546-024-006-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407789		4546-024-007-0006	No	Not evaluated	UNK	No		0.75	ABAND			2016-2024		<Null>		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407790		4546-024-007-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407791		4546-025-005-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407792		4546-025-005-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407793		4546-025-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407794		4546-025-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091			2016-2024		Galvanized		0.75	BEDA 3091	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407795		4546-025-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407796		4546-023-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407797		4546-023-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407798		4546-023-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407799		4546-023-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407800		4546-023-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 20 pg 7	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 20 pg 7	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407801		4546-026-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407802		4546-023-019-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407803		4546-023-020-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407804		4546-027-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 24	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 24	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407805		4546-027-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407806		4546-023-021-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 38			2016-2024		Galvanized		0.75	Book 6 Pg 38	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407807		4546-023-001-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407808		4546-023-002-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407809		4546-023-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407810		4546-023-022-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407811		4546-027-010-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407812		4546-027-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407813		4546-027-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407823		4546-022-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407824		4546-027-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407825		4546-022-007-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407826		4546-027-001-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407827		4546-021-012-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407828		4546-021-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407829		4546-027-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407830		4546-028-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407831		4546-028-008-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407832		4546-021-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407833		4546-021-014-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407834		4546-028-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407835		4546-028-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407836		4546-021-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407837		4546-021-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407838		4546-028-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407839		4546-028-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407840		4546-021-017-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407841		4546-021-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407842		4546-021-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407843		4546-021-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407844		4546-021-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407845		4546-021-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407846		4546-021-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407847		4546-021-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407848		4546-021-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407849		4546-021-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407850		4546-021-011-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407851		4546-022-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407852		4546-023-004-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407853		4546-023-007-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407854		4546-023-007-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407855		4546-016-025-0406	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407856		4546-016-025-0505	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407857		4546-016-030-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407858		4546-017-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407859		4546-017-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407860		4546-017-011-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407861		4546-017-003-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407862		4546-018-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407863		4546-017-002-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407864		4546-018-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407865		4546-017-002-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407866		4546-018-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407867		4546-018-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407868		4546-018-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407869		4546-018-008-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407870		4546-017-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407871		4546-017-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407872		4546-017-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407873		4546-017-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407874		4546-017-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407875		4546-017-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407876		4546-017-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407877		4546-016-001-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407878		4546-016-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407879		4546-016-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407880		4546-016-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407881		4546-016-005-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407882		4546-016-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407883		4546-013-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407884		4546-013-018-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407885		4546-013-020-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407886		4546-013-020-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407887		4546-012-010-0402	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407888		4546-012-010-0303	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407889		4546-012-009-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407890		4546-012-011-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407891		4546-012-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407892		4546-012-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407893		4546-012-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407894		4546-012-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407895		4546-012-017-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407896		4546-012-020-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407897		4546-012-022-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407898		4546-009-009-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407899		4546-009-010-0002	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407900		212401-4-004-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407901		212401-4-004-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407902		212401-4-004-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407903		212401-4-004-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407904		212401-3-005-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407905		212401-3-005-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407906		212401-4-011-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407907		212401-1-102-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407908		212401-1-102-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407909		212401-1-068-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407910		212401-1-068-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407911		212401-1-069-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407912		212401-1-067-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407913		212401-1-067-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407914		212401-1-065-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown	

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2407921		212401-2-142-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407922		212401-2-121-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407923		212401-2-059-2008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407924		212401-2-107-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407925		212401-2-091-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407926		212401-2-060-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407927		212401-2-102-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407928		212401-2-102-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407929		212401-2-149-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407930		212401-2-092-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407931		212401-2-061-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407932		212401-2-165-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407933		212401-2-062-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407934		212401-2-065-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407935		212401-2-137-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407936		212401-2-137-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2407937		212401-2-137-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407938		212401-2-137-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407939		212401-2-068-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407940		212401-2-067-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407941		212401-2-157-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407942		212401-1-063-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407943		212401-2-045-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407944		212401-2-046-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407945		212401-2-047-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407946		212401-2-048-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407947		212401-2-057-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407948		4627-001-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407949		4627-001-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407950		4627-001-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407951		212401-2-050-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407952		212401-2-051-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407953		212401-2-052-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407954		212401-2-053-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407955		212401-2-054-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407956		212401-2-162-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407957		212401-2-161-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407958		212401-2-019-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407959		212401-2-164-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407960		212401-2-014-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407961		212401-2-011-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407962		212401-2-008-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 31	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 31	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407963		212401-2-007-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407964		212401-2-004-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407965		212401-2-003-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407966		212401-2-002-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407967		212401-2-001-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407968		162401-3-073-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407969		162401-3-072-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407970		162401-3-071-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407971		162401-3-070-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407972		162401-3-055-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407973		162401-3-079-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407974		162401-3-074-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407975		162401-3-075-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Galvanized		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407976		162401-3-076-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407977		212401-2-147-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407978		212401-2-148-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407979		212401-2-006-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407980		212401-2-012-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407981		212401-2-013-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407982		212401-2-016-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407983		212401-2-016-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407984		212401-2-017-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407985		212401-2-163-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407986		212401-2-020-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407987		212401-2-021-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407988		212401-2-022-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407989		212401-2-022-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407990		212401-2-023-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407991		212401-2-025-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2407992		212401-2-167-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407993		4627-001-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407994		4527-001-024-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407995		4627-001-023-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2407996		4627-001-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407997		4627-001-020-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407998		4627-001-003-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2407999		4627-001-020-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408000		4627-001-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408001		4527-001-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408002		4627-001-008-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408003		4627-001-015-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408004		4627-001-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408005		212401-2-056-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408006		212401-2-083-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408007		212401-2-128-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408008		212401-2-126-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408009		212401-2-126-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408010		212401-2-131-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408019		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408020		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408021		202401-1-003-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408022		202401-1-003-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408023		202401-1-003-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408024		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408025		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408026		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408027		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408028		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408029		202401-1-003-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408030		202401-1-003-2008	No	Not evaluated	Galvanized	No	Prior to 1998	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408031		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408032		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408033		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408034		202401-1-003-2008	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408035		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408036		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408037		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408038		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408039		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408040		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408041		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408042		202401-1-003-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408043		212401-2-086-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408044		212401-2-086-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408045		212401-2-111-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408046		212401-2-076-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408047		212401-2-076-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408048		212401-2-113-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408049		212401-2-072-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408050		212401-2-072-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408051		212401-2-089-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408052		4627-002-019-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408053		4627-002-019-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408054		4627-002-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408055		212401-2-073-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408056		4508-002-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408057		4508-002-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408058		212401-2-125-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408059		4508-001-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408060		4508-001-009-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408061		4508-001-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408062		4508-001-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408063		4508-001-005-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408064		4508-001-005-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408065		212401-2-158-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408066		4508-001-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408067		162401-3-116-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408068		162401-3-115-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408069		4508-001-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408070		4508-001-022-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408071		4508-001-023-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408072		4508-001-021-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408073		4508-001-021-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408074		4508-001-021-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408075		4508-001-020-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408076		4508-001-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408077		4508-001-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408078		4508-001-009-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408079		4508-001-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408080		4508-001-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408081		4508-001-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408082		4508-002-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408083		4508-002-020-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408084		4508-002-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408085		212401-2-114-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408086		212401-2-114-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408087		4508-002-013-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408088		212401-2-115-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408089		212401-2-030-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408090		212401-2-032-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408091		212401-2-150-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408092		212401-2-109-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408093		212401-2-105-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408094		212401-2-088-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408095		212401-2-041-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408096		212401-2-042-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408097		212401-2-042-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408098		202401-1-011-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408099		212401-1-012-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408100		202401-1-011-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408101		202401-1-002-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408102		212401-2-033-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408103		212401-2-034-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408104		212401-2-036-2006	No	Not evaluated	Galvanized	No	Prior to 1969	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408105		212401-2-037-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408106		212401-2-039-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408107		162401-3-023-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 77	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 77	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408108		162401-3-023-2006	No	Not

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408117		162401-3-038-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408118		162401-3-039-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408119		162401-3-077-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408120		162401-3-124-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408121		162401-3-036-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408122		162401-3-041-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408123		162401-3-033-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408124		162401-3-031-2006	No	Not evaluated	Non-Lead - Other	No		4.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		4.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408125		162401-3-030-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408126		162401-3-020-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408127		162401-3-105-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408128		162401-3-018-2003	No	Not evaluated	Galvanized	No	Prior to 1953	0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408129		162401-3-017-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408130		162401-3-016-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408131		162401-3-122-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408132		162401-3-122-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408133		162401-3-078-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408134		162401-3-112-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408135		162401-3-013-2008	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408136		162401-3-013-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408137		4626-001-005-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408138		162401-3-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 82	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 82	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408139		162401-3-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 82	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 82	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408140		162401-3-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 82	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 82	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408141		3719-002-046-0503	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 76			2016-2024		Non-Lead - Plastic		0.75	Tap log 76	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408142		3719-002-046-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	W177	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W177		Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408143		4626-001-003-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408144		4626-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408145		4626-002-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050			2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408146		4626-002-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 25			2016-2024		Non-Lead - Plastic		0.75	Book 13 pg 25	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408147		4626-002-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408148		4626-002-004-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408149		4626-002-005-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408150		4626-002-007-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408151		4626-002-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408152		4626-002-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408153		4626-003-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408154		4626-003-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3090			2016-2024		Non-Lead - Copper		0.75	BEDA 3090	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408155		4626-003-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 49	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408156		4626-003-004-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408157		4626-003-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408158		4626-003-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408159		4626-003-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408160		4626-003-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408161		4626-003-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408162		162401-3-001-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408163		4626-004-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408164		4626-004-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408165		4626-004-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408166		4626-004-005-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408167		4626-004-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408168		4626-004-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408169		4626-004-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408170		162401-3-110-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408171		172401-4-005-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408172		172401-4-005-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408173		172401-4-008-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408174		172401-4-008-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408175		172401-4-008-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408176		172401-4-010-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408177		172401-4-012-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408178		172401-4-011-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408179		172401-4-011-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408180		202401-2-002-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408181		202401-2-003-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408182		202401-2-042-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408183		202401-2-043-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408184		202401-2-035-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408185		202401-2-036-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408186		202401-2-045-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408187		202401-2-034-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408188		202401-2-015-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408189		172401-4-015-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408190		172401-4-023-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408191		162401-3-010-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408192		162401-3-130-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408193		162401-3-008-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408194		162401-3-129-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408195		162401-3-007-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408196		162401-3-053-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408197		162401-3-053-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408198		162401-3-005-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408199		162401-3-082-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408200		162401-3-080-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408201		162401-3-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408202		162401-3-003-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408203		162401-3-002-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408204		4506-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408205		4506-000-013-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408206		4506-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408215		4506-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408216		4506-000-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2080	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2080	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408217		172401-1-062-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408218		172401-1-061-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408219		172401-1-061-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408220		172401-1-089-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408221		172401-1-091-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408222		172401-1-068-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408223		172401-1-006-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408224		172401-1-076-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408225		172401-1-105-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408226		3719-003-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)			2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408227		3719-003-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408228		4506-000-009-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408229		4506-000-009-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408230		4506-000-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408231		4506-000-007-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408232		4506-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408233		3719-002-037-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408234		3719-002-017-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408235		3719-002-017-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408236		3719-002-026-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408237		3719-002-027-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408238		3719-002-027-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408239		3719-002-027-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408240		3719-002-022-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408241		3719-002-021-0403	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408242		3719-002-021-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408243		3719-002-021-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408244		3719-002-019-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408245		3719-002-018-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408246		3719-002-019-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408247		3719-002-014-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408248		3719-002-014-0303	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408249		3719-002-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408250		3719-002-014-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408251		3719-002-010-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408252		3719-002-011-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408253		3719-002-011-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408254		3719-002-010-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408255		3719-002-011-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408256		3719-002-011-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408257		3719-002-011-0504	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408258		3719-002-011-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408259		3719-002-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408260		3719-002-010-0406	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408261		3719-002-010-0307	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408262		3719-002-009-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408263		3719-002-009-0300	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408264		3719-002-009-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408265		3719-002-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408266		3719-002-009-0201	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408267		3719-002-008-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408268		3719-002-008-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408269		3719-002-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408270		3719-002-008-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408271		3719-002-008-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408272		3719-002-008-0509	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408273		3719-002-007-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408274		3719-002-007-0401	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408275		3719-002-007-0708	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408276		3719-002-007-0708	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408277		3719-002-007-0708	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408278		3719-002-007-0807	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408279		3719-002-006-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408280		3719-002-007-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408281		172401-1-021-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408282		172401-1-021-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408283		172401-1-022-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408284		172401-1-148-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408285		172401-1-148-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408286		3719-002-005-0403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408287		3719-002-005-0403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408288		3719-002-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408289		3719-002-005-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408290		3719-002-005-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408291		3719-002-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408292		4558-000-022-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408293		4558-000-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408294		4558-000-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408295		4558-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408296		4558-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408297		4558-000-020-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408298		4558-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408299		4558-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408300		4558-000-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408301		4558-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408302		4558-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408303		4558-000-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408304		4558-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408305		4558-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408306		4558-000-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408313		4558-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408314		4558-000-026-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408315		4558-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408316		4558-000-024-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408317		4558-000-023-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408318		3719-002-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408319		3719-002-013-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408320		3719-002-013-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408321		3719-002-020-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408322		3719-002-020-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408323		3719-002-021-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408324		3719-002-021-0700	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408325		172401-1-051-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408326		172401-1-052-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408327		3719-002-028-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408328		172401-1-103-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408329		172401-1-094-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408330		172401-1-086-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408331		172401-1-086-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408332		172401-1-086-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408333		172401-1-067-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408334		172401-1-067-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408335		172401-1-053-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408336		172401-1-054-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408337		172401-1-049-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408338		172401-1-050-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408339		172401-1-048-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408340		172401-1-044-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408341		172401-1-039-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408342		172401-1-041-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408343		172401-1-041-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408344		172401-1-040-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408345		172401-1-113-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408346		172401-1-113-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408347		172401-1-114-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408348		172401-1-115-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408349		172401-1-119-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408350		172401-1-118-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408351		172401-1-118-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408352		172401-1-030-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408353		172401-1-120-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408354		172401-1-046-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408355		172401-1-077-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408356		172401-1-130-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408357		172401-1-028-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408358		172401-1-059-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408359		172401-1-100-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408360		172401-1-078-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408361		172401-1-073-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Live abandon service		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Live abandon service	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408362		172401-1-074-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408363		172401-1-075-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408364		172401-1-071-2000	No	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check			2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown	Unknown		
BremSLI-2408365		172401-1-071-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408366		172401-1-026-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408367		172401-1-070-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408368		172401-1-035-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408369		172401-1-080-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408370		172401-1-066-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408371		172401-1-145-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408372		172401-1-146-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408373		172401-1-131-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408374		172401-1-065-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408375		4548-000-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408376		4548-000-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408377		4548-000-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408378		4548-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408379		4548-000-002-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408380		4548-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408381		4558-000-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408382		172401-1-063-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408383		4558-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408384		172401-1-029-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408385		172401-1-064-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408386		172401-1-024-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408387		4588-000-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408388		4588-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408389		4588-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408390		4588-000-007-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408391		4588-000-006-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408392		4588-000-005-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408393		4588-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408394		4588-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408395		4588-000-003-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408396		4588-000-003-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408397		4588-000-002-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408398		4588-000-002-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408399		4588-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408400		172401-1-011-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408401		172401-1-010-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408402		172401-1-012-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408403		172401-1-124-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408404		172401-1-123-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408405		172401-1-125-2006	No	Not evaluated	Non-Lead - Copper	No		0.75

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408411		172401-1-007-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408412		172401-1-147-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408413		4547-003-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408414		4547-003-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408415		172401-1-140-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408416		172401-1-143-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408417		4547-003-016-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408418		172401-1-136-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408419		172401-1-135-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408420		172401-1-135-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408421		172401-1-134-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408422		172401-1-133-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408423		4547-003-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408424		4547-003-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408425		4547-003-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408426		4547-003-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408427		4547-003-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408428		172401-1-025-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408429		4547-003-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408430		172401-1-027-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408431		4547-002-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408432		4547-002-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408433		4547-002-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408434		4547-002-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408435		4547-002-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408436		4547-002-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408437		4547-002-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408438		4547-002-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408439		4547-002-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408440		4547-002-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408441		4547-002-020-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408442		4547-002-021-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408443		4547-001-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408444		4547-001-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408445		4547-001-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408446		4547-001-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408447		4547-001-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408448		4547-001-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408449		4547-001-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408450		4547-004-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408451		4547-004-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408452		082401-4-073-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408453		172401-1-002-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408454		172401-1-101-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408455		172401-1-013-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408456		172401-1-148-2009	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408457		172401-1-020-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408458		3719-002-002-0307	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408459		3719-002-002-0604	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408460		3719-002-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408461		3719-002-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408462		4673-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408463		3719-001-029-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408464		3719-001-023-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408465		3719-001-026-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408466		3719-001-026-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408467		3719-001-026-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408468		3719-001-026-0608	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408469		3719-001-027-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408470		3719-001-027-0201	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408471		3719-001-023-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408472		082401-4-020-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408473		082401-4-020-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408474		082401-4-021-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408475		082401-4-081-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408476		082401-4-023-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408477		082401-4-084-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408478		082401-4-084-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408479		082401-4-084-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408480		082401-4-019-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408481		082401-4-019-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408482		082401-4-016-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408483		082401-4-015-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408484		082401-4-014-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408485		082401-4-018-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408486		082401-4-026-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408487		082401-4-027-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408488		082401-4-091-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408489		082401-4-091-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408490		082401-4-041-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408491		082401-4-085-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408492		082401-4-085-2009	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408493		082401-4-071-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408494		082401-4-037-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408495		082401-4-075-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408496		082401-4-035-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408497		082401-4-030-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408498		082401-4-034-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408499		082401-4-070-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408500		3765-000-014-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408509		0824O1-3-026-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408510		0824O1-3-023-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408511		0824O1-3-027-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408512		0824O1-3-022-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408513		0824O1-3-010-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408514		0824O1-3-020-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408515		0824O1-3-021-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408516		0824O1-3-019-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408517		0824O1-3-013-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408518		0824O1-3-211-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408519		0824O1-3-009-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408520		0824O1-3-007-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408521		0824O1-3-007-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408522		0824O1-3-232-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408523		0824O1-3-232-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408524		0824O1-3-231-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408525		0824O1-3-231-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408526		0824O1-3-230-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408527		0824O1-3-230-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408528		0824O1-4-010-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408529		0824O1-3-202-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408530		0824O1-3-202-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408531		0824O1-4-009-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408532		0824O1-3-114-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408533		0824O1-3-114-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408534		0824O1-4-008-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408535		0824O1-4-007-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408536		0824O1-4-017-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408537		5297-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408538		5297-000-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408539		5297-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408540		5297-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408541		5297-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408542		5297-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408543		5297-000-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408544		5297-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408545		5297-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408546		5297-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408547		5297-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408548		5297-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408549		5297-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408550		5297-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408551		0824O1-4-060-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408552		0824O1-4-013-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408553		0824O1-4-063-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408554		0824O1-4-005-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408555		0824O1-4-090-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408556		0824O1-4-090-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408557		0824O1-4-089-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408558		0824O1-4-067-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408559		0824O1-4-067-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408560		0824O1-4-058-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408561		5127-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408562		5127-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408563		5127-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408564		5127-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408565		5127-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408566		0824O1-4-059-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408567		0824O1-4-069-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408568		0824O1-4-077-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408569		0824O1-4-006-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408570		0824O1-4-057-2003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408571		0824O1-3-005-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408572		8028-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408573		8028-000-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408574		0824O1-3-004-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408575		0824O1-3-167-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408576		0824O1-3-003-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408577		0824O1-3-189-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408578		0824O1-3-189-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408579		0824O1-3-033-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408580		0824O1-3-031-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408581		0824O1-3-171-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408582		0824O1-3-188-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408583		0824O1-3-032-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408584		0824O1-3-220-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408585		0824O1-3-219-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408586		0824O1-3-036-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408587		0824O1-3-162-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408588		0824O1-3-162-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408589		0824O1-3-001-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408590		0824O1-2-097-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408591		4518-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408592		4518-000-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408593		4518-000-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408594		4518-000-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408595		4518-000-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408596		4518-000-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408597		4519-000-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408607		4519-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408608		4518-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408609		4519-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408610		4518-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408611		4518-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408612		082401-1-018-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408613		4519-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408614		082401-2-087-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408615		082401-2-088-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408616		4519-000-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408617		4519-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408618		082401-2-089-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408619		082401-2-090-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408620		4519-000-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408621		4519-000-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408622		082401-2-091-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408623		082401-2-092-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408624		4519-000-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408625		4519-000-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408626		082401-2-093-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408627		4519-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408628		082401-2-094-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408629		082401-2-094-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408630		4519-000-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408631		082401-2-095-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408632		082401-2-096-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408633		082401-2-124-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408634		082401-2-125-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408635		082401-2-126-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408636		082401-3-037-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408637		082401-3-205-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408638		082401-3-206-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408639		082401-3-039-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408640		082401-3-207-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408641		082401-3-176-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408642		082401-3-173-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408643		082401-3-030-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408644		082401-3-040-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408645		082401-3-043-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408646		082401-3-042-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408647		082401-3-029-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408648		082401-3-028-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408649		082401-3-041-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408650		082401-3-046-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408651		082401-3-045-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408652		082401-3-044-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408653		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408654		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408655		3721-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408656		3721-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408657		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408658		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408659		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408660		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408661		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408662		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408663		3721-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408664		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408665		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408666		3721-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408667		082401-2-150-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408668		082401-3-069-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408669		082401-3-070-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408670		082401-3-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408671		082401-3-072-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408672		082401-3-073-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408673		082401-3-074-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408674		082401-3-075-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408675		082401-3-076-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408676		082401-2-082-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408677		082401-3-077-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408678		082401-3-078-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408679		082401-3-079-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408680		082401-3-081-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408681		082401-3-080-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408682		082401-3-082-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408683		082401-3-084-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408684		082401-3-085-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408685		082401-3-086-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408686		082401-3-067-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408687		082401-3-067-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408688		082401-3-225-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408689		082401-3-226-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408690		082401-3-227-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408691		082401-3-057-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408692		082401-3-222-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408693		082401-3-059-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408694		082401-3-060-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408695		082401-3-060-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408696		082401-3-061-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408705		082401-3-158-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408706		082401-3-155-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408707		082401-3-157-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408708		082401-3-241-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408709		082401-3-152-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408710		082401-3-151-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408711		082401-3-149-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408712		082401-3-121-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408713		082401-3-118-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408714		082401-3-092-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408715		082401-3-238-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408716		082401-3-093-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408717		082401-3-095-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408718		082401-3-096-2008	No	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408719		082401-3-249-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408720		082401-3-248-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408721		082401-3-102-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408722		082401-3-103-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408723		082401-3-104-2008	No	Not evaluated	Non-Lead - Plastic	No		6.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		6.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408724		082401-3-105-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408725		082401-3-242-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408726		082401-3-107-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408727		082401-2-109-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Abandon		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Abandon	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408728		082401-2-058-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408729		082401-2-058-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408730		082401-2-107-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408731		082401-2-107-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408732		082401-2-061-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408733		082401-2-062-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408734		082401-2-064-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408735		082401-2-101-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408736		082401-2-065-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408737		082401-2-065-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408738		082401-2-066-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408739		082401-2-067-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408740		082401-2-128-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408741		082401-2-129-2001	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408742		082401-2-070-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408743		082401-2-071-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408744		082401-2-071-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408745		082401-2-078-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408746		082401-2-079-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408747		072401-1-049-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408748		072401-1-049-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408749		072401-1-029-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408750		072401-1-031-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408751		072401-1-035-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408752		072401-1-035-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408753		072401-1-036-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408754		072401-1-037-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408755		082401-2-046-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408756		082401-2-047-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408757		082401-2-048-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408758		082401-2-050-2004	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year			2016-2024		<Null>		1.50	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408759		082401-2-051-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408760		082401-2-052-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408761		082401-2-053-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408762		082401-2-054-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408763		072401-1-026-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408764		072401-1-028-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408765		072401-1-018-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408766		072401-1-048-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408767		072401-4-078-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408768		072401-4-078-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408769		072401-4-078-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408770		072401-4-078-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408771		072401-1-020-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408772		072401-1-021-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408773		072401-1-019-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408774		072401-1-023-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408775		072401-1-046-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408776		082401-2-149-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408777		082401-2-149-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408778		082401-3-108-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408779		082401-3-109-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408780		082401-3-110-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408781		082401-3-111-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408782		072401-4-011-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408783		072401-4-009-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408784		072401-4-007-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408785		072401-4-103-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408786		072401-4-014-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408787		072401-4-072-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408788		072401-1-041-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408789		072401-4-076-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408790		072401-1-040-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408791		072401-4-028-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408792		072401-4-027-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408793		072401-4-074-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408803		072401-4-031-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408804		072401-4-108-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408805		072401-4-094-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408806		072401-4-094-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408807		072401-4-093-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408808		072401-4-093-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408809		072401-4-035-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408810		072401-4-109-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408811		072401-4-020-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408812		072401-4-019-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408813		072401-4-019-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408814		072401-4-013-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408815		072401-4-018-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408816		072401-4-017-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408817		082401-3-164-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408818		082401-3-002-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408819		082401-3-112-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408820		082401-3-112-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408821		082401-3-112-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408822		072401-4-015-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408823		082401-3-165-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408824		082401-3-115-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408825		082401-3-116-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408826		072401-4-039-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408827		072401-4-039-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408828		072401-4-039-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408829		072401-4-119-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408830		072401-4-120-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408831		072401-4-121-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408832		072401-4-122-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408833		072401-4-082-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408834		072401-4-056-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408835		072401-4-055-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408836		072401-4-054-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408837		072401-4-053-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408838		072401-4-053-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408839		072401-4-058-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408840		072401-4-069-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408841		072401-4-071-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408842		072401-4-067-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408843		072401-4-067-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408844		072401-4-066-2003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408845		072401-4-065-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408846		072401-4-063-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408847		082401-3-197-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408848		082401-3-134-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408849		082401-3-133-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408850		082401-3-132-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408851		082401-3-131-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408852		082401-3-130-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408853		082401-3-129-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408854		082401-3-215-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408855		082401-3-124-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408856		082401-3-185-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408857		082401-3-137-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408858		082401-3-136-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408859		082401-3-135-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408860		172401-2-048-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408861		172401-2-047-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408862		172401-2-066-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408863		172401-2-072-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408864		172401-2-046-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408865		172401-2-045-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408866		172401-2-058-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408867		172401-2-056-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408868		172401-2-013-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408869		172401-2-017-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408870		172401-2-018-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408871		172401-2-078-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408872		172401-2-041-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408873		172401-2-023-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408874		172401-2-024-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408875		172401-2-053-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408876		172401-2-053-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408877		172401-2-035-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408878		172401-2-034-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485			2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408879		172401-2-032-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408880		172401-2-030-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408881		172401-2-031-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408882		172401-2-029-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408883		172401-2-036-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408884		172401-2-028-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408885		172401-2-068-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408886		172401-2-067-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408887		172401-2-067-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408888		172401-2-025-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408889		172401-2-022-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408890		172401-2-021-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408891		172401-2-020-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408892		172401-2-019-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408901		172401-2-055-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408902		172401-2-075-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408903		172401-2-061-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408904		172401-2-076-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408905		172401-2-060-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408906		172401-2-060-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408907		172401-2-008-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408908		172401-2-007-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408909		172401-2-073-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408910		172401-2-002-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408911		082401-3-138-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408912		082401-3-138-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408913		082401-3-212-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408914		082401-3-140-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408915		082401-3-141-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408916		082401-3-193-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408917		082401-3-145-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408918		082401-3-146-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408919		172401-2-033-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408920		082401-3-235-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408921		3765-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408922		3765-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408923		3765-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408924		3765-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408925		3765-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408926		3765-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408927		3765-000-010-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408928		3765-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408929		3765-000-009-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408930		3765-000-007-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408931		3765-000-007-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408932		3765-000-006-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408933		3765-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408934		3765-000-004-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408935		3765-000-003-0501	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408936		3765-000-003-0501	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408937		3765-000-003-0501	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408938		3765-000-003-0501	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408939		3765-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408940		082401-3-247-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2408941		082401-3-246-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408942		082401-3-191-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408943		082401-3-163-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408944		082401-4-054-2006	No	Not evaluated	UNK	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408945		082401-4-055-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408946		082401-4-053-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408947		082401-4-052-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408948		082401-4-051-2009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408949		082401-4-056-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408950		5092-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408951		5092-000-139-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408952		5092-000-140-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408953		5092-000-141-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408954		5092-000-141-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408955		5092-000-142-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408956		5092-000-143-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408957		5092-000-138-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408958		5092-000-137-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408959		5092-000-136-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408960		5092-000-136-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2408961		5092-000-131-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408962		5092-000-130-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408963		5092-000-129-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408964		5092-000-129-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408965		5092-000-144-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408966		5092-000-144-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408967		5092-000-145-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408968		5092-000-146-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408969		5092-000-147-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408970		5092-000-148-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408971		5092-000-149-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408972		5092-000-150-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408973		5092-000-151-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408974		5092-000-152-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408975		5092-000-153-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408976		5092-000-154-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408977		5092-000-155-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408978		5092-000-155-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408979		5092-000-155-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408980		5092-000-156-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408981		5092-000-159-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408982		5092-000-157-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408983		5092-000-158-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408984		5092-000-127-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2408985		5092-000-127-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408986		5092-000-125-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408987		5092-000-124-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408988		5092-000-162-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408989		5092-000-163-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408990		5092-000-123-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408991		5092-000-122-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408992		5092-000-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2408993		5092-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2408999		5092-000-118-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409000		5092-000-117-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409001		5092-000-116-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409002		5092-000-115-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409003		5092-000-114-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409004		5092-000-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409005		5092-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409006		5092-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409007		5092-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409008		5092-000-113-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409009		5092-000-112-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409010		5092-000-110-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409011		5092-000-108-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409012		5092-000-108-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409013		5092-000-107-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409014		5092-000-107-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409015		5092-000-106-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409016		5092-000-105-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409017		5092-000-104-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409018		5092-000-103-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409019		5092-000-101-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409020		5092-000-100-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409021		5092-000-099-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409022		5092-000-098-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409023		5092-000-097-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409024		5092-000-096-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409025		5092-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409026		5092-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409027		5092-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409028		5092-000-091-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409029		5092-000-090-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409030		5092-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409031		5092-000-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409032		5092-000-020-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409033		5092-000-088-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409034		5092-000-088-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409035		5092-000-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409036		5092-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409037		5092-000-023-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409038		5092-000-024-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409039		5092-000-087-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409040		5092-000-087-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409041		5092-000-084-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409042		5092-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409043		5092-000-026-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409044		5092-000-027-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409045		5092-000-030-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409046		5092-000-083-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409047		5092-000-082-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409048		5092-000-082-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409049		5092-000-031-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409050		5092-000-032-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409051		5092-000-033-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409052		5092-000-034-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409053		5092-000-035-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409054		5092-000-036-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409055		5092-000-037-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409056		5092-000-038-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409057		5092-000-079-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409058		5092-000-079-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409059		5092-000-077-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409060		5092-000-077-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409061		5092-000-039-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409062		5092-000-040-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409063		5092-000-041-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409064		5092-000-042-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409065		5092-000-043-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409066		5092-000-044-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409067		5092-000-045-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409068		5092-000-046-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409069		5092-000-047-0003	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409070		5092-000-048-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409071		5092-000-049-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409072		5092-000-049-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409073		5092-000-050-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409074		5092-000-075-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409075		5092-000-051-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409076		5092-000-052-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409077		5092-000-074-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409078		5092-000-073-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409079		5092-000-053-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409080		5092-000-054-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409081		5092-000-072-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409082		5092-000-071-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409083		5092-000-070-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409084		5092-000-069-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409085		5092-000-068-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409086		5092-000-067-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409087		5092-000-066-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409088		5092-000-065-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409097		5092-000-057-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409098		5092-000-058-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409099		3918-003-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409100		3913-009-001-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409101		3913-009-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409102		3913-010-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409103		3913-010-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409104		3913-010-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409105		5500470	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409106		3913-023-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409107		3913-023-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409108		3913-023-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409109		3913-023-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409110		3913-023-003-0009	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409111		3913-023-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409112		3913-023-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409113		3913-023-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409114		3913-023-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409115		3913-024-001-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409116		3913-024-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409117		5500851	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409118		3913-025-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409119		3913-025-006-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Unknown		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409120		3913-025-006-0407	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409121		3913-025-006-0407	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409122		3913-025-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409123		3913-025-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409124		3913-025-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409125		3913-025-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409126		3913-025-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409127		3913-026-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409128		3913-026-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409129		3913-026-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409130		3913-026-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409131		3913-026-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409132		3913-026-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409133		3913-026-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409134		3913-026-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409135		3923-004-014-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409136		3923-004-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409137		3923-004-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409138		3923-004-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409139		3923-004-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409140		3923-004-006-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409141		3923-004-004-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409142		3923-004-003-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409143		3923-004-003-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409144		3923-003-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2082	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2082	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409145		3923-003-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409146		3923-003-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409147		3923-003-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409148		3923-003-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409149		3923-003-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409150		3923-003-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E435	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409151		3923-003-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435			2016-2024		Non-Lead - Plastic		0.75	E435	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409152		3923-003-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	E435	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409153		3923-003-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	E475	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E475	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409154		3949-000-014-1109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409155		3949-000-014-1109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409156		3949-000-014-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409157		3923-002-026-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409158		3923-002-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 24	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 24	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409159		3923-002-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 17			2016-2024		<Null>		0.75	Book 6 pg 17	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409160		3923-002-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409161		3923-002-012-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409162		3913-017-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409163		3913-020-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409164		3913-022-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409165		3913-022-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409166		3913-022-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409167		3913-022-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409168		3913-022-002-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409169		8543-000-000-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409170		3913-011-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409171		3913-011-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409172		3913-011-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409173		3913-008-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409174		3913-008-002-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409175		3913-008-001-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409176		3913-008-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409177		3918-003-002-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409178		3918-003-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074			2016-2024		Galvanized		0.75	BEDA 2074	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409179		3913-007-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409180		3913-007-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409181		3913-007-003-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409182		3913-012-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409183		3913-006-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409184		3913-006-009-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	<Null>	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409185		3913-006-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409186		3913-006-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409187		3913-006-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409195		3913-013-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409196		3913-005-007-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409197		8020-000-000-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409198		8020-000-000-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>			2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409199		8020-000-000-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409200		3913-005-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409201		3913-005-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409202		3913-005-002-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409203		3913-005-004-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409204		3913-005-004-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409205		3913-005-005-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409206		3913-013-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409207		3913-013-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409208		3913-013-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409209		3913-021-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409210		3913-020-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409211		3913-020-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409212		3913-020-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409213		3913-020-011-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409214		3913-014-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409215		3913-014-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409216		3913-014-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409217		3913-004-007-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409218		3913-004-009-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409219		3913-004-010-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409220		3913-004-012-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409221		3913-004-001-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409222		3913-004-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409223		3913-004-004-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409224		3913-004-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409225		3913-004-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409226		3913-014-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409227		3913-014-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409228		3913-014-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409229		3913-020-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409230		3913-020-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409231		3913-020-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409232		3913-020-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409233		3913-019-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409234		3913-019-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409235		3913-015-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409236		3913-015-007-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409237		3913-015-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409238		3913-015-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409239		3913-015-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409240		3913-015-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409241		3913-003-007-0007	Yes - Other	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Galvanized		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409242		3913-003-008-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409243		3913-003-009-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>			2016-2024		Non-Lead - Plastic		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409244		3913-003-010-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409245		3913-003-011-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409246		3913-003-011-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409247		3913-003-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409248		3913-003-003-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409249		3913-003-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>			2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409250		3913-003-006-0008	No	Not evaluated	Non-Lead - Other	No		2.00	<Null>			2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409251		3913-015-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409252		3913-015-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409253		3913-015-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409254		3913-015-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409255		3913-015-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409256		3913-015-005-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409257		3913-019-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409258		3913-018-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409259		3913-016-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409260		3913-016-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409261		3913-002-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409262		3913-002-007-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409263		3913-002-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409264		3913-002-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409265		3913-002-001-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409266		3913-002-002-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409267		3913-002-002-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND	Visual inspection at the meter pit		2016-2024		None		0.75	ABAND	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409268		3913-002-003-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409269		3913-002-003-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409270		3913-002-005-0001	No	Not evaluated	Non-Lead - Other	No		2.00	<Null>			2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409271		3913-016-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409272		3913-016-002-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409273		3913-016-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409274		3913-017-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409275		3913-017-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409276		3913-017-011-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409277		3913-001-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409278		3913-001-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409279		3913-001-007-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409280		3913-001-010-0006	No	Not evaluated	UNK	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409281		3913-001-011-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409282		3913-001-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409283		3913-001-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409284		3913-001-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409285		3913-001-005-0102	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		1.50	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.50		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409286		3923-005-007-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409287		3923-005-005-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409288		3923-005-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND			2016-2024		None		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409289		3923-005-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409290		3923-002-015-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter p

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409293		3923-002-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409294		3923-002-021-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409295		3923-002-022-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409296		3923-002-024-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435			2016-2024		Non-Lead - Plastic		0.75	E435	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409297		3923-002-027-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409298		3949-000-014-0903	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409299		3949-000-013-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409300		3949-000-013-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409301		3949-000-012-0509	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409302		3949-000-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409303		3949-000-010-0501	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409304		3949-000-010-0303	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409305		3949-000-010-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409306		3949-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409307		3949-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409308		3949-000-009-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409309		3949-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409310		3949-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409311		3949-000-007-0704	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409312		3949-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409313		3949-000-006-0903	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409314		3949-000-006-0903	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409315		3949-000-006-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409316		3949-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409317		3949-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409318		3949-000-004-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409319		3949-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409320		3949-000-002-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409321		3949-000-002-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409322		3949-000-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409323		3949-000-001-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409324		072402-3-066-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409325		072402-3-100-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409326		072402-3-098-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409327		072402-3-068-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409328		4556-000-020-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409329		4556-000-020-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409330		4556-000-020-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409331		4556-000-019-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409332		4556-000-019-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409333		4556-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409334		4556-000-018-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409335		4556-000-017-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409336		4556-000-017-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409337		4556-000-017-0407	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409338		4556-000-017-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409339		4556-000-017-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409340		4556-000-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409341		4556-000-016-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409342		4556-000-014-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409343		4556-000-015-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409344		072402-3-054-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409345		072402-3-055-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409346		072402-3-056-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409347		072402-3-060-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409348		072402-3-062-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409349		072402-3-063-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409350		4556-000-025-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409351		4556-000-025-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409352		4556-000-024-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409353		4556-000-024-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409354		4556-000-023-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409355		4556-000-023-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409356		4556-000-022-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409357		4556-000-022-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409358		4556-000-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409359		4556-000-021-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409360		4556-000-021-0203	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409361		4556-000-022-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409362		4556-000-022-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409363		4556-000-023-0300	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409364		4556-000-024-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409365		4556-000-025-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409366		4556-000-025-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409367		072402-3-061-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409368		3900-003-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409369		3900-004-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409370		3900-004-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409371		3900-004-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409372		3949-000-004-0400	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409373		3949-000-005-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409374		3949-000-006-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409375		3949-000-006-0507	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409376		3949-000-006-0408	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409377		3949-000-007-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409378		3949-000-007-0407	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409379		3949-000-007-0407	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409380		3949-000-007-0506	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409381		3935-000-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409382		3935-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409383		3935-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier					Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Other Potential Sources of: Is there a Lead Connector?	Other Potential Sources of: Is there Lead Solder in the Service Line?	Other Potential Sources of: Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409391		3949-000-013-0607	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409392		3949-000-014-1000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409393		3949-000-014-0507	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409394		3923-001-007-0009	No	Not evaluated	Galvanized	No	Prior to 1972	0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409395		3923-001-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409396		3923-001-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409397		3923-001-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 49	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409398		3923-001-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 49	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409399		3923-001-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	E440	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	E440	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409400		3923-001-002-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409401		3923-001-001-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409402		3949-000-014-0408	No	Not evaluated	Non-Lead - Plastic	No		0.75	E475	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E475	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409403		3949-000-014-0606	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409404		3949-000-014-0705	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409405		3949-000-013-0409	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409406		3949-000-013-0201	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409407		3949-000-013-0300	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409408		3949-000-011-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409409		3949-000-011-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409410		3949-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409411		3949-000-010-0402	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409412		3935-000-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409413		3949-000-008-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409414		3949-000-007-0605	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409415		3949-000-006-0606	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409416		3949-000-006-0606	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409417		3949-000-005-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409418		3949-000-005-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409419		3949-000-005-0300	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409420		3949-000-004-1200	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409421		3949-000-004-0806	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409422		3949-000-004-1002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409423		3900-002-009-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409424		3900-002-008-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409425		3900-002-007-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409426		3949-000-004-1101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409427		3949-000-004-1101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409428		3900-002-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409429		3900-002-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409430		3949-000-004-0905	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409431		3949-000-004-0905	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409432		3949-000-004-0905	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409433		3949-000-004-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409434		3900-004-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409435		3900-004-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409436		3900-004-005-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409437		3900-004-004-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409438		3900-004-003-0004	Yes - Schoo	Not evaluated	Non-Lead - Other	No		4.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		4.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409439		3900-003-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409440		3900-003-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409441		3900-003-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409442		3900-003-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409443		3900-003-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409444		3900-003-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409445		3900-003-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409446		3900-003-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409447		3900-003-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409448		3900-001-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409449		3900-001-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409450		3900-001-012-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409451		3900-001-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409452		3900-001-009-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409453		3900-001-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409454		3900-001-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409455		122401-4-150-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409456		122401-4-150-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409457		122401-4-150-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409458		122401-4-150-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409459		122401-4-149-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409460		122401-4-148-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409461		122401-4-147-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409462		072402-3-057-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409463		072402-3-051-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409464		072402-3-052-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409465		072402-3-053-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409466		072402-3-053-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409467		072402-3-048-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409468		072402-3-128-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409469		072402-3-046-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409470		072402-3-042-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409471		4556-000-014-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409472		4556-000-014-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409473		4556-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409474		072402-3-029-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409475		4556-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409476		4556-000-008-0200	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409477		4556-000-008-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409478		4556-000-009-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409479		4556-000-009-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409480		4556-000-010-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409489		4556-000-012-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409490		4556-000-011-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409491		4556-000-010-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409492		4556-000-009-0407	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409493		4556-000-009-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409494		4556-000-008-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409495		072402-3-033-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409496		072402-3-034-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409497		4655-001-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409498		4655-001-016-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409499		4655-001-017-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409500		072402-3-035-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409501		072402-3-036-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409502		4556-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409503		4556-000-001-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409504		4556-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409505		4556-000-002-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409506		4556-000-002-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409507		4556-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409508		4556-000-003-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409509		4556-000-004-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409510		4556-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409511		4556-000-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409512		4556-000-007-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409513		4556-000-007-0003	No	Not evaluated	Galvanized	No	Prior to 1957	0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	Possible	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409514		4556-000-006-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409515		4556-000-006-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409516		4556-000-005-0203	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409517		4556-000-005-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409518		4556-000-004-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409519		4556-000-003-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409520		4556-000-003-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409521		4556-000-002-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409522		4556-000-002-0206	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409523		4556-000-001-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409524		4556-000-001-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409525		072402-3-038-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409526		072402-3-037-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409527		4655-001-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409528		4655-001-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409529		4655-001-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409530		4655-001-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409531		4655-001-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409532		4655-001-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409533		4655-001-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409534		4655-001-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409535		4655-001-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409536		072402-3-028-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409537		4655-002-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409538		4655-002-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409539		4655-002-015-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409540		4655-002-016-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409541		4655-002-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409542		4655-002-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409543		4655-002-002-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409544		4655-002-003-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409545		4655-002-004-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409546		4655-002-005-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409547		4655-002-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409548		4655-002-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409549		4655-002-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409550		4655-002-008-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409551		4655-002-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409552		4655-002-009-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409553		072402-3-114-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409554		072402-3-021-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409555		072402-3-022-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409556		072402-3-099-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409557		072402-3-024-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409558		072402-3-024-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409559		072402-3-044-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409560		072402-3-047-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409561		072402-3-049-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409562		072402-3-011-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409563		3916-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409564		3916-000-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409565		3916-000-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409566		3916-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409567		3916-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409568		3916-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409569		3916-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409570		3916-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409571		3916-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409572		3916-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409573		3916-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409574		3906-000-020-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409575		3906-000-021-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409576		3906-000-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409577		3906-000-023-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409578		3906-000-024-0

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409587		122401-4-120-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409588		3906-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409589		3906-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409590		3906-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409591		3906-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409592		3906-000-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409593		3906-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409594		3906-000-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409595		3906-000-017-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check (AB)			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409596		3906-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409597		3906-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409598		3985-000-035-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409599		3985-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409600		3985-000-034-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409601		3985-000-034-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409602		3985-000-034-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409603		3985-000-034-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409604		3946-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409605		3946-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409606		3946-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409607		3946-000-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409608		122401-4-105-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409609		122401-4-105-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409610		122401-4-104-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409611		122401-4-103-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409612		122401-4-102-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409613		122401-4-099-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409614		122401-4-099-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409615		122401-4-098-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409616		122401-4-098-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409617		3920-000-020-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409618		3920-000-044-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409619		132401-1-003-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409620		132401-1-006-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409621		3945-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409622		3945-000-029-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409623		132401-1-021-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409624		132401-1-013-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409625		3975-000-040-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409626		3975-000-040-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409627		3975-000-040-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409628		4586-000-001-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409629		4586-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409630		4586-000-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409631		4586-000-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409632		3975-000-020-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409633		3975-000-020-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409634		3975-000-020-0209	No	Not evaluated	Non-Lead - Plastic	No		1.50	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409635		3975-000-020-0407	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409636		3975-000-020-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	E467	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E467	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409637		3975-000-020-0506	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Non-Lead - Plastic		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409638		3975-000-001-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409639		3975-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409640		3975-000-001-0301	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409641		3975-000-001-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409642		3975-000-002-0508	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409643		3975-000-002-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409644		3975-000-002-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 20 Pg 73	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 20 Pg 73	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409645		3975-000-002-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 27	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 27	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409646		3975-000-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409647		3975-000-019-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 6 Pg 38			2016-2024		Galvanized		0.75	Book 6 Pg 38	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409648		3975-000-019-0608	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409649		3975-000-019-0509	No	Not evaluated	Non-Lead - Plastic	No		0.75	E436			2016-2024		Galvanized		0.75	E436	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409650		3975-000-019-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409651		3975-000-019-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Fielc Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409652		3975-000-019-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409653		3975-000-019-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409654		4586-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409655		4586-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409656		4586-000-011-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409657		4586-000-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409658		4586-000-012-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409659		4586-000-013-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409660		4586-000-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409661		3931-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409662		3931-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409663		3931-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409664		3975-000-039-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409665		3975-000-039-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409666		3975-000-039-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409667		3975-000-039-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409668		3975-000-040-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409669		132401-1-016-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409670		132401-1-015-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409671		132401-1-014-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409672		132401-1-097-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409673		132401-1-018-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409674		132401-1-019-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409675		132401-1-020-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409676		132401-1-022-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409677		132401-1-098-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409678		3945-000-025-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic	

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409685		132401-1-012-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409686		3945-000-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409687		3945-000-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409688		3945-000-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409689		3945-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409690		3945-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409691		3945-000-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409692		3945-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409693		3945-000-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409694		3945-000-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409695		3945-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409696		3945-000-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409697		3961-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409698		3961-000-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409699		3961-000-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409700		3961-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409701		3961-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409702		3961-000-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409703		132401-1-008-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409704		132401-1-009-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409705		132401-1-010-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409706		132401-1-007-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409707		132401-1-007-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409708		132401-1-002-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409709		132401-1-001-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409710		3961-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409711		3961-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409712		3961-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409713		3961-000-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409714		3961-000-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409715		3920-000-034-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409716		3920-000-036-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409717		3920-000-037-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409718		3920-000-038-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409719		3920-000-039-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409720		3920-000-040-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409721		3920-000-041-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409722		3920-000-042-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409723		3920-000-043-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409724		3920-000-020-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409725		3920-000-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409726		3920-000-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409727		3920-000-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409728		3920-000-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409729		3920-000-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409730		3920-000-014-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409731		3920-000-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409732		3920-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409733		122401-4-122-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409734		122401-4-095-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409735		122401-4-094-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409736		3943-000-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409737		3943-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409738		3943-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409739		3943-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409740		3943-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409741		3943-000-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409742		3943-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409743		122401-4-106-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409744		122401-4-011-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409745		122401-4-011-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409746		122401-4-010-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409747		122401-4-010-2003	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409748		122401-4-011-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409749		122401-4-107-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409750		122401-4-108-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409751		122401-4-109-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409752		122401-4-109-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409753		122401-4-110-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409754		122401-4-111-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409755		122401-4-113-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409756		122401-4-114-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409757		122401-4-115-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409758		122401-4-116-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409759		122401-4-116-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409760		122401-4-117-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409761		122401-4-118-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409762		122401-4-119-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409763		3946-000-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409764		3946-000-020-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409765		3946-000-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409766		3946-000-017-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409767		3946-000-015-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409768		3946-000-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409769		3946-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409770		3946-000-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409771		3946-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409772		3946-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409773		3946-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409774		3946-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409775		3946-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409776		3946-000-003-0008	No	Not evaluated

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409783		3906-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409784		3906-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409785		3906-000-005-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409786		3906-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409787		3906-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409788		3906-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409789		3906-000-009-0000	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409790		3985-000-029-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409791		3985-000-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409792		3985-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409793		3985-000-026-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409794		3985-000-025-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409795		122401-4-062-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409796		122401-4-065-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409797		122401-4-067-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409798		122401-4-070-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409799		122401-4-071-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409800		122401-4-072-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409801		122401-4-146-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409802		3903-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409803		3903-000-005-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409804		3903-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409805		3903-000-004-0008	No	Not evaluated	Galvanized	No	Prior to 2027	2.00	Field Check	Visual inspection at the meter pit		2016-2024		Unknown		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown	Yes		
BremSLI-2409806		3903-000-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409807		122401-4-132-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409808		122401-4-083-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409809		122401-4-084-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409810		122401-4-086-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409811		122401-4-136-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409812		122401-4-137-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409813		122401-4-093-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409814		122401-4-093-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409815		3985-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409816		3985-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409817		3985-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409818		3985-000-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409819		3985-000-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409820		3985-000-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409821		3985-000-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409822		3985-000-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409823		3985-000-009-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409824		3985-000-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409825		3985-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409826		3985-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409827		3985-000-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409828		3985-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409829		3985-000-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409830		3985-000-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409831		3985-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409832		3985-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409833		3985-000-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409834		3985-000-020-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409835		3985-000-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409836		3985-000-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409837		3985-000-023-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409838		3985-000-024-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409839		122401-4-091-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409840		122401-4-091-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409841		122401-4-089-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409842		3920-000-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409843		3920-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409844		3920-000-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409845		3920-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409846		3920-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409847		3920-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409848		3920-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409849		3920-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409850		3920-000-023-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409851		3920-000-025-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409852		3920-000-026-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409853		3920-000-027-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409854		3920-000-027-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409855		3920-000-028-0009	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409856		3920-000-029-0008	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409857		3920-000-030-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409858		3920-000-031-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409859		3920-000-032-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409860		3920-000-033-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409861		3920-000-033-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409862		3961-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409863		3961-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409864		3961-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409865		3961-000-016-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409866		3961-000-017-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409867		3961-000-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409868		3921-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409869		3921-000-005-0005	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409870		3921-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409871		3921-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409872		3921-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409873		3921-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409881		132401-1-039-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409882		3910-000-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409883		3910-000-005-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409884		3910-000-005-0008	Yes - Other	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409885		3910-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409886		3910-000-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409887		3910-000-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409888		3910-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409889		3910-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409890		3945-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409891		3945-000-018-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409892		3945-000-020-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409893		3945-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409894		3945-000-022-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409895		3942-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409896		3942-000-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409897		3942-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409898		3931-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409899		3931-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409900		3931-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409901		3975-000-023-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409902		3975-000-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409903		3975-000-023-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409904		3975-000-023-0305	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown			
BremSLI-2409905		3975-000-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 24			2016-2024		Galvanized		0.75	Book 6 Pg 24	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409906		3975-000-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 24	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 24	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409907		3975-000-003-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409908		3975-000-003-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown			
BremSLI-2409909		3975-000-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409910		3975-000-003-0606	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 3	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 3	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409911		3975-000-003-0507	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409912		3975-000-003-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409913		3975-000-004-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409914		3975-000-004-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409915		3975-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409916		3919-002-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409917		3919-002-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409918		3919-001-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409919		3919-002-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 Pg 38	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 19 Pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409920		3919-002-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 63			2016-2024		Non-Lead - Plastic		0.75	Book 4 Pg 63	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409921		3919-002-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409922		3919-002-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409923		3975-000-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409924		3975-000-024-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409925		3975-000-024-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409926		3975-000-024-0304	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409927		3975-000-024-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409928		3975-000-037-0408	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409929		3975-000-037-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409930		3975-000-037-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409931		3975-000-037-0606	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409932		3942-000-002-0003	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown			
BremSLI-2409933		132401-1-025-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409934		132401-1-024-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409935		132401-1-024-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409936		132401-1-038-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409937		132401-1-028-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409938		3975-000-036-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409939		3975-000-036-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409940		3975-000-036-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409941		3975-000-036-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409942		3975-000-036-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409943		3975-000-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409944		3975-000-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409945		3975-000-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409946		3975-000-025-0808	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409947		3975-000-025-0907	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409948		3975-000-025-0907	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409949		3947-001-006-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409950		3911-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409951		3947-001-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409952		3947-001-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409953		3947-001-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409954		3947-001-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409955		3947-002-007-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409956		3947-002-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409957		3947-002-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409958		3947-002-001-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409959		3975-000-036-0300	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409960		132401-1-029-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409961		132401-1-030-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409962		132401-1-031-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409963		132401-1-032-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409964		132401-1-033-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409965		3945-000-015-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409966		132401-1-035-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409967		132401-1-036-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409968		132401-1-037-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409969		3909-001-006-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409970		3975-000-033-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409971		3947-003-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409972		3947-003-005-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown			
BremSLI-2409973		3947-003-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized	

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2409979		3911-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409980		3941-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	E439	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E439	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409981		3911-000-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409982		3941-000-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 41			2016-2024		Unknown		0.75	Book 6 Pg 41	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409983		3919-001-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409984		3975-000-007-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 20			2016-2024		Non-Lead - Plastic		0.75	Book 6 pg 20	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409985		3975-000-007-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 49	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409986		3919-001-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409987		3919-001-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409988		3919-001-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)			2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409989		3975-000-007-0404	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409990		3975-000-007-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2409991		3975-000-008-0403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2409992		3975-000-008-0601	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409993		3975-000-008-0601	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409994		3975-000-008-0304	No	Not evaluated	Non-Lead - Plastic	No		1.50	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.50	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409995		3975-000-008-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409996		3975-000-008-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409997		3975-000-008-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2409998		3975-000-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2409999		3975-000-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410000		3975-000-013-0307	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410001		3975-000-013-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410002		3975-000-013-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	FC	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410003		3975-000-013-0406	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field	Field/CUSTOMER		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Field/CUSTOMER	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410004		3975-000-013-0406	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410005		3975-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410006		3975-000-033-0303	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410007		3975-000-033-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410008		3909-001-006-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410009		3909-001-006-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410010		3909-001-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410011		3909-002-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410012		3909-002-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410013		3909-002-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410014		3909-002-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410015		3909-002-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410016		3975-000-032-0502	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410017		3975-000-032-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410018		3975-000-032-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410019		3912-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410020		3930-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410021		3930-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410022		3930-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410023		3940-029-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410024		3940-029-006-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410025		3940-029-007-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410026		3950-000-010-0002	Yes - Schoo	Not evaluated	Galvanized	No	Prior to 1954	1.00	fb 5 page 31	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	fb 5 page 31	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410027		3950-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410028		3960-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410029		3960-000-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410030		3960-000-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 39	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 19 pg 39	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410031		3960-000-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410032		3960-000-015-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410033		3950-000-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 17			2016-2024		Galvanized		0.75	Book 6 pg 17	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410034		3950-000-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 17			2016-2024		Non-Lead - Copper		0.75	Book 6 pg 17	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410035		3950-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb5 pg 52	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb5 pg 52	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410036		3950-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb5 pg 52	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb5 pg 52	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410037		3950-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410038		3940-029-005-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410039		3940-029-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410040		3940-029-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410041		3930-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410042		3930-000-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410043		3975-000-032-0304	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410044		3975-000-032-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410045		3975-000-032-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410046		3909-002-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410047		3909-002-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410048		3909-002-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410049		3910-000-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410050		3910-000-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410051		3910-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410052		3921-000-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410053		132401-1-041-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410054		3920-000-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410055		3920-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410056		3920-000-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410057		122401-4-087-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410058		122401-4-088-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410059		122401-4-085-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410060		122401-4-082-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410061		122401-4-081-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410062		122401-4-080-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410063		122401-4-078-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410064		122401-4-077-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410065		122401-4-076-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410066		122401-4-076-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410067		3903-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410068		3903-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410069		3903-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410077		122401-4-059-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410078		4510-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410079		122401-1-125-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410080		122401-1-191-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410081		122401-1-190-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410082		122401-1-120-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410083		122401-1-112-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410084		122401-1-112-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410085		122401-1-113-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410086		4562-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410087		4562-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410088		4562-000-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410089		4562-000-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410090		122401-1-129-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410091		122401-1-129-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410092		122401-1-129-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410093		122401-1-129-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410094		122401-1-129-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410095		122401-1-129-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410096		122401-1-129-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410097		122401-1-129-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410098		122401-1-129-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410099		4575-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410100		4575-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410101		4575-000-008-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410102		3968-001-017-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410103		4575-000-007-0000	No	Not evaluated	Galvanized	No	Prior to 2000	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410104		3968-001-016-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410105		3968-001-015-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410106		122401-1-032-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410107		122401-1-032-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410108		3968-001-013-0007	No	Not evaluated	Non-Lead - Copper	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410109		3968-001-011-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410110		3968-007-003-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410111		3968-007-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410112		3968-007-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410113		3968-007-001-0008	No	Not evaluated	Non-Lead - Plastic	No		3.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		3.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410114		122401-1-069-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410115		122401-1-061-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410116		122401-1-061-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410117		122401-1-061-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410118		122401-1-061-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410119		122401-1-071-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410120		122401-1-075-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410121		122401-1-079-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410122		122401-1-079-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410123		122401-1-082-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410124		122401-1-084-2000	No	Not evaluated	Galvanized	No	Prior to 2037	0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410125		122401-1-088-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410126		122401-1-092-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410127		122401-1-174-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410128		122401-4-001-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410129		122401-4-006-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410130		122401-4-006-2009	No	Not evaluated	Galvanized	No	Prior to 2023	0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410131		3968-007-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410132		3968-007-014-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410133		3968-008-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410134		3968-008-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410135		3968-008-010-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410136		3968-007-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410137		3968-008-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410138		3968-007-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410139		3968-008-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410140		3968-007-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410141		3968-007-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410142		3968-008-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410143		3968-007-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410144		3968-008-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410145		3968-007-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410146		3968-007-007-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410147		3968-007-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410148		3968-007-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410149		3968-001-009-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410150		3968-001-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Ceck			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410151		3968-001-009-0003	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410152		3968-001-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410153		3968-001-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410154		3968-001-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410155		3968-001-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410156		3968-001-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410157		3968-001-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	E479	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E479	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410158		3968-001-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3031/3032	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3031/3032	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410159		3968-001-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410160		3968-001-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410161		3968-002-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410162		3968-008-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410163		3968-008-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410164		3968-002-004-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410165		3968-008-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410166		3968-008-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410167		3968-002-005-0005	Yes - Schoo	Not evaluated	Non-Lead - Copper

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410175		3968-003-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410176		3968-003-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410177		3968-008-008-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410178		3968-008-008-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410179		3968-003-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410180		3968-003-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410181		3968-003-007-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410182		3968-003-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410183		3968-003-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435			2016-2024		Non-Lead - Plastic		0.75	E435	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410184		3968-003-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410185		3968-004-004-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 49	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 49	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410186		3968-004-004-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410187		3968-004-003-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 20			2016-2024		Non-Lead - Plastic		0.75	Book 6 pg 20	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410188		3968-004-003-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65			2016-2024		Galvanized		0.75	Book 6 pg 65	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410189		3968-004-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	E462	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	E462	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410190		3968-004-002-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410191		3968-004-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410192		3968-006-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410193		3968-006-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410194		3968-004-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410195		3968-006-002-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410196		3968-006-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410197		3968-004-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410198		3968-004-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410199		3968-006-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410200		3968-006-005-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check			2016-2024		<Null>		2.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410201		3968-004-008-0206	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410202		3968-004-008-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410203		3968-004-009-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410204		3968-005-016-0203	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410205		3968-006-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410206		3968-005-016-0401	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410207		3968-006-008-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410208		3968-005-016-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410209		3968-006-008-0201	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410210		3968-006-008-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410211		3968-006-008-0300	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410212		3968-006-008-0300	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410213		3968-005-016-0708	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410214		3968-005-016-0609	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410215		3968-005-016-0609	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410216		3968-005-016-0302	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410217		3968-005-016-0302	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410218		3968-006-008-0508	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410219		3968-006-008-0508	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410220		3968-006-008-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410221		3968-006-008-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410222		3968-006-008-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410223		3968-006-008-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410224		3968-005-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410225		3968-005-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410226		3968-005-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410227		3968-005-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410228		3968-005-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410229		3968-005-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410230		3968-006-008-0607	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410231		3968-006-008-0607	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410232		3968-006-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410233		3968-006-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410234		3968-005-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410235		3968-006-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410236		3968-005-007-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410237		3968-005-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410238		3968-005-009-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410239		3968-005-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410240		3968-005-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410241		3968-005-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410242		3968-005-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410243		3968-005-015-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410244		3968-005-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410245		122401-4-004-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410246		122401-4-013-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410247		122401-4-012-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410248		3915-000-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410249		3915-000-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410250		3915-000-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410251		3915-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410252		3915-000-014-0002	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410253		3915-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410254		3968-004-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410255		3968-004-009-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410256		3968-004-009-0403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410257		3915-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410258		3915-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410259		3915-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410260		3915-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410261		3915-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410262		3915-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410263		3915-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410264		122401-4-005-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410265		122401-4-021-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410266		122401-4-022-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410267		122401-4-022-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual in

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410273		122401-4-040-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410274		122401-4-032-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410275		122401-4-035-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410276		122401-4-101-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410277		122401-4-101-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410278		122401-4-042-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410279		122401-4-140-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410280		122401-4-140-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410281		122401-4-142-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410282		122401-4-142-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410283		122401-4-142-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410284		3932-000-014-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410285		3932-000-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410286		3932-000-012-0003	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410287		3932-000-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410288		3932-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410289		3932-000-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410290		3932-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410291		122401-4-046-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410292		122401-4-046-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410293		3932-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410294		3932-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410295		3932-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410296		3932-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410297		3932-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410298		3932-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410299		3932-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410300		3938-000-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410301		3938-000-014-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410302		3938-000-015-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410303		3938-000-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410304		3938-000-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410305		3938-000-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410306		3938-000-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410307		3938-000-020-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410308		3938-000-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410309		3938-000-022-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410310		3938-000-022-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410311		3938-000-023-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410312		3938-000-024-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410313		3938-000-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410314		3938-000-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410315		3938-000-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410316		3938-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410317		3938-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410318		3938-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410319		3938-000-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410320		3938-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410321		3938-000-010-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410322		3938-000-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410323		3938-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410324		3938-000-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410325		3907-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410326		3907-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410327		3907-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410328		3907-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410329		3907-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410330		3907-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410331		122401-4-020-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410332		3907-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410333		3907-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410334		3907-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410335		3907-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410336		3907-000-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410337		3907-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410338		3915-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410339		3915-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410340		3915-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410341		3915-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410342		3915-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410343		122401-4-016-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410344		122401-4-016-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410345		122401-4-017-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410346		122401-4-018-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410347		122401-4-019-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410348		122401-4-047-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410349		122401-4-048-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410350		122401-4-050-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410351		122401-4-053-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410352		3934-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410353		3934-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410354		3934-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410355		3934-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410356		3934-000-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410357		3934-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410358		122401-4-044-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410359		122401-4-045-2002	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410360		122401-4-057-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410361		122401-4-056-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410362		3934-000-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410363		3934-000-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the me

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410371		3934-000-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410372		1224014-4-055-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410373		1224001-4-054-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410374		1224014-4-054-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410375		1324001-1-086-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410376		1324001-1-086-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410377		1324001-1-042-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410378		1324001-1-042-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410379		1324001-1-043-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410380		1324001-1-044-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410381		1324001-1-044-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410382		1324001-1-056-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410383		1324001-1-055-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410384		1324001-1-054-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410385		1324001-1-053-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410386		1324001-1-052-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410387		1324001-1-064-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410388		4985-001-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410389		4985-001-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410390		4985-005-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410391		4985-005-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410392		4985-005-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410393		4985-005-006-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410394		4985-005-006-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410395		4985-004-001-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410396		4985-004-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410397		4985-004-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410398		4985-005-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410399		4985-005-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410400		4985-005-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410401		1324001-1-048-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410402		4985-006-001-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410403		4985-006-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410404		4985-006-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410405		4985-006-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410406		4985-006-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410407		4985-004-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410408		4985-004-021-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410409		4985-004-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410410		4985-004-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410411		4985-004-013-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410412		4985-004-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410413		4985-003-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410414		4985-003-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410415		4985-003-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410416		4985-003-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410417		4985-003-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410418		4985-003-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410419		3914-004-001-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410420		3914-004-001-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410421		3914-004-002-0207	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410422		3914-004-002-0207	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410423		3914-004-002-0207	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410424		3939-000-008-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410425		3914-004-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410426		3939-000-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410427		3939-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410428		3914-004-001-0802	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410429		3914-004-001-0802	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410430		4985-003-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410431		4985-002-019-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410432		4985-003-004-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410433		4985-002-018-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410434		4985-002-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410435		4985-002-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410436		4985-002-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410437		4985-002-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410438		4985-002-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410439		4985-002-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410440		4985-004-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410441		4985-002-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410442		4985-004-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410443		4985-004-008-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410444		4985-002-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410445		4985-002-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410446		4985-002-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410447		4985-004-007-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410448		4985-004-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410449		4985-002-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410450		4985-002-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410451		4985-002-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410452		4985-002-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410453		4985-004-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410454		4985-002-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410455		4985-002-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410456		1324001-1-070-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410457		1324001-1-069-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410458		1324001-1-066-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410459		1324001-1-063-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410460		1324001-1-062-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410461		1324001-1-061-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410462		1324001-1-057-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Vis

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410469		132401-1-085-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410470		3956-000-009-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410471		3956-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410472		3956-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410473		3956-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410474		3956-000-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410475		3956-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410476		3956-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410477		3956-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410478		3956-000-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410479		3956-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410480		3970-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410481		3970-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410482		3970-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410483		132401-1-084-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410484		132401-1-079-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410485		132401-1-081-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410486		3970-000-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410487		3970-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410488		3970-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410489		3970-000-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410490		3970-000-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410491		3970-000-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410492		3970-000-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410493		132401-1-082-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410494		132401-1-083-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410495		8102-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410496		8102-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410497		3922-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410498		3922-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410499		3922-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410500		3922-000-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410501		3922-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410502		132401-1-068-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410503		132401-1-071-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410504		132401-1-072-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410505		132401-1-072-2003	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410506		132401-1-073-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410507		3956-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410508		3956-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410509		3956-000-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410510		3956-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410511		3956-000-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410512		3956-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410513		3956-000-018-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410514		3956-000-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410515		3956-000-020-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410516		3956-000-021-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410517		3956-000-022-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410518		3956-000-023-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410519		3939-000-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410520		3939-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410521		3939-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410522		3914-001-001-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410523		3914-001-001-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410524		3914-001-001-0600	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410525		3914-001-001-0709	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410526		3914-001-001-0808	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410527		3929-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410528		3929-000-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410529		3929-000-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410530		3929-000-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410531		3929-000-006-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410532		3929-000-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410533		3939-000-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410534		3939-000-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410535		3939-000-015-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410536		3939-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410537		3908-000-018-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410538		3908-000-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410539		3908-000-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410540		3908-000-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410541		3908-000-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410542		3908-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410543		3908-000-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410544		3908-000-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410545		3908-000-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410546		3908-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410547		3908-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410548		3908-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410549		3908-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410550		3908-000-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410551		3908-000-001-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410552		3908-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410553		3908-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410554		3914-002-006-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410555		3914-002-001-0301	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410556		3914-002-001-0608	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410557		3914-002-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410558		3914-002-001-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410559		3914-002-002-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410560		3914-002-002-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024	

Location Information					System-Owned Portion								Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410567		3918-001-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 39	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 13 pg 39	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410568		3918-001-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 16 pg 4	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 16 pg 4	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410569		3918-001-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2082	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2082	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410570		3918-001-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410571		3918-001-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410572		3918-001-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410573		3918-001-014-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410574		3918-001-012-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410575		3918-001-012-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown	Yes		
BremSLI-2410576		3918-001-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	E435	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410577		3914-002-003-0408	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb5 pg 52	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb5 pg 52	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410578		3914-002-003-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410579		3914-002-002-0409	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410580		3914-002-002-0300	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410581		3914-002-002-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410582		3914-002-001-0509	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410583		3914-002-001-0202	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410584		3914-002-001-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410585		3914-002-002-0508	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410586		3914-002-002-0607	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410587		3914-002-003-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410588		3914-002-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410589		3914-002-003-0606	No	Not evaluated	Non-Lead - Plastic	No		0.75	E467	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E467	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410590		3918-002-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410591		3918-002-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 66	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 66	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410592		3918-002-004-0007	No	Not evaluated	Galvanized	No	Prior to 1974	0.75	Book 19 pg 3	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 19 pg 3	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410593		3918-002-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3734	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410594		3918-002-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410595		3918-002-020-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410596		3918-003-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2082	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2082	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410597		3918-002-019-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410598		3918-002-018-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410599		3918-003-003-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410600		3918-002-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410601		3918-002-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 Pg 64	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 19 Pg 64	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410602		3902-001-002-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410603		3902-001-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	E467	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E467	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410604		3914-002-004-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410605		3914-002-003-0804	No	Not evaluated	Non-Lead - Plastic	No		1.00	field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410606		3914-002-004-0308	No	Not evaluated	Non-Lead - Plastic	No		1.00	FC			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410607		3914-002-004-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410608		3914-002-005-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410609		3914-002-005-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410610		3914-002-002-1001	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410611		3914-002-002-0904	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410612		3914-002-002-0904	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410613		3908-000-014-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410614		3914-002-006-0306	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410615		3914-002-005-0406	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410616		3914-002-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410617		3914-002-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410618		3902-001-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	E436			2016-2024		Galvanized		0.75	E436	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410619		3902-001-009-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410620		3902-001-009-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410621		3902-002-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410622		3902-002-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410623		3902-002-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410624		8087-000-000-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 54			2016-2024		Galvanized		0.75	Book 6 Pg 54	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410625		8087-002-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	E467			2016-2024		Non-Lead - Plastic		0.75	E467	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410626		8065-000-000-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	fb 5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	fb 5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410627		3914-003-003-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410628		3914-003-003-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410629		3905-000-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410630		3905-000-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410631		3905-000-003-0106	No	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410632		3905-000-003-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410633		8029-000-000-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410634		3951-002-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410635		3914-004-003-0800	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410636		3914-004-003-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410637		3914-004-002-1007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410638		3914-004-002-1403	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410639		3914-004-002-0306	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410640		3914-004-002-0405	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410641		3914-004-001-0901	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410642		3914-004-001-0604	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410643		8170-000-000-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410644		132401-2-073-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410645		4985-008-005-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410646		4985-008-005-0207	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410647		4985-008-005-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410648		4985-008-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410649		4985-008-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410650		5277-000-002-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410651		3976-030-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410652		3976-030-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410653		3976-030-003-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410654		3976-030-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410655		3976-030-022-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410656		3976-030-025-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410657		3976-030-026-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410658		3976-030-028-0009	No	Not

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410665		5471-000-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 25			2016-2024		Galvanized		0.75	Book 13 pg 25	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410666		3976-029-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410667		5471-000-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410668		5471-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 38			2016-2024		Galvanized		0.75	Book 6 Pg 38	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410669		5471-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 18			2016-2024		Galvanized		0.75	Book 6 Pg 18	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410670		5471-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 6	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 6	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410671		5471-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48			2016-2024		Galvanized		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410672		5471-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 27	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 27	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410673		5471-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410674		5471-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410675		3976-028-004-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410676		5471-000-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410677		5471-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410678		5471-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410679		5471-000-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2187	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2187	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410680		3976-028-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410681		5471-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3090			2016-2024		Galvanized		0.75	BEDA 3090	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410682		5471-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410683		3966-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410684		3966-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410685		3966-004-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410686		3967-001-001-0200	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410687		3967-001-017-0707	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410688		3967-001-017-0103	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410689		3967-001-017-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410690		3967-001-017-0608	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410691		3967-001-017-0608	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410692		3967-001-017-0806	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410693		3967-001-017-0806	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410694		3976-001-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410695		3976-001-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410696		3976-001-001-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410697		3976-001-001-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410698		3976-001-001-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410699		122401-4-033-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410700		122401-4-027-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410701		122401-4-027-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410702		122401-4-027-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410703		122401-4-026-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410704		122401-4-024-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410705		122401-4-024-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410706		3967-010-001-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410707		3968-003-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410708		3967-011-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410709		3967-011-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410710		3967-010-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1675	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1675	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410711		3967-011-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1724	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1724	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410712		3967-011-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Non-Lead - Copper		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410713		3967-010-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Non-Lead - Copper		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410714		3967-009-010-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-Builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-Builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410715		3967-010-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410716		3967-010-005-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410717		3967-010-006-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410718		3967-010-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410719		3967-009-011-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410720		3967-009-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.50	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410721		3967-009-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410722		3971-000-004-0104	No	Not evaluated	Non-Lead - Other	No		2.00	<Null>			2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410723		3967-009-013-0001	No	Not evaluated	Non-Lead - Copper	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410724		3971-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410725		3901-000-010-0002	No	Not evaluated	Non-Lead - Copper	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410726		3901-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W311	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W311	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410727		3901-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W311	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	W311	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410728		3971-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00				2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	<Null>	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410729		3901-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Plastic		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410730		3901-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	W202			2016-2024		Non-Lead - Plastic		0.75	W202	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410731		3971-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W180			2016-2024		Non-Lead - Copper		0.75	W180	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410732		3901-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79			2016-2024		Non-Lead - Plastic		0.75	Tap log 79	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410733		3901-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 79	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410734		3901-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410735		3901-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410736		3901-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Replaced			2016-2024		Non-Lead - Copper		0.75	Replaced	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410737		3901-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410738		3901-000-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410739		3901-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410740		3901-000-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410741		3933-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410742		3933-000-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410743		3933-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410744		3933-000-013-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410745		3971-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410746		3933-000-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410747		3933-000-014-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410748		3971-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410749		3971-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 79	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410750		3971-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	W248	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W248	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410751		3971-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	W248	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W248	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410752		3971-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410753		3971-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410754		3971-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Plastic		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410755		3971-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 81	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410756		3971-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410757		3933-000-015-0009	No	Not evaluated	Non

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410763		3967-006-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410764		3967-006-001-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410765		3967-001-012-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410766		3967-001-012-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410767		3967-001-009-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410768		3967-001-009-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410769		3967-001-009-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410770		3967-001-009-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410771		3967-001-009-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410772		3967-001-009-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410773		3967-001-008-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410774		3967-002-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410775		3967-002-021-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		<Null>		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410776		3967-002-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410777		3933-000-002-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410778		3967-002-004-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410779		3933-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410780		3933-000-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410781		3967-002-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410782		3967-002-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410783		3933-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410784		3967-002-014-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410785		3967-002-014-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410786		3967-002-014-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410787		3933-000-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410788		3933-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410789		3933-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410790		3967-002-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410791		3967-002-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410792		3967-002-009-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Unknown Type			2016-2024		Non-Lead - Plastic		1.00	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410793		3967-002-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410794		3967-002-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410795		3966-004-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410796		3966-003-001-1601	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410797		3966-003-001-1502	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410798		3966-003-001-1502	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410799		3966-003-001-1502	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410800		3966-004-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410801		3966-003-001-0504	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410802		3966-003-001-1304	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410803		3966-004-009-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410804		3966-004-009-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410805		3966-004-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410806		3966-003-001-1106	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410807		3966-003-001-1106	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410808		3966-002-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410809		3966-002-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410810		3966-002-003-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410811		3966-003-001-1403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410812		3966-003-001-1403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410813		3966-003-001-1403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410814		3966-003-001-1403	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410815		3966-002-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410816		3965-000-165-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410817		3965-000-165-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410818		3965-000-166-0007	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410819		3965-000-167-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410820		3965-000-168-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other		Unknown	Unknown		
BremSLI-2410821		3965-000-173-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410822		3965-000-174-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410823		3965-000-169-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410824		3965-000-155-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410825		3965-000-159-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410826		3965-000-160-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown	Unknown		
BremSLI-2410827		3965-000-160-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other		Unknown	Unknown		
BremSLI-2410828		3965-000-161-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410829		3965-000-161-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field inspection	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410830		3965-000-162-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410831		3965-000-162-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410832		3965-000-164-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410833		3965-000-163-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other		Unknown	Unknown		
BremSLI-2410834		8073-000-000-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410835		8073-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410836		8073-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410837		8073-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410838		8073-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410839		3967-003-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410840		3967-003-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410841		3967-003-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410842		3967-003-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building		Unknown	Unknown		
BremSLI-2410843		3967-003-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Building		Unknown	Unknown		
BremSLI-2410844		3967-009-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410845		3967-009-003-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410846		3967-009-003-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410847		3967-009-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410848		3967-009-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410849		3967-009-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410850		3967-003-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410851		3967-003-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410852		3967-003-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410861		3901-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Galvanized		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410862		3967-008-024-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 79	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410863		3901-000-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81			2016-2024		Non-Lead - Copper		0.75	Tap log 81	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410864		3967-008-005-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410865		3967-008-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410866		3901-000-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	W181			2016-2024		Non-Lead - Copper		0.75	W181	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410867		3901-000-012-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410868		3967-008-006-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410869		3967-008-007-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410870		3967-008-007-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410871		3967-008-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND			2016-2024		None		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410872		3967-009-005-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410873		3967-009-006-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410874		3967-008-009-0108	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410875		3967-008-009-0108	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410876		3967-008-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1555	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1555	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410877		3967-009-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410878		3967-009-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410879		3967-011-007-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410880		3967-011-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410881		3967-011-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410882		3967-011-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410883		3967-011-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410884		3967-008-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410885		3967-008-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410886		3967-008-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410887		3967-011-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410888		3967-011-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2410889		3967-011-002-0000	No	Not evaluated	Galvanized	No	Prior to 2038	0.75	Field Check. In-line	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410890		3967-008-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410891		3967-008-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410892		3968-001-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410893		3968-001-020-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410894		3968-001-020-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410895		3968-001-019-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410896		3968-001-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410897		3967-008-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410898		3967-007-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410899		3967-007-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410900		3967-007-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410901		3967-008-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410902		3967-007-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410903		3967-007-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410904		3967-007-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410905		3967-008-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410906		3967-008-020-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1724	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1724	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410907		3967-008-020-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762			2016-2024		Non-Lead - Plastic		0.75	BEDA 1762	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410908		3967-007-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Galvanized		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410909		3967-008-021-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410910		3967-007-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Galvanized		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410911		3967-008-022-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410912		3967-007-002-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410913		3967-007-002-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410914		3967-008-004-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410915		3967-007-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410916		3967-007-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		<Null>		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410917		3967-007-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>			2016-2024		Non-Lead - Copper		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410918		3967-007-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410919		3967-007-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410920		1224O1-2-008-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410921		1224O1-2-009-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410922		1224O1-2-009-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410923		1224O1-2-013-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410924		1224O1-2-014-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410925		1224O1-2-011-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410926		1224O1-2-011-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410927		1224O1-2-011-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410928		1224O1-2-011-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410929		1224O1-2-011-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410930		1224O1-2-011-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410931		1224O1-2-018-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410932		1224O1-2-018-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410933		1224O1-2-036-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410934		1224O1-2-017-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410935		1224O1-2-017-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410936		3924-000-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410937		1224O1-2-026-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410938		1224O1-2-025-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410939		1224O1-2-024-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410940		1224O1-2-021-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410941		1224O1-2-019-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410942		1224O1-2-020-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410943		3924-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410944		3924-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410945		3924-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410946		3924-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410947		3924-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410948		3924-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410949		3924-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410950		3924-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410951		3924-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410952		3924-000-008-0009	No	Not evaluated	Non-Lead - Plastic

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2410959		3924-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410960		3924-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410961		3924-000-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410962		3924-000-014-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410963		3973-004-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410964		3973-004-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410965		3973-004-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410966		3973-004-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410967		3973-004-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410968		3973-004-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410969		3973-004-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410970		3973-004-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410971		3973-004-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410972		3973-004-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2410973		3973-004-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410974		3973-004-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410975		3973-004-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410976		3973-004-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410977		3973-004-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410978		3973-004-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410979		3973-004-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410980		3973-004-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410981		3973-004-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410982		3973-004-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410983		3973-004-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410984		3973-004-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410985		3973-003-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410986		3973-003-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410987		3973-003-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410988		3973-003-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410989		3973-003-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410990		3973-003-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410991		3973-003-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410992		3973-003-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410993		3973-003-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2410994		3973-003-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410995		3973-003-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410996		3973-003-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410997		3973-002-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410998		3973-002-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2410999		3973-002-009-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411000		3973-002-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411001		3973-002-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411002		3973-001-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411003		3973-001-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411004		3973-001-014-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411005		3973-001-015-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411006		3973-001-016-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411007		3973-001-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411008		3973-001-018-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411009		3973-001-019-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411010		3973-001-020-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411011		3973-001-021-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411012		3973-001-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411013		3973-001-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411014		3973-001-024-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411015		3973-001-025-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411016		3973-001-026-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411017		3973-001-027-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411018		3973-001-028-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411019		3973-001-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411020		3973-001-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411021		3973-001-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411022		3973-001-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Abandon / couldn't find		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Abandon / couldn't find	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411023		3973-001-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411024		3925-000-021-0001	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411025		3973-001-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411026		3925-000-022-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411027		3973-001-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411028		3925-000-023-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411029		3973-001-008-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411030		3925-000-024-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411031		3973-001-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411032		3973-001-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411033		3973-001-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411034		3925-000-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411035		3973-001-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411036		3973-002-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411037		3973-002-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411038		3925-000-028-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411039		3973-002-003-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411040		3925-000-029-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411041		3973-002-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411042		3973-002-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411043		3925-000-030-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411044		3973-002-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411045		3926-000-022-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411046		3926-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411047		3926-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411048		3926-000-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411057		3926-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411058		3926-000-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411059		3926-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411060		3926-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411061		3926-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411062		3926-000-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411063		3926-000-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411064		3926-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411065		3926-000-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411066		3925-000-020-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411067		3925-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411068		3925-000-018-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411069		3925-000-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411070		3925-000-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411071		3925-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411072		3925-000-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411073		3925-000-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411074		3925-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411075		3925-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411076		3925-000-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411077		3925-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411078		3925-000-008-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411079		3925-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411080		3925-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411081		3925-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411082		3925-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411083		3925-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411084		3926-000-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411085		3926-000-024-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411086		3926-000-024-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411087		8039-000-000-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411088		3936-035-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411089		3967-008-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411090		3926-000-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411091		3926-000-026-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411092		3926-000-027-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411093		3926-000-028-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411094		3926-000-031-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411095		3926-000-031-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411096		3926-000-032-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411097		3926-000-032-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411098		3926-000-033-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411099		3926-000-034-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411100		3926-000-035-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411101		3926-000-036-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411102		3926-000-037-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411103		3926-000-038-0100	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411104		3926-000-039-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411105		3926-000-040-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411106		3926-000-040-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411107		3926-000-042-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411108		122401-2-037-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411109		122401-2-037-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411110		122401-2-038-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411111		122401-2-037-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411112		122401-2-040-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411113		122401-2-032-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411114		122401-2-031-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411115		122401-2-030-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411116		3972-000-001-0601	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411117		3972-000-001-0601	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411118		3972-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411119		3972-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411120		3972-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411121		3972-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411122		3972-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411123		3972-000-008-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411124		3972-000-008-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411125		3972-000-001-0502	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411126		3972-000-001-0502	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411127		3972-000-007-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411128		3972-000-001-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411129		012401-2-096-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411130		012401-2-098-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411131		012401-2-100-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411132		012401-2-103-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411133		012401-2-163-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411134		3928-002-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411135		3928-002-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411136		3928-002-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411137		3928-002-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411138		3928-002-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411139		3928-002-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411140		3992-001-001-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411141		3992-001-001-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411142		3992-001-001-0209	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411143		3992-001-001-0209	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411144		3992-001-001-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411145		3992-001-001-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411146		3992-001-001-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411155		3972-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411156		3972-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411157		3972-000-010-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411158		3972-000-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411159		3972-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411160		3972-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411161		3972-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411162		3972-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411163		3972-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411164		3972-000-014-0200	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411165		3972-000-014-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411166		3972-000-014-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411167		3972-000-014-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411168		3972-000-015-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411169		3972-000-016-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411170		3972-000-016-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411171		3972-000-016-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411172		3972-000-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411173		3972-000-016-0406	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411174		3972-000-016-0703	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411175		3972-000-016-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411176		3972-000-016-0505	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411177		3972-000-016-0604	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411178		3972-000-016-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411179		3972-000-016-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411180		3972-000-017-0702	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411181		3972-000-017-0702	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411182		3972-000-017-0702	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411183		3972-000-018-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411184		3972-000-018-0404	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411185		3972-000-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411186		3972-000-017-0009	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411187		3972-000-018-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411188		3972-000-018-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411189		3972-000-018-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411190		3972-000-017-0405	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411191		3972-000-017-0603	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411192		3972-000-017-0306	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411193		3972-000-017-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411194		3928-001-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411195		3972-000-017-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411196		3928-001-009-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411197		3972-000-018-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411198		3972-000-018-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411199		3972-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411200		3928-002-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411201		3928-002-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411202		3928-001-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411203		3928-001-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411204		3928-001-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411205		3928-002-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411206		3928-002-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411207		3928-002-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411208		3928-002-017-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411209		3928-002-016-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411210		3928-001-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411211		3928-002-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411212		3928-002-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411213		3928-001-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411214		3928-001-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411215		3928-002-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411216		012401-2-102-2009	No	Not evaluated	Galvanized	No	Prior to 1984	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411217		012401-2-151-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411218		3928-001-003-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411219		3928-001-002-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411220		3928-001-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411221		012401-2-111-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411222		012401-2-110-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411223		012401-2-108-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411224		012401-2-101-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411225		012401-2-106-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411226		012401-2-106-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411227		012401-2-104-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411228		012401-2-097-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411229		012401-2-115-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411230		3984-002-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411231		3984-001-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411232		3984-002-002-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411233		3984-002-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411234		3984-003-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411235		3984-003-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411236		3984-003-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411237		3984-003-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411238		3984-003-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411239		3984-003-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411240		3984-001-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411241		3984-001-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411242		3984-001-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411243		3984-001-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411244		3984-003-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411245		3984-003-002-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411253		012401-2-092-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411254		012401-2-088-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411255		012401-2-093-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411256		012401-2-094-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411257		012401-2-095-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411258		3984-003-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411259		3984-003-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411260		3984-003-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411261		012401-2-089-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411262		3983-000-020-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411263		3983-000-019-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411264		3983-000-021-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411265		3983-000-022-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411266		3983-000-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411267		3983-000-024-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411268		3983-000-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411269		3983-000-017-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411270		3983-000-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411271		3983-000-015-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411272		3983-000-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411273		3983-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411274		3983-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411275		3983-000-011-0002	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411276		3983-000-025-0006	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411277		3983-000-026-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411278		3983-000-027-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411279		3983-000-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411280		3983-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411281		3983-000-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411282		3983-000-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411283		3983-000-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411284		3983-000-006-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411285		3983-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411286		012401-2-176-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411287		3983-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411288		3983-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411289		3983-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411290		3983-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411291		012401-2-178-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411292		012401-2-082-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411293		012401-2-082-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411294		012401-2-081-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411295		3989-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411296		3989-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411297		3989-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411298		3989-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411299		3989-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411300		3989-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411301		3989-000-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411302		3989-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411303		3989-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411304		3989-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411305		3989-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411306		3989-000-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411307		3989-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411308		012401-2-079-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411309		012401-2-121-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411310		012401-2-121-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411311		012401-2-072-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411312		012401-2-072-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411313		012401-2-057-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411314		4528-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411315		4528-000-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411316		4528-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411317		4528-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411318		4528-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411319		4528-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411320		4528-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411321		4528-000-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411322		4528-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411323		3818-000-041-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411324		3818-000-043-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411325		3818-000-043-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411326		3818-000-044-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411327		4528-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411328		4528-000-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411329		4528-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411330		012401-2-077-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411331		3990-000-039-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411332		3990-000-038-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411333		3990-000-037-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411334		3990-000-036-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411335		3990-000-035-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411336		3990-000-034-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411337		3990-000-033-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411338		3990-000-033-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411339		3990-000-032-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411340		3990-000-031-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411341		3990-000-030-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411342		3990-000-029-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411351		3990-000-020-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411352		3990-000-019-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411353		3990-000-018-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411354		3990-000-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411355		3990-000-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411356		3990-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411357		3990-000-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411358		012401-2-150-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411359		3937-004-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411360		3937-003-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411361		3937-003-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411362		3937-004-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411363		3937-004-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411364		3937-003-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411365		3937-003-013-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411366		3937-004-005-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411367		3937-003-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411368		3937-004-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411369		3937-003-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411370		3937-004-007-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411371		3937-004-008-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411372		3937-003-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411373		3937-003-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411374		012401-2-134-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411375		3937-002-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411376		3937-002-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411377		3937-003-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411378		3937-003-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411379		3937-002-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411380		3937-002-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411381		3937-002-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411382		3937-003-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411383		3937-003-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411384		3937-002-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411385		3937-002-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411386		3937-003-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411387		3937-002-016-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411388		3937-003-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411389		3937-002-017-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411390		3937-002-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411391		3937-002-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411392		3937-002-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411393		3937-002-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411394		3937-002-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411395		3937-002-006-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411396		3937-002-007-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411397		012401-2-136-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411398		012401-2-140-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411399		012401-2-078-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411400		012401-2-080-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411401		3825-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411402		3825-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411403		3825-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411404		3825-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411405		3825-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411406		3825-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411407		012401-2-119-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411408		3937-001-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411409		3937-001-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411410		3937-001-006-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411411		3937-001-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411412		3937-001-004-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411413		3937-001-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411414		3937-001-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411415		3984-001-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411416		012401-2-105-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411417		012401-2-107-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411418		3937-001-001-0009	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411419		012401-2-114-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411420		012401-2-113-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411421		012401-2-109-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411422		012401-2-112-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411423		3927-000-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411424		3927-000-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411425		3927-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411426		3927-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411427		3927-000-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411428		3927-000-006-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411429		3927-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411430		3927-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411431		012401-2-148-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411432		012401-2-147-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411433		012401-2-147-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411434		012401-2-146-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411435		012401-2-145-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411436		012401-2-144-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411437		012401-2-144-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411438		012401-2-142-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411439		012401-2-130-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411440		012401-2-137-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411441		012401-2-139-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411442		012401-2-135-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GI

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411449		012401-2-126-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411450		012401-2-124-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411451		012401-2-127-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411452		012401-2-125-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411453		012401-2-128-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411454		012401-2-128-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411455		3819-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411456		3819-000-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411457		3819-000-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411458		3819-000-013-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411459		012401-2-120-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411460		3819-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411461		3819-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411462		3819-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411463		3819-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411464		3819-000-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411465		3819-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411466		3819-000-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411467		3819-000-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411468		3819-000-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411469		012401-2-193-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411470		012401-2-153-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411471		012401-2-153-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411472		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411473		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411474		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411475		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411476		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411477		3824-000-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411478		3824-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411479		3824-000-002-0303	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411480		3824-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411481		3824-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411482		022401-1-060-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411483		022401-1-060-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411484		3824-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411485		3824-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411486		3824-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411487		3824-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411488		3824-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411489		022401-1-059-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411490		022401-1-059-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411491		3824-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411492		022401-1-069-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411493		022401-1-069-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411494		022401-1-069-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411495		022401-1-025-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411496		022401-1-025-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>			2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411497		022401-1-037-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411498		022401-1-037-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411499		022401-1-036-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411500		022401-1-051-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411501		022401-1-121-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411502		022401-1-121-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411503		022401-1-121-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411504		022401-1-121-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411505		022401-1-089-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411506		022401-1-089-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411507		022401-1-089-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411508		022401-1-032-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411509		4574-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411510		4574-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411511		5369-000-042-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411512		5369-000-041-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411513		5369-000-040-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411514		5369-000-039-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411515		5369-000-038-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411516		5369-000-037-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411517		5369-000-036-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411518		5369-000-035-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411519		5369-000-034-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411520		5369-000-033-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411521		5369-000-032-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411522		5369-000-031-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411523		5369-000-030-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411524		5369-000-029-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411525		5369-000-028-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411526		5369-000-027-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411527		5369-000-026-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411528		5369-000-025-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411529		5369-000-024-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411530		5369-000-023-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411531		5369-000-022-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411532		5369-000-021-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411533		5369-000-020-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411534		5369-000-019-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411535		5369-000-019-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411536		5369-000-018-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411537		5369-000-017-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411538		5369-000-016-0006	No	Not evaluated	Non-Lead - Pl

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411547		5369-000-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411548		5369-000-006-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1724	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1724	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411549		5369-000-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411550		5369-000-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411551		5369-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411552		5369-000-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411553		5369-000-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411554		4574-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411555		0224O1-1-043-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411556		0224O1-1-043-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411557		0224O1-1-055-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1555	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1555	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411558		0224O1-1-055-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1555	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1555	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411559		0224O1-1-054-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1579			2016-2024		Non-Lead - Copper		0.75	BEDA 1579	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411560		0224O1-1-054-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1579	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1579	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411561		3981-000-091-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411562		3981-000-090-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411563		3981-000-089-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411564		3981-000-088-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411565		3981-000-087-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 74			2016-2024		Non-Lead - Plastic		0.75	Tap log 74	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411566		3981-000-086-0004	No	Not evaluated	Non-Lead - Plastic	No		1.50	System records	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	System records	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411567		3981-000-085-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411568		3981-000-084-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411569		3981-000-083-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411570		3981-000-082-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411571		3981-000-081-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411572		3981-000-080-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411573		3962-000-021-0302	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411574		3962-000-021-0203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411575		3962-000-021-0609	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411576		3962-000-021-0708	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411577		3962-000-021-0807	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411578		3962-000-021-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411579		3962-000-021-0401	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411580		3962-000-021-0500	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411581		3981-000-100-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411582		3981-000-099-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411583		3981-000-098-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411584		3981-000-097-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411585		3981-000-096-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411586		3981-000-095-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	No service			2016-2024		Unknown		0.75	No service	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411587		3981-000-094-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log (1811)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log (1811)	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411588		3981-000-093-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411589		3981-000-092-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411590		0224O1-1-045-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411591		0224O1-1-046-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411592		0224O1-1-047-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411593		0224O1-1-048-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411594		0224O1-1-035-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411595		0224O1-4-053-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411596		0224O1-4-067-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411597		0224O1-4-066-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411598		3982-000-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 31	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 pg 31	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411599		3982-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 48	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411600		3982-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 8550	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 8550	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411601		3982-000-005-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411602		3982-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411603		3982-000-006-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411604		3982-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411605		3982-000-007-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411606		3982-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	W288			2016-2024		Non-Lead - Copper		0.75	W288	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411607		3982-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	W224	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W224	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411608		3982-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 76	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 76	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411609		3982-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411610		3982-000-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411611		3982-000-012-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411612		3982-000-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411613		3978-000-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411614		3978-000-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411615		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411616		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411617		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411618		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411619		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411620		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411621		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411622		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411623		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411624		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411625		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411626		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411627		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411628		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411629		0224O1-4-068-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411630		3979-000-044-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411631		3979-000-045-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411632		3979-000-043-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411633		3979-000-046-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411634		3979-000-047-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411635		3979-000-048-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411636		3979-000-049-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411637		3979-000-042-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411645		3979-000-038-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411646		3979-000-054-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411647		3979-000-055-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411648		3979-000-056-0004	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411649		3979-000-037-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411650		3979-000-057-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411651		3979-000-058-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411652		3979-000-058-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411653		3978-000-022-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411654		3978-000-021-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411655		3979-000-036-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411656		3978-000-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411657		3978-000-024-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411658		3979-000-035-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411659		3979-000-034-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411660		3978-000-025-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411661		3978-000-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411662		3979-000-033-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411663		3979-000-032-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411664		3978-000-027-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411665		3978-000-028-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411666		3979-000-031-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411667		3979-000-030-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411668		3978-000-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411669		3978-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411670		3978-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411671		3978-000-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411672		3978-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411673		3978-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411674		3978-000-017-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411675		3978-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411676		3978-000-020-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411677		3978-000-019-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411678		022401-4-025-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411679		3978-000-008-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411680		3978-000-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411681		022401-4-027-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411682		022401-4-030-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411683		022401-4-031-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411684		022401-4-034-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411685		022401-4-035-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411686		022401-4-036-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411687		022401-4-026-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411688		022401-4-011-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411689		3980-000-075-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411690		3980-000-079-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411691		3980-000-076-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411692		022401-4-074-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411693		3980-000-074-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411694		3980-000-073-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411695		3980-000-072-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411696		3980-000-071-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411697		3980-000-070-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411698		3980-000-069-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411699		3980-000-068-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411700		3980-000-067-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411701		3980-000-066-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411702		3980-000-065-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411703		3980-000-064-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411704		3980-000-063-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411705		3980-000-062-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411706		3980-000-062-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411707		3980-000-061-0004	Yes - Day C	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411708		3980-000-060-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411709		3980-000-059-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411710		022401-4-012-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411711		022401-4-013-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411712		022401-4-014-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411713		022401-4-015-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411714		3978-000-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411715		3978-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411716		3978-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411717		3978-000-003-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411718		3978-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411719		3978-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411720		3978-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411721		3982-000-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411722		3982-000-016-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Non-Lead - Plastic	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Non-Lead - Plasti	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411723		3982-000-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Tap log 77	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap log 77	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411724		3982-000-018-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Plastic		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411725		022401-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411726		022401-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411727		022401-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411728		022401-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411729		022401-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411730		022401-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411731		022401-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411732		022401-4-078-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411743		022401-4-077-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411744		022401-4-077-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411745		022401-4-050-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411746		022401-4-009-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411747		3953-001-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411748		3953-002-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411749		3953-001-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411750		3953-002-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411751		3953-002-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411752		3953-001-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411753		3953-001-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411754		3953-002-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411755		3953-001-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411756		3953-002-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411757		3953-001-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411758		3953-002-006-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411759		3953-002-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411760		3953-001-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411761		3953-001-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411762		3953-002-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411763		3953-001-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411764		3953-002-009-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411765		3953-001-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411766		3953-002-011-0004	No	Not evaluated	Galvanized	No	Prior to 1982	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411767		3953-001-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411768		3953-002-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411769		3953-002-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411770		3953-001-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411771		3953-002-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411772		3953-001-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411773		3953-001-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411774		3953-002-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411775		3953-001-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411776		3953-002-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411777		3953-001-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411778		3953-005-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411779		3953-005-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411780		3953-002-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411781		3953-005-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411782		3953-002-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411783		3953-005-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	No			2016-2024		Non-Lead - Plastic		0.75	No	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411784		3953-002-018-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411785		3953-005-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log (1704.5)			2016-2024		Non-Lead - Plastic		0.75	Tap Log (1704.5)	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411786		3953-002-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 74	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Tap log 74	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411787		3953-005-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 81	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411788		3953-002-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	W131			2016-2024		Galvanized		0.75	W131	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411789		3953-005-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Copper		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411790		3953-002-021-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411791		3953-002-022-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411792		3953-002-023-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	W245	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W245	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411793		3953-002-024-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 76	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 76	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411794		3953-002-025-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411795		3953-002-026-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411796		3953-003-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411797		3953-002-027-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411798		3953-003-012-0001	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411799		3953-002-028-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411800		3953-003-011-0002	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411801		3953-002-029-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411802		3953-003-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411803		3953-002-030-0001	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411804		3953-003-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411805		3953-002-031-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411806		3953-003-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411807		3953-002-032-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411808		3953-003-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411809		3953-002-033-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411810		3953-003-006-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411811		3953-002-034-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411812		3953-003-005-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411813		3953-002-035-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411814		3953-003-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411815		3953-003-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411816		3953-002-036-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411817		3953-002-037-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411818		3953-003-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411819		3953-002-038-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411820		3953-003-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411821		3953-003-026-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411822		3953-004-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411823		3953-004-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411824		3953-003-025-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411825		3953-004-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411826		3953-003-024-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411827		3953-004-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411828		3953-003-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411829		3953-004-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411830		3953-003-022-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411831		3953-003-021-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411841		3953-003-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411842		3953-004-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411843		3953-003-015-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411844		3953-004-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411845		3953-003-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411846		3953-004-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411847		3953-004-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411848		3953-004-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411849		3953-004-016-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411850		3953-005-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411851		3953-005-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411852		3953-005-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411853		3952-004-001-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411854		3952-003-008-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411855		3952-003-007-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411856		3952-003-007-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411857		3952-003-006-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411858		3952-003-005-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411859		3952-003-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3090			2016-2024		Non-Lead - Copper		0.75	BEDA 3090	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411860		3952-003-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3771 (FM)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3771 (FM)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411861		3952-003-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411862		3952-001-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411863		3952-001-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411864		3952-001-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411865		3952-001-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411866		3952-001-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411867		3952-001-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411868		3952-001-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411869		3952-001-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411870		3952-001-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411871		3952-001-010-0008	No	Not evaluated	Galvanized	No	Prior to 1986	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411872		3952-001-011-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411873		3952-001-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 Pg 48			2016-2024		Galvanized		0.75	Book 5 Pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411874		3952-001-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 19 Pg 38	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 Pg 38	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411875		3952-001-014-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2752	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2752	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411876		3952-001-015-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074			2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411877		3952-002-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411878		3952-002-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3090			2016-2024		Galvanized		0.75	BEDA 3090	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411879		3952-002-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411880		3952-002-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411881		3952-002-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411882		3952-002-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411883		3952-002-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411884		3952-002-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411885		3952-002-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411886		3952-002-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411887		3952-002-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2080	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2080	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411888		3952-002-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060			2016-2024		Galvanized		0.75	BEDA 2060	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411889		3952-004-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411890		3952-004-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411891		3952-002-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411892		3952-004-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411893		3952-002-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411894		3952-004-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411895		3952-002-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411896		3952-004-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411897		3952-002-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411898		3952-004-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411899		3952-002-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411900		3952-004-007-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411901		3952-002-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411902		3952-004-008-0006	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411903		3952-004-009-0005	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411904		3952-004-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411905		3952-004-011-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411906		3952-004-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411907		3955-002-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411908		3955-002-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411909		3955-001-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411910		3955-001-011-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411911		3955-002-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411912		3955-002-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411913		3955-001-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411914		3955-001-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411915		3955-002-001-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411916		3955-001-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411917		3955-001-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411918		112401-1-003-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411919		112401-1-012-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411920		112401-1-023-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411921		112401-1-024-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2411922		112401-1-025-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411923		112401-1-027-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411924		112401-1-028-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411925		112401-1-086-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411926		112401-1-086-2009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411927		112401-1-087-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411928		112401-1-042-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411929		112401-1-040-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411930		112401-1-040-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremS

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			litional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2411939		3965-000-183-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411940		3965-000-183-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411941		3965-000-141-0106	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411942		3965-000-142-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411943		3965-000-142-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411944		3965-000-143-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411945		3965-000-144-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411946		3965-000-145-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411947		3965-000-146-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411948		3965-000-147-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411949		3965-000-147-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411950		3965-000-148-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411951		3965-000-149-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411952		3965-000-150-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411953		3965-000-150-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411954		3965-000-150-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411955		112401-1-083-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>			2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411956		112401-1-051-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411957		112401-1-041-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411958		112401-1-043-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411959		112401-1-044-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411960		112401-1-051-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411961		112401-1-045-2009	No	Not evaluated	UNK	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411962		112401-1-046-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411963		112401-1-047-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411964		112401-1-048-2006	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411965		112401-1-049-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2411966		112401-1-050-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411967		112401-1-053-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411968		112401-1-055-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411969		112401-1-027-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411970		112401-1-058-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411971		112401-1-059-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411972		112401-1-026-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411973		112401-1-062-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411974		112401-1-102-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2411975		112401-1-095-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411976		112401-1-094-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411977		112401-1-065-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411978		112401-1-085-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411979		112401-1-016-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411980		112401-1-066-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411981		112401-1-068-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411982		112401-1-072-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411983		112401-1-097-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411984		112401-1-010-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411985		112401-1-008-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2081	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2081	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411986		112401-1-005-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5486	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 5486	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411987		112401-1-006-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2080	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2080	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411988		112401-1-092-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411989		112401-1-007-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411990		112401-1-091-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411991		112401-1-091-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411992		112401-1-090-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411993		112401-1-076-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411994		3954-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411995		3954-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411996		3954-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Plastic		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411997		3954-000-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	W131	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W131	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411998		3954-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2411999		3954-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412000		3954-000-007-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412001		3954-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412002		3954-000-009-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412003		3954-000-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412004		3954-000-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412005		3954-000-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412006		3954-000-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412007		3954-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412008		4585-000-007-0305	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412009		4585-000-007-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412010		4585-000-007-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412011		3944-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412012		3944-000-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412013		3954-000-015-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412014		3944-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412015		3944-000-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412016		3954-000-016-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412017		3954-000-027-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Replaced	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Replaced	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412018		3954-000-026-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412019		3954-000-017-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412020		3954-000-025-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412021		3954-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412022		3954-000-019-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412023		3954-000-024-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412024		3954-000-023-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412025		3954-000-020-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412026		3954-000-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412027		3954-000-022-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	No service			2016-2024		<Null>		0.75	No service	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412028		3954-000-034-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412029		3954-000-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter p

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412037		3954-000-029-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412038		3954-000-028-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	W131			2016-2024		Non-Lead - Plastic		0.75	W131	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412039		3944-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412040		3944-000-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81			2016-2024		Non-Lead - Copper		0.75	Tap log 81	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412041		3944-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W292	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	W292	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412042		3944-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412043		3954-000-039-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412044		3944-000-009-0004	No	Not evaluated	Non-Lead - Copper	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412045		3954-000-040-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412046		3954-000-041-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412047		3954-000-042-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412048		3954-000-043-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412049		3954-000-044-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412050		3954-000-045-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412051		112401-1-075-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412052		112401-1-096-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412053		112401-1-071-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412054		112401-1-067-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412055		112401-1-064-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412056		112401-1-063-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412057		112401-1-098-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412058		112401-1-060-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412059		112401-1-057-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412060		112401-1-056-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412061		112401-1-054-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412062		112401-1-103-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412063		112401-1-103-2008	Yes - Schoo	Not evaluated	Non-Lead - Other	No		4.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Other		4.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412064		112401-1-080-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412065		112401-1-084-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412066		3965-001-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412067		3965-001-001-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412068		3965-001-001-0509	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412069		8011-000-001-0009	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412070		8011-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412071		8011-000-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412072		8011-000-004-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412073		8011-000-005-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412074		8011-000-006-0103	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412075		8011-000-000-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412076		8011-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412077		8011-000-009-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412078		3965-001-001-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412079		3965-001-001-0400	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412080		3965-001-001-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412081		4585-000-007-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412082		4585-000-007-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412083		3965-001-001-0806	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412084		3965-001-001-0608	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412085		3965-001-001-1002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412086		3965-001-001-0905	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412087		3965-001-001-0707	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412088		3965-001-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412089		3948-000-031-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412090		3948-000-030-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412091		3948-000-029-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412092		3948-000-028-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412093		3948-000-027-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412094		3948-000-026-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412095		3948-000-025-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412096		3948-000-024-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412097		3948-000-023-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412098		3948-000-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412099		3948-000-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412100		3948-000-020-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412101		3948-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412102		3948-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412103		3948-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412104		3948-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412105		3948-000-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412106		3948-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412107		3948-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412108		3948-000-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412109		3948-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		1.50	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		1.50	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412110		3948-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412111		4585-000-002-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412112		4585-000-002-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412113		3948-000-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412114		3948-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412115		3948-000-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412116		3948-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412117		3948-000-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412118		3948-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412119		3948-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412120		3948-000-001-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412121		3948-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412122		4585-000-008-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412123		4585-000-008-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412124		4585-000-008-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412125		5372-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412126		5372-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412135		3965-000-012-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412136		3965-000-005-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412137		3965-000-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412138		3965-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412139		3965-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		<Null>		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412140		3965-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412141		3965-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412142		3965-000-012-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412143		3965-000-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412144		3965-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412145		3965-000-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412146		3965-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412147		3965-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412148		3965-000-010-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412149		3965-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412150		5372-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412151		4585-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412152		4585-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412153		4585-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412154		4585-000-011-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412155		4585-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412156		4585-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412157		4585-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412158		4585-000-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412159		3965-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412160		3965-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412161		3964-000-067-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412162		4585-000-010-0300	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412163		4585-000-010-1001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412164		4585-000-010-1100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412165		4585-000-010-1209	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412166		4585-000-010-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412167		4585-000-010-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412168		4585-000-010-1704	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412169		4585-000-010-1506	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412170		4585-000-010-1605	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412171		4585-000-010-1407	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412172		4585-000-010-1407	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412173		4585-000-010-0607	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412174		4585-000-010-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412175		4585-000-010-0706	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412176		4585-000-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412177		4585-000-011-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412178		4585-000-011-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412179		4585-000-012-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412180		4585-000-012-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412181		4585-000-012-0902	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412182		4585-000-013-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412183		8022-004-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412184		8022-004-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412185		8022-004-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412186		8022-004-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412187		8022-004-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412188		4585-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412189		4585-000-013-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412190		4585-000-002-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412191		4585-000-002-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412192		4585-000-002-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412193		4585-000-002-0409	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412194		4585-000-002-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412195		4585-000-015-0107	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412196		4585-000-015-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412197		4585-000-015-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412198		4585-000-015-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412199		4585-000-015-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412200		5462-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412201		5462-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412202		5462-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412203		5462-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412204		5462-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412205		5462-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412206		5462-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412207		5462-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412208		5462-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412209		8015-000-000-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412210		8015-000-000-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412211		8015-000-000-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412212		8015-000-000-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412213		8015-000-000-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412214		4585-000-016-0502	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412215		4585-000-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412216		4585-000-016-0700	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412217		4585-000-016-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412218		4585-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412219		3980-000-077-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412220		3980-000-077-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412221		3980-000-078-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412222		022401-4-055-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412223		022401-4-047-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412224		022401-4-037-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412233		022401-4-045-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412234		022401-4-033-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412235		022401-4-032-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412236		022401-4-029-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412237		022401-4-028-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412238		022401-4-020-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412239		022401-4-020-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412240		022401-4-021-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412241		022401-4-022-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412242		022401-4-054-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412243		022401-4-019-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412244		022401-4-017-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412245		022401-4-016-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412246		022401-4-070-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412247		022401-4-048-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412248		4631-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412249		4631-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412250		4631-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412251		4631-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412252		4631-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412253		4631-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412254		4631-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412255		4631-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412256		4631-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412257		4631-000-044-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412258		4631-000-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412259		4631-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412260		4631-000-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412261		4631-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412262		4631-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412263		4631-000-017-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412264		4631-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412265		4631-000-047-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412266		4631-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412267		4631-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412268		4631-000-048-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412269		4631-000-049-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412270		4631-000-021-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412271		4631-000-021-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412272		4631-000-022-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412273		4631-000-023-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412274		4631-000-024-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412275		4631-000-025-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412276		4631-000-050-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412277		4631-000-051-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412278		4631-000-026-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412279		4631-000-027-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit/abandon		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit/al	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412280		4631-000-028-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412281		4631-000-028-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412282		4631-000-052-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412283		4631-000-030-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412284		4631-000-031-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412285		4631-000-043-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412286		4631-000-032-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412287		4631-000-033-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412288		4631-000-034-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412289		4631-000-035-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412290		4631-000-036-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412291		4631-000-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412292		4631-000-038-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412293		4631-000-039-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412294		4631-000-040-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412295		4631-000-041-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412296		4631-000-042-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412297		5238-000-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412298		5238-000-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412299		5238-000-025-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412300		5238-000-026-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412301		5238-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412302		5238-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412303		5238-000-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412304		5238-000-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412305		5238-000-032-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412306		5238-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412307		5238-000-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412308		5238-000-035-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412309		5238-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412310		5238-000-037-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412311		5238-000-038-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412312		5238-000-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412313		5238-000-041-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412314		5238-000-042-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412315		5238-000-043-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412316		5238-000-044-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412317		5238-000-045-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412318		5238-000-046-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412319		5238-000-047-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412320		5238-000-048-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412321		5238-000-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412322		5238-000-050-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412331		5238-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412332		5238-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412333		5238-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412334		5238-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412335		5238-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412336		5238-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412337		5238-000-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412338		5238-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412339		5238-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412340		5238-000-015-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412341		5238-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412342		5238-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412343		5238-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412344		5238-000-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412345		5238-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412346		5238-000-021-0404	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412347		5238-000-022-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412348		4688-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412349		4688-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412350		4688-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412351		4688-000-004-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412352		4688-000-005-0006	No	Not evaluated	UNK	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412353		4688-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412354		4688-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412355		4688-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412356		4688-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412357		4688-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412358		4688-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412359		4688-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412360		4688-000-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412361		4688-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412362		4688-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412363		4688-000-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412364		4688-000-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412365		4688-000-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412366		4688-000-020-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412367		4688-000-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412368		4688-000-022-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412369		4688-000-023-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412370		4688-000-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412371		4688-000-025-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412372		4688-000-026-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412373		4688-000-027-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412374		4688-000-028-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412375		4688-000-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412376		4688-000-030-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412377		022401-1-021-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412378		022401-1-019-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412379		022401-1-018-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412380		022401-1-020-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412381		4604-002-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412382		4688-000-031-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412383		4688-000-032-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412384		4688-000-033-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412385		4604-002-016-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412386		4604-002-015-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412387		4688-000-034-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412388		4688-000-035-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412389		4604-002-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412390		4604-002-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412391		4688-000-036-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412392		4688-000-037-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412393		4604-002-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412394		4604-002-011-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412395		4688-000-038-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412396		4688-000-039-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412397		4604-002-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412398		4688-000-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412399		4604-001-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412400		4604-001-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412401		4604-002-009-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412402		4604-001-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412403		4604-001-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412404		4604-001-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412405		4604-001-009-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412406		4604-002-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412407		4604-002-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412408		4604-001-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412409		4604-001-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412410		4604-002-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412411		4604-001-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412412		4604-002-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412413		4604-002-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412414		4604-001-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412415		4604-002-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412416		4604-001-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412417		4604-001-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412418		4604-002-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412419		4604-001-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412429		5235-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412430		5235-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412431		5235-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412432		5235-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412433		022401-1-012-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412434		022401-1-011-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412435		022401-1-010-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412436		022401-1-009-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412437		022401-1-104-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412438		022401-1-006-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412439		022401-1-066-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412440		022401-1-066-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412441		022401-1-005-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412442		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412443		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412444		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412445		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412446		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412447		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412448		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412449		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412450		022401-1-004-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412451		022401-1-003-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412452		022401-1-088-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2187	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2187	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412453		022401-1-087-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412454		022401-1-083-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412455		022401-1-083-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412456		352501-2-009-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412457		352501-2-050-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412458		352501-2-063-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412459		352501-2-062-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412460		352501-2-061-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412461		352501-2-106-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412462		352501-2-105-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412463		352501-2-105-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412464		352501-2-103-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412465		5217-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412466		5217-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412467		5217-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412468		5217-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412469		5217-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412470		5217-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412471		352501-2-047-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412472		5217-000-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412473		5217-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412474		5217-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412475		5217-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412476		5217-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412477		5217-000-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412478		5217-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412479		5217-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412480		5217-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412481		5217-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412482		5217-000-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412483		5217-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412484		352501-2-001-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412485		5217-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412486		352501-2-067-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412487		352501-2-066-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412488		352501-2-065-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412489		4969-000-037-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412490		4969-000-038-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412491		4969-000-022-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412492		4969-000-023-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412493		4969-000-035-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412494		4969-000-034-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412495		4969-000-033-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412496		4969-000-033-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412497		4969-000-033-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412498		4968-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412499		4968-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412500		4968-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412501		4969-000-031-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412502		4969-000-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412503		4969-000-028-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412504		4969-000-026-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412505		4969-000-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412506		4969-000-020-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412507		4969-000-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412508		4969-000-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412509		4969-000-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412510		4969-000-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412511		4969-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412512		4969-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412513		4968-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412514		4968-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412515		4968-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412516		4969-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412517		4969-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412518		4969-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the me

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412527		4969-000-002-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412528		4934-000-058-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412529		4934-000-046-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412530		4934-000-045-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412531		4934-000-044-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412532		4934-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412533		4934-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412534		4934-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412535		4934-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412536		4934-000-043-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412537		4934-000-043-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412538		4934-000-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412539		4934-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412540		4934-000-041-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412541		4934-000-040-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412542		4934-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412543		4934-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412544		4934-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412545		4934-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412546		4934-000-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412547		4934-000-038-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412548		4934-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412549		4934-000-013-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412550		4934-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412551		4934-000-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412552		4934-000-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412553		4934-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412554		4934-000-018-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412555		4934-000-037-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412556		4934-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412557		4934-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412558		4934-000-021-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412559		4934-000-022-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412560		4934-000-022-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412561		4934-000-025-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412562		4934-000-026-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412563		4934-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412564		4934-000-035-0002	No	Not evaluated	Non-Lead - Other	No		8.00	GIS Mains Year	Couldn't find		2016-2024		Unknown		8.00	GIS Mains Year	No	Couldn't find	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412565		4934-000-035-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412566		4934-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412567		4934-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412568		4934-000-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412569		4934-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412570		4934-000-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412571		4948-000-037-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412572		4934-000-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412573		4934-000-031-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412574		4934-000-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412575		4934-000-048-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412576		4934-000-047-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412577		4934-000-055-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412578		4934-000-055-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412579		4934-000-052-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412580		4934-000-052-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412581		4934-000-051-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412582		4934-000-051-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412583		4934-000-051-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412584		4934-000-051-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412585		4934-000-049-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412586		4934-000-049-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412587		4948-000-034-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412588		4948-000-033-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412589		4948-000-032-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412590		4948-000-038-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412591		4948-000-038-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412592		4948-000-031-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412593		4948-000-040-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412594		4948-000-041-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412595		4948-000-041-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412596		4948-000-043-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412597		4948-000-043-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412598		4948-000-029-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412599		4948-000-028-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412600		4948-000-027-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412601		4948-000-026-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412602		4948-000-044-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412603		4948-000-044-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412604		4948-000-045-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412605		4948-000-045-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412606		4948-000-046-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412607		4948-000-023-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412608		4948-000-022-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412609		4948-000-048-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412610		4948-000-048-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412611		4948-000-049-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412612		4948-000-050-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412613		4948-000-052-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412614		4948-000-052-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412615		4948-000-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412616		4948-000-020-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412625		4948-000-058-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412626		4948-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412627		4948-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412628		4948-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412629		4948-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412630		4948-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412631		4948-000-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Service line not in use/Abandon?		2016-2024		None		0.75	GIS Mains Year	No	Service line not in use/Abandon?	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412632		4948-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412633		4948-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412634		4948-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412635		4948-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412636		4948-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412637		4948-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412638		4948-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412639		4948-000-059-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412640		352501-3-055-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412641		352501-3-055-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412642		352501-3-076-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412643		352501-3-076-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412644		352501-3-076-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412645		352501-3-077-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412646		8522-000-033-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412647		8522-000-032-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412648		8522-000-031-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412649		8522-000-030-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412650		8522-000-030-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412651		8522-000-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412652		8522-000-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412653		8522-000-028-000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412654		8522-000-027-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412655		8522-000-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412656		8522-000-026-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412657		8522-000-024-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412658		8522-000-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412659		8522-000-022-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412660		8522-000-022-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412661		8522-000-020-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412662		8522-000-020-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412663		8522-000-019-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412664		8522-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412665		8522-000-017-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412666		8522-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412667		8522-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412668		8522-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412669		8522-000-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412670		8522-000-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412671		8522-000-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412672		352501-3-134-2115	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412673		8522-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412674		9000-009-557-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412675		9000-009-558-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412676		9000-009-699-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412677		8522-000-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412678		8522-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412679		8522-000-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412680		8522-000-003-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412681		8522-000-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412682		3962-000-016-0606	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412683		3962-000-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412684		3962-000-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412685		3962-000-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412686		3962-000-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412687		3962-000-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412688		3962-000-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412689		3962-000-011-0007	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412690		3962-000-011-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412691		3962-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412692		022401-2-005-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412693		3957-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412694		3957-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412695		3957-000-043-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412696		3957-000-045-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412697		3957-000-042-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412698		3957-000-041-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412699		3957-000-041-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412700		3957-000-041-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412701		3957-000-040-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412702		3957-000-040-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412703		3957-000-039-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412704		3957-000-039-0002	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412705		3957-000-036-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412706		3957-000-036-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412707		3957-000-047-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412708		3957-000-048-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412709		3957-000-035-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412710		3957-000-049-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412711		3957-000-050-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412712		3957-000-034-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412713		3957-000-033-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412723		3957-000-028-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412724		3957-000-027-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412725		3957-000-055-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412726		3957-000-056-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412727		3957-000-057-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412728		3957-000-058-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412729		3957-000-026-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412730		3957-000-025-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412731		3957-000-024-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412732		3957-000-023-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412733		3957-000-021-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412734		3957-000-021-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412735		3957-000-021-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412736		3957-000-020-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412737		3957-000-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412738		3957-000-018-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412739		3957-000-018-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412740		3957-000-059-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412741		3957-000-061-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412742		3957-000-062-0002	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412743		3957-000-063-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412744		3957-000-064-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412745		3957-000-065-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412746		3957-000-066-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412747		3957-000-067-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412748		3957-000-068-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412749		3957-000-069-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412750		3957-000-044-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412751		3957-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412752		3957-000-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412753		3957-000-005-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412754		3957-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412755		3957-000-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412756		3957-000-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412757		3957-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412758		3957-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412759		3957-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412760		3957-000-013-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412761		3957-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412762		3957-000-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412763		3957-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412764		3958-000-028-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412765		3958-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412766		3958-000-029-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412767		3958-000-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412768		3958-000-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412769		3958-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412770		3958-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412771		3958-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412772		3958-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412773		3958-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412774		3958-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412775		3958-000-031-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412776		3958-000-032-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412777		3958-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412778		3958-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412779		3958-000-033-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412780		3958-000-034-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412781		3958-000-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412782		3958-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412783		3958-000-035-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412784		3958-000-036-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412785		3958-000-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412786		3958-000-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412787		3958-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412788		3958-000-016-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412789		3958-000-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412790		3958-000-037-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412791		3958-000-038-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412792		3958-000-039-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412793		3958-000-040-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412794		3958-000-041-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412795		3958-000-042-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412796		3958-000-027-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412797		3958-000-026-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412798		3958-000-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412799		3958-000-024-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412800		3958-000-023-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412801		3958-000-022-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412802		3958-000-021-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412803		3958-000-020-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412804		3958-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412805		3958-000-018-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412806		022401-3-082-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412807		022401-3-066-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412808		022401-3-066-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	C		2016-2024		Galvanized		0.75	GIS Mains Year	No	C	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412809		022401-3-079-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412810		022401-3-046-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412811		022401-3-163-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412821		022401-3-051-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412822		022401-3-054-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412823		3991-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412824		3991-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412825		3991-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412826		3991-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412827		3991-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412828		3991-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412829		3991-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412830		022401-3-056-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412831		022401-3-057-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412832		022401-3-058-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412833		022401-3-067-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412834		022401-3-099-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412835		022401-3-100-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412836		022401-3-101-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412837		022401-3-097-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412838		022401-3-098-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412839		022401-3-062-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412840		022401-3-070-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412841		022401-3-071-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412842		8100-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412843		8100-000-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412844		8100-000-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412845		8100-000-031-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412846		8100-000-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412847		8100-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412848		8100-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412849		8100-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412850		8100-000-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412851		8100-000-032-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412852		8100-000-033-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412853		8100-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412854		8100-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412855		8100-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412856		8100-000-034-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412857		8100-000-034-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412858		8100-000-017-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412859		8100-000-018-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412860		8100-000-019-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412861		8100-000-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412862		8100-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412863		8100-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412864		8100-000-036-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412865		8100-000-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412866		8100-000-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412867		8100-000-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412868		8100-000-026-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412869		8100-000-028-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412870		8100-000-028-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412871		8100-000-028-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412872		8100-000-028-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412873		8100-000-039-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412874		8100-000-040-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412875		8100-000-029-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412876		8100-000-030-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412877		8100-000-000-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412878		8100-000-000-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412879		8100-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412880		8100-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412881		8100-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412882		8100-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412883		8100-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412884		8100-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412885		022401-3-064-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412886		5312-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412887		5312-000-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412888		5312-000-023-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412889		5312-000-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412890		5312-000-017-0003	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		<Null>		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412891		5312-000-017-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412892		5312-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412893		5312-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412894		5312-000-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412895		5312-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412896		5312-000-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412897		5312-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412898		5312-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412899		5312-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412900		5312-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412901		5312-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412902		5312-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412903		5312-000-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412904		5312-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412905		5312-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412906		5312-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412907		5312-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412908		5312-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2412919		3959-000-020-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412920		3959-000-021-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412921		3959-000-022-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412922		3959-000-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412923		3959-000-024-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412924		3959-000-025-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412925		3959-000-026-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412926		3959-000-036-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412927		3959-000-035-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412928		3959-000-027-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412929		3959-000-034-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412930		3959-000-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412931		3959-000-029-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412932		3959-000-030-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412933		3959-000-031-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412934		3959-000-031-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412935		3959-000-032-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412936		3959-000-033-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412937		3959-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412938		3959-000-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412939		3959-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412940		3959-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412941		3959-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412942		3959-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412943		3959-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412944		3959-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412945		3959-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412946		5076-000-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412947		5076-000-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412948		5076-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412949		5076-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412950		5076-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412951		5076-000-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Abandon(couldn't find)		2016-2024		Unknown		0.75	GIS Mains Year	No	Abandon(couldn't find)	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412952		5076-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412953		5076-000-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412954		5076-000-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412955		5076-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412956		5076-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412957		5076-000-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412958		5076-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412959		5076-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412960		5076-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412961		5076-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412962		5076-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412963		5076-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412964		5076-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412965		5076-000-024-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412966		5076-000-023-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412967		5076-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412968		5076-000-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412969		3959-000-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412970		3959-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412971		3959-000-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412972		3959-000-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412973		3959-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412974		5076-000-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412975		5076-000-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412976		5076-000-025-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412977		3959-000-015-0008	No	Not evaluated	Non-Lead - Other	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Other		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2412978		3959-000-017-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412979		4512-001-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412980		4512-002-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412981		4512-001-004-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412982		4512-002-002-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412983		4512-001-003-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2412984		4512-002-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412985		4512-001-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412986		4512-003-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412987		4512-003-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412988		4512-003-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412989		4512-003-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412990		4512-003-011-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412991		4512-003-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412992		4512-003-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412993		4512-002-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412994		4512-003-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412995		4512-003-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412996		4512-003-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412997		4512-003-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2412998		022401-3-002-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2412999		022401-3-002-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413000		032401-4-004-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413001		032401-4-004-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413002		032401-4-025-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413003		032401-4-018-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413004		8132-000-369-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413005		8132-000-369-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413006		8132-000-359-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413007		8132-000-359-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413008		8132-000-357-0003	No	Not evaluated	Non-Lead - Copper	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413017		022401-3-122-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413018		022401-3-135-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413019		022401-3-135-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413020		022401-3-136-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413021		022401-3-138-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413022		022401-3-157-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413023		022401-3-017-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413024		022401-3-018-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413025		022401-3-020-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413026		022401-3-140-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413027		022401-3-140-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413028		022401-3-140-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413029		022401-3-111-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413030		022401-3-111-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413031		022401-3-111-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413032		022401-3-139-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413033		022401-3-139-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413034		022401-3-085-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413035		022401-3-084-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413036		8147-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413037		8147-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413038		8147-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413039		8147-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413040		8147-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413041		022401-3-031-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413042		8147-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413043		8147-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413044		8147-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413045		022401-3-065-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413046		022401-3-065-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413047		8147-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413048		8147-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413049		8147-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413050		8147-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413051		8147-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413052		8147-000-014-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413053		8147-000-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Abandon service		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Abandon service	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413054		8147-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		<Null>		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413055		8147-000-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413056		8147-000-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413057		022401-3-065-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413058		022401-3-065-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413059		022401-3-038-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413060		022401-3-077-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413061		022401-3-039-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413062		4557-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413063		4557-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413064		4557-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413065		4557-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413066		4557-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413067		4557-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413068		4557-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413069		4557-000-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413070		022401-3-069-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413071		022401-3-035-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413072		022401-3-034-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413073		022401-3-037-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413074		022401-3-037-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413075		022401-3-037-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413076		022401-3-128-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413077		022401-3-128-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413078		022401-3-128-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413079		022401-3-128-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413080		8059-000-000-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413081		112401-2-103-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413082		112401-2-057-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413083		112401-2-013-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413084		112401-2-013-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413085		112401-2-007-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413086		112401-2-007-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413087		112401-2-130-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413088		112401-2-129-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413089		112401-2-128-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413090		022401-3-129-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413091		022401-3-129-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413092		022401-3-029-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413093		022401-3-029-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413094		022401-3-029-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413095		022401-3-141-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413096		022401-3-023-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413097		022401-3-169-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413098		022401-3-030-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413099		112401-2-062-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413100		112401-2-083-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413101		112401-2-187-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413102		112401-2-055-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413103		112401-2-054-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413104		112401-2-078-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413105		3993-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413115		3993-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413116		3993-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413117		3993-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413118		3993-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413119		3993-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413120		3993-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413121		3993-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413122		3993-000-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413123		3993-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413124		3993-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413125		3993-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413126		112401-2-046-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413127		112401-2-045-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413128		112401-2-088-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413129		112401-2-087-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413130		112401-2-048-2004	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413131		112401-2-048-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413132		112401-2-048-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413133		112401-2-047-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413134		112401-2-043-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413135		112401-2-044-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413136		112401-2-030-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413137		112401-2-149-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413138		112401-2-149-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413139		112401-2-149-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413140		112401-2-148-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413141		112401-2-035-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413142		112401-2-036-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413143		112401-2-036-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413144		5410-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413145		3964-000-023-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413146		5410-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413147		5410-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413148		5410-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413149		5410-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413150		112401-2-038-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413151		112401-2-039-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413152		3995-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413153		3995-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413154		3995-000-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413155		3995-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413156		3995-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413157		3995-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413158		3995-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413159		3995-000-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413160		112401-2-168-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413161		112401-2-051-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413162		112401-2-169-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413163		112401-2-169-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413164		112401-2-063-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413165		112401-2-063-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413166		112401-2-064-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413167		112401-2-084-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413168		112401-2-065-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413169		112401-2-069-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413170		112401-2-069-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413171		112401-2-081-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413172		112401-2-081-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413173		112401-2-068-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413174		112401-2-068-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413175		112401-2-105-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413176		112401-2-105-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413177		112401-2-104-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413178		112401-2-104-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413179		112401-2-070-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413180		112401-2-096-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413181		112401-2-099-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413182		112401-2-098-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown	Yes		
BremSLI-2413183		112401-2-098-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413184		112401-2-072-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413185		112401-2-072-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413186		112401-2-173-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413187		3969-000-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413188		3969-000-022-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413189		3969-000-020-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413190		3969-000-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413191		3969-000-024-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413192		3969-000-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413193		3969-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413194		3969-000-025-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413195		3969-000-026-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413196		3969-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413197		3969-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413198		3969-000-015-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413199		3969-000-014-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413200		3969-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413201		3969-000-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413202		3969-000-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413203		3969-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSL

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413213		3969-000-032-0005	No	Not evaluated	Galvanized	No	Prior to 1983	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413214		3969-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413215		3969-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413216		3969-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413217		3969-000-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413218		3969-000-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413219		3969-000-035-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413220		3969-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413221		112401-2-095-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413222		112401-2-095-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413223		112401-2-015-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413224		112401-2-021-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413225		112401-2-021-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413226		112401-2-019-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413227		112401-2-017-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413228		3964-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413229		3964-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413230		3964-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413231		3964-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413232		3964-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413233		3964-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413234		3964-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413235		3964-000-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413236		3964-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413237		3964-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413238		3964-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413239		3964-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413240		3964-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413241		3964-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413242		3964-000-021-0003	No	Not evaluated	Non-Lead - Copper	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413243		3964-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413244		3964-000-038-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413245		3964-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413246		3964-000-025-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413247		3964-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413248		3964-000-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413249		3964-000-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413250		3964-000-039-0003	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413251		3964-000-040-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413252		3964-000-027-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413253		3964-000-028-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413254		3964-000-028-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413255		3964-000-029-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413256		3964-000-069-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413257		3964-000-069-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413258		3964-000-070-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413259		3964-000-031-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413260		3964-000-031-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413261		3964-000-072-0308	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413262		3964-000-072-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413263		3964-000-072-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413264		3964-000-073-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413265		3964-000-073-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413266		3964-000-073-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413267		3964-000-032-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413268		3964-000-033-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413269		3964-000-033-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413270		3964-000-074-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413271		3964-000-075-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413272		3964-000-034-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413273		3964-000-035-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413274		3964-000-036-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413275		3964-000-055-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	No meter		2016-2024		<Null>		0.75	GIS Mains Year	No	No meter	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413276		3964-000-055-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413277		3964-000-055-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413278		3964-000-055-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413279		3964-000-037-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413280		3964-000-041-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413281		3964-000-042-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413282		3964-000-043-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413283		3964-000-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413284		3964-000-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413285		3964-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413286		3964-000-044-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413287		3964-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413288		3964-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413289		3964-000-045-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413290		3964-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413291		3964-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413292		3964-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413293		3964-000-018-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413294		3964-000-061-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413295		3964-000-061-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 2050	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413296		3964-000-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413297		3964-000-020-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	FC	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413298		3964-000-062-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413299		3964-000-063-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413300		3964-000-064-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413301		3964-000-065-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413302		3964-000-065-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413303		3964-000-065-0000	No	Not evaluated	Non-Lead - Plastic	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413311		3964-000-046-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413312		3964-000-047-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413313		3964-000-047-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413314		3964-000-048-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413315		3964-000-048-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413316		3964-000-048-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413317		3964-000-049-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413318		3964-000-049-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413319		3964-000-050-0007	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413320		3964-000-051-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413321		3964-000-052-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413322		3964-000-052-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413323		3964-000-052-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413324		3964-000-126-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413325		3964-000-098-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413326		3964-000-099-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413327		3964-000-100-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413328		3964-000-101-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413329		3964-000-102-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413330		3964-000-103-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413331		3964-000-104-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413332		3964-000-105-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413333		3964-000-096-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413334		3964-000-097-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413335		3964-000-097-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413336		3964-000-097-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413337		3964-000-097-0408	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413338		3964-000-097-0408	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413339		3964-000-097-0408	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413340		3964-000-097-0408	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413341		3964-000-127-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413342		3964-000-127-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413343		3964-000-076-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413344		3964-000-076-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413345		3964-000-077-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413346		3964-000-078-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413347		3964-000-078-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413348		3964-000-079-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413349		3964-000-080-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413350		3964-000-081-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413351		3964-000-082-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413352		3964-000-083-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413353		3964-000-083-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413354		3964-000-083-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413355		3964-000-085-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413356		3964-000-086-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413357		8168-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413358		3964-000-088-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413359		3964-000-089-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413360		3964-000-089-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413361		3964-000-090-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413362		3964-000-090-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413363		3964-000-091-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	C		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	C	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413364		3964-000-091-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413365		3964-000-092-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413366		3964-000-092-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413367		3964-000-093-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413368		3965-000-033-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413369		3965-000-032-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413370		3965-000-031-0000	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413371		3965-000-028-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413372		3965-000-026-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413373		3965-000-027-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413374		3965-000-028-0203	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413375		3965-000-028-0203	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413376		3965-000-036-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413377		3965-000-039-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413378		3965-000-038-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413379		3965-000-038-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413380		3965-000-038-0003	Yes - Schoo	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413381		3965-000-038-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413382		3965-000-040-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413383		3965-000-035-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413384		3965-000-035-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413385		3965-000-034-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413386		3965-000-041-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413387		3965-000-041-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413388		3965-000-042-0403	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413389		3965-000-042-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413390		3965-000-042-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413391		3965-000-043-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413392		3965-000-043-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413393		3965-000-044-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413394		3965-000-044-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Work			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413395		3965-000-045-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413396		3965-000-057-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413397		3965-000-056-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413398		3965-000-045-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413399		3965-000-046-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413400		3965-000-048-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413401		3965-000-048-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413409		3965-000-055-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413410		3965-000-054-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413411		3965-000-052-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413412		3965-000-053-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413413		3965-000-058-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413414		3965-000-059-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413415		3965-000-060-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413416		3965-000-060-0202	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413417		3965-000-060-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413418		3965-000-061-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413419		3965-000-064-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413420		3965-000-064-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413421		3965-000-064-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413422		3965-000-065-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413423		3965-000-065-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413424		3965-000-077-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413425		3965-000-076-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413426		3965-000-075-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413427		3965-000-081-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413428		3965-000-080-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413429		3965-000-080-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413430		3965-000-079-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413431		3965-000-079-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413432		3965-000-079-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413433		3965-000-078-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413434		3965-000-084-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413435		3965-000-085-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413436		3965-000-086-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413437		3965-000-087-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413438		3965-000-088-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413439		3965-000-066-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413440		3965-000-089-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413441		3965-000-089-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413442		3965-000-090-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413443		3965-000-090-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413444		3965-000-091-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413445		3965-000-092-0006	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413446		3965-000-092-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413447		3965-000-092-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413448		3965-000-093-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413449		3965-000-095-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413450		3965-000-096-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413451		3965-002-001-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413452		3965-002-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413453		3965-000-110-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413454		3965-000-111-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413455		3965-000-112-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413456		3965-000-113-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413457		3965-000-114-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413458		3965-000-114-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413459		3965-000-116-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413460		3965-000-117-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413461		3965-000-118-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413462		3965-000-119-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413463		3965-000-120-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413464		3965-000-122-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413465		3965-000-122-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413466		3965-000-123-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413467		3965-000-123-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413468		3965-000-125-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413469		3965-000-126-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413470		3965-000-127-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413471		3965-000-128-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413472		3965-000-129-0003	No	Not evaluated	Galvanized	No	Prior to 2029	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413473		3965-000-130-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413474		3965-000-130-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413475		3965-000-130-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413476		3965-000-133-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413477		3965-000-134-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413478		8001-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413479		8001-000-000-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413480		3965-000-105-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413481		3965-000-104-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413482		3965-000-103-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413483		3965-000-102-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413484		3965-000-102-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413485		3965-000-101-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413486		3965-000-100-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413487		3965-000-099-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413488		3965-000-098-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413489		3965-000-098-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413490		3965-000-097-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413491		3965-003-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413492		3965-000-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413493		3965-000-015-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413494		3965-000-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413495		3965-000-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413496		3965-000-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413497		3965-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413507		3965-000-025-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413508		112401-4-003-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413509		3964-000-120-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413510		3964-000-119-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413511		3964-000-118-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413512		112401-4-003-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413513		112401-4-003-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413514		3964-000-121-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413515		3964-000-117-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413516		8153-001-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413517		3964-000-122-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413518		3964-000-122-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413519		3964-000-122-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413520		3964-000-122-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413521		8153-003-002-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413522		8153-003-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413523		8153-003-001-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413524		8153-004-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413525		8153-004-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413526		8153-004-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413527		3964-000-123-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413528		8153-005-002-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413529		8153-005-002-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413530		8153-005-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413531		3964-000-124-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413532		3964-000-111-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413533		3964-000-110-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413534		3964-000-109-0008	No	Not evaluated	Galvanized	No	Prior to 1988	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413535		3964-000-107-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413536		3964-000-106-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413537		112401-2-156-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413538		112401-2-156-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413539		112401-2-143-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413540		112401-2-107-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413541		112401-2-108-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413542		112401-2-113-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413543		112401-2-114-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413544		112401-2-115-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413545		112401-2-112-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413546		112401-2-112-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413547		112401-2-012-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413548		4706-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413549		4706-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413550		4706-000-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413551		4706-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413552		4706-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413553		4706-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413554		4706-000-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413555		102401-1-002-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413556		102401-1-001-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413557		4715-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413558		4715-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413559		4715-000-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413560		112401-2-079-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413561		112401-2-029-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413562		112401-2-119-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413563		112401-2-118-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413564		5512-000-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413565		5512-000-014-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413566		5512-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413567		5512-000-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413568		5512-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413569		5512-000-010-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413570		5512-000-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413571		5512-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413572		5512-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413573		5512-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413574		5512-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413575		5512-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413576		5512-000-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413577		5512-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413578		022401-3-107-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413579		022401-3-103-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413580		022401-3-009-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413581		8004-003-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413582		8004-003-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413583		8004-003-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413584		8004-003-004-0009	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413585		8004-003-005-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413586		8004-003-000-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413587		8004-003-000-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413588		8004-003-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413589		8004-003-008-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413590		8004-003-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413591		8004-002-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413592		8004-002-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413593		8004-002-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413594		8004-002-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413595		8004-002-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413596		8004-004-000-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier				Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413605		022401-3-004-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413606		022401-3-004-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413607		022401-4-006-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413608		032401-4-008-2008	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413609		032401-4-021-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413610		032401-4-044-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413611		032401-4-044-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413612		032401-4-044-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413613		032401-4-038-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413614		032401-4-039-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413615		032401-4-039-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413616		032401-4-041-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413617		032401-4-041-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413618		032401-4-041-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413619		032401-4-009-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413620		032401-4-010-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413621		032401-4-011-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413622		032401-4-022-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413623		032401-4-014-2000	No	Not evaluated	Galvanized	No	Prior to 1985	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413624		032401-1-042-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413625		032401-1-071-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413626		032401-1-071-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413627		032401-1-041-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413628		032401-1-083-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413629		032401-1-083-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413630		032401-1-075-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413631		032401-1-075-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413632		032401-1-081-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413633		032401-1-081-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413634		032401-1-079-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413635		032401-1-082-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413636		032401-1-082-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413637		032401-1-082-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413638		032401-1-074-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413639		032401-1-074-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413640		032401-1-097-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413641		032401-1-097-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413642		032401-1-094-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413643		032401-1-094-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413644		032401-1-040-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413645		032401-1-040-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413646		032401-1-037-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413647		032401-1-034-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413648		032401-1-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413649		032401-1-064-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413650		032401-1-049-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413651		032401-1-049-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413652		032401-1-114-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413653		032401-1-031-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413654		032401-1-061-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413655		032401-1-066-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413656		032401-1-066-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413657		032401-1-091-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413658		032401-1-091-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413659		032401-1-091-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413660		032401-1-103-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413661		032401-1-086-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413662		032401-1-048-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413663		032401-1-047-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413664		032401-1-047-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413665		032401-1-045-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413666		032401-1-069-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413667		032401-1-053-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413668		032401-1-058-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413669		032401-1-059-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413670		032401-1-050-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413671		032401-1-054-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413672		032401-1-085-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413673		032401-1-106-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413674		032401-1-107-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413675		032401-1-088-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413676		032401-1-109-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413677		032401-1-109-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413678		032401-1-005-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413679		032401-1-004-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413680		032401-1-115-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413681		032401-1-003-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413682		032401-1-002-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413683		032401-1-001-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050			2016-2024		Galvanized		0.75	BEDA 2050	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413684		032401-1-062-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413685		5128-000-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413686		5128-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413687		5128-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413688		5128-000-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413689		5128-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413690		5128-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413691		5128-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413692		022401-2-018-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413693		022401-2-018-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413694		5128-000-009-0106	No	Not evaluated	Non-Lead - Plastic	No	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413703		3962-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413704		3962-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413705		3962-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413706		352501-3-135-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413707		352501-3-050-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413708		352501-3-053-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413709		352501-3-051-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413710		352501-3-052-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413711		352501-3-054-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413712		4483-000-024-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413713		4483-000-024-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413714		4483-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413715		4483-000-020-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413716		4483-000-019-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413717		4483-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413718		4483-000-018-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413719		4483-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413720		4483-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413721		4483-000-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413722		4483-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413723		4483-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413724		352501-3-059-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413725		352501-3-095-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413726		352501-3-140-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413727		352501-3-139-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413728		352501-3-131-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413729		352501-3-101-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413730		352501-3-061-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413731		352501-3-060-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413732		4483-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413733		4483-000-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413734		4483-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413735		4483-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413736		4483-000-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413737		4483-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413738		4483-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413739		4483-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413740		4483-000-009-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413741		4483-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413742		4483-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413743		4483-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413744		4483-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413745		352501-3-137-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413746		352501-3-152-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413747		352501-3-126-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413748		352501-3-040-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413749		352501-3-041-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413750		352501-3-038-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413751		352501-3-037-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413752		352501-3-033-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413753		352501-3-151-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413754		352501-3-115-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413755		352501-3-115-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413756		352501-3-115-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413757		352501-3-115-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413758		352501-3-026-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413759		352501-3-028-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413760		352501-3-148-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413761		352501-3-148-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413762		352501-3-113-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413763		352501-3-113-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413764		352501-3-030-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413765		352501-3-030-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413766		352501-3-121-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413767		352501-3-103-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413768		352501-3-109-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413769		352501-3-120-2004	No	Not evaluated	Galvanized	No	Prior to 2028	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413770		352501-3-102-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413771		352501-3-123-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413772		352501-3-117-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413773		352501-3-116-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413774		352501-3-122-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413775		352501-3-074-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413776		352501-3-005-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413777		352501-3-006-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413778		352501-3-009-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413779		352501-3-099-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413780		352501-3-096-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413781		352501-3-081-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413782		352501-3-085-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413783		352501-3-130-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413784		352501-3-066-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413785		352501-3-066-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413786		352501-3-064-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413787		352501-3-067-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413788		352501-3-067-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413789		352501-3-067-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413790		352501-3-067-2009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Resid

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413801		4452-003-009-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413802		4452-003-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413803		4452-002-008-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413804		4452-002-005-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413805		4452-002-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413806		4474-020-016-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Typ	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413807		4474-021-004-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413808		4474-021-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413809		4474-021-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413810		4474-021-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413811		4474-020-027-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413812		4474-022-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413813		4474-022-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413814		4474-022-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413815		4474-022-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413816		4474-022-029-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413817		4474-022-001-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413818		4474-022-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413819		4474-022-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413820		4474-019-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413821		4474-019-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413822		4474-019-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413823		4474-019-019-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413824		4474-019-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413825		4474-019-023-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413826		4474-019-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413827		4474-019-003-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413828		4474-019-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413829		4474-019-007-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413830		4474-019-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413831		4474-019-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413832		4474-019-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Tap log 78	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Tap log 78	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413833		4474-020-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413834		4474-020-004-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413835		4474-020-006-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413836		4474-020-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413837		4474-020-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413838		4474-020-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413839		4474-020-013-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413840		4452-002-001-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413841		4452-002-001-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413842		4452-002-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413843		4452-002-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413844		4452-002-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413845		4452-002-015-0004	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413846		4452-002-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413847		4452-005-015-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413848		4452-005-015-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413849		4452-005-007-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413850		4452-005-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413851		4452-005-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413852		4452-005-001-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413853		4452-006-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413854		342501-1-004-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413855		342501-1-132-2005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413856		352501-2-072-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413857		5043-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413858		5043-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413859		5043-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413860		5043-000-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413861		5043-000-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413862		5043-000-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413863		5043-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413864		5043-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413865		5043-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413866		5043-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413867		5043-000-006-0002	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413868		5043-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413869		5043-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413870		5043-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413871		5043-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413872		5043-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Typ	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413873		5043-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413874		352501-2-038-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413875		352501-2-089-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413876		352501-2-090-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413877		352501-2-091-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413878		352501-2-037-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413879		352501-2-082-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413880		352501-2-081-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413881		352501-2-080-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413882		352501-2-030-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413883		352501-2-054-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413884		352501-2-032-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413885		352501-2-101-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413886		352501-2-125-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413887		352501-2-007-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413888		352501-2-007-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413889		352501-2-051-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413890		352501-2-058-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413899		5442-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413900		5442-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413901		5442-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413902		5442-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413903		5442-000-030-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413904		5442-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413905		5442-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413906		5442-000-031-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413907		5442-000-033-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413908		5442-000-033-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413909		5442-000-034-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413910		5442-000-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413911		5442-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413912		5442-000-035-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413913		5442-000-036-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413914		5442-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413915		5442-000-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413916		5442-000-015-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413917		5442-000-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413918		5442-000-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413919		5442-000-018-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413920		5442-000-019-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413921		5442-000-019-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413922		5442-000-021-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413923		5442-000-022-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413924		5442-000-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413925		5442-000-024-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413926		5442-000-025-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413927		5442-000-027-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413928		5442-000-027-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413929		5442-000-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413930		5442-000-029-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413931		5387-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413932		5387-000-022-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413933		5387-000-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413934		5387-000-024-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413935		5387-000-025-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413936		5387-000-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413937		5387-000-020-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413938		5387-000-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413939		5387-000-027-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413940		5387-000-028-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413941		5387-000-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413942		5387-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413943		5387-000-017-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413944		5387-000-030-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413945		5387-000-031-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413946		5387-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413947		5387-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413948		5387-000-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413949		5387-000-032-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413950		5387-000-032-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2413951		5387-000-035-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413952		5387-000-035-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413953		5387-000-036-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413954		5387-000-037-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413955		5387-000-038-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413956		5387-000-039-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413957		5387-000-040-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413958		5387-000-041-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413959		5387-000-042-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413960		5387-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413961		5387-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413962		5387-000-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413963		5387-000-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413964		5387-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413965		5387-000-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413966		5387-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413967		5387-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413968		5387-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413969		5387-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413970		5387-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Asbuilt		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Asbuilt	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413971		5387-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413972		5387-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413973		352501-2-046-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413974		352501-2-046-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413975		352501-2-046-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413976		352501-2-046-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413977		352501-2-046-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413978		352501-2-019-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413979		352501-2-099-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413980		352501-2-019-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413981		352501-2-123-2003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413982		352501-2-017-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413983		352501-2-120-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413984		352501-2-121-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2413985		352501-2-122-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413986		352501-2-018-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413987		352501-2-018-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413988		352501-2-016-2003	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2413989		352501-2-016-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-L

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2413997		352501-2-108-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413998		352501-2-011-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2413999		352501-2-010-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414000		352501-2-010-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414001		5267-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414002		5267-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414003		5267-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414004		5267-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414005		5267-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414006		5267-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414007		5267-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414008		5267-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414009		5267-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414010		5267-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414011		5267-000-030-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414012		5267-000-030-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414013		5267-000-028-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414014		5267-000-027-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414015		5267-000-032-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414016		5267-000-024-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414017		5267-000-023-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414018		5267-000-022-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414019		5267-000-022-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414020		5267-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414021		5267-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414022		5267-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414023		5267-000-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414024		5267-000-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414025		5267-000-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414026		5267-000-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414027		5267-000-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414028		5267-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414029		5267-000-016-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414030		5442-000-037-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414031		5442-000-038-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414032		5442-000-039-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414033		5442-000-040-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414034		5442-000-041-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414035		5442-000-042-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414036		5442-000-043-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414037		5442-000-044-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414038		5442-000-045-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414039		5442-000-046-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414040		5442-000-046-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414041		5442-000-047-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414042		5442-000-048-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414043		5442-000-049-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414044		5442-000-050-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414045		5442-000-052-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414046		5442-000-052-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414047		5442-000-053-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414048		5442-000-054-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414049		5442-000-055-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414050		5442-000-056-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414051		5442-000-057-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414052		5442-000-058-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414053		5442-000-071-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	FC	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414054		5442-000-059-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414055		5442-000-060-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414056		5442-000-061-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414057		5442-000-062-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414058		5442-000-063-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414059		5442-000-064-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414060		5442-000-066-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414061		5442-000-066-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414062		262501-2-010-2000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414063		262501-2-010-2000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414064		262501-2-019-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414065		262501-2-009-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414066		262501-2-019-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414067		262501-2-019-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414068		262501-2-019-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414069		262501-2-019-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414070		262501-2-019-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414071		262501-2-019-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414072		262501-2-033-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414073		262501-2-032-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414074		262501-2-032-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414075		262501-2-032-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414076		262501-2-016-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414077		262501-2-016-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414078		262501-2-027-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414079		262501-2-029-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414080		262501-2-028-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414081		262501-2-026-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414082		262501-2-008-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414083		262501-2-008-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414084		262501-2-008-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414085		262501-2-008-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414086		262501-2-008-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414087		262501-2-008-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414095		5022-000-088-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414096		5022-000-087-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414097		5022-000-086-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414098		5022-000-085-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414099		5022-000-084-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414100		5022-000-084-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414101		5022-000-082-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414102		5022-000-081-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414103		5022-000-080-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414104		5022-000-079-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414105		5022-000-078-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414106		5022-000-075-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414107		5022-000-075-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414108		5022-000-074-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414109		5022-000-073-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414110		5022-000-071-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414111		5022-000-071-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414112		5022-000-068-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414113		5022-000-069-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414114		5022-000-067-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414115		5022-000-067-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414116		4982-000-031-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year/field			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year/fi	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414117		4982-000-030-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414118		4982-000-028-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414119		4982-000-028-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414120		4982-000-027-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414121		4982-000-026-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414122		4982-000-025-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414123		4982-000-024-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414124		4982-000-023-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year/ Fi	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year/ F	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414125		4982-000-022-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414126		4982-000-021-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414127		4982-000-020-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414128		4982-000-019-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414129		4982-000-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414130		4982-000-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414131		4982-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414132		4982-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414133		4982-000-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414134		4982-000-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414135		4982-000-010-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414136		4992-000-054-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414137		4992-000-052-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414138		4992-000-051-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414139		4992-000-051-0000	No	Not evaluated	Non-Lead - Other	No		4.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		4.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414140		4992-000-055-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414141		4992-000-056-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414142		4992-000-050-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414143		4992-000-049-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414144		4992-000-057-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414145		4992-000-058-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414146		4992-000-047-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414147		4992-000-047-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414148		4992-000-046-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414149		4992-000-045-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414150		4992-000-044-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414151		4992-000-043-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414152		4992-000-059-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414153		4992-000-059-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414154		4992-000-042-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414155		4992-000-041-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414156		4992-000-040-0004	Yes - Other	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414157		4992-000-039-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414158		4992-000-038-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414159		4992-000-037-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414160		4992-000-036-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414161		4992-000-061-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414162		4992-000-062-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414163		4992-000-035-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414164		4992-000-034-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414165		4992-000-063-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414166		4992-000-064-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414167		4992-000-033-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414168		4992-000-032-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414169		4992-000-065-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414170		4982-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414171		4982-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414172		4982-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414173		4982-000-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414174		4982-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414175		4982-000-004-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414176		4982-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414177		4982-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414178		4982-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414179		5026-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414180		5026-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414181		5026-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414182		5026-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	<Null>	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414183		5026-000-010-0007	No	Not evaluated	Non-Lead - Other	No		4.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		4.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414184		5026-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremS

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414193		5026-000-020-0005	No	Not evaluated	Galvanized	No	Prior to 1955	0.75				2016-2024	Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414194		5026-000-021-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414195		5026-000-022-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024	Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414196		5026-000-024-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00		Visual inspection at the meter pit		2016-2024	Galvanized		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414197		5026-000-024-0001	No	Not evaluated	Galvanized	No	Prior to 2030	0.75		Visual inspection at the meter pit		2016-2024	Galvanized		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414198		4444-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024	Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414199		4444-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414200		4444-000-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414201		4444-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414202		4444-000-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414203		4444-000-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414204		4444-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414205		4444-000-016-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414206		4444-000-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414207		4444-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414208		4444-000-018-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024	Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414209		4444-000-019-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414210		4444-000-020-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414211		4444-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414212		4444-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414213		4444-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414214		4444-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414215		4444-000-062-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414216		4444-000-061-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414217		4444-000-065-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414218		4444-000-059-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414219		4444-000-078-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414220		4444-000-077-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414221		4444-000-076-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414222		4444-000-075-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Abandon		2016-2024	Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Abandon	2016-2024		Non-lead	Possible	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414223		4444-000-058-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414224		4444-000-057-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414225		4444-000-056-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414226		4444-000-055-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414227		4444-000-055-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414228		4444-000-053-0002	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Copper		2.00	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414229		4444-000-052-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414230		4444-000-074-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414231		4444-000-074-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414232		4444-000-048-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024	Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414233		4444-000-048-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414234		4444-000-048-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414235		4444-000-047-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414236		4444-000-046-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414237		4444-000-072-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Unknown Type			2016-2024	Non-Lead - Plastic		1.00	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414238		4444-000-071-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414239		4444-000-071-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414240		4444-000-070-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414241		4444-000-044-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414242		4444-000-044-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414243		4444-000-069-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414244		4444-000-068-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414245		4444-000-067-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414246		4444-000-066-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414247		4444-000-021-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414248		4444-000-022-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414249		4444-000-023-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414250		4444-000-024-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414251		4444-000-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414252		4444-000-026-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414253		4444-000-027-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414254		4444-000-028-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414255		4444-000-029-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414256		4444-000-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414257		4493-000-190-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414258		4444-000-042-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414259		4444-000-032-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414260		4444-000-032-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414261		4444-000-032-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414262		4444-000-033-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414263		4444-000-034-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414264		4444-000-034-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414265		4444-000-040-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414266		4444-000-038-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414267		4444-000-037-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414268		4444-000-035-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414269		4444-000-035-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414270		4482-000-112-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414271		4482-000-111-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024	Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414272		4482-000-113-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414273		4482-000-114-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414274		4482-000-115-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414275		4482-000-110-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414276		4482-000-109-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414277		4482-000-116-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414278		4482-000-117-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414279		4482-000-108-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414280		4482-000-107-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414281		4493-000-167-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024	Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414282		4493-000-155-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414291		4493-000-162-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit/abandon		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit/al	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414292		4493-000-161-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414293		4493-000-184-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414294		4493-000-218-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414295		4493-000-185-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414296		4493-000-186-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414297		4493-000-217-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414298		4493-000-216-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414299		4493-000-214-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414300		4493-000-214-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414301		352501-2-104-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414302		9000-006-794-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414303		9000-004-206-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414304		9000-009-329-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414305		9000-009-329-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414306		9000-006-390-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414307		9000-006-798-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414308		9000-007-299-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414309		9000-006-941-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414310		9000-007-563-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414311		9000-006-796-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414312		9000-007-164-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414313		9000-007-544-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414314		9000-007-545-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414315		9000-006-939-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414316		9000-007-165-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414317		9000-006-351-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414318		9000-009-846-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414319		9000-009-135-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414320		9000-001-207-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414321		9000-007-610-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414322		9000-005-415-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414323		9000-005-415-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414324		9000-006-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414325		9000-009-556-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414326		9000-007-288-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414327		9000-008-846-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414328		9000-006-799-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414329		9000-005-619-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414330		9000-007-171-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414331		9000-007-171-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414332		9000-008-847-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414333		9000-006-899-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414334		9000-007-543-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414335		9000-007-543-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414336		9000-007-839-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414337		9000-007-839-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414338		9000-009-684-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414339		9000-007-612-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414340		262501-3-019-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414341		262501-3-019-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414342		9000-010-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414343		9000-005-189-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414344		9000-006-509-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414345		9000-005-681-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414346		9000-005-681-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414347		9000-005-681-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414348		9000-007-564-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414349		9000-007-167-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414350		9000-007-611-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414351		9000-002-221-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414352		9000-007-837-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414353		9000-005-966-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414354		9000-008-845-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414355		9000-006-765-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414356		9000-006-396-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414357		9000-006-140-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414358		9000-009-137-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414359		9000-004-544-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414360		9000-007-541-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414361		9000-006-801-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414362		9000-006-801-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414363		9000-006-391-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414364		9000-007-170-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414365		9000-004-538-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414366		9000-004-539-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414367		9000-008-547-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414368		9000-004-861-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414369		9000-004-357-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414370		9000-006-802-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414371		9000-008-849-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414372		9000-004-838-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414373		9000-007-169-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414374		9000-006-453-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414375		9000-008-505-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414376		9000-005-591-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414377		9000-008-506-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414378		9000-008-506-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414379		9000-006-172-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Un

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414389		9000-009-687-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414390		9000-008-852-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414391		9000-008-866-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414392		9000-009-688-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414393		9000-008-853-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414394		9000-008-496-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414395		9000-008-854-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414396		9000-008-855-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414397		9000-010-026-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414398		9000-010-026-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414399		9000-009-139-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414400		9000-009-140-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414401		9000-009-143-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414402		9000-008-556-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414403		9000-008-856-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414404		9000-008-856-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414405		9000-009-850-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414406		9000-009-850-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414407		9000-009-470-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414408		9000-009-248-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414409		9000-008-561-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414410		9000-008-560-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414411		9000-009-333-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414412		9000-009-333-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414413		9000-009-141-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414414		9000-008-863-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414415		9000-009-914-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414416		9000-008-514-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414417		9000-009-249-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414418		9000-008-859-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414419		9000-009-145-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414420		9000-009-250-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414421		9000-009-243-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414422		9000-009-244-0008	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414423		9000-009-251-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414424		9000-009-461-0004	No	Not evaluated	Non-Lead - Other	No		2.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		2.00	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414425		9000-009-461-0004	No	Not evaluated	Galvanized	No	Prior to 2033	0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414426		9000-009-245-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414427		9000-009-327-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414428		9000-010-006-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414429		9000-009-252-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	W247	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W247	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414430		9000-009-692-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414431		9000-009-146-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414432		9000-009-147-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414433		9000-009-253-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414434		9000-009-463-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414435		9000-009-463-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414436		9000-008-575-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414437		9000-009-148-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414438		9000-009-149-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414439		9000-008-516-0001	No	Not evaluated	Non-Lead - Plastic	No		1.50				2016-2024		<Null>		1.50		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414440		9000-008-558-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414441		9000-008-558-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414442		9000-008-517-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414443		9000-008-550-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414444		9000-009-242-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414445		9000-009-144-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414446		9000-009-471-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414447		9000-009-686-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414448		9000-008-557-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414449		9000-008-851-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414450		9000-009-241-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414451		9000-008-865-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414452		9000-008-864-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414453		9000-008-850-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414454		9000-008-850-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414455		9000-008-549-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414456		9000-008-868-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414457		9000-008-512-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414458		9000-009-469-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414459		9000-008-861-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414460		9000-008-511-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414461		9000-008-508-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414462		9000-009-240-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414463		9000-008-510-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414464		9000-008-509-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414465		9000-008-527-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414466		9000-008-526-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414467		9000-008-860-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414468		9000-008-545-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414469		9000-009-685-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414470		9000-008-546-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414471		9000-008-546-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414472		9000-007-291-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414473		9000-008-524-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414474		9000-008-507-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414475		9000-007-684-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414476		9000-005-518-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414477		9000-006-804-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414478		9000-005-053-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414479		9000-007-835-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414487		9000-006-392-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414488		9000-007-613-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414489		9000-007-168-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414490		9000-005-529-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414491		9000-007-681-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414492		9000-007-682-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414493		9000-006-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414494		9000-007-296-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414495		9000-008-848-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414496		9000-008-848-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414497		9000-006-808-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414498		9000-008-504-0005	No	Not evaluated	Galvanized	No	Prior to 2035	0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414499		9000-002-286-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414500		9000-007-680-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414501		9000-009-328-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414502		9000-005-457-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414503		9000-005-454-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414504		9000-006-764-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414505		9000-005-174-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414506		9000-004-530-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414507		9000-005-125-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414508		9000-005-888-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414509		9000-007-180-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414510		9000-007-838-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414511		9000-010-282-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414512		9000-004-557-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414513		9000-004-558-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414514		9000-004-543-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414515		9000-004-565-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414516		9000-004-356-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414517		262501-3-019-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414518		262501-3-019-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414519		9000-009-693-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414520		9000-004-998-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414521		9000-004-998-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414522		9000-006-171-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414523		9000-008-502-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414524		9000-007-176-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414525		9000-005-455-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414526		9000-007-649-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414527		9000-005-839-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414528		9000-008-844-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414529		4493-000-213-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414530		4493-000-212-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414531		4493-000-212-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414532		4493-000-211-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414533		4493-000-187-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414534		4493-000-210-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414535		4493-000-191-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414536		4493-000-192-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414537		4493-000-193-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414538		4493-000-209-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414539		4493-000-194-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414540		4493-000-195-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414541		4493-000-196-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414542		4493-000-207-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414543		4493-000-207-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414544		4493-000-197-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414545		4493-000-198-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414546		4493-000-199-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414547		4493-000-206-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414548		4493-000-206-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414549		4493-000-200-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414550		4493-000-201-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414551		4493-000-202-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414552		4493-000-204-0000	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414553		4493-000-203-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414554		4493-000-179-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414555		4493-000-179-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414556		4493-000-180-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414557		4493-000-177-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414558		4493-000-181-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414559		4493-000-182-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414560		4493-000-176-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414561		4493-000-175-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414562		4493-000-183-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414563		4493-000-183-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414564		4493-000-166-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414565		4493-000-168-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414566		4493-000-171-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414567		4493-000-172-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414568		4493-000-172-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414569		4493-000-174-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414570		4915-000-262-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414571		4915-000-261-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414572		4915-000-265-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414573		4915-000-266-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414574		4915-000-266-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414575		4915-000-267-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414576		4915-000-278-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414585		4915-000-248-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414586		4915-000-247-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414587		4915-000-250-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414588		4915-000-250-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414589		4915-000-246-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414590		4915-000-245-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414591		4915-000-244-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414592		4915-000-244-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414593		4915-000-242-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414594		4915-000-252-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414595		4915-000-252-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414596		4915-000-253-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414597		4915-000-254-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414598		4915-000-255-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414599		4915-000-219-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414600		4915-000-221-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414601		4915-000-221-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414602		4915-000-222-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414603		4915-000-223-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414604		4915-000-240-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414605		4915-000-239-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414606		4915-000-224-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414607		4915-000-225-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414608		4915-000-238-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414609		4915-000-237-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414610		4915-000-226-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414611		4915-000-227-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414612		4915-000-228-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414613		4915-000-229-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414614		4915-000-236-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414615		4915-000-235-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414616		4915-000-230-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414617		4915-000-231-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414618		4915-000-234-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414619		4915-000-233-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414620		4915-000-232-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414621		4915-000-273-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414622		4915-000-274-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414623		4915-000-275-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414624		4915-000-272-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414625		4915-000-271-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414626		4915-000-276-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414627		4915-000-277-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414628		4915-000-270-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414629		4915-000-269-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414630		4915-000-268-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414631		4930-000-283-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414632		4930-000-284-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414633		4930-000-315-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414634		4930-000-314-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414635		4930-000-286-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414636		4930-000-286-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414637		4930-000-313-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414638		4930-000-312-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414639		4930-000-311-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414640		4930-000-287-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414641		4930-000-288-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414642		4930-000-310-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414643		4930-000-309-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414644		4930-000-289-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414645		4930-000-290-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414646		4930-000-308-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414647		4930-000-307-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414648		4930-000-292-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414649		4930-000-292-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414650		4930-000-306-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414651		4930-000-293-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414652		4930-000-294-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414653		4930-000-305-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414654		4930-000-304-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414655		4930-000-295-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414656		4930-000-295-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414657		4930-000-296-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414658		4930-000-302-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414659		4936-000-428-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414660		4936-000-427-0006	No	Not evaluated	Galvanized	No	Prior to 2013	2.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414661		4936-000-426-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414662		4936-000-425-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414663		4936-000-429-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414664		4936-000-430-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414665		4936-000-424-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414666		4936-000-423-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414667		4936-000-431-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414668		4936-000-432-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414669		4936-000-422-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414670		4936-000-421-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414671		4936-000-419-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414672		4936-000-419-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414673		4936-000-417-0008	No	Not eva

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie				Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414683		4936-000-411-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414684		4936-000-410-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414685		4936-000-409-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414686		4930-000-298-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414687		4930-000-299-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414688		4930-000-301-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414689		4930-000-300-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414690		4930-000-331-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414691		4930-000-332-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414692		4930-000-330-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414693		4930-000-329-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt			2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414694		4930-000-346-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414695		4930-000-346-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414696		4930-000-348-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414697		4930-000-349-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414698		4930-000-328-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414699		4930-000-328-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414700		4930-000-326-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414701		4930-000-326-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414702		4930-000-325-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414703		4930-000-325-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414704		4930-000-352-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414705		4930-000-323-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414706		4930-000-323-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414707		4930-000-353-0000	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414708		4930-000-322-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414709		4930-000-321-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414710		4930-000-320-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414711		4930-000-320-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414712		4930-000-318-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414713		4930-000-318-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414714		4915-000-263-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414715		4915-000-263-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414716		4930-000-357-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414717		4930-000-355-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414718		4930-000-355-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414719		4930-000-354-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414720		4930-000-407-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414721		4930-000-406-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414722		4930-000-405-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414723		4930-000-404-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414724		4930-000-401-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414725		4930-000-401-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414726		4930-000-400-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414727		4930-000-399-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414728		4930-000-398-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414729		4930-000-397-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414730		4930-000-395-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414731		4930-000-395-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414732		4930-000-394-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414733		4930-000-394-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414734		4930-000-376-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414735		4930-000-376-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414736		4930-000-374-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414737		4930-000-373-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414738		4930-000-372-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414739		4930-000-372-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414740		4930-000-372-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414741		4930-000-359-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414742		4930-000-370-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414743		4930-000-360-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414744		4930-000-361-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414745		4930-000-369-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414746		4930-000-368-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414747		4930-000-367-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414748		4930-000-362-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414749		4930-000-363-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414750		4930-000-366-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414751		4930-000-364-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414752		4930-000-345-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414753		4930-000-345-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414754		4930-000-365-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414755		4930-000-333-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414756		4930-000-333-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414757		4930-000-335-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414758		4930-000-336-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414759		4930-000-337-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414760		4930-000-338-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414761		4930-000-338-0000	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414762		4930-000-343-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414763		4930-000-382-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414764		4930-000-383-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414765		4930-000-384-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414766		4930-000-384-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414767		4930-000-384-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414768		4930-000-386-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414769		4930-000-387-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1916	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1916	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414770		4930-000-388-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414771		4930-000-389-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414772		4930-000-390-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414773		4930-000-377-

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414781		4930-000-341-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414782		4490-000-148-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414783		4490-000-147-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414784		4490-000-145-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414785		4490-000-145-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414786		4490-000-145-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414787		4490-000-145-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414788		4490-000-152-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414789		4490-000-144-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414790		4490-000-143-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414791		4490-000-143-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414792		4490-000-142-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414793		4490-000-141-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414794		4490-000-141-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414795		4490-000-154-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414796		4490-000-132-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414797		4490-000-131-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414798		4490-000-130-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414799		4490-000-129-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414800		4490-000-133-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414801		4490-000-134-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414802		4490-000-135-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414803		4490-000-128-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414804		4490-000-137-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414805		4490-000-137-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414806		4490-000-127-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414807		4490-000-126-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414808		4490-000-138-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414809		4490-000-125-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414810		4490-000-125-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414811		4482-000-106-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414812		4482-000-105-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414813		4482-000-104-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414814		4482-000-104-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414815		4482-000-119-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414816		4486-000-121-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414817		4486-000-122-0008	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414818		4486-000-123-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414819		4482-000-120-0004	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414820		4482-000-103-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414821		4482-000-093-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414822		4482-000-094-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414823		4482-000-095-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414824		4482-000-092-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414825		4482-000-091-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414826		4482-000-097-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414827		4482-000-098-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414828		4482-000-099-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414829		4482-000-090-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414830		4482-000-089-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414831		4482-000-088-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414832		4482-000-087-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414833		4482-000-086-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414834		4482-000-085-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414835		4482-000-100-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414836		4482-000-101-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414837		4482-000-084-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414838		4482-000-083-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414839		4486-000-124-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414840		4482-000-082-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414841		4482-000-081-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414842		4482-000-102-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414843		4482-000-080-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414844		4444-000-064-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414845		4444-000-063-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414846		4444-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414847		4444-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414848		4444-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414849		4444-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414850		4444-000-079-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414851		262501-2-034-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414852		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414853		262501-2-034-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414854		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414855		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		<Null>		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414856		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414857		262501-2-035-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414858		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414859		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414860		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414861		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414862		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414863		262501-2-034-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414864		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414865		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414866		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414867		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414868		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414869		262501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414879		262501-2-030-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414880		262501-2-030-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414881		262501-2-030-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414882		262501-2-030-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414883		262501-2-030-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		<Null>		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414884		262501-2-030-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414885		262501-2-030-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414886		262501-2-030-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414887		262501-2-030-2006	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414888		8062-000-000-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414889		8062-000-000-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414890		8062-000-000-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414891		8062-000-000-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414892		5051-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414893		5051-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414894		5051-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414895		5051-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414896		5051-000-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414897		5051-000-020-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414898		5051-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414899		5051-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414900		5051-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414901		5051-000-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414902		5051-000-021-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414903		5051-000-021-0002	No	Not evaluated	Galvanized	No	Prior to 2026	0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414904		5051-000-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414905		5051-000-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414906		5051-000-022-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414907		5051-000-022-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414908		5051-000-022-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414909		5051-000-023-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414910		5051-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414911		5051-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414912		5051-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414913		5051-000-015-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414914		5051-000-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414915		5051-000-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414916		232501-3-033-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414917		232501-3-002-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414918		232501-3-002-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414919		232501-3-007-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414920		232501-3-007-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414921		232501-3-020-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414922		232501-3-001-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414923		232501-3-001-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414924		232501-3-001-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414925		232501-2-032-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414926		232501-2-019-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414927		232501-2-021-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unkown Type			2016-2024		Galvanized		0.75	GIS Unkown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414928		232501-2-018-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414929		232501-2-049-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414930		232501-2-049-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414931		5020-000-040-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414932		5020-000-040-0007	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414933		5020-000-038-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414934		5020-000-037-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414935		5020-000-036-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414936		5020-000-035-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414937		5020-000-034-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414938		5020-000-033-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414939		5020-000-032-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414940		5020-000-031-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414941		5020-000-030-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414942		5020-000-029-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414943		5020-000-029-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414944		5025-000-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414945		5025-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414946		5025-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414947		5025-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414948		5025-000-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414949		5025-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414950		5025-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414951		5020-000-025-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414952		5020-000-025-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414953		5020-000-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414954		5020-000-023-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414955		5020-000-021-0000	Yes - School	Not evaluated	Non-Lead - Plastic	No		2.00	Main Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Non-Lead - Copper		2.00	Main Year	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414956		5020-000-018-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414957		5020-000-017-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414958		5020-000-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414959		5020-000-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414960		5020-000-014-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414961		5020-000-013-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414962		5020-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414963		5020-000-012-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414964		5020-000-010-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414965		232501-2-058-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414966		232501-2-059-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414967		232501-2-041-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414968		232501-2-040-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier					Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Other Potential Sources of: Is there a Lead Connector?	Other Potential Sources of: Is there Lead Solder in the Service Line?	Other Potential Sources of: Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2414977		5020-000-002-0003	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	Main Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	Main Year	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414978		5020-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unkown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unkown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414979		5020-000-001-0004	Yes - Schoo	Not evaluated	Non-Lead - Copper	No		2.00	Main Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Non-Lead - Copper		2.00	Main Year	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414980		232501-2-046-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414981		232501-2-042-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414982		232501-2-045-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414983		232501-2-064-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414984		232501-2-029-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414985		232501-2-029-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414986		232501-2-029-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414987		232501-2-029-2002	No	Not evaluated	Non-Lead - Plastic	No		4.00	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		4.00	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2414988		232501-2-029-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414989		232501-2-027-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414990		232501-2-028-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 77	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap log 77	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414991		232501-2-022-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	W247	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W247	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414992		232501-2-022-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	W247	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W247	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414993		232501-2-025-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2414994		222501-1-021-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	W268			2016-2024		Non-Lead - Copper		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414995		222501-1-045-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W226			2016-2024		Galvanized		0.75	W226	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414996		222501-1-045-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W226	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W226	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414997		222501-1-045-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W226	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W226	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2414998		222501-1-045-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W226	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W226	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2414999		222501-1-023-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81			2016-2024		Galvanized		0.75	Tap log 81	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415000		222501-1-022-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Tap log 80	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 80	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415001		222501-1-022-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap log 81	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415002		222501-1-004-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415003		222501-1-031-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415004		222501-1-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Plastic		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415005		222501-1-032-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415006		222501-1-003-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415007		222501-1-035-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Copper		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415008		222501-1-039-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	W248	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W248	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415009		222501-1-043-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415010		222501-1-029-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415011		222501-1-029-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415012		222501-1-029-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415013		222501-1-042-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415014		222501-1-040-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415015		222501-1-028-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415016		222501-1-028-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415017		222501-1-027-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415018		222501-1-024-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew			2016-2024		Galvanized		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415019		222501-1-026-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415020		222501-1-025-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415021		4497-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415022		4497-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415023		4497-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415024		4497-000-004-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415025		4497-000-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415026		222501-1-020-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415027		4467-000-027-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415028		4467-000-026-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050			2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415029		4467-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415030		4467-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415031		4467-000-023-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415032		4467-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415033		4467-000-021-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415034		4467-000-020-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415035		4981-000-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415036		4981-000-016-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415037		4981-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415038		4981-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415039		4981-000-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415040		4981-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415041		4981-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415042		222501-4-017-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415043		4981-000-005-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415044		4981-000-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415045		4981-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415046		4467-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415047		4467-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415048		4467-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415049		4467-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415050		4467-000-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415051		4467-000-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415052		4467-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415053		4467-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415054		4467-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415055		4467-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415056		4467-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415057		4467-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415058		4467-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415059		4467-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415060		4467-000-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415061		4467-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415062		4467-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415063		4467-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415064		4467-000-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415065		4467-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415066		4467-000-001-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415067		4467-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415068

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415075		4499-000-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415076		4499-000-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415077		4499-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415078		4499-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415079		4499-000-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415080		4499-000-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415081		4499-000-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050			2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415082		4931-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415083		4931-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415084		4931-000-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415085		4931-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415086		4931-000-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415087		4931-000-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415088		4931-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415089		4931-000-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415090		4931-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415091		222501-4-016-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415092		4931-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415093		4931-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415094		4931-000-013-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415095		4931-000-014-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415096		4931-000-016-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415097		4931-000-016-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415098		4941-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415099		4941-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415100		4941-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415101		4941-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415102		4941-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415103		4941-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415104		4941-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415105		4941-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415106		4941-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415107		4931-000-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415108		4941-000-010-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415109		4941-000-010-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415110		4941-000-010-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415111		4941-000-011-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415112		4941-000-011-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415113		4941-000-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415114		4941-000-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415115		4941-000-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415116		4941-000-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415117		4941-000-018-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415118		4941-000-019-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415119		4941-000-020-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415120		4941-000-022-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415121		4941-000-022-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415122		4941-000-026-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415123		4941-000-026-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415124		4931-000-018-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415125		4931-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415126		4931-000-021-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415127		4931-000-022-0000	No	Not evaluated	Galvanized	No	Prior to 1950	0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415128		4931-000-023-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415129		4931-000-024-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415130		4931-000-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415131		4953-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415132		4953-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415133		4953-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415134		4953-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415135		4953-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415136		4953-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415137		4953-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415138		4953-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415139		4953-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415140		4953-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415141		4953-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415142		4953-000-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415143		4953-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415144		4953-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415145		4953-000-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415146		4953-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415147		4953-000-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415148		4953-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415149		4953-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415150		4953-000-020-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415151		4993-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415152		4993-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415153		4993-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Material			2016-2024		<Null>		2.00	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415154		4993-000-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415155		4993-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415156		4993-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415157		4993-000-008-0003	No	Not evaluated	Non-Lead - Other	No		4.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		4.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415158		4993-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415159		4993-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415160		4993-000-011-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415161		4993-000-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415162		4993-000-013-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415163		4993-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415164		4993-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415165		4993-000-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual insp

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415173		4993-000-024-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415174		4993-000-025-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415175		4993-000-026-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415176		4993-000-028-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415177		4993-000-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415178		4993-000-030-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415179		4993-000-031-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415180		4993-000-032-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415181		4993-000-033-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415182		4993-000-034-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415183		4993-000-035-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415184		4993-000-036-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415185		4993-000-037-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415186		4993-000-038-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415187		4993-000-039-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415188		4993-000-040-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415189		4993-000-041-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415190		4993-000-042-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415191		4993-000-044-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415192		4993-000-045-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415193		4993-000-046-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415194		4993-000-047-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415195		4993-000-048-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415196		4993-000-049-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415197		4993-000-050-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415198		4993-000-051-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415199		4993-000-052-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415200		4993-000-053-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415201		4993-000-054-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415202		4993-000-055-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415203		4993-000-056-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415204		4993-000-057-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415205		4993-000-058-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415206		4993-000-059-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415207		4993-000-060-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415208		4993-000-061-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415209		4993-000-062-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415210		4993-000-064-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415211		4993-000-064-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415212		4993-000-065-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415213		4993-000-066-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415214		4993-000-067-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415215		4993-000-068-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415216		4993-000-069-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415217		4993-000-070-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415218		4993-000-071-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415219		4993-000-071-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415220		4993-000-074-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415221		4993-000-074-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415222		4993-000-075-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415223		4993-000-077-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415224		4993-000-078-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415225		4993-000-079-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415226		5307-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415227		5307-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year/fie	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year/fi	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415228		5307-000-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415229		5307-000-019-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415230		5307-000-020-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415231		5307-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415232		5307-000-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415233		5307-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415234		5307-000-007-0002	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415235		5307-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415236		5307-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415237		5307-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415238		5307-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415239		5307-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415240		5307-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415241		5307-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415242		5307-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415243		5307-000-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415244		5307-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415245		5307-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415246		272501-1-001-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415247		272501-1-006-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415248		272501-1-005-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415249		272501-1-005-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415250		272501-1-003-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415251		272501-1-020-2009	No	Not evaluated	Non-Lead - Copper	No		1.50	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.50	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415252		4996-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415253		4996-000-002-0006	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415254		4996-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415255		4996-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415256		4996-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415257		4996-000-006-0002	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415258		4996-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415259		4996-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415260		4996-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415261		4996-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415262		4996-000-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415263		4996-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the me

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415271		4996-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415272		4996-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415273		4996-000-023-0001	No	Not evaluated	Galvanized	No	Prior to 1951	0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415274		4996-000-024-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415275		4996-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415276		4996-000-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415277		4996-000-027-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415278		4996-000-027-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415279		4996-000-028-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415280		4996-000-030-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415281		4996-000-030-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415282		4987-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415283		4987-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415284		4987-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415285		4987-000-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415286		4987-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415287		4987-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415288		4987-000-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415289		4987-000-030-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415290		4987-000-030-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415291		4987-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415292		4987-000-009-0000	No	Not evaluated	Non-Lead - Other	No		4.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		4.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415293		4987-000-028-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415294		4987-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415295		4987-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415296		4987-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415297		4987-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415298		4987-000-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415299		4987-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415300		4987-000-027-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415301		4987-000-026-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415302		4987-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415303		4987-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415304		4987-000-017-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415305		4987-000-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415306		4987-000-019-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415307		4987-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415308		4987-000-025-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415309		4987-000-024-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415310		4987-000-023-0002	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415311		4987-000-021-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415312		4987-000-022-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415313		5348-000-019-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415314		5348-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415315		5348-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415316		5348-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415317		5348-000-003-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415318		5348-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415319		5348-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415320		5348-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415321		5348-000-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415322		5348-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415323		5348-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415324		5348-000-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415325		5348-000-010-0008	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415326		5348-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415327		5348-000-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415328		5348-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415329		5348-000-015-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415330		5348-000-015-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415331		5348-000-017-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415332		5348-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415333		5348-000-020-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415334		5348-000-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415335		5348-000-022-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415336		5348-000-023-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415337		5348-000-024-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415338		5348-000-025-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415339		5348-000-030-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415340		5348-000-031-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415341		5348-000-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415342		5348-000-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415343		5348-000-034-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415344		5348-000-035-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415345		5348-000-036-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415346		5348-000-037-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415347		5348-000-039-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415348		5348-000-040-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415349		5348-000-041-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415350		5348-000-043-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415351		5348-000-045-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415352		5348-000-046-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415353		5348-000-047-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415354		5348-000-047-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415355		5348-000-048-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415356		5348-000-049-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415357		5348-000-050-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415358		5348-000-052-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415359		5348-000-052-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415369		4914-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415370		4914-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415371		4914-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415372		4914-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415373		4914-000-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415374		4914-000-007-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415375		4914-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415376		4914-000-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415377		4914-000-010-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415378		4914-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415379		4914-000-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415380		4914-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415381		4914-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415382		4914-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415383		4914-000-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415384		4914-000-017-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415385		4914-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415386		4914-000-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415387		4914-000-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415388		4914-000-020-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415389		4914-000-021-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415390		4914-000-023-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415391		4914-000-025-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415392		4914-000-025-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415393		4914-000-026-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415394		4914-000-027-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415395		4914-000-029-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415396		4914-000-029-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415397		4914-000-029-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415398		4914-000-030-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415399		4914-000-031-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415400		4970-000-060-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415401		4970-000-059-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415402		4970-000-058-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415403		4970-000-058-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415404		4970-000-055-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415405		4970-000-055-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415406		4970-000-054-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415407		4970-000-052-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415408		4970-000-051-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415409		4970-000-050-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415410		4970-000-049-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415411		4970-000-048-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415412		4970-000-047-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415413		4970-000-046-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415414		4970-000-045-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415415		4970-000-044-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415416		4970-000-044-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415417		4970-000-042-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415418		4970-000-041-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415419		4970-000-040-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415420		4970-000-039-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415421		4970-000-039-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415422		4970-000-037-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415423		4970-000-037-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415424		4970-000-035-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415425		4970-000-033-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415426		4970-000-033-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415427		4970-000-032-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415428		4970-000-032-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415429		4970-000-032-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415430		4970-000-030-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415431		4970-000-029-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415432		4970-000-028-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415433		4970-000-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415434		4970-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415435		4970-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415436		4970-000-023-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415437		4970-000-023-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415438		4970-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415439		4970-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415440		4970-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415441		4970-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415442		4970-000-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415443		4970-000-017-0009	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415444		4970-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415445		4970-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415446		4970-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415447		4970-000-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415448		4970-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415449		4970-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415450		4970-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415451		4970-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415452		4970-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415453		4970-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415454		4970-000-005-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415455		4970-000-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	<Null>	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415456		4970-000-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415457		4970-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415458		4970-000-062-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GI

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415467		342501-1-083-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415468		342501-1-083-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415469		342501-1-030-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415470		342501-1-111-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415471		342501-1-112-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415472		342501-1-013-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415473		342501-4-051-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415474		4452-004-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415475		4452-004-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415476		4474-017-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415477		4474-017-018-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415478		4474-017-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415479		4474-017-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415480		4474-017-027-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415481		4474-017-027-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415482		4474-017-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415483		4474-018-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415484		4474-018-021-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415485		4474-018-023-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415486		4474-018-025-0309	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415487		4474-018-029-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415488		4474-018-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415489		4474-015-025-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415490		032401-1-009-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415491		4474-015-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415492		4474-015-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415493		4474-015-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415494		4474-015-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415495		4474-015-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415496		4474-015-014-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415497		4474-015-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415498		4474-015-016-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415499		4474-015-020-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415500		4474-018-007-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415501		4474-018-009-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415502		4474-018-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415503		4474-017-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415504		4474-016-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415505		4474-016-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415506		4474-016-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415507		4474-016-013-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415508		4474-017-012-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415509		4474-017-010-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415510		4474-017-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415511		342501-4-020-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415512		342501-4-059-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415513		342501-4-015-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415514		342501-4-014-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415515		342501-4-013-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415516		4474-013-021-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415517		4474-013-023-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415518		4474-013-026-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415519		4474-013-027-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415520		4474-013-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415521		4474-014-007-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415522		4474-014-024-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415523		4474-014-027-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415524		032401-1-012-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415525		4474-014-009-0209	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415526		4474-014-011-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415527		4474-014-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415528		4474-014-016-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415529		4474-013-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415530		4474-013-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415531		4474-013-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415532		4474-013-012-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415533		4472-001-016-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415534		4472-001-025-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415535		4472-002-016-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415536		4472-002-021-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415537		4472-002-025-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415538		4472-002-025-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415539		4472-002-026-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415540		4472-002-026-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415541		4472-002-028-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415542		032401-1-013-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415543		032401-1-014-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415544		032401-1-015-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415545		032401-1-016-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415546		4472-002-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415547		4472-004-028-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415548		4472-002-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415549		4472-002-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415550		4472-004-025-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415551		4472-002-010-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415552		4472-004-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415553		4472-002-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415554		4472-002-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415565		4472-001-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415566		4472-003-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415567		342501-4-045-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415568		4472-003-012-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415569		4472-005-019-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415570		4472-003-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415571		4472-003-006-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415572		4472-005-027-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415573		4472-003-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415574		4472-003-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415575		4472-005-029-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415576		4472-004-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415577		4472-004-007-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415578		4472-004-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415579		032401-1-017-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415580		4472-006-029-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415581		032401-1-025-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415582		032401-1-098-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415583		032401-1-093-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415584		032401-1-024-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415585		032401-1-023-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415586		032401-1-023-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415587		032401-1-022-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415588		032401-1-021-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415589		4472-009-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415590		4472-009-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415591		4472-009-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415592		4472-008-001-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415593		4472-006-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415594		4472-006-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415595		4472-006-003-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415596		4472-008-003-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415597		4472-008-005-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415598		4472-006-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415599		4472-008-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415600		4472-008-020-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415601		4472-008-020-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415602		4472-008-020-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415603		4472-008-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415604		4472-006-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415605		4472-005-001-0207	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415606		4472-005-001-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415607		4472-007-028-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415608		4472-007-028-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415609		4472-005-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415610		4472-007-025-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415611		4472-005-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415612		4472-007-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415613		4472-005-007-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415614		4472-005-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415615		4472-007-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415616		4472-007-011-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415617		4472-007-014-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415618		342501-4-042-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415619		342501-4-049-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415620		342501-4-049-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415621		5151-000-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415622		5151-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415623		5151-000-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415624		5151-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415625		5151-000-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415626		5151-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415627		5151-000-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415628		5151-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415629		5151-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415630		5151-000-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415631		5151-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415632		5151-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415633		4997-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415634		4997-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415635		4997-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415636		4997-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415637		4997-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415638		4997-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415639		4997-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415640		4997-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415641		4997-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415642		342501-1-008-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415643		342501-1-010-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415644		342501-1-080-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415645		342501-1-100-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415646		342501-1-101-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415647		342501-1-102-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415648		342501-1-009-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415649		4492-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415650		4492-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415651		4492-000-016-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415652		4492-000-016-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415663		4492-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415664		4492-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415665		4492-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415666		4907-000-018-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415667		4907-000-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415668		4907-000-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415669		4907-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415670		4907-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415671		4907-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415672		4907-000-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415673		4907-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415674		4907-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415675		4907-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415676		4907-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415677		4907-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415678		4907-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415679		4907-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415680		4907-000-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415681		4907-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415682		4907-000-002-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415683		4907-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415684		342501-1-121-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415685		342501-1-121-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415686		342501-1-120-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415687		342501-1-122-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415688		342501-1-021-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415689		342501-1-020-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415690		342501-1-028-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415691		342501-1-028-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415692		342501-1-085-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415693		342501-1-085-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415694		342501-1-084-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415695		342501-1-084-2003	No	Not evaluated	Non-Lead - Copper	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415696		342501-1-091-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415697		342501-1-091-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415698		342501-1-091-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415699		342501-1-091-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415700		342501-1-092-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415701		342501-1-033-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415702		342501-1-033-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415703		342501-1-016-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415704		342501-1-115-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415705		342501-1-116-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415706		342501-1-117-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415707		342501-1-118-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415708		4450-000-016-0801	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415709		4450-000-016-0702	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415710		4450-000-016-0900	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415711		4450-000-016-0405	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415712		4450-000-016-0405	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415713		4450-000-016-0405	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415714		4450-000-016-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415715		4450-000-009-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415716		4450-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415717		4450-000-007-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415718		4450-000-007-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415719		4450-000-007-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415720		4450-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415721		4450-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415722		4450-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415723		4450-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415724		272501-4-021-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415725		272501-4-021-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415726		272501-4-021-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415727		342501-1-104-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415728		342501-1-075-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415729		342501-1-026-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415730		342501-1-089-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415731		342501-1-025-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415732		342501-1-129-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415733		342501-1-129-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415734		342501-1-039-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415735		342501-1-040-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415736		4453-000-017-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415737		4453-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415738		4453-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415739		4453-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415740		4453-000-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415741		4453-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415742		4453-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415743		4453-000-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415744		4453-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415745		4453-000-010-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415746		4453-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415747		342501-1-041-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415748		342501-1-042-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415749		342501-1-042-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415750		342501-1-047-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415751		342501-1-047-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415752		342501-1-048-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415753		342501-1-043-2003	No	Not evaluated

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415761		5034-000-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415762		5034-000-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415763		5034-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415764		5034-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415765		5034-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415766		5034-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415767		5034-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415768		5034-000-005-0004	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415769		5034-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415770		5034-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415771		5034-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415772		5034-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415773		5034-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415774		5034-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415775		5624-000-034-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415776		5281-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415777		5281-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415778		5281-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415779		5281-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415780		5281-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415781		5281-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415782		5281-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415783		5281-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415784		272501-4-020-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415785		272501-4-019-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415786		5281-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415787		5281-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415788		5281-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415789		5281-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415790		272501-4-028-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415791		272501-4-016-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415792		272501-4-007-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415793		272501-4-006-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415794		272501-4-043-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415795		272501-4-039-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415796		272501-4-025-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415797		272501-4-050-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415798		272501-4-051-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415799		272501-4-051-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415800		272501-4-041-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415801		272501-4-010-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415802		272501-4-010-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415803		272501-4-003-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415804		272501-4-009-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415805		272501-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415806		272501-4-002-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415807		4421-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415808		4421-000-025-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415809		4421-000-025-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415810		4421-000-026-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415811		4421-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415812		4421-000-021-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415813		4421-000-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415814		4421-000-023-0006	No	Not evaluated	Galvanized	No	Prior to 1980	0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415815		4476-000-052-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415816		4476-000-053-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415817		4476-000-054-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415818		4476-000-055-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415819		4476-000-056-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415820		4476-000-051-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415821		4476-000-050-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415822		4476-000-057-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415823		4476-000-058-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415824		4476-000-048-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415825		4476-000-048-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415826		4476-000-059-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415827		4476-000-060-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415828		4476-000-047-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415829		4476-000-047-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415830		4476-000-045-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415831		4476-000-044-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415832		4476-000-061-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2415833		4476-000-062-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415834		4476-000-063-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415835		4476-000-064-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415836		4476-000-043-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415837		4476-000-041-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415838		4476-000-041-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415839		4476-000-065-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415840		4476-000-066-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415841		4476-000-067-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415842		4476-000-068-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415843		4476-000-069-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415844		4476-000-070-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415845		4476-000-040-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415846		4476-000-072-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415847		4476-000-072-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415848		4476-000-039-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415849		4476-000-038-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415850		4476-000-073-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415859		4491-000-109-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415860		4491-000-108-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415861		4491-000-107-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415862		4491-000-106-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415863		4491-000-105-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415864		4491-000-104-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415865		4491-000-103-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415866		4491-000-102-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415867		4491-000-076-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415868		4491-000-077-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material			2016-2024		Galvanized		1.00	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415869		4491-000-078-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material			2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415870		4491-000-079-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415871		4491-000-080-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415872		4491-000-101-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415873		4491-000-100-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415874		4491-000-082-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415875		4491-000-082-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415876		4491-000-083-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415877		4491-000-084-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415878		4491-000-099-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415879		4491-000-098-0001	No	Not evaluated	Galvanized	No	Prior to 1965	0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415880		4491-000-097-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415881		4491-000-096-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415882		4491-000-095-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415883		4491-000-094-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415884		4491-000-093-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415885		4491-000-092-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415886		4491-000-092-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415887		4491-000-091-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415888		4491-000-090-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415889		4491-000-090-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415890		4491-000-089-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415891		4491-000-086-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415892		4491-000-088-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415893		4491-000-088-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415894		4421-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415895		4421-000-015-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415896		4421-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415897		4421-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415898		4421-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415899		4421-000-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415900		4421-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415901		4421-000-035-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415902		4421-000-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415903		4421-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415904		4421-000-032-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415905		4421-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415906		4421-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415907		4421-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415908		4421-000-009-0004	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415909		4421-000-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415910		4421-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415911		4421-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415912		4421-000-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415913		4421-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415914		4421-000-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415915		4421-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415916		4421-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415917		4421-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415918		4421-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415919		4421-000-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415920		4421-000-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415921		272501-1-014-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415922		272501-1-028-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415923		4925-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415924		4925-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415925		4937-000-001-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415926		4937-000-002-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415927		4937-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415928		4937-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415929		4937-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415930		4942-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415931		4942-000-041-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415932		4942-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415933		4942-000-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415934		4942-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415935		4942-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415936		4942-000-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415937		4942-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415938		4942-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415939		4942-000-040-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415940		4942-000-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415941		4942-000-038-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415942		4942-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415943		4942-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415944		4942-000-037-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415945		4942-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415946		4942-000-035-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415947		4942-000-034-0003	No	Not evaluated	Non-Lead - Copper	No

Location Information					System-Owned Portion									Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2415957		4942-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415958		4942-000-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415959		4942-000-021-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2415960		4942-000-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415961		4942-000-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415962		4942-000-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415963		4942-000-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415964		4942-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415965		4942-000-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415966		4942-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415967		4942-000-025-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415968		4942-000-026-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415969		4937-000-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415970		4937-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415971		4937-000-015-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415972		4937-000-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415973		4937-000-017-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415974		4937-000-018-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit/abandon		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit/al	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415975		4937-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year			2016-2024		<Null>		1.50	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2415976		4937-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415977		4937-000-020-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415978		4937-000-021-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415979		4937-000-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415980		4937-000-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415981		4937-000-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415982		4937-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415983		4937-000-022-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415984		4937-000-023-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415985		4937-000-024-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415986		4937-000-025-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415987		4937-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415988		4937-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415989		4937-000-026-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415990		4937-000-027-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415991		4925-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415992		4925-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415993		4925-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415994		4925-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415995		4909-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415996		4909-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415997		4909-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415998		4909-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2415999		4909-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416000		4909-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416001		4909-000-006-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416002		4909-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416003		4909-000-009-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416004		4909-000-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416005		4909-000-011-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416006		4909-000-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416007		4909-000-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416008		4909-000-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416009		4909-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416010		4909-000-016-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416011		272501-1-010-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416012		4975-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416013		4975-000-125-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416014		4975-000-124-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416015		4975-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416016		4975-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416017		4975-000-123-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Unknown Type			2016-2024		Galvanized		1.00	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416018		4975-000-122-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416019		4975-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416020		4975-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material			2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416021		4975-000-121-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year/Fi	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year/F	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416022		4975-000-120-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416023		4975-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416024		4975-000-119-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416025		4975-000-119-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416026		4975-000-118-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416027		4975-000-008-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416028		4975-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416029		4975-000-117-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416030		4975-000-116-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416031		4975-000-115-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416032		4975-000-114-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416033		4975-000-113-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416034		4975-000-112-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416035		4975-000-111-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416036		4975-000-110-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416037		4975-000-109-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416038		4975-000-108-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416039		4975-000-107-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416040		4975-000-106-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Ty	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416041		4975-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416042		4975-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416043		4975-000-105-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416044		4975-000-104-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416045		4975-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416046		4975-000-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead -

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416055		4975-000-019-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416056		4975-000-101-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416057		4975-000-100-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416058		4975-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416059		4975-000-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416060		4975-000-099-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416061		4975-000-098-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416062		4975-000-022-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416063		4975-000-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416064		4975-000-024-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416065		4975-000-025-0004	No	Not evaluated	Galvanized	No	Prior to 2001	0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416066		4975-000-026-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416067		4975-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416068		4975-000-028-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416069		4975-000-029-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416070		4975-000-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416071		4975-000-031-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416072		4975-000-032-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416073		4975-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416074		4975-000-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416075		4975-000-035-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416076		4975-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416077		4975-000-037-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416078		4975-000-038-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416079		4975-000-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416080		4975-000-097-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416081		4975-000-096-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416082		4975-000-040-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416083		4975-000-041-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416084		4975-000-095-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416085		4975-000-094-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416086		4975-000-042-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416087		4975-000-043-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416088		4975-000-044-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416089		4975-000-045-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416090		4975-000-046-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416091		4975-000-047-0008	No	Not evaluated	Galvanized	No	Prior to 1996	0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416092		4975-000-048-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Unknown Type			2016-2024		Non-Lead - Plastic		1.00	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416093		4975-000-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416094		4975-000-050-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416095		4975-000-051-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416096		4975-000-052-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416097		4975-000-093-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416098		4975-000-053-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416099		4975-000-092-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416100		4975-000-091-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416101		4975-000-090-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		<Null>		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416102		4975-000-089-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416103		4975-000-088-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416104		4975-000-088-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416105		4975-000-086-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416106		4975-000-085-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416107		4975-000-084-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416108		4975-000-083-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416109		4975-000-082-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416110		4975-000-081-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416111		4975-000-080-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416112		4975-000-079-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416113		4975-000-054-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416114		4975-000-055-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416115		4975-000-056-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416116		4975-000-057-0005	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Unknown Type			2016-2024		Non-Lead - Plastic		1.50	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416117		4975-000-058-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416118		4975-000-059-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416119		4975-000-060-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416120		4975-000-061-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416121		4975-000-062-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416122		4975-000-063-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416123		4975-000-064-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416124		4975-000-065-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416125		4975-000-066-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416126		4975-000-067-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416127		4975-000-068-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416128		4975-000-069-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416129		4975-000-070-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416130		4975-000-071-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416131		4975-000-072-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416132		4975-000-073-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416133		4975-000-078-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416134		4975-000-077-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416135		4975-000-074-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416136		4975-000-075-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416137		4975-000-076-0002	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416138		4978-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416139		4978-000-011-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416140		4978-000-009-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416141		4978-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416142		4978-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416143		4978-000-006-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416153		222501-3-032-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416154		222501-3-063-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416155		222501-3-064-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416156		222501-3-046-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416157		272501-2-009-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416158		272501-2-009-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416159		272501-2-009-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416160		272501-2-009-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416161		272501-2-009-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416162		272501-2-009-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416163		272501-2-004-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416164		272501-2-010-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416165		4967-000-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416166		4967-000-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416167		4967-000-038-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416168		4967-000-037-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416169		4967-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416170		4967-000-035-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416171		4967-000-034-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416172		4967-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416173		4967-000-032-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416174		4967-000-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416175		4967-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416176		4967-000-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416177		4967-000-030-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416178		4967-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416179		4967-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416180		4967-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416181		4967-000-028-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Galvanized		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416182		4967-000-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416183		4967-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416184		4967-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416185		4967-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416186		4967-000-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416187		4967-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416188		4967-000-027-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416189		4967-000-026-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416190		4967-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416191		4967-000-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416192		4967-000-025-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416193		4967-000-024-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416194		4967-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416195		4967-000-015-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416196		4967-000-016-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416197		4967-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416198		4967-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416199		4967-000-019-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416200		4967-000-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416201		4967-000-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416202		4967-000-020-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416203		4967-000-021-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416204		4967-000-040-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416205		4967-000-041-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416206		4967-000-042-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416207		4967-000-043-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416208		4967-000-044-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416209		4967-000-045-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416210		4967-000-046-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416211		4967-000-047-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416212		4967-000-048-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416213		4967-000-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416214		4967-000-050-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416215		4967-000-051-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416216		4967-000-052-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416217		4967-000-053-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416218		4967-000-054-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416219		4967-000-055-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416220		4967-000-056-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416221		4967-000-057-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416222		4967-000-058-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416223		4967-000-059-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416224		4967-000-060-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416225		4967-000-061-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416226		4967-000-063-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		<Null>		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416227		4967-000-064-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416228		5036-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416229		5036-000-013-0002	No	Not evaluated	Non-Lead - Other	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416230		5036-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416231		5036-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416232		272501-3-067-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416233		5036-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416234		5036-000-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416235		5036-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416236		5036-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416237		5036-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416238		5036-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416239		5036-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416240		5036-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416241		5036-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416242		5036-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416243		272501-3-047-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416244		4967-000-065

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416251		5023-000-003-0009	No	Not evaluated	Non-Lead - Other	No		4.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		4.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416252		5023-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416253		5023-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416254		5023-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416255		5023-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416256		5023-000-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416257		5023-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416258		5023-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416259		5023-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416260		5023-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416261		5023-000-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416262		5023-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416263		5023-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416264		5023-000-017-0003	No	Not evaluated	Galvanized	No	Prior to 2034	0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416265		5023-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416266		5023-000-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416267		5023-000-020-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416268		5023-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416269		5023-000-022-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416270		5023-000-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416271		5023-000-024-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416272		5023-000-025-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416273		272501-3-039-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416274		272501-3-039-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416275		272501-2-009-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416276		272501-2-009-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416277		272501-3-089-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416278		272501-3-090-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416279		272501-3-037-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416280		272501-3-061-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416281		272501-3-077-2007	No	Not evaluated	Non-Lead - Copper	No		0.75				2016-2024		Galvanized		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416282		5428-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416283		5428-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416284		5428-000-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416285		5428-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416286		5428-000-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416287		5428-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416288		5428-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416289		5428-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416290		5428-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416291		5428-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416292		5428-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416293		5428-000-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416294		5428-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416295		5428-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416296		5428-000-015-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416297		5428-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416298		5428-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416299		5428-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416300		272501-3-078-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416301		272501-3-079-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416302		5576-000-040-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416303		272501-3-060-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416304		342501-2-031-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416305		272501-3-082-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416306		342501-2-023-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416307		342501-2-058-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416308		342501-2-059-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416309		342501-2-021-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416310		342501-2-026-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416311		342501-2-026-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416312		342501-2-029-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416313		342501-2-047-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416314		342501-2-047-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416315		342501-2-030-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416316		342501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416317		342501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416318		342501-2-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416319		342501-2-033-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416320		272501-3-027-2008	No	Not evaluated	Non-Lead - Other	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416321		272501-3-026-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416322		272501-3-025-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416323		272501-3-023-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416324		272501-3-094-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416325		272501-3-093-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416326		272501-3-093-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416327		272501-3-092-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416328		272501-3-091-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416329		272501-3-097-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416330		272501-3-097-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416331		272501-3-022-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416332		272501-3-022-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416333		272501-3-020-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416334		272501-3-020-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416335		272501-3-019-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416336		272501-3-018-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416337		272501-3-016-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416338		272501-3-015-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416339		272501-3-013-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416340		272501-3-066-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416341		272501-3-066-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
B

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416349		5067-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416350		5067-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416351		5067-000-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416352		5067-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416353		5067-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416354		5067-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416355		5067-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416356		5067-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416357		5067-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416358		5067-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416359		5067-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416360		5475-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416361		5475-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416362		5475-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416363		5475-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416364		5475-000-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416365		5475-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416366		5475-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416367		272501-2-005-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416368		282501-1-003-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416369		282501-1-004-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416370		282501-1-006-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416371		282501-1-007-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416372		282501-1-021-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416373		282501-1-035-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416374		282501-1-035-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416375		282501-1-035-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416376		282501-1-034-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416377		282501-1-020-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416378		282501-1-015-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416379		282501-1-014-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416380		282501-1-013-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	No meter		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	No meter	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416381		282501-1-010-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416382		282501-1-032-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416383		282501-1-032-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416384		282501-1-032-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416385		282501-1-032-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416386		282501-1-040-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416387		282501-1-040-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416388		282501-1-039-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416389		282501-1-016-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416390		282501-1-028-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416391		282501-1-029-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416392		282501-1-029-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416393		4973-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416394		4973-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416395		4973-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416396		4973-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416397		4973-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416398		4973-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416399		4973-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416400		4973-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416401		4973-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416402		4973-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416403		4973-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416404		4973-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416405		4973-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416406		282501-4-070-2001	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other		Unknown	Unknown		
BremSLI-2416407		282501-4-049-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416408		282501-4-049-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416409		282501-4-050-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416410		282501-4-005-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416411		282501-4-006-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416412		282501-4-009-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416413		282501-4-010-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416414		282501-4-081-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416415		282501-4-081-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416416		282501-4-015-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416417		282501-4-080-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416418		282501-4-013-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416419		282501-4-012-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416420		282501-4-011-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416421		282501-4-079-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416422		282501-4-058-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416423		282501-4-078-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416424		282501-4-016-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416425		282501-4-060-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416426		282501-4-057-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416427		282501-4-066-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416428		282501-4-066-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416429		282501-4-066-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416430		282501-4-020-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416431		4424-000-022-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416432		4424-000-022-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416433		4424-000-018-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416434		4424-000-001-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416435		4424-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416436		4424-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416437		4424-000-004-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416438		4424-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416439		4424-000-009-0001	No	Not evaluated	Non

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416447		282501-4-043-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416448		282501-4-043-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416449		282501-4-028-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416450		282501-4-075-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416451		282501-4-075-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416452		282501-4-040-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416453		282501-4-036-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416454		282501-4-038-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416455		4419-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416456		4419-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416457		4419-000-016-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416458		282501-4-039-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416459		282501-4-039-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416460		4419-000-016-0900	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416461		4419-000-016-0306	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416462		4419-000-014-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416463		4419-000-014-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416464		4419-000-014-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416465		4419-000-014-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416466		4419-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416467		4419-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416468		4419-000-014-0605	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416469		4419-000-014-0704	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416470		4419-000-014-0506	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416471		4419-000-014-0803	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416472		4419-000-011-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416473		4419-000-011-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416474		4419-000-010-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416475		4419-000-009-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416476		4419-000-009-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416477		4419-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416478		4419-000-004-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416479		4419-000-003-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416480		342501-2-046-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	E435	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	E435	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416481		342501-2-045-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 pg 25			2016-2024		Galvanized		0.75	Book 13 pg 25	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416482		4419-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416483		4419-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416484		4419-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416485		4419-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416486		4419-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416487		4419-000-001-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 23	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 Pg 23	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416488		342501-2-016-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416489		342501-2-041-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416490		4419-000-020-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416491		4419-000-019-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416492		4419-000-019-0204	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416493		4419-000-019-0204	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416494		4419-000-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416495		4419-000-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416496		4419-000-020-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416497		342501-2-040-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416498		342501-2-040-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416499		342501-2-040-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416500		342501-2-039-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416501		342501-2-038-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416502		342501-2-038-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416503		342501-2-037-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416504		342501-2-037-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416505		342501-2-036-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416506		342501-2-054-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416507		342501-2-051-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416508		342501-2-050-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416509		342501-2-050-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416510		342501-2-044-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416511		342501-2-044-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416512		4437-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416513		4437-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416514		4437-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416515		4437-000-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416516		4437-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416517		4437-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416518		342501-2-013-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416519		342501-2-012-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416520		342501-2-011-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416521		342501-2-011-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416522		342501-2-009-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416523		342501-2-008-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416524		4437-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416525		4437-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416526		4437-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416527		4437-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416528		4437-000-001-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416529		342501-2-007-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416530		342501-2-006-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416531		342501-2-061-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416532		342501-2-004-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416533		342501-1-052-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416534		342501-1-045-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416535		342501-1-049-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416536		342501-1-050-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416537		342501-1-051-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Resid

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416545		4442-000-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416546		4442-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416547		342501-1-057-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416548		4442-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416549		342501-1-056-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416550		342501-1-063-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416551		342501-1-063-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416552		342501-1-065-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416553		342501-1-065-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416554		342501-1-066-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416555		342501-1-076-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416556		342501-1-076-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416557		342501-1-077-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416558		5046-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416559		5046-000-002-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416560		5046-000-003-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416561		5046-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416562		5046-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416563		5046-000-005-0000	No	Not evaluated	Galvanized	No	Prior to 2022	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416564		342501-1-067-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416565		342501-1-067-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416566		342501-1-067-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416567		5046-000-006-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416568		5046-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416569		5046-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416570		342501-4-027-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416571		342501-4-027-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416572		342501-4-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416573		342501-4-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416574		342501-4-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416575		342501-4-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416576		342501-4-005-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416577		342501-4-029-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416578		342501-4-031-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416579		3717-003-038-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416580		3717-003-038-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416581		4546-016-031-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416582		222401-4-098-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416583		222401-4-098-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416584		222401-4-098-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416585		222401-4-098-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416586		112301-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416587		162401-4-088-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416588		162401-4-088-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416589		162401-4-088-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416590		3787-000-011-0208	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416591		4502-019-003-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416592		4546-010-004-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416593		4546-010-009-0201	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416594		3719-002-014-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416595		4556-000-024-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416596		022401-3-160-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416597		022401-3-160-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416598		5475-000-008-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416599		5475-000-009-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416600		172401-2-079-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416601		172401-2-079-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416602		172401-2-079-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416603		4600-022-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416604		3982-000-005-0209	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416605		5092-000-092-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416606		3968-005-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416607		3968-005-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416608		082401-2-127-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416609		3718-010-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416610		4546-010-010-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416611		4969-000-023-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416612		3777-006-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416613		3777-006-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416614		112401-3-109-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416615		102401-3-208-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416616		4511-000-008-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416617		352501-3-112-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416618		352501-3-112-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416619		4452-006-005-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416620		212401-1-128-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416621		212401-1-128-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416622		3964-000-103-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416623		082401-3-239-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416624		4450-000-001-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416625		202401-1-011-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416626		202401-1-011-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416627		3806-003-043-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416628		5524-000-013-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416629		3739-000-008-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416630		3739-000-008-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416631		4546-017-012-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416632		4546-008-009-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416633		4546-008-009-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416634		3806-003-041-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416635		3806-003-040-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416643		4683-000-010-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416644		022401-4-017-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416645		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416646		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416647		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416648		5486-000-002-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416649		5486-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416650		5486-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416651		5486-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416652		5486-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416653		022401-4-073-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416654		3734-010-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416655		022401-4-075-2007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416656		022401-4-076-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416657		3799-007-012-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416658		3786-000-004-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416659		5487-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416660		5487-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416661		5487-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416662		5487-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416663		4546-010-006-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416664		4624-007-012-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416665		4624-007-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416666		282401-1-022-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416667		282401-1-022-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416668		282401-1-022-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416669		022401-3-161-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416670		022401-3-161-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416671		5481-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416672		4630-003-001-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416673		4546-016-029-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416674		5486-000-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Filed Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416675		5486-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416676		5486-000-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416677		5534-000-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416678		5534-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416679		5534-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416680		4624-007-011-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416681		3790-007-020-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416682		3768-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416683		3768-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416684		5486-000-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416685		3786-000-006-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416686		3968-001-020-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416687		3968-001-020-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416688		3968-001-020-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416689		212401-2-157-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416690		5524-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416691		5524-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416692		5487-000-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416693		5487-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416694		3778-001-008-0004	No	Not evaluated	Galvanized	No	Prior to 1964	0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416695		3778-001-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416696		5532-000-040-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416697		5532-000-022-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416698		5532-000-027-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416699		5532-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416700		4630-001-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416701		4630-001-016-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416702		222401-2-107-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416703		222401-2-107-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416704		5530-000-182-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416705		3739-000-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416706		5534-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416707		5532-000-023-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416708		5532-000-039-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416709		5532-000-028-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416710		5532-000-032-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416711		5486-000-066-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416712		5486-000-050-0001	No	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416713		5486-000-065-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416714		5486-000-081-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416715		5486-000-074-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416716		5486-000-075-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416717		5486-000-076-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416718		5486-000-078-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416719		5486-000-092-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416720		5486-000-085-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416721		5486-000-084-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416722		4502-001-020-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416723		282401-1-016-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416724		5486-000-090-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416725		5486-000-089-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416726		5486-000-089-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416727		5486-000-086-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416728		5486-000-080-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416729		5486-000-082-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416730		5486-000-045-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416731		5486-000-046-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416732		5486-000-049-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416741		3749-002-019-0005	No	Not evaluated	Galvanized	No	Prior to 1967	0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416742		5532-000-042-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416743		5532-000-031-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416744		5532-000-034-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416745		5532-000-035-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416746		5532-000-036-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416747		4512-001-005-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416748		142401-2-208-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416749		3719-001-031-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416750		3719-002-027-0407	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416751		152401-3-127-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416752		4546-010-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416753		5092-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416754		5092-000-008-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416755		5486-000-069-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416756		5486-000-055-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416757		5486-000-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416758		5486-000-015-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416759		5486-000-016-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416760		5486-000-017-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416761		5486-000-035-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416762		5486-000-043-0001	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416763		5486-000-056-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416764		5486-000-058-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416765		5486-000-060-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416766		5486-000-044-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416767		3774-008-025-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416768		3774-008-025-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416769		5486-000-068-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416770		5486-000-032-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416771		162401-1-162-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416772		5532-000-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416773		5532-000-021-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416774		5486-000-067-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416775		5486-000-039-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416776		5486-000-033-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416777		5486-000-034-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416778		5486-000-062-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416779		5486-000-083-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416780		5486-000-063-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416781		5486-000-048-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416782		5486-000-087-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416783		7301170	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416784		8184-000-000-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416785		8184-000-000-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416786		8179-000-000-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416787		8179-000-000-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416788		3717-005-039-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416789		4546-011-010-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416790		4546-011-009-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416791		1546-011-007-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416792		4546-011-007-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416793		4546-011-007-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416794		5486-000-037-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416795		5486-000-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416796		5486-000-031-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416797		5486-000-079-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416798		5486-000-030-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416799		5486-000-038-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416800		5486-000-040-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416801		5486-000-041-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416802		5486-000-047-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416803		5486-000-052-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416804		5486-000-051-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416805		162401-4-085-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416806		3783-007-021-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416807		3783-007-021-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416808		5606040	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416809		5481-000-006-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416810		222501-1-030-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416811		3793-000-024-1302	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416812		3793-000-024-1203	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416813		5532-000-038-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416814		5532-000-041-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416815		5532-000-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416816		5486-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416817		5486-000-019-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416818		5486-000-020-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416819		5486-000-022-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416820		5486-000-027-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416821		5486-000-027-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416822		352501-3-145-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416823		4508-002-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416824		4508-002-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416825		4546-011-008-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416826		5486-000-023-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416827		5486-000-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416828		5486-000-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416829		5486-000-070-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416830		5486-000-024-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416839		5486-000-042-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416840		3718-014-030-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416841		3718-014-030-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416842		4546-023-006-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416843		4546-023-005-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416844		5530-000-121-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416845		5530-000-122-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416846		5530-000-123-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416847		5530-000-124-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416848		5530-000-125-0008	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416849		5486-000-036-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416850		4600-012-001-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416851		3703-002-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416852		112401-2-179-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416853		112401-2-178-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416854		112401-2-177-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416855		3787-000-010-1009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416856		3787-000-010-1009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416857		5524-000-029-0003	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416858		4546-010-008-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416859		5530-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416860		5530-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416861		5530-000-020-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416862		5530-000-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416863		5530-000-104-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416864		5530-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416865		5530-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416866		5530-000-115-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416867		5530-000-103-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416868		5527-000-019-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416869		3718-023-035-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416870		3792-000-021-0308	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416871		332401-4-009-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416872		5529-000-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416873		5092-000-132-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416874		5092-000-132-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416875		4502-001-012-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416876		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416877		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416878		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416879		082401-3-068-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416880		4546-011-004-0105	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416881		4546-011-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416882		5534-000-018-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416883		5534-000-017-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416884		5534-000-016-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416885		5534-000-013-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416886		5534-000-012-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416887		5530-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416888		5530-000-101-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416889		5530-000-126-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416890		5530-000-109-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416891		5530-000-119-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416892		5530-000-134-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416893		3745-000-040-0600	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416894		3804-006-001-1006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416895		022401-3-162-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416896		032401-4-047-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416897		032401-4-047-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416898		5530-000-105-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416899		5530-000-120-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416900		5530-000-132-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416901		5530-000-131-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416902		5530-000-023-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416903		5530-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416904		5530-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416905		5530-000-117-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416906		5530-000-112-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416907		5530-000-127-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416908		4419-000-005-0705	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416909		4419-000-005-0705	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416910		4624-013-011-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416911		4624-013-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416912		4624-013-012-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416913		5532-000-059-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416914		5532-000-050-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416915		5530-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416916		5530-000-106-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416917		5530-000-030-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416918		5530-000-143-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416919		5529-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416920		4546-013-016-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416921		5530-000-108-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416922		5530-000-111-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416923		5530-000-107-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416924		5530-000-107-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416925		5530-000-025-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416926		5530-000-027-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416927		032401-3-082-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416928		5530-000-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416929		5530-000-026-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2416937		4504-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	No meter Visual inspection at the meter pit		2016-2024		<Null>		0.75	GIS Mains Year	No	No meter Visual inspection at the m	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416938		5527-000-022-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416939		5527-000-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416940		5527-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416941		5527-000-004-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416942		5527-000-003-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 28	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 28	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416943		5527-000-002-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799			2016-2024		Galvanized		0.75	BEDA 1799	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416944		5527-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416945		5530-000-178-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416946		5530-000-114-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416947		5530-000-133-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416948		5530-000-135-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416949		5530-000-029-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416950		5530-000-031-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416951		5530-000-141-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416952		5530-000-138-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416953		5530-000-028-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416954		5530-000-136-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416955		5530-000-180-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416956		5530-000-142-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416957		5530-000-179-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416958		212401-1-125-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416959		5527-000-073-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416960		5527-000-021-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416961		5527-000-032-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416962		9999-999-999-9999	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416963		4546-015-001-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416964		222401-2-108-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416965		5530-000-118-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416966		5530-000-032-0000	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416967		3973-004-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416968		3973-004-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416969		5532-000-045-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416970		5524-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416971		5529-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416972		5529-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2416973		5529-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416974		022401-1-003-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2416975		3718-016-026-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416976		3732-003-005-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416977		212401-1-125-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416978		5529-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416979		5530-000-098-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416980		5530-000-102-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416981		5527-000-068-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416982		5527-000-067-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416983		5532-000-055-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416984		132401-2-076-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416985		032401-3-059-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416986		9999-999-999-9999	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416987		5486-000-057-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416988		5530-000-037-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416989		5530-000-154-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416990		242401-2-007-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416991		3775-000-034-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416992		102401-3-154-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416993		5527-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416994		5527-000-026-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416995		5527-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416996		5527-000-070-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2416997		5527-000-069-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416998		5530-000-139-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2416999		5530-000-033-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417000		5530-000-035-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417001		352501-2-126-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417002		5527-000-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417003		5527-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417004		5529-000-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417005		5529-000-023-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417006		5530-000-081-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417007		5530-000-172-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417008		5530-000-090-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417009		5530-000-173-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417010		5530-000-174-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417011		5530-000-175-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417012		5530-000-034-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417013		5530-000-039-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417014		5529-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417015		5529-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417016		3732-003-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 31	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 31	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417017		3732-003-007-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417018		5534-000-011-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417019		5534-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417020		5534-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417021		5534-000-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417022		112401-2-180-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417023		8205-000-000-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417024		3732-001-015-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417025		5527-000-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417026		5529-000-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417027		5529-000-022-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417035		5530-000-149-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417036		3718-022-008-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417037		5529-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417038		5530-000-091-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417039		5530-000-041-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417040		5530-000-164-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417041		5530-000-078-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417042		5524-000-012-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417043		5529-000-020-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417044		5529-000-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417045		212401-2-166-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417046		202401-2-047-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417047		262501-2-030-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417048		5530-000-113-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417049		5530-000-148-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417050		5530-000-036-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417051		5530-000-161-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417052		5530-000-170-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417053		3964-000-096-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417054		3964-000-100-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417055		5127-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417056		5532-000-064-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417057		5532-000-053-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417058		5532-000-043-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417059		5532-000-044-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417060		5532-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417061		5530-000-171-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417062		5530-000-159-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417063		5530-000-046-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417064		5530-000-051-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417065		4585-000-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417066		4585-000-001-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417067		5529-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417068		5529-000-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417069		5530-000-146-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417070		5530-000-157-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417071		5530-000-053-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417072		5530-000-167-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417073		5534-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417074		5534-000-003-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417075		5534-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417076		5534-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417077		5534-000-001-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417078		122401-4-145-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417079		152401-3-020-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417080		5532-000-056-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417081		5532-000-047-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417082		5529-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417083		5529-000-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417084		072402-3-032-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417085		3947-003-007-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417086		212401-4-004-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417087		5529-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417088		202401-2-046-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417089		5549-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417090		5549-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417091		112401-2-176-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417092		5559-000-092-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417093		3936-031-001-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417094		5530-000-088-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417095		5529-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417096		5530-000-110-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417097		5532-000-046-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417098		5532-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417099		5529-000-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417100		5530-000-089-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417101		5530-000-097-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417102		5530-000-040-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417103		202401-1-027-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417104		272501-3-098-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417105		272501-3-098-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417106		352501-2-033-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417107		5527-000-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417108		5527-000-038-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417109		5527-000-037-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417110		5527-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417111		5527-000-035-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417112		5527-000-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417113		5529-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417114		5529-000-026-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417115		5530-000-083-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417116		5530-000-158-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417117		5547-000-169-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417118		5530-000-093-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417119		5530-000-093-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417120		5530-000-079-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417121		5532-000-058-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417122		5532000-057-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417123		352501-3-147-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417124		3746-001-001-0000	No	Not evaluated	Non-Lead -

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417133		5530-000-085-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417134		5530-000-082-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417135		5530-000-055-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417136		5529-000-027-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417137		5530-000-129-0004	No	Not evaluated	Galvanized	No	Prior to 2036	0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417138		5530-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417139		212401-4-004-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417140		212401-4-004-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417141		212401-4-004-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417142		212401-4-004-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417143		5530-000-165-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417144		4474-020-016-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417145		5527-000-042-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417146		5530-000-047-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417147		5530-000-092-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417148		5527-000-043-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417149		5527-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417150		5527-000-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417151		5527-000-025-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417152		5530-000-006-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417153		5559-000-076-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417154		5559-000-030-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417155		5559-000-030-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417156		5529-000-032-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417157		3783-008-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417158		3719-001-011-0605	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417159		5530-000-095-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417160		5530-000-052-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417161		4502-001-001-0408	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799			2016-2024		Non-Lead - Plastic		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417162		072401-1-051-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417163		3719-002-011-0801	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417164		3719-002-011-0801	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417165		3719-002-011-0900	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417166		5530-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417167		5530-000-096-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417168		5530-000-156-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417169		5530-000-160-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417170		5530-000-056-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417171		5559-000-032-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417172		5559-000-032-0006	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417173		5527-000-047-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417174		5527-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417175		5527-000-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417176		5527-000-005-0008	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417177		5530-000-145-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417178		5530-000-155-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417179		5530-000-059-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417180		3732-023-001-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417181		3914-004-002-1106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417182		9999-999-999-9999	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417183		332401-4-035-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417184		332401-4-035-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417185		332401-4-034-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417186		5530-000-057-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417187		5530-000-061-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417188		5530-000-063-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417189		5527-000-064-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417190		5527-000-015-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417191		5527-000-014-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417192		5527-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417193		5527-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417194		9999-999-999-9999	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417195		212401-2-075-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417196		5534-000-019-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417197		5527-000-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417198		5527-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417199		5527-000-060-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417200		5529-000-030-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417201		5529-000-028-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417202		5530-000-084-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417203		5530-000-163-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417204		112401-1-099-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417205		5524-000-026-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417206		5481-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417207		5527-000-051-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417208		5527-000-050-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417209		5527-000-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417210		5527-000-010-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417211		5527-000-009-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417212		152401-3-185-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417213		3787-000-003-1008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417214		3787-000-003-1008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417215		5530-000-144-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417216		5530-000-058-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417217		5530-000-060-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417218		5530-000-062-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417219		9999-999-999-9999	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417220		9999-999-999-9999	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417221		152401-1-218-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417222		152401-1-218-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417223		3718-007-014-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			litional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417231		5527-000-059-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417232		5527-000-058-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417233		4502-026-005-0005	No	Not evaluated	Non-Lead - Plastic	No		1.50				2016-2024		<Null>		1.50		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417234		4502-026-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417235		5530-000-166-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417236		5530-000-064-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417237		5530-000-075-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417238		5530-000-074-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417239		072402-3-026-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417240		082401-4-079-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417241		5530-000-005-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417242		5530-000-150-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417243		5530-000-066-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417244		5530-000-076-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417245		5565-000-012-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417246		5565-000-011-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417247		5530-000-070-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417248		5530-000-071-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417249		4600-008-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417250		5527-000-049-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417251		5527-000-048-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417252		5527-000-023-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417253		5527-000-066-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417254		5527-000-065-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417255		332401-4-098-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417256		5530-000-038-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417257		5530-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417258		5486-000-059-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417259		5529-000-031-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417260		5529-000-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417261		5527-000-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417262		5527-000-086-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417263		5527-000-085-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417264		5527-000-084-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417265		5547-000-171-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417266		5486-000-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417267		5530-000-086-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417268		5530-000-176-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417269		5530-000-067-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417270		5547-000-066-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417271		5547-000-071-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417272		5547-000-071-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417273		5547-000-075-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417274		5547-000-075-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417275		5565-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417276		5560-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417277		5560-000-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417278		5560-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417279		5527-000-063-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417280		5527-000-062-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417281		5527-000-057-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417282		5527-000-056-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417283		8205-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417284		8205-000-002-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417285		5532-000-063-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417286		5530-000-072-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417287		5547-000-070-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417288		5547-000-070-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417289		5547-000-074-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417290		5547-000-074-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417291		5527-000-055-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417292		5527-000-054-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417293		5527-000-089-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417294		5527-000-090-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417295		132401-3-178-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417296		5486-000-061-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417297		5530-000-130-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417298		5530-000-140-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417299		5530-000-050-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417300		5530-000-077-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417301		5530-000-068-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417302		5530-000-069-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417303		5559-000-024-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417304		5565-000-018-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417305		5565-000-018-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417306		5530-000-153-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417307		5530-000-151-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417308		5547-000-068-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417309		5547-000-068-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417310		5547-000-130-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417311		5547-000-130-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417312		5547-000-112-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417313		5547-000-112-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417314		5547-000-073-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417315		5547-000-073-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417316		5527-000-088-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417317		5527-000-087-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417318		4640-004-022-0202	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417319		4640-004-019-0207	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417320		162401-1-165-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417321		162401-1-166-2007	No	Not evaluated	Non-Lead - Plastic	No	

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier					Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Other Potential Sources of: Is there a Lead Connector?	Other Potential Sources of: Is there Lead Solder in the Service Line?	Other Potential Sources of: Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417329		9999-999-999-9999	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417330		5530-000-152-0004	No	Not evaluated	Non-Lead - Copper	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417331		5547-000-069-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417332		5547-000-069-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417333		5532-000-066-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417334		5532-000-062-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417335		5532-000-060-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417336		5532-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417337		5547-000-137-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417338		5547-000-137-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417339		5547-000-067-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417340		5547-000-067-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417341		5296-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	W310	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	W310	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417342		3734-013-019-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417343		3734-013-019-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417344		5524-000-034-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417345		5530-000-065-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417346		5530-000-162-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417347		5530-000-048-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417348		5547-000-060-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417349		5547-000-063-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417350		5547-000-146-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417351		5547-000-146-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417352		5547-000-126-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417353		5547-000-126-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417354		352501-3-111-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417355		4624-008-014-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417356		5547-000-061-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417357		5547-000-127-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417358		5547-000-127-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417359		5530-000-045-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417360		5530-000-049-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417361		5530-000-073-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417362		5547-000-151-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417363		5547-000-147-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417364		5547-000-128-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417365		5547-000-128-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417366		5547-000-113-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417367		5547-000-113-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417368		3719-002-021-0809	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417369		3719-002-021-0809	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417370		022401-3-170-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417371		5530-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417372		5530-000-002-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417373		5530-000-004-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417374		5530-000-044-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417375		5547-000-049-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417376		5547-000-064-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417377		5547-000-149-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417378		5547-000-135-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417379		5547-000-135-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417380		5547-000-133-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417381		5547-000-111-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417382		5547-000-111-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417383		5547-000-101-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417384		5547-000-101-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417385		5547-000-077-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417386		5547-000-077-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417387		3710-000-007-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417388		3733-004-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417389		5547-000-076-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417390		5547-000-076-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417391		5547-000-080-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417392		5547-000-080-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417393		5547-000-048-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417394		5547-000-160-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417395		5547-000-160-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417396		5530-000-042-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417397		212401-2-117-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417398		9999-999-999-9999	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417399		9999-999-999-9999	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417400		162401-1-163-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417401		112401-1-100-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417402		5547-000-163-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417403		5547-000-155-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417404		5547-000-155-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417405		5547-000-155-0002	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417406		5547-000-155-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417407		5547-000-081-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417408		5547-000-081-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417409		5547-000-082-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417410		5547-000-082-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417411		5547-000-079-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417412		5547-000-079-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417413		5547-000-108-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417414		5547-000-108-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417415		5547-000-100-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417416		5547-000-100-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417417		5547-000-114-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417427		5547-000-165-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417428		5547-000-153-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417429		5547-000-152-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417430		5547-000-115-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417431		5547-000-115-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417432		3733-002-009-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417433		3733-002-010-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417434		3733-002-011-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417435		3733-002-012-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417436		3733-002-013-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417437		3733-002-014-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417438		5547-000-136-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417439		5547-000-136-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417440		5547-000-162-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417441		5486-000-073-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417442		5486-000-072-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417443		4504-000-005-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417444		4539-000-005-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417445		3702-003-009-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417446		5547-000-158-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417447		5547-000-158-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417448		5547-000-051-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417449		5547-000-131-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417450		5547-000-170-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417451		5547-000-129-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417452		5547-000-129-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417453		5547-000-102-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417454		5547-000-102-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417455		5560-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417456		5560-000-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417457		5559-000-025-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417458		5559-000-025-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417459		102401-4-125-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417460		102401-4-124-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417461		3732-002-009-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417462		5547-000-104-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417463		5547-000-104-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417464		5547-000-105-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417465		5547-000-105-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417466		5547-000-166-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417467		5547-000-166-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417468		5547-000-047-0004	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417469		5547-000-142-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417470		5547-000-142-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417471		5547-000-140-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417472		5547-000-140-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417473		5547-000-119-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417474		5547-000-119-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417475		5547-000-139-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417476		5547-000-139-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417477		5547-000-109-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417478		5547-000-109-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417479		5547-000-103-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417480		5547-000-103-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417481		5547-000-083-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417482		5547-000-083-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417483		5547-000-084-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417484		5547-000-084-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417485		5547-000-085-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417486		5547-000-085-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417487		5547-000-086-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417488		5547-000-086-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417489		5547-000-096-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417490		5547-000-096-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417491		5547-000-097-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417492		5547-000-097-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417493		5547-000-078-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417494		5547-000-078-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417495		5560-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417496		272501-2-009-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417497		3718-009-001-0205	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417498		3718-009-001-0205	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417499		3733-004-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417500		5530-000-003-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417501		5530-000-043-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417502		5486-000-071-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417503		022401-3-156-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417504		022401-3-156-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417505		5547-000-050-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417506		5547-000-056-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417507		5547-000-057-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417508		5547-000-164-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417509		5547-000-058-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417510		5547-000-110-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417511		5547-000-110-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417512		5559-000-082-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417513		5559-000-082-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417514		5559-000-079-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417515		5559-000-080-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417516		5559-000-081-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417517

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tie				Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417525		5547-000-040-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417526		5547-000-040-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417527		5547-000-044-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417528		5547-000-045-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417529		5547-000-054-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417530		5547-000-065-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417531		5547-000-090-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417532		5547-000-090-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417533		5547-000-120-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417534		5547-000-120-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417535		5547-000-154-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417536		3736-002-021-0204	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417537		5486-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417538		4546-011-001-0405	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417539		5547-000-092-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417540		5547-000-092-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417541		5532-000-016-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417542		5532-000-015-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417543		5532-000-052-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417544		5532-000-051-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417545		5547-000-035-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417546		5547-000-035-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417547		5547-000-038-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417548		5547-000-038-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417549		5547-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417550		5547-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417551		5547-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417552		5547-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417553		082401-3-175-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417554		3733-004-003-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417555		3732-003-013-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417556		3732-003-012-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417557		5560-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417558		5560-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417559		5560-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417560		3718-006-033-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417561		5547-000-039-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417562		5547-000-039-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417563		5547-000-087-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417564		5547-000-087-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417565		5547-000-088-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417566		5547-000-088-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417567		5547-000-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417568		5547-000-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417569		5547-000-150-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417570		112401-1-101-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417571		5547-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417572		5547-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417573		5547-000-141-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417574		5547-000-141-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417575		4504-000-006-0601	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417576		4504-000-006-0601	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417577		5547-000-117-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417578		5547-000-117-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417579		5547-000-027-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417580		5547-000-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417581		5547-000-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417582		5547-000-116-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417583		5547-000-116-0000	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417584		4539-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417585		5560-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417586		5532-000-067-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417587		5532-000-054-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417588		5565-000-015-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417589		4985-003-003-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417590		4985-003-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417591		3804-006-001-1006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417592		5547-000-023-0002	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417593		5547-000-023-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417594		5547-000-025-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417595		5547-000-031-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417596		5547-000-031-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417597		5547-000-032-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417598		5547-000-032-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417599		5547-000-053-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417600		352401-4-003-1007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417601		3790-010-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417602		5547-000-118-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417603		5547-000-118-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417604		5547-000-122-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417605		5547-000-122-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417606		5547-000-143-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417607		5547-000-143-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417608		5547-000-159-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Checl			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417609		5547-000-159-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field inspection	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417610		5547-000-161-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417611		5547-000-161-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417612		5547-000-052-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417613		5547-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417614		5547-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417623		5547-000-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417624		5547-000-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417625		5547-000-042-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417626		5547-000-043-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417627		5584-000-171-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417628		5584-000-171-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417629		5584-000-171-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417630		4502-008-026-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417631		4502-008-026-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417632		5547-000-138-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417633		5547-000-138-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417634		5547-000-034-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417635		5547-000-034-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417636		5547-000-132-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417637		5559-000-027-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417638		5559-000-027-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417639		112401-1-029-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417640		5559-000-077-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417641		5532-000-048-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417642		022401-1-083-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417643		5560-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417644		5560-000-002-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417645		5560-000-005-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417646		5570-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417647		5570-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417648		5570-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417649		5570-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417650		5570-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417651		5570-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417652		5570-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417653		5570-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417654		5570-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417655		5570-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417656		5570-000-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417657		5570-000-001-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417658		5570-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417659		5570-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417660		5570-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417661		5570-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417662		5570-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417663		5570-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417664		5570-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417665		5570-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417666		5570-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417667		5570-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417668		5576-000-032-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417669		5576-000-033-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417670		5547-000-019-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417671		5547-000-019-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417672		5547-000-026-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417673		5547-000-026-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417674		5547-000-089-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417675		5547-000-089-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417676		5570-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417677		5570-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417678		5547-000-107-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417679		5547-000-107-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417680		3733-004-001-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417681		3733-004-001-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417682		5570-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417683		5570-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417684		5570-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417685		5570-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417686		5570-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417687		5570-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417688		5570-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417689		5570-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417690		5570-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417691		5570-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417692		5570-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417693		5570-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417694		5570-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417695		5570-000-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417696		5570-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417697		5570-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417698		5570-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417699		5570-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417700		5570-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417701		5570-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417702		5570-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417703		4472-009-010-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417704		5570-000-045-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417705		5570-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417706		5570-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417707		5570-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417708		5570-000-046-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417709		5570-000-045-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417710		5570-000-044-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417711		5570-000-044-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417721		5570-000-042-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417722		5570-000-042-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417723		5570-000-042-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417724		5570-000-041-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417725		5570-000-041-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417726		5570-000-041-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417727		5570-000-041-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417728		5570-000-041-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417729		5570-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417730		5570-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417731		5570-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417732		5570-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417733		5570-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417734		5547-000-106-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417735		5547-000-106-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417736		5547-000-145-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417737		5547-000-145-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417738		5547-000-144-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417739		5547-000-144-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417740		5547-000-041-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417741		5547-000-041-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417742		5547-000-041-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417743		5547-000-028-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417744		5547-000-028-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417745		5547-000-030-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417746		5547-000-030-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417747		5547-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417748		5547-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417749		5547-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417750		5547-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417751		5547-000-005-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417752		5547-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417753		5547-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417754		5547-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417755		5547-000-020-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417756		5547-000-020-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417757		5576-000-011-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417758		5576-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417759		5547-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417760		5547-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417761		5576-000-006-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Typ	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417762		5576-000-005-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Typ	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417763		5547-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417764		5547-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417765		5547-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417766		5547-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417767		5547-000-036-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417768		5547-000-036-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417769		5547-000-091-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417770		5547-000-091-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417771		5547-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417772		5547-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417773		5547-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417774		5547-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417775		3774-006-016-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417776		3774-006-016-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417777		3792-000-004-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417778		322401-4-094-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417779		322401-4-094-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417780		322401-4-093-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417781		3783-008-029-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417782		5580-000-022-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417783		5580-000-022-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417784		3719-002-048-0303	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417785		3719-002-048-0303	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417786		3719-002-048-0303	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417787		232501-2-066-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417788		232501-2-066-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417789		5547-000-094-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417790		5547-000-094-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417791		5547-000-029-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417792		5547-000-029-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417793		5527-000-072-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417794		5576-000-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417795		5576-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417796		5570-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417797		5570-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417798		5570-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417799		5547-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417800		5547-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417801		5547-000-012-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417802		5547-000-124-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417803		5547-000-124-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417804		5547-000-121-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417805		5547-000-121-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417806		5547-000-098-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417807		5547-000-098-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417808		5524-000-021-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417809		5524-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Un

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417819		122401-4-029-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417820		5576-000-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417821		5576-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Galvanized		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417822		1301820	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417823		5547-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417824		5547-000-009-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417825		5547-000-125-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417826		5547-000-125-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417827		5547-000-123-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417828		5547-000-123-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417829		5524-000-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417830		5524-000-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417831		5576-000-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417832		5527-000-071-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417833		3718-019-012-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417834		222401-2-029-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417835		5547-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417836		5547-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417837		3704-003-004-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417838		5580-000-020-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417839		5580-000-019-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417840		5580-000-018-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417841		5580-000-017-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417842		5580-000-016-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417843		5580-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417844		5580-000-011-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417845		5580-000-012-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417846		5580-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417847		5580-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417848		5580-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417849		5580-000-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417850		5580-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417851		5580-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417852		5580-000-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417853		5580-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417854		5580-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417855		5580-000-003-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417856		5580-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417857		5570-000-034-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417858		5547-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417859		5547-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417860		5547-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417861		5547-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417862		5547-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417863		5547-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417864		5547-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417865		5547-000-093-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417866		5547-000-093-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417867		5547-000-095-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417868		5547-000-095-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417869		5584-000-136-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417870		5584-000-135-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417871		5524-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417872		5524-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417873		5576-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417874		5576-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417875		5576-000-026-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417876		5576-000-015-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	W310	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	W310	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417877		5576-000-007-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit/ abandon		2016-2024		None		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit/ a	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417878		5576-000-010-0001	No	Not evaluated	Non-Lead - Other	No		6.00	Main Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		6.00	Main Year	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417879		092401-1-050-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417880		092401-1-050-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Work			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417881		5547-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417882		5547-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417883		5092-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417884		5532-000-018-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417885		5532-000-017-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417886		5565-000-016-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417887		5524-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417888		5524-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417889		5524-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417890		5524-000-032-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417891		5524-000-031-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417892		5524-000-033-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417893		4472-009-010-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417894		4472-009-010-0208	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417895		5576-000-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417896		5576-000-036-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417897		5576-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417898		5487-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417899		5487-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417900		212401-1-131-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417901		212401-1-131-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417902		212401-1-131-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417903		5584-000-130-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417904		5532-000-024-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417905		5524-000-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417906		5524-000-018-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417907		5524-000-028-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417908		8204-000-755-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unkn

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2417917		8204-000-760-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417918		5524-000-022-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417919		5524-000-023-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417920		5532-000-010-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417921		5576-000-035-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417922		5576-000-021-0008	No	Not evaluated	Non-Lead - Other	No		3.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		3.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417923		5593-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417924		5593-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417925		5584-000-130-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417926		5584-000-129-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417927		5570-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417928		5570-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417929		5570-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417930		5590-000-033-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417931		5590-000-033-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417932		5559-000-034-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417933		5559-000-035-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417934		5559-000-009-0104	Yes - Schoo	Not evaluated	Non-Lead - Copper	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Galvanized		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417935		5559-000-009-0104	No	Not evaluated	Non-Lead - Other	No		4.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		4.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417936		5524-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417937		5576-000-037-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417938		5576-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417939		3718-014-001-0304	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417940		5570-000-036-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417941		5570-000-025-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417942		5570-000-022-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417943		5570-000-021-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417944		5584-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417945		5584-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417946		5584-000-128-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417947		5527-000-082-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417948		5527-000-082-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417949		5527-000-075-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417950		232501-2-065-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417951		5593-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417952		5593-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417953		5576-000-038-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417954		5576-000-022-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417955		5559-000-036-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417956		5559-000-036-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417957		5559-000-036-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417958		5576-000-023-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417959		9999-999-999-9999	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417960		3774-006-018-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417961		102401-2-115-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417962		102401-2-115-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417963		4630-002-016-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417964		4630-002-017-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417965		4630-002-017-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417966		5584-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417967		5584-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417968		5584-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417969		5584-000-126-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417970		5559-000-013-0108	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417971		5559-000-012-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417972		5559-000-012-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417973		5524-000-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417974		042301-1-065-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Unknown		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417975		5559-000-038-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762			2016-2024		Galvanized		0.75	BEDA 1762	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417976		5559-000-038-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417977		022401-1-093-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417978		022401-1-093-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417979		022401-1-093-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417980		022401-1-093-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417981		022401-1-093-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417982		022401-1-093-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417983		022401-1-093-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417984		5532-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417985		5524-000-007-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417986		5524-000-024-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2417987		5524-000-027-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417988		5565-000-022-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417989		5565-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417990		5565-000-001-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417991		5584-000-137-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417992		5570-000-029-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417993		5532-000-049-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417994		5487-000-014-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2417995		5487-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417996		5487-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417997		5487-000-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2417998		5570-000-028-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2417999		5570-000-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418000		5559-000-050-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418001		5559-000-050-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418002		5559-000-050-0102	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418003		5559-000-037-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418004		5559-000-044-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418005		5559-000-044-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418006		5559-000-044-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418007		5559-000-021-0108	No	Not evaluated	Non-Lead - Plastic	No

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418015		4600-005-033-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418016		3918-002-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 13/14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 13/14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418017		3918-002-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 4 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 4 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418018		5559-000-085-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 5485	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 5485	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418019		5559-000-020-0109	No	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418020		5559-000-020-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418021		5565-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418022		5565-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418023		5565-000-021-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418024		352501-2-100-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418025		352501-2-100-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418026		352501-2-100-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418027		352501-2-100-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418028		5593-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418029		5593-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418030		5576-000-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418031		5576-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81			2016-2024		Non-Lead - Copper		0.75	Tap log 81	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418032		5576-000-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Non-Lead - Plastic	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Non-Lead - Plasti	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418033		5487-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418034		5487-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418035		5487-000-018-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418036		5487-000-018-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418037		5487-000-017-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418038		4600-005-032-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418039		5570-000-027-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418040		5570-000-038-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418041		5532-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418042		5532-000-069-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418043		5532-000-037-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418044		5565-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418045		5565-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418046		5565-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418047		5576-000-024-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418048		5570-000-040-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418049		5570-000-039-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418050		5559-000-018-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418051		5559-000-018-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418052		5559-000-016-0105	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418053		5559-000-062-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418054		5559-000-062-0108	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418055		4981-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418056		5593-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418057		5593-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Galvanized		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418058		3709-001-003-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418059		102401-2-116-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418060		032401-4-023-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418061		3949-000-010-0600	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418062		5559-000-084-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3091	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 3091	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418063		5559-000-028-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418064		5559-000-028-0101	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418065		5559-000-088-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418066		5565-000-033-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418067		5593-000-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418068		5593-000-014-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418069		122301-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418070		082401-2-116-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418071		5487-000-016-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418072		5487-000-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418073		4981-000-014-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418074		5487-000-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418075		5487-000-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418076		5487-000-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418077		5487-000-021-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418078		3792-000-009-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418079		5590-000-079-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418080		5527-000-077-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418081		5559-000-070-0108	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>			2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418082		5559-000-070-0108	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418083		5559-000-070-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418084		5559-000-001-0003	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418085		5559-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418086		5559-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418087		5559-000-086-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418088		5559-000-006-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418089		5570-000-024-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418090		5570-000-023-0002	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418091		5565-000-038-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418092		5565-000-037-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418093		5565-000-037-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418094		5565-000-028-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418095		5565-000-028-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418096		5565-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418097		5565-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418098		5565-000-005-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418099		5565-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418100		4600-002-001-0209	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418101		122301-2-009-1003	No	Not evaluated	Non-Lead - Copper	No		2.00	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418102		5532-000-014-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418103		4640-004-023-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418104		4539-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418105		4539-000-001-0001	No	Not evaluated

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418113		5570-000-020-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418114		1204870	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418115		1204870	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418116		5596-000-104-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418117		5590-000-083-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418118		5590-000-043-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418119		202401-1-036-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418120		5532-000-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418121		5532-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418122		5559-000-068-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418123		5559-000-068-0102	No	Not evaluated	Non-Lead - Plastic	No		1.50	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418124		5559-000-002-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418125		5559-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418126		5559-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418127		5559-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418128		5559-000-047-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418129		5559-000-047-0108	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418130		5527-000-079-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418131		5527-000-078-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418132		5565-000-041-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418133		5565-000-041-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418134		5565-000-041-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418135		5565-000-041-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418136		5565-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418137		5570-000-032-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418138		5570-000-031-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418139		5570-000-030-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418140		5584-000-021-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418141		5590-000-088-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418142		5590-000-076-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418143		5590-000-074-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418144		5590-000-073-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418145		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418146		5296-000-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 81 2018	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 81 2018	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418147		3721-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418148		3721-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418149		5590-000-087-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418150		5590-000-087-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418151		5593-000-006-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2060	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2060	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418152		5559-000-046-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418153		5593-000-007-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418154		022401-4-078-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418155		4985-005-009-0100	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418156		5559-000-048-0107	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418157		5565-000-030-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418158		5565-000-030-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418159		5565-000-030-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418160		5565-000-036-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418161		342501-1-003-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418162		4585-000-012-1009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418163		5565-000-032-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418164		5565-000-032-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418165		5565-000-035-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418166		5565-000-034-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418167		4452-005-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418168		4452-005-007-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418169		352501-2-023-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418170		5593-000-010-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418171		5590-000-071-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418172		5590-000-070-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418173		5590-000-069-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418174		5590-000-066-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418175		5590-000-086-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418176		222401-2-111-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418177		222401-2-078-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418178		222401-2-078-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418179		152401-2-088-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418180		5596-000-060-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418181		282401-1-058-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418182		5590-000-089-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418183		5590-000-072-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418184		5590-000-075-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418185		082401-2-117-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418186		082401-2-117-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418187		5584-000-090-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418188		5532-000-020-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418189		5532-000-068-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418190		5527-000-080-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418191		5527-000-081-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418192		4640-004-015-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418193		4640-004-009-0407	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418194		4640-004-009-0308	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418195		4640-004-008-0507	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418196		5596-000-089-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418197		5596-000-124-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418198		5584-000-163-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418199		5559-000-073-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418200		4585-000-012-0704	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418201		4585-000-012-0803	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418211		5590-000-068-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418212		4585-000-012-1306	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418213		4640-004-026-0307	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418214		122401-1-074-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418215		5590-000-065-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418216		5590-000-077-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418217		3734-016-001-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418218		5596-000-085-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418219		5596-000-084-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418220		5596-000-079-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418221		5596-000-051-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418222		082401-2-083-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418223		5092-000-029-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418224		5559-000-075-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418225		5559-000-078-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418226		5559-000-078-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418227		4585-000-012-1207	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418228		4585-000-012-1108	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418229		152401-3-190-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418230		152401-3-190-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418231		5596-000-082-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418232		5596-000-050-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418233		5596-000-088-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418234		4472-001-020-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418235		5596-000-081-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418236		5584-000-165-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418237		5590-000-063-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418238		5590-000-063-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418239		5596-000-080-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418240		5596-000-094-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418241		5596-000-095-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418242		5596-000-086-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418243		5596-000-086-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418244		5596-000-087-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418245		5596-000-083-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418246		5590-000-060-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418247		032401-1-117-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418248		5590-000-099-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418249		5590-000-099-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418250		4640-003-009-0201	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418251		5590-000-061-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418252		5590-000-061-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418253		5590-000-097-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418254		5590-000-097-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418255		5576-000-019-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418256		5596-000-108-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418257		5596-000-112-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418258		5596-000-113-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418259		5596-000-077-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418260		5596-000-056-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418261		5596-000-055-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418262		5590-000-103-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418263		5590-000-093-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418264		5590-000-093-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418265		5590-000-094-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418266		5590-000-095-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418267		5590-000-096-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418268		5596-000-109-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418269		4472-001-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418270		5596-000-110-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418271		5596-000-111-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418272		5596-000-122-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418273		5596-000-078-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418274		5596-000-062-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418275		5596-000-054-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418276		112401-2-184-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418277		5576-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418278		5576-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418279		4640-004-010-0404	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418280		4640-004-010-0404	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418281		4640-004-010-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418282		5596-000-119-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418283		5590-000-082-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418284		5590-000-082-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418285		5593-000-008-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418286		3779-001-022-0104	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418287		5596-000-102-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418288		5596-000-114-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418289		5596-000-115-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418290		5596-000-116-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418291		5596-000-117-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418292		5596-000-118-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418293		5596-000-069-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418294		3795-001-023-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418295		3795-001-023-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418296		112401-3-076-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418297		272501-3-106-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418298		272501-3-106-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418299		272501-3-106-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418300		5565-000-027-0005	No	Not evaluated

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418309		5596-000-074-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418310		5596-000-073-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418311		5590-000-101-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418312		5590-000-102-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418313		082401-223-2004	No	Not evaluated	Non-Lead - Copper	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418314		4640-004-012-0303	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418315		5584-000-122-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418316		5584-000-123-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418317		5590-000-57-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418318		4502-007-029-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418319		5596-000-045-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418320		5590-000-110-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418321		5590-000-052-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418322		102401-3-041-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418323		102401-3-041-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418324		5611-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418325		5611-000-002-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418326		5584-000-121-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418327		5596-000-034-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418328		4640-004-007-0409	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418329		4640-004-007-0300	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418330		5584-000-120-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418331		5590-000-055-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418332		5590-000-055-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418333		5590-000-109-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418334		102401-2-001-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418335		5590-000-054-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418336		5590-000-054-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418337		5620-000-020-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418338		5620-000-022-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418339		5590-000-117-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418340		5611-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418341		3718-006-018-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418342		5611-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418343		5620-000-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418344		3914-002-003-0903	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418345		5596-000-044-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418346		5596-000-043-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418347		5596-000-039-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418348		5596-000-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418349		5596-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418350		5596-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418351		5590-000-025-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418352		5590-000-092-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418353		5590-000-092-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418354		5590-000-107-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418355		5590-000-107-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418356		5590-000-104-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418357		5593-000-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418358		5611-000-046-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418359		5611-000-047-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418360		5611-000-048-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418361		5590-000-035-0004	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418362		5590-000-030-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418363		5590-000-030-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418364		5590-000-106-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418365		5296-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418366		5596-000-002-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418367		5596-000-003-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418368		5596-000-025-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418369		5596-000-025-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418370		5590-000-112-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418371		5590-000-112-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418372		5590-000-118-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418373		5596-000-004-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418374		5611-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418375		5590-000-119-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418376		5590-000-039-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418377		5590-000-049-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418378		5590-000-049-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418379		5590-000-048-0009	No	Not evaluated	Galvanized	No	Prior to 2012	0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418380		5590-000-048-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418381		5590-000-116-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418382		5590-000-116-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418383		5611-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418384		5611-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418385		5611-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418386		5611-000-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418387		5590-000-113-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418388		5590-000-113-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418389		5611-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418390		4472-007-006-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418391		3719-001-011-0506	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418392		3719-001-011-0407	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418393		5611-000-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418394		5611-000-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418395		5611-000-040-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418396		022401-3-115-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418397		4624-004-011-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418398		4624-004-011-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Vis

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418407		4640-004-014-0400	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418408		4640-004-013-0500	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418409		5590-000-034-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418410		5590-000-027-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418411		5590-000-044-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418412		5590-000-125-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418413		4640-004-013-0401	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418414		5590-000-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418415		5611-000-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418416		5611-000-015-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418417		5565-000-024-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418418		5590-000-026-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418419		5590-000-045-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418420		5590-000-045-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418421		5624-000-021-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418422		5611-000-045-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418423		5611-000-039-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418424		5620-000-023-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418425		5620-000-025-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418426		5620-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418427		5620-000-021-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418428		5620-000-024-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418429		5590-000-040-0007	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418430		5565-000-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418431		022401-1-113-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Galvanized		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418432		5611-000-041-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418433		5611-000-042-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418434		5611-000-043-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418435		5611-000-044-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418436		4640-003-012-0206	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418437		4640-003-011-0207	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418438		5611-000-016-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418439		5611-000-017-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418440		5611-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418441		022401-1-113-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418442		5620-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418443		112401-2-190-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418444		5611-000-019-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418445		5611-000-019-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418446		5611-000-038-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418447		5620-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418448		112401-2-004-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418449		5624-000-024-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418450		5624-000-023-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418451		5624-000-022-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418452		152401-1-221-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418453		152401-1-222-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418454		5611-000-020-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418455		5611-000-026-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418456		4502-026-039-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418457		3968-001-012-0008	No	Not evaluated	Non-Lead - Other	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418458		3968-001-012-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418459		5620-000-016-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418460		3719-001-011-0209	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418461		5620-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418462		5620-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418463		5611-000-036-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Unknown		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418464		5611-000-036-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418465		5611-000-034-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418466		5611-000-035-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418467		5611-000-021-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418468		5627-000-146-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418469		5611-000-023-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418470		5627-000-166-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418471		5627-000-167-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418472		3929-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418473		5611-000-033-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418474		5611-000-033-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418475		3809-000-013-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418476		5620-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418477		5620-000-018-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418478		5620-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418479		5620-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418480		5611-000-025-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418481		3759-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418482		5611-000-022-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418483		5611-000-028-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418484		3901-000-018-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418485		5611-000-029-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418486		5611-000-030-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418487		5611-000-031-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418488		5611-000-027-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418489		5620-000-014-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418490		5611-000-024-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418491		5627-000-145-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418492		5624-000-018-005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418493		5624-000-017-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418494		5624-000-016-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418495		5624-000-027-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Type	Yes		2016-

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418505		5627-000-131-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418506		5627-000-135-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418507		5627-000-136-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418508		5627-000-137-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418509		5627-000-137-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418510		5627-000-138-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418511		3804-008-003-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418512		3804-008-003-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418513		4624-004-012-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418514		5624-000-025-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418515		5624-000-030-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418516		5624-000-030-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418517		5627-000-127-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418518		5627-000-127-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418519		5627-000-132-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418520		5627-000-133-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418521		5627-000-134-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418522		5480-000-001-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418523		5620-000-010-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418524		5620-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418525		5624-000-028-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418526		5624-000-002-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418527		5624-000-001-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418528		5627-000-171-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418529		5627-000-172-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418530		5627-000-174-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418531		4600-001-014-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418532		5627-000-260-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418533		5627-000-259-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418534		5627-000-259-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418535		5627-000-259-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418536		5627-000-219-009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418537		5596-000-125-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418538		5627-000-222-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418539		5627-000-181-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418540		5627-000-175-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418541		5627-000-175-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418542		5624-000-003-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418543		5624-000-032-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418544		5624-000-032-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418545		342501-1-096-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418546		4683-000-009-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418547		5627-000-177-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418548		5627-000-177-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418549		5627-000-179-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418550		5627-000-179-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418551		5627-000-139-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418552		5627-000-142-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418553		4600-005-007-0107	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418554		4600-005-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418555		4600-005-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418556		5627-000-217-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418557		5627-000-218-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418558		5627-000-221-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418559		5627-000-227-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418560		5627-000-140-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418561		3918-002-012-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418562		3918-002-012-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Date	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Date	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418563		3918-002-011-0602	No	Not evaluated	Non-Lead - Plastic	No		0.75	E475	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E475	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418564		3768-000-001-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418565		3768-000-001-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418566		3768-000-001-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418567		5624-000-014-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418568		5624-000-013-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418569		082401-2-084-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418570		3804-008-001-1200	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418571		022401-1-103-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418572		022401-1-103-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418573		022401-1-103-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418574		022401-1-103-2009	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418575		022401-1-103-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418576		022401-1-103-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418577		4624-004-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418578		4624-004-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418579		4492-000-008-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418580		5627-000-228-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418581		5627-000-220-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418582		5627-000-224-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown	Yes		
BremSLI-2418583		3804-008-002-0805	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-built	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-built	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418584		022401-3-120-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418585		5627-000-211-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418586		5627-000-141-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418587		022401-1-103-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418588		5627-000-226-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418589		4640-003-016-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418590		4640-003-016-0301	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418591		5624-000-012-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418592		5624-000-015-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418593		3918-002-013-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 Pg 38			2016-2024		Galvanized		0.75	Book 6 Pg 38	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418594		342501-1-097-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418595		5627-000-207-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418603		022401-1-103-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418604		4474-016-027-0103	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418605		4474-016-029-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418606		5627-000-206-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418607		5627-000-212-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418608		5627-000-223-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418609		022401-1-103-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Galvanized		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418610		3918-002-015-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418611		3918-002-014-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418612		5624-000-005-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418613		5624-000-004-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418614		5627-000-229-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418615		5627-000-262-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418616		5627-000-208-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418617		5627-000-230-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418618		5627-000-232-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418619		5627-000-268-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418620		5627-000-203-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418621		5627-000-205-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418622		5627-000-225-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418623		5627-000-210-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418624		5627-000-250-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418625		4546-001-009-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418626		5627-000-261-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418627		5627-000-204-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418628		5627-000-251-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418629		5624-000-026-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Plastic		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418630		5624-000-006-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Material	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418631		3733-002-005-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418632		5627-000-256-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418633		5627-000-233-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418634		5627-000-265-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418635		3968-001-004-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418636		5624-000-007-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Galvanized		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418637		3775-000-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418638		152401-4-023-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418639		272501-4-047-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418640		5627-000-235-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418641		5627-000-239-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418642		5627-000-240-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418643		5627-000-266-001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418644		5627-000-252-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418645		5627-000-234-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418646		5627-000-236-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418647		5627-000-241-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418648		3804-008-001-1408	No	Not evaluated	Non-Lead - Copper	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	<Null>	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418649		9000-007-143-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418650		5627-000-237-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418651		5627-000-238-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418652		5627-000-267-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418653		5627-000-255-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418654		4624-004-005-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418655		5627-000-231-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418656		5627-000-249-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418657		352501-3-016-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418658		5627-000-247-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418659		5627-000-245-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418660		3804-008-001-1309	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418661		5627-000-263-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418662		5627-000-254-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418663		4450-000-015-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418664		4450-000-015-0208	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418665		5596-000-130-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418666		5627-000-264-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418667		5627-000-253-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418668		5627-000-246-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418669		5645-000-021-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418670		5627-000-248-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418671		5627-000-271-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418672		5627-000-270-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418673		5627-000-269-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418674		3733-002-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418675		3733-002-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418676		3733-002-003-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418677		5627-000-244-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418678		5627-000-243-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418679		5627-000-258-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418680		162401-3-114-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418681		162401-3-114-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418682		5627-000-242-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418683		5627-000-275-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418684		5627-000-274-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418685		5624-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418686		5624-000-008-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418687		4624-005-009-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418688		222401-2-114-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418689		4452-006-001-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418690		5645-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418691		5645-000-020-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418692		4600-009-009-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418693		5627-000-273-0002	No	Not evaluated

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418701		5627-000-198-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418702		5597-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418703		5597-000-001-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418704		5645-000-081-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418705		5645-000-008-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1579	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1579	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418706		5645-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418707		5645-000-013-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418708		5645-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418709		5645-000-019-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	asbuilt			2016-2024		Non-Lead - Plastic		1.00	asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418710		5645-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418711		5645-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418712		5645-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	<Null>	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418713		5645-000-091-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418714		5092-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418715		5627-000-193-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418716		5627-000-194-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418717		3787-000-001-0606	No	Not evaluated	Non-Lead - Other	No		4.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Other		4.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418718		5627-000-191-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418719		5627-000-192-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418720		022401-4-081-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418721		5645-000-011-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418722		5645-000-010-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418723		5645-000-009-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418724		5645-000-015-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418725		5645-000-016-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418726		5645-000-017-0001	No	Not evaluated	Non-Lead - Plastic	No		1.50	Asbuilt			2016-2024		Non-Lead - Plastic		1.50	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418727		5645-000-025-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418728		5645-000-025-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418729		5624-000-010-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418730		5627-000-189-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418731		5627-000-190-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418732		5627-000-285-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418733		5627-000-284-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418734		5627-000-188-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418735		5627-000-287-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418736		5627-000-286-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418737		5627-000-289-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418738		5627-000-288-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418739		3967-009-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418740		3967-009-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418741		342501-4-061-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418742		5627-000-282-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418743		5627-000-281-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418744		5645-000-078-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418745		5645-000-077-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418746		5645-000-076-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418747		5645-000-075-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418748		5627-000-283-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418749		5624-000-011-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418750		3783-003-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418751		3783-003-018-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418752		3968-001-004-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 11	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 11	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418753		3968-001-004-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 12	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 12	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418754		3968-001-004-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 12			2016-2024		Galvanized		0.75	Book 5 pg 12	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418755		3968-001-004-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 12	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 12	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418756		3968-001-004-0305	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 12	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 5 pg 12	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418757		022401-4-079-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418758		022401-4-080-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418759		5645-000-023-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418760		5645-000-083-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418761		5645-000-082-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418762		5645-000-082-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418763		5627-000-290-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418764		5627-000-186-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418765		5627-000-187-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418766		5627-000-280-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418767		5627-000-279-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418768		5627-000-278-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418769		5627-000-277-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418770		152401-1-217-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418771		152401-1-217-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418772		5645-000-036-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418773		5645-000-037-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418774		5645-000-035-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418775		5645-000-034-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418776		5645-000-032-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418777		5645-000-033-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418778		5645-000-031-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418779		5645-000-030-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418780		5645-000-029-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418781		5645-000-028-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418782		282401-4-005-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418783		282401-4-005-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418784		3914-002-006-0504	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418785		212401-2-140-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418786		162401-1-157-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418787		162401-1-158-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418788		5627-000-276-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418789		5627-000-173-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418790		4450-000-015-0307	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418791		4600-013-034-0207	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418792		4505-000-015-0005	No	Not evaluated

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418799		5645-000-080-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418800		5645-000-088-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418801		5645-000-079-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418802		4506-000-008-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418803		5571-000-008-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418804		5654-000-009-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418805		4640-003-018-0200	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418806		4640-003-018-0309	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418807		5645-000-040-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418808		5645-000-039-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418809		5645-000-038-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418810		4419-000-002-0401	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418811		5660-000-016-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418812		5660-000-015-003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418813		5660-000-014-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418814		5660-000-013-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418815		5654-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418816		3719-002-048-0402	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418817		3719-002-048-0402	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418818		222401-2-115-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Material			2016-2024		Non-Lead - Copper		0.75	GIS Material	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418819		5660-000-017-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418820		5660-000-018-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418821		5660-000-019-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418822		5660-000-012-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418823		5660-000-011-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418824		5660-000-010-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418825		5660-000-009-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418826		5645-000-071-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418827		5645-000-072-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418828		5645-000-073-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418829		5645-000-074-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418830		5645-000-070-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418831		5645-000-069-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418832		5645-000-068-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418833		5645-000-067-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418834		5645-000-065-0002	Yes - Other	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418835		5645-000-064-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418836		5645-000-063-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418837		5660-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND			2016-2024		None		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418838		5660-000-001-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND			2016-2024		None		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418839		5645-000-041-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418840		5660-000-020-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418841		5660-000-021-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418842		5660-000-022-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418843		3965-000-158-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418844		5660-000-008-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418845		5660-000-006-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418846		5645-000-066-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418847		5660-000-062-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Galvanized		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418848		5660-000-061-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Galvanized		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418849		5660-000-060-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418850		5655-000-002-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418851		5660-000-005-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418852		3733-001-003-0201	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418853		3733-001-003-0201	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418854		3733-001-003-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418855		3733-001-003-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418856		3965-000-069-0104	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418857		3965-000-069-0104	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418858		022401-1-098-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418859		022401-1-098-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418860		022401-1-098-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418861		5654-000-016-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418862		5660-000-059-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1555	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1555	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418863		5660-000-058-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418864		5660-000-057-0002	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418865		5660-000-056-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418866		5645-000-062-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418867		5645-000-061-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418868		5645-000-060-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418869		5645-000-059-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418870		5645-000-058-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418871		5660-000-007-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418872		5571-000-040-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418873		3741-000-010-0105	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418874		3743-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418875		3743-001-001-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418876		4474-020-009-0107	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418877		5654-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418878		152401-2-240-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418879		152401-1-169-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418880		5660-000-004-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	<Null>	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418881		5660-000-003-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418882		5645-000-057-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418883		5645-000-056-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418884		5645-000-049-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418885		5645-000-048-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418886		5645-000-047-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418887		5645-000-046-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418888		5645-000-045-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418889		5645-000-044-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418890		5645-000-043-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2418891		5645-000-042-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024	

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418897		5670-000-009-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418898		5670-000-010-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418899		152401-1-169-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418900		152401-1-169-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418901		5660-000-054-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418902		5660-000-045-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1675	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1675	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418903		5660-000-055-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418904		5660-000-053-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418905		5660-000-052-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418906		5660-000-049-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418907		5660-000-048-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Non-Lead - Copper		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418908		5660-000-047-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418909		5660-000-046-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418910		152401-3-194-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418911		152401-3-193-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418912		5654-000-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418913		5645-000-052-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418914		5645-000-051-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418915		5645-000-050-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418916		5660-000-051-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418917		5660-000-050-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1564	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1564	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418918		5660-000-023-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418919		5660-000-027-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418920		5645-000-055-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418921		5645-000-054-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418922		5645-000-053-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418923		5660-000-026-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418924		5571-000-012-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1807	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1807	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418925		3799-011-017-0106	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418926		3799-011-017-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418927		3799-011-017-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418928		5660-000-028-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	ABAND			2016-2024		None		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418929		5660-000-029-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418930		5660-000-032-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418931		5660-000-033-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418932		5660-000-025-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	<Null>	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418933		5660-000-034-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418934		5571-000-013-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418935		5571-000-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418936		5670-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418937		5670-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418938		5670-000-003-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418939		5670-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418940		4624-012-003-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418941		5675-000-121-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418942		5675-000-123-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418943		3765-000-005-0103	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418944		5654-000-007-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418945		4981-000-004-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Work			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418946		322401-4-091-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418947		072402-3-104-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418948		5660-000-035-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418949		5660-000-030-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418950		5660-000-030-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418951		5660-000-101-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418952		5660-000-102-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418953		5660-000-103-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418954		5660-000-088-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418955		5660-000-089-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418956		5670-000-048-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418957		5670-000-049-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418958		5670-000-050-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418959		5670-000-050-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418960		5670-000-051-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418961		5660-000-036-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418962		5660-000-037-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1724	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1724	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418963		5660-000-024-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418964		5660-000-090-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418965		5660-000-091-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418966		5660-000-092-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418967		5655-000-001-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418968		5655-000-012-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418969		5655-000-013-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418970		5660-000-100-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418971		5571-000-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418972		5571-000-015-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418973		5660-000-097-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418974		5660-000-096-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418975		5660-000-038-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418976		5571-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418977		5571-000-018-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418978		5571-000-032-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418979		3965-000-015-0307	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418980		5549-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418981		5549-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418982		5660-000-095-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418983		5660-000-094-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418984		152401-2-144-2003	No	Not evaluated	Non-Lead - Copper	No		3.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		3.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2418985		5660-000-039-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418986		5660-000-039-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418987		5660-000-093-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418988		5655-000-006-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418989		5660

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2418995		5660-000-099-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418996		5660-000-098-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418997		202401-4-161-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2418998		4624-006-011-0101	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2418999		202401-4-160-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419000		202401-4-159-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419001		202401-4-167-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419002		202401-4-166-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419003		4600-005-012-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419004		4600-004-033-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419005		5670-000-047-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419006		8522-000-001-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Non-Lead - Copper		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419007		5571-000-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419008		5571-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419009		5661-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419010		5660-000-107-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419011		5660-000-107-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419012		5660-000-107-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419013		5660-000-107-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419014		5670-000-028-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419015		5571-000-007-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419016		5571-000-006-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419017		5654-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419018		5571-000-031-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419019		5571-000-031-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419020		5660-000-104-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419021		5660-000-105-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419022		5660-000-106-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419023		3923-002-00-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 Pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 13 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419024		3787-000-013-1600	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419025		3794-001-009-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419026		5655-000-011-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419027		5670-000-014-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419028		5670-000-015-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419029		5670-000-016-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419030		5670-000-017-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419031		112401-2-193-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419032		5660-000-125-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Non-Lead - Copper		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419033		5660-000-124-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1655	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419034		5655-000-007-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419035		5655-000-008-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419036		5660-000-126-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419037		5675-000-021-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419038		5675-000-001-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419039		5675-000-002-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419040		5675-000-003-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419041		5675-000-004-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419042		5675-000-005-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419043		5660-000-138-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419044		5661-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419045		5661-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419046		5661-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419047		5661-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419048		202401-4-157-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419049		202401-4-156-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Non-Lead - Plastic	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Non-Lead - Plasti	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419050		202401-4-168-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Tap Log			2016-2024		Galvanized		1.00	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419051		202401-4-169-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 79	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Tap log 79	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419052		202401-4-155-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419053		202401-4-154-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 77	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 77	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419054		202401-4-170-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	W224	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	W224	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419055		5661-000-006-0003	No	Not evaluated	Galvanized	No	Prior to 2025	0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419056		5661-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419057		5661-000-006-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419058		5655-000-004-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419059		5655-000-014-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419060		5654-000-014-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419061		202401-4171-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419062		022401-1-105-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419063		5655-000-005-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419064		3708-001-003-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419065		3739-000-013-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419066		3739-000-013-0205	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419067		202401-4-153-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	W202			2016-2024		Galvanized		0.75	W202	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419068		5682-000-113-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419069		5670-000-011-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419070		5670-000-012-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419071		5670-000-018-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419072		5670-000-019-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419073		5670-000-020-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419074		5670-000-021-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419075		5670-000-022-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419076		5670-000-023-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419077		5670-000-024-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419078		4450-000-016-0603	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419079		262501-3-007-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419080		5655-000-009-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419081		5655-000-010-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419082		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419083		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419084		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2

Location Information					System-Owned Portion								Customer-Owned Portion							Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419093		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419094		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419095		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419096		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419097		202401-4-152-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Plastic		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419098		092401-1-001-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419099		092401-1-001-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419100		102401-3-089-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419101		5675-000-013-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419102		5675-000-014-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419103		5675-000-015-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419104		5675-000-016-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419105		5675-000-017-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419106		5675-000-018-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419107		5675-000-019-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419108		5675-000-020-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419109		202401-4-052-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419110		202401-4-054-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419111		202401-4-069-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419112		202401-4-068-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419113		202401-4-067-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419114		5597-000-012-0103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419115		5675-000-006-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419116		5675-000-007-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419117		5675-000-009-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419118		5675-000-010-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419119		5675-000-011-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419120		5675-000-012-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419121		202401-4-056-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419122		202401-4-055-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419123		202401-4-172-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Year Built	Year Built		2016-2024		Non-Lead - Plastic		1.00	Year Built	Yes	Year Built	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419124		3790-007-009-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419125		152401-2-234-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419126		5661-000-008-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>			2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419127		5661-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419128		5661-000-010-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419129		5660-000-134-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419130		5670-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419131		5670-000-013-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419132		5670-000-040-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419133		352501-3-098-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419134		5677-000-004-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419135		5677-000-003-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419136		4600-003-039-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419137		5677-000-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419138		5677-000-022-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419139		5677-000-022-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419140		5677-000-024-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419141		5670-000-041-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419142		5675-000-008-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419143		5675-000-039-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419144		5675-000-040-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419145		5675-000-042-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419146		5675-000-042-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419147		5675-000-043-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419148		202401-4-057-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419149		5661-000-013-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419150		5661-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419151		5571-000-010-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1916	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1916	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419152		5571-000-011-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419153		5571-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419154		5571-000-025-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419155		5571-000-026-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419156		5682-000-113-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419157		5682-000-113-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419158		3718-007-009-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419159		3787-000-013-2103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419160		3787-000-013-2103	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419161		3787-000-013-2103	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419162		5670-000-045-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419163		5660-000-136-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419164		5660-000-137-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419165		5670-000-046-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419166		202401-1-040-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419167		202401-1-040-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419168		202401-4-053-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419169		202401-4-059-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419170		5660-000-135-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419171		5660-000-130-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419172		5660-000-129-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419173		202401-4-058-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419174		202401-4-065-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419175		202401-4-064-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419176		202401-4-063-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419177		202401-4-066-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419178		202401-4-251-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W288			2016-2024		Non-Lead - Copper		0.75	W288	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419179		5682-000-103-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419180		202401-4-062-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419181		202401-4-060-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419182		202401-4-251-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419183		5675-000-034-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419184		202401-4-061-2001	No	Not evaluated	Non-Lead -

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419191		202401-4-203-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419192		032401-1-120-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419193		032401-1-120-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419194		032401-1-120-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419195		5670-000-037-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419196		5670-000-042-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419197		5670-000-043-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419198		5670-000-044-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419199		5675-000-030-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419200		5675-000-031-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419201		5675-000-032-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419202		5675-000-033-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419203		202401-4-204-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419204		202401-4-200-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419205		082401-3-063-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419206		082401-3-063-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419207		082401-3-063-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419208		5675-000-026-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419209		5675-000-027-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419210		5675-000-028-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419211		5675-000-029-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419212		3965-000-182-0106	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419213		3965-000-182-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419214		3965-000-182-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419215		3965-000-182-0106	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419216		202401-4-205-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419217		5660-000-065-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419218		5660-000-066-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1797	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1797	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419219		202401-4-202-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419220		202401-4-201-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419221		202401-4-206-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419222		202401-4-199-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419223		5571-000-034-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419224		5571-000-033-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419225		5670-000-031-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419226		5670-000-032-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419227		5670-000-033-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419228		5670-000-034-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419229		5670-000-035-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419230		5670-000-036-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419231		5670-000-038-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419232		5670-000-039-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419233		202401-4-207-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419234		032401-1-126-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419235		3778-003-008-0307	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1808	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1808	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419236		5675-000-131-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419237		032401-1-125-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419238		5670-000-027-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419239		5670-000-029-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419240		5670-000-030-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419241		202401-4-198-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Meter Crew			2016-2024		Galvanized		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419242		202401-4-197-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log			2016-2024		Non-Lead - Copper		0.75	Tap Log	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419243		202401-4-210-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W131			2016-2024		Non-Lead - Plastic		0.75	W131	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419244		202401-4-209-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 73	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 73	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419245		3918-001-001-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2077	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 2077	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419246		5571-000-036-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419247		5571-000-035-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419248		202401-4-196-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Tap Log (1511.5)			2016-2024		Non-Lead - Plastic		1.00	Tap Log (1511.5)	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419249		5661-000-011-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419250		202401-4-195-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Tap log 81	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Tap log 81	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419251		5684-000-092-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419252		5684-000-093-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419253		4505-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		<Null>		1.00	GIS Mains Year	No				Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419254		5660-000-041-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419255		5660-000-041-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419256		202401-4-208-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419257		5571-000-038-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419258		5571-000-037-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419259		202401-4-212-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419260		5660-000-123-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419261		5660-000-122-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419262		5660-000-121-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419263		5660-000-120-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419264		5660-000-119-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419265		5660-000-118-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419266		202401-4-211-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	W248	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	W248	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419267		202401-4-194-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	W245			2016-2024		Non-Lead - Copper		0.75	W245	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419268		202401-4-145-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419269		202401-4-144-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419270		202401-4-077-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419271		5682-000-101-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419272		5670-000-026-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419273		202401-4-193-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Copper		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419274		202401-4-230-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2085	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2085	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419275		202401-4-180-2007	No	Not evaluated	UNK	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419276		202401-4-080-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419277		202401-4-179-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419278		202401-4-079-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419279		202401-4-078-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419280		112301-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419281		112301-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419282		5682-000-001-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419289		202401-4-081-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419290		5675-000-113-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419291		5675-000-120-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419292		5675-000-119-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419293		5675-000-118-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419294		5675-000-117-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419295		5675-000-116-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419296		5675-000-115-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419297		5675-000-114-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419298		5675-000-114-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419299		202401-4-185-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419300		202401-4-184-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Non-Lead - Copper		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419301		202401-4-133-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 3031/3032			2016-2024		Galvanized		0.75	BEDA 3031/3032	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419302		202401-4-085-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419303		202401-4-083-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419304		202401-4-082-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419305		202401-4-084-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419306		202401-4-070-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419307		202401-4-141-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419308		202401-4-141-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419309		202401-4-140-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419310		3787-000-020-0405	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419311		3787-000-020-0405	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419312		5661-000-007-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419313		202401-4-087-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419314		202401-4-086-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419315		5682-000-015-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419316		5682-000-017-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419317		5682-000-018-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419318		5682-000-019-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419319		202401-4-088-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419320		5682-000-002-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419321		5682-000-003-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419322		5684-000-037-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419323		5684-000-038-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419324		5684-000-039-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419325		202401-4-143-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419326		5660-000-067-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419327		5660-000-068-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419328		5660-000-069-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419329		5660-000-070-0005	No	Not evaluated	Galvanized	No	Prior to 2032	0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419330		5660-000-078-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419331		5660-000-077-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419332		5660-000-076-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419333		5660-000-075-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419334		5677-000-014-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419335		5677-000-013-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419336		5677-000-012-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419337		5677-000-011-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419338		202401-4-131-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 14	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 14	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419339		5677-000-015-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419340		5677-000-016-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419341		5677-000-017-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419342		5677-000-018-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419343		202401-4-130-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Book 5 pg 48			2016-2024		Galvanized		0.75	Book 5 pg 48	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419344		5675-000-105-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419345		5675-000-106-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419346		5675-000-107-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419347		5675-000-108-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419348		5675-000-109-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419349		5682-000-004-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419350		5660-000-043-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419351		5660-000-044-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419352		5660-000-042-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419353		5661-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419354		5677-000-002-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419355		5677-000-001-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419356		5682-000-099-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419357		5682-000-100-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419358		5675-000-112-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419359		5675-000-111-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419360		5675-000-110-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419361		202401-4-045-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419362		202401-4-044-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419363		202401-4-232-2005	No	Not evaluated	Galvanized	No	Prior to 2021	0.75	Book 19 pg 3	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 19 pg 3	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419364		202401-4-142-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419365		202401-4-236-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 72	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 7 Pg 72	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419366		202401-4-234-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 Pg 5	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 Pg 5	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419367		4640-003-002-0406	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419368		4640-003-002-0406	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419369		202401-4-214-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419370		3965-000-074-0107	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419371		3965-000-074-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419372		3965-000-074-0305	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419373		202401-4-227-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419374		202401-4-218-2003	No	Not evaluated	Non-Lead - Other	No		2.00	<Null>			2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419375		202401-4-043-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419376		202401-4-042-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419377		202401-4-041-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419378		202401-4-040-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419379		5682-000-008-0006	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419380		5682-000-011-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419387		5675-000-088-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419388		5675-000-089-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419389		5675-000-090-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419390		5675-000-100-0002	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419391		5675-000-101-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419392		5675-000-102-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419393		5675-000-103-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419394		5675-000-085-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419395		5675-000-104-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419396		3718-007-009-0102	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419397		202401-4-158-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419398		202401-4-215-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Galvanized		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419399		202401-4-039-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419400		202401-4-038-2001	Yes - Schoo	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419401		4640-003-002-0307	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419402		5682-000-007-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419403		5682-000-009-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419404		202401-4-129-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 17			2016-2024		Non-Lead - Plastic		0.75	Book 6 pg 17	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419405		202401-4-127-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	E436	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	E436	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419406		202401-4-126-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Fb5 pg 62	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Fb5 pg 62	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419407		5682-000-024-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419408		5661-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419409		5661-000-015-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419410		5677-000-019-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419411		5677-000-020-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419412		5677-000-008-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419413		5677-000-007-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419414		5677-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419415		5677-000-005-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419416		5677-000-036-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419417		5677-000-035-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419418		5677-000-034-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419419		5677-000-033-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419420		5677-000-028-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419421		5677-000-027-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419422		5682-000-032-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419423		5682-000-032-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419424		5682-000-035-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419425		5660-000-114-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419426		5660-000-115-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419427		5660-000-131-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419428		5660-000-116-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419429		5660-000-117-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419430		202401-4-037-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419431		202401-4-036-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419432		202401-4-035-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419433		5682-000-005-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Galvanized		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Galvanized	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419434		5682-000-010-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419435		202401-4-137-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419436		202401-4-136-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1655	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419437		5675-000-086-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419438		5675-000-087-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419439		5682-000-014-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419440		5682-000-102-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419441		202401-4-134-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1724	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1724	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419442		202401-4-238-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419443		202401-4-125-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419444		202401-4-124-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419445		202401-4-239-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419446		202401-4-251-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419447		202401-4-034-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419448		202401-4-033-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419449		5682-000-034-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419450		202401-4-229-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074			2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419451		202401-4-123-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419452		202401-4-122-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	No service		2016-2024		<Null>		0.75	Field Check	Yes	No service	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419453		202401-4-191-2004	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00				2016-2024		<Null>		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419454		5296-000-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419455		202401-4-217-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419456		202401-4-240-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419457		5677-000-030-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419458		5677-000-029-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419459		5677-000-010-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419460		5677-000-009-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419461		5684-000-043-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419462		5684-000-087-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419463		5684-000-088-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419464		5684-000-045-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419465		5684-000-048-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419466		5660-000-080-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419467		5660-000-081-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419468		5682-000-025-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419469		5682-000-028-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419470		5682-000-030-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419471		5682-000-031-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419472		5660-000-082-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419473		5660-000-079-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419474		5660-000-074-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419475		5660-000-073-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419476		5660-000-072-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419477		5660-000-071-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419485		5675-000-096-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419486		5675-000-096-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419487		5675-000-097-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419488		5675-000-098-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419489		5675-000-099-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419490		5682-000-020-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419491		5682-000-021-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419492		5682-000-022-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419493		5682-000-023-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419494		202401-4-216-2005	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419495		202401-4-219-2002	No	Not evaluated	Non-Lead - Other	No		8.00	<Null>			2016-2024		Unknown		8.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419496		202401-4-135-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419497		5684-000-046-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419498		5684-000-049-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419499		5682-000-067-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419500		5682-000-065-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419501		5682-000-063-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419502		5660-000-083-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419503		5660-000-084-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419504		5660-000-085-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check			2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419505		5660-000-086-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419506		5660-000-087-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419507		5677-000-032-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419508		5677-000-031-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419509		5677-000-038-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419510		5677-000-037-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419511		5675-000-052-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419512		5675-000-053-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419513		5675-000-053-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419514		202401-4-235-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 30	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 6 pg 30	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419515		202401-4-241-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419516		5675-000-065-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419517		5675-000-066-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419518		5675-000-067-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419519		5675-000-092-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419520		5675-000-093-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419521		5675-000-069-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		<Null>		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419522		5675-000-094-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419523		5675-000-070-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419524		5682-000-062-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419525		5682-000-064-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419526		5682-000-066-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419527		202401-4-138-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1575	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1575	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419528		202401-4-138-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1575	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1575	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419529		5682-000-091-0004	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419530		5682-000-093-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419531		5682-000-098-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419532		202401-4-233-2004	No	Not evaluated	Galvanized	No	Prior to 1952	0.75	Book 5 pg 15	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Book 5 pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419533		202401-4-237-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	E469	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	E469	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419534		202401-4-128-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 6 pg 65	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 6 pg 65	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419535		202401-4-119-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419536		202401-4-245-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419537		202401-4-117-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419538		202401-4-248-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419539		5675-000-064-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419540		5682-000-029-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419541		5682-000-026-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419542		5682-000-027-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419543		5677-000-040-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419544		5677-000-039-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419545		5682-000-095-0000	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419546		5682-000-096-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419547		232501-3-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419548		232501-3-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419549		232501-3-040-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419550		5571-000-023-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419551		232501-3-038-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Typ	Visual inspection at the meter pit		2016-2024		None		0.75	GIS Unknown Ty	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419552		202401-4-149-2007	No	Not evaluated	Non-Lead - Copper	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419553		202401-4-148-2008	Yes - Schoo	Not evaluated	Non-Lead - Copper	No		2.00		Visual inspection at the meter pit		2016-2024		Galvanized		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419554		202401-4-147-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419555		202401-4-132-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 13 Pg 15	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 13 Pg 15	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419556		202401-4-221-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419557		5675-000-091-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419558		202401-4-050-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419559		202401-4-049-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419560		202401-4-047-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419561		202401-4-046-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419562		5675-000-048-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419563		5675-000-049-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1917	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419564		5675-000-050-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 5 pg 31	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Book 5 pg 31	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419565		5675-000-051-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419566		5675-000-068-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419567		5684-000-033-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419568		5684-000-035-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419569		5684-000-050-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419570		5684-000-047-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419571		5684-000-044-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419572		5684-000-042-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419573		5682-000-086-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419574		5682-000-086-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419583		5682-000-097-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419584		202401-4-150-2003	No	Not evaluated	Non-Lead - Plastic	No		2.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419585		202401-4-220-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419586		202401-4-225-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1555	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1555	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419587		202401-4-048-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419588		5682-000-104-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419589		5682-000-108-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419590		5682-000-068-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419591		202401-4-222-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419592		202401-4-243-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419593		5684-000-034-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419594		5682-000-082-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419595		5682-000-084-0003	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419596		5682-000-085-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419597		202401-4-228-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419598		3718-024-031-0109	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2074	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 2074	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419599		3783-005-024-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419600		5682-000-109-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419601		5682-000-109-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419602		5682-000-083-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419603		202401-4-175-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419604		202401-4-146-2000	Yes - Schoo	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419605		202401-4-178-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419606		202401-4-223-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt			2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419607		202401-4-223-2006	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419608		202401-4-074-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419609		202401-4-073-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419610		20241-4-072-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419611		202401-4-071-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419612		5682-000-107-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419613		5682-000-106-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419614		5682-000-105-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419615		5684-000-032-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419616		5684-000-080-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419617		5682-000-045-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419618		5682-000-046-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419619		202401-4-177-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419620		202401-4-121-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419621		5682-000-043-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419622		5682-000-044-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419623		5682-000-053-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419624		5682-000-053-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419625		5682-000-042-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419626		5682-000-054-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419627		5684-000-026-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419628		5684-000-078-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419629		5684-000-079-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419630		202401-4-231-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	BEDA 3734 (CTS)	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 3734 (CTS)	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419631		202401-4-176-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419632		202401-4-118-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419633		5684-000-005-0007	No	Not evaluated	Galvanized	No	Prior to 2024	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419634		5684-000-006-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419635		5684-000-007-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419636		5684-000-008-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419637		5684-000-028-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419638		5684-000-029-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419639		5684-000-030-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419640		5682-000-049-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419641		5684-000-027-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419642		5684-000-025-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419643		5682-000-039-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419644		5682-000-036-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419645		5682-000-037-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419646		202401-4-186-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419647		202401-4-165-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew			2016-2024		Galvanized		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419648		5684-000-031-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419649		202401-4-247-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419650		5682-000-057-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419651		282401-3-043-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419652		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Copper		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419653		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	<Null>			2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419654		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419655		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419656		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419657		022401-1-071-2007	No	Not evaluated	STL	No		6.00	ABAND			2016-2024		None		6.00	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419658		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419659		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419660		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419661		022401-1-071-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419662		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419663		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419664		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419665		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419666		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419667		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419668		5682-000-041-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419669		5682-000-038-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419670		202401-4-075-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419671		5682-000-051-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419672		5682-000-055-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419673		5684-000-077-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2

Location Information					System-Owned Portion								Customer-Owned Portion								Additional Information to Assign Tap Monitoring Tier				Lead Service	
Location Identifier										If "Yes" Service Line Material						If "Yes" Service Line Material Was Field										
Unique Service Line ID	Street Address	Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	Describe the Field Verification Method	Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419681		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419682		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1656	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1656	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419683		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1655			2016-2024		Galvanized		0.75	BEDA 1655	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419684		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419685		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419686		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419687		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1564	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1564	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419688		4640-003-001-0407	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419689		5682-000-040-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419690		5682-000-059-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419691		5682-000-059-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419692		022401-1-071-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1550			2016-2024		Non-Lead - Copper		0.75	BEDA 1550	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419693		022401-4-063-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419694		4474-022-004-0702	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419695		5675-000-061-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419696		5675-000-060-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419697		5675-000-059-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419698		5675-000-058-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419699		5682-000-048-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419700		5684-000-082-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419701		4640-003-001-0308	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419702		5684-000-021-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419703		5684-000-074-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419704		5684-000-024-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419705		5682-000-056-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419706		5684-000-022-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419707		5684-000-023-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419708		5675-000-055-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419709		5675-000-054-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419710		5675-000-081-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419711		5675-000-080-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419712		5675-000-079-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419713		5675-000-078-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419714		5675-000-077-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419715		5675-000-076-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419716		5675-000-074-0004	No	Not evaluated	Non-Lead - Plastic	No		1.00	fc	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419717		5675-000-075-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 2050			2016-2024		Non-Lead - Plastic		0.75	BEDA 2050	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419718		5675-000-082-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1799	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1799	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419719		202401-4-028-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419720		5675-000-072-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1762	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1762	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419721		5675-000-063-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1917			2016-2024		Non-Lead - Copper		0.75	BEDA 1917	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419722		5675-000-062-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Book 7 Pg 71	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Book 7 Pg 71	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419723		5682-000-058-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419724		202401-4-250-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419725		202401-4-027-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419726		202401-4-226-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419727		5675-000-047-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419728		5675-000-057-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419729		5675-000-056-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419730		202401-4-095-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419731		202401-4-093-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419732		202401-4-032-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419733		202401-4-030-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419734		4419-000-005-1208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419735		4419-000-005-1307	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419736		202401-4-097-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419737		202401-4-090-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419738		032401-3-081-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419739		5682-000-081-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419740		4640-003-019-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419741		5684-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419742		5684-000-019-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419743		5684-000-020-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419744		202401-4-164-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419745		202401-4-163-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419746		202401-4-162-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Meter Crew	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419747		3718-003-001-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419748		3718-003-001-0208	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419749		5682-000-069-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419750		5684-000-075-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419751		202401-4-024-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419752		202401-4-020-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419753		202401-4-018-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419754		202401-4-017-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419755		5684-000-064-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419756		5684-000-070-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419757		5684-000-071-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419758		5684-000-072-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419759		5684-000-073-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419760		202401-4-242-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419761		202401-4-120-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419762		4624-014-008-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419763		4624-014-008-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419764		202401-4-016-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419765		202401-4-014-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419766		202401-4-105-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419767		5682-000-050-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419768		202401-4-187-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	BEDA 1654	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	BEDA 1654	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419769		5684-000-069-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419770		202401-4-012-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419779		5684-000-060-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419780		5684-000-061-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419781		5684-000-062-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419782		202401-4-023-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419783		202401-4-026-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419784		202401-4-025-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419785		3786-000-010-0309	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419786		5695-000-001-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419787		5695-000-002-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419788		5695-000-075-0009	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419789		112401-1-014-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419790		5694-000-082-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419791		5694-000-081-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419792		5694-000-081-0002	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419793		202401-4-022-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419794		202401-4-021-2000	No	Not evaluated	Galvanized	No	Prior to 1973	0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419795		202401-4-101-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	Possible	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419796		5684-000-063-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419797		5682-000-079-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419798		5682-000-078-0001	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419799		5682-000-077-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419800		5682-000-073-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419801		5684-000-001-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419802		5684-000-003-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419803		5684-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419804		5684-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419805		5684-000-004-0008	No	Not evaluated	Non-Lead - Plastic	No		1.50	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.50	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419806		5682-000-072-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419807		5694-000-084-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419808		5694-000-083-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419809		3968-002-003-0205	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419810		3968-002-003-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419811		3968-002-003-0205	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419812		202401-4-092-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419813		5684-000-002-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419814		202401-4-029-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419815		202401-4-013-2000	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419816		202401-4-013-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419817		202401-4-116-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419818		202401-4-019-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419819		202401-4-011-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419820		4474-022-005-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419821		202401-4-103-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419822		202401-4-102-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419823		202401-4-100-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419824		202401-4-098-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419825		5694-000-085-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419826		5694-000-086-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419827		5694-000-067-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419828		5694-000-068-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419829		5694-000-065-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419830		5694-000-066-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419831		202401-4-107-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419832		202401-4-106-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419833		5682-000-076-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419834		5682-000-075-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419835		5682-000-074-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419836		202401-4-015-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419837		202401-4-115-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419838		202401-4-114-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419839		202401-4-111-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419840		202401-4-109-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419841		5687-000-059-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419842		5684-000-017-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419843		5684-000-065-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419844		5684-000-066-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419845		5684-000-067-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419846		5695-000-062-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419847		5695-000-063-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419848		5695-000-064-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419849		3732-011-023-0108	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419850		5694-000-064-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419851		5694-000-063-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419852		202401-4-091-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Copper		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419853		202401-4-110-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419854		202401-4-112-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419855		5684-000-068-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419856		202401-4-104-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419857		202401-4-096-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419858		202401-4-113-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419859		202401-4-099-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419860		202401-4-094-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419861		5684-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419862		5684-000-016-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419863		5695-000-060-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419864		5695-000-061-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419865		5694-000-069-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419866		5694-000-070-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419867		5694-000-078-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419868		5694-000-078-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Pl

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419877		5694-000-077-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419878		4419-000-005-1505	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419879		4419-000-005-1406	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419880		3786-000-006-0909	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419881		3786-000-006-0909	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419882		3786-000-006-0909	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419883		202401-4-108-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419884		5694-000-099-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419885		5694-000-100-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419886		5694-000-071-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419887		5694-000-072-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419888		5694-000-073-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419889		5694-000-074-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419890		5694-000-087-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419891		5694-000-088-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419892		5695-000-065-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419893		032401-1-124-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419894		032401-1-124-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419895		5684-000-009-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419896		5684-000-052-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419897		5684-000-053-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419898		5684-000-054-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419899		5698-000-074-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419900		202401-4-076-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419901		022401-3-025-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419902		5694-000-104-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419903		5694-000-103-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419904		5694-000-095-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419905		5694-000-096-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419906		342501-4-030-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419907		4985-004-017-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419908		032401-1-123-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419909		5694-000-059-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419910		5694-000-060-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419911		5694-000-062-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419912		5694-000-101-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419913		5694-000-102-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419914		5694-000-061-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419915		5571-000-002-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419916		5684-000-013-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419917		5695-000-018-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419918		5684-000-010-0000	No	Not evaluated	Non-Lead - Other	No		6.00	GIS Mains Year			2016-2024		Non-Lead - Other		6.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419919		5684-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419920		5684-000-011-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419921		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419922		5694-000-057-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419923		5694-000-058-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419924		5695-000-066-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419925		112301-3-001-1000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419926		202401-4-353-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419927		202401-4-352-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419928		202401-4-351-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		<Null>		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419929		202401-4-350-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419930		202401-4-349-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419931		202401-4-348-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419932		5571-000-003-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419933		5684-000-055-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419934		5571-000-004-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419935		5661-000-016-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419936		5661-000-016-0100	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419937		3742-000-001-0105	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419938		202401-4-347-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419939		202401-4-346-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419940		202401-4-331-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419941		202401-4-332-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419942		202401-4-296-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419943		022401-1-002-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419944		5694-000-093-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419945		5694-000-094-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419946		5684-000-058-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419947		202401-4-303-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419948		202401-4-307-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419949		5695-000-005-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419950		202401-4-306-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419951		202401-4-308-2004	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419952		202401-4-333-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419953		5684-000-056-0005	No	Not evaluated	Non-Lead - Plastic	No		2.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419954		202401-4-334-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419955		202401-4-335-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419956		202401-4-336-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419957		5694-000-076-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419958		5694-000-075-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419959		4419-000-016-0801	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419960		4985-005-007-0102	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419961		5694-000-089-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419962		5694-000-091-0075	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419963		5694-000-090-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419964		5694-000-092-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419965		5695-000-008-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419966		202401-4-337-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419967		202401-4-338-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-

Location Information					System-Owned Portion									Customer-Owned Portion								Entire Service Line Material Classification	Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes		Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2419975		5684-000-086-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419976		202401-4-304-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419977		202401-4-305-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419978		202401-4-301-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419979		202401-4-302-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419980		5684-000-085-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419981		202401-4-309-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419982		202401-4-310-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419983		202401-4-312-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419984		5684-000-057-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419985		5695-000-013-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419986		4502-016-009-0101	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2419987		5684-000-041-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419988		5684-000-040-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419989		152401-2-225-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419990		5698-000-079-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2419991		5694-000-055-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419992		5694-000-056-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419993		032401-1-119-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419994		032401-1-119-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419995		4600-008-010-0007	No	Not evaluated	Non-Lead - Plastic	No	1950-2024	0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2419996		202401-4-318-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419997		5695-000-006-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419998		202401-1-040-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2419999		5684-000-036-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420000		202401-4-317-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420001		202401-4-322-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420002		202401-4-341-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420003		4419-000-005-1109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420004		202401-4-314-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420005		202401-4-315-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420006		122301-2-012-1008	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type			2016-2024		Galvanized		0.75	GIS Unknown Ty	Yes		2016-2024		Non-lead	Unknown	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420007		5695-000-019-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420008		5695-000-019-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420009		202401-4-313-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420010		5695-000-017-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420011		202401-4-316-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420012		202401-4-324-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420013		202401-4-325-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420014		282401-1-059-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420015		202401-4-342-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420016		202401-4-326-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420017		202401-4-344-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420018		202401-4-327-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420019		5695-000-007-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420020		352501-2-040-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420021		202401-4-329-2009	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420022		202401-4-290-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420023		202401-4-294-2000	No	Not evaluated	Non-Lead - Plastic	No		2.00	Asbuilt	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Asbuilt	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420024		202401-4-355-2006	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420025		5695-000-012-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420026		202401-4-319-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420027		202401-4-311-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420028		5695-000-021-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420029		5695-000-020-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420030		5695-000-015-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420031		5695-000-014-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420032		202401-4-323-2005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420033		202401-4-323-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420034		202401-4-320-2008	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420035		202401-4-321-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420036		282501-4-044-2004	No	Not evaluated	Non-Lead - Plastic	No		2.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420037		3924-000-015-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420038		5695-000-081-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420039		5718-000-175-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420040		5597-000-008-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420041		5597-000-008-0109	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420042		3972-000-006-0309	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420043		202401-4-340-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420044		202401-4-343-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420045		5695-000-054-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420046		5695-000-011-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420047		202401-4-328-2000	No	Not evaluated	Non-Lead - Other	No		4.00	Field Check			2016-2024		Non-Lead - Copper		4.00	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420048		202401-4-345-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420049		122301-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420050		122301-2-009-1003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log (1024 B)	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log (1024 B)	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420051		202401-4-356-2005	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420052		202401-4-330-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420053		5695-000-059-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420054		202401-4-354-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420055		4600-008-009-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420056		4640-003-008-0202	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420057		4640-003-008-0202	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420058		202401-4-359-2002	No	Not evaluated	Non-Lead - Plastic	No		2.00	<Null>	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		2.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420059		202401-4-358-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	ABAND			2016-2024		Unknown		0.75	ABAND	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420060		202401-4-292-2002	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420061		202401-4-357-2004	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2420062		202401-4-295-2009	No	Not evaluated	Non-Lead - Plastic	No		1.00	As-builts	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	As-builts	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420063		5698-000-074-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420064		3965-000-066-0206	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check			2016-2024		Galvanized		0.75	Field Check	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420065		202401-4-291-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420066		202401-4-293-2001	No	Not evaluated	Non-Lead - Plastic	No		1.00	Asbuilt			2016-2024		Non-Lead - Plastic		1.00	Asbuilt	No		2016-2024

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2420073		202401-4-269-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Meter Crew			2016-2024		Galvanized		0.75	Meter Crew	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420074		202401-4-270-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420075		202401-4-271-2007	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 75	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 75	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420076		202401-4-272-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	W164	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	W164	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420077		202401-4-287-2009	No	Not evaluated	Non-Lead - Plastic	No		2.00				2016-2024		Non-Lead - Plastic		2.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420078		5695-000-050-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420079		5695-000-051-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420080		5695-000-053-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420081		132401-2-072-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420082		132401-2-072-2001	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420083		5698-000-063-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420084		5698-000-063-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420085		5698-000-056-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420086		5698-000-056-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420087		5698-000-044-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420088		5698-000-003-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420089		5698-000-032-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420090		5698-000-001-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420091		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420092		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420093		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420094		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420095		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420096		012401-2-182-2002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420097		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420098		202401-4-266-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap log 77	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap log 77	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420099		202401-4-274-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75	W288			2016-2024		Non-Lead - Copper		0.75	W288	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420100		202401-4-265-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W202			2016-2024		Galvanized		0.75	W202	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420101		202401-4-264-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Non-Lead - Plastic		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420102		202401-4-263-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	W310	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	W310	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2420103		202401-4-275-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420104		202401-4-276-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420105		202401-4-277-2001	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown	Yes		
BremSLI-2420106		202401-4-278-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75		Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420107		202401-4-279-2009	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420108		202401-4-273-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75	W268			2016-2024		Galvanized		0.75	W268	Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420109		5695-000-055-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2420110		5695-000-055-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2420111		5695-000-056-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420112		5695-000-057-0001	No	Not evaluated	Galvanized	No	Prior to 2020	0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420113		5695-000-058-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420114		5718-000-019-0001	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420115		5718-000-017-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420116		5718-000-009-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420117		202401-4-267-2003	No	Not evaluated	Non-Lead - Plastic	No		0.75	Tap Log	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Tap Log	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420118		202401-4-268-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	Non-Lead - Plastic	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Non-Lead - Plasti	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420119		202401-4-280-2006	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420120		202401-4-281-2005	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420121		5718-000-021-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420122		5695-000-042-0009	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420123		5695-000-041-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420124		5718-000-018-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420125		3733-006-017-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420126		3733-006-017-0204	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420127		5698-000-031-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420128		5698-000-016-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420129		012401-2-182-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420130		012401-2-195-2007	No	Not evaluated	Non-Lead - Plastic	No		1.00	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420131		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420132		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420133		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420134		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420135		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420136		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420137		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420138		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420139		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420140		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420141		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420142		012401-2-195-2007	No	Not evaluated	Non-Lead - Copper	No		0.75	Field check	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420143		222501-4-009-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Unknown Type	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Unknown Type	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420144		5718-000-013-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420145		5718-000-012-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420146		5718-000-011-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420147		5718-000-010-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420148		202401-4-282-2004	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420149		202401-4-283-2003	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Other	Unknown	Unknown			
BremSLI-2420150		5695-000-048-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420151		082401-3-179-2008	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420152		082401-3-177-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420153		082401-3-177-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420154		082401-3-177-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420155		3719-001-004-0109	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420156		5698-000-069-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420157		5698-000-057-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420158		5698-000-033-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420159		5698-000-045-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420160		5698-000-004-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420161		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420162		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420163		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420164		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420165		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		2.00	G

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tie			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2420171		5695-000-044-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420172		5695-000-004-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420173		5695-000-003-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420174		202401-4-288-2008	No	Not evaluated	Non-Lead - Plastic	No		1.00	<Null>			2016-2024		Non-Lead - Plastic		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420175		202401-4-284-2002	No	Not evaluated	Non-Lead - Plastic	No		1.50				2016-2024		Non-Lead - Plastic		1.50		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420176		022401-1-102-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420177		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420178		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420179		202401-4-285-2001	No	Not evaluated	Non-Lead - Copper	No		0.75		Visual inspection at the meter pit		2016-2024		Galvanized		0.75		Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420180		202401-4-286-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420181		042301-2-038-2006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420182		042301-2-038-2006	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420183		202401-4-051-2003	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420184		5695-000-047-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420185		5698-000-058-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420186		5698-000-058-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420187		5698-000-058-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420188		5698-000-068-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420189		5709-000-111-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420190		5698-000-030-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420191		5698-000-029-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420192		5698-000-029-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420193		5698-000-017-0007	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420194		5698-000-017-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420195		5698-000-046-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420196		5698-000-046-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420197		5698-000-006-0000	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420198		5698-000-005-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420199		5698-000-035-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year			2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420200		5698-000-034-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420201		5709-000-053-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420202		5709-000-054-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420203		5695-000-046-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420204		5718-000-058-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420205		5718-000-059-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420206		5718-000-059-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420207		5718-000-015-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420208		5695-000-049-0002	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420209		5718-000-056-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420210		5718-000-057-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420211		5695-000-040-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420212		5695-000-039-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420213		5695-000-039-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420214		5695-000-043-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420215		5695-000-035-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420216		5718-000-016-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420217		5718-000-014-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420218		072401-4-133-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420219		5695-000-034-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420220		5695-000-037-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420221		5695-000-033-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420222		5695-000-032-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420223		5695-000-031-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420224		5695-000-036-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420225		5695-000-030-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420226		5695-000-022-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420227		5695-000-023-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420228		5695-000-023-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420229		5695-000-024-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420230		352501-3-007-2002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420231		4585-000-012-0100	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420232		5709-000-109-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420233		5709-000-109-0003	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420234		5709-000-110-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420235		5709-000-110-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420236		5709-000-052-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420237		5709-000-051-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420238		5709-000-050-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420239		5709-000-112-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420240		5709-000-112-0008	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420241		5709-000-113-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420242		5709-000-114-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420243		5718-000-020-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420244		3781-000-052-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420245		5718-000-053-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420246		5718-000-053-0008	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420247		5718-000-054-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420248		5718-000-054-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420249		5698-000-066-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75				2016-2024		Non-Lead - Plastic		0.75		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420250		5698-000-027-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420251		5695-000-025-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420252		5698-000-054-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420253		5698-000-008-0008	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420254		5709-000-115-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420255		5709-000-116-0004	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420256		5709-000-146-0008	No	Not evaluated	Non-Lead - Copper	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420257		5709-000-042-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420258		5709-000-151-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420259		5709-000-152-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420260		5709-000-041-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-

Location Information					System-Owned Portion								Customer-Owned Portion								Other Potential Sources of			Additional Information to Assign Tap Monitoring Tier			Lead Service	
Unique Service Line ID	Location Identifier: Street Address	Location Identifier: Other Location Identifier	Sensitive Population? (Yes/No)	Disadvantaged Neighborhood? (Yes/No)	System-Owned Portion Service Line Material Classification	If Non-Lead in Column G, Was Material Ever Previous	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material: Describe the Field Verification Method	If "Yes" Service Line Material: Enter the Date of Field Verification	Notes	Customer-Owned Portion Service Line Material Classification	Service Line Installation Date	Service Line Size	Basis of Material Classification	Was the Service Line Material Field Verified?	If "Yes" Service Line Material Was Field: Describe the Field Verification Method	If "Yes" Service Line Material Was Field: Enter the Date of Field Verification	Notes	Entire Service Line Material Classification	Is there a Lead Connector?	Is there Lead Solder in the Service Line?	Describe Other Fittings and Equipment Connected to the Service Line that Contain Lead	Building Type Connected to Service Line	Point-of-Entry or Point-of-Use Treatment Present?	Does the Interior Building Plumbing Contain Copper Pipes with Lead	Current LCR Sampling Site?	Date of System-owned LSLR	Date of Customer-owned LSLR
BremSLI-2420269		5695-000-028-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Galvanized		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420270		5718-000-048-0006	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420271		5718-000-0490005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420272		5698-000-025-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420273		5698-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420274		5698-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420275		5698-000-019-0005	Yes - Other	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420276		5698-000-019-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420277		5698-000-039-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420278		5698-000-039-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420279		5698-000-007-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420280		5698-000-037-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420281		5698-000-037-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420282		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420283		022401-1-102-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420284		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420285		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420286		022401-1-102-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420287		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420288		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420289		022401-1-102-2000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420290		022401-1-102-2000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420291		5709-000-150-0001	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420292		5709-000-044-0001	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420293		5709-000-149-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Copper		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420294		5709-000-043-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420295		5698-000-060-0003	No	Not evaluated	Non-Lead - Plastic	No		1.00				2016-2024		<Null>		1.00		Yes		2016-2024		Non-lead	No	Unknown	Unknown	Building	Unknown	Unknown			
BremSLI-2420296		5728-000-038-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420297		5728-000-038-0006	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420298		5709-000-046-0009	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420299		5693-000-006-0005	No	Not evaluated	Non-Lead - Plastic	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420300		5693-000-006-0005	No	Not evaluated	Non-Lead - Copper	No		0.75	Field Check	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	Field Check	Yes	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420301		5693-000-021-0006	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420302		5718-000-005-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420303		5718-000-005-0007	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Galvanized		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420304		5725-000-136-0000	No	Not evaluated	Non-Lead - Copper	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420305		5718-000-158-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Multiple Family Residence	Unknown	Unknown			
BremSLI-2420306		5709-000-045-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420307		5698-000-053-0002	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420308		5698-000-023-0009	No	Not evaluated	Non-Lead - Plastic	No		1.00	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		1.00	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420309		5698-000-022-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420310		5698-000-022-0000	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420311		5698-000-051-0004	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420312		5698-000-011-0003	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420313		5698-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420314		5698-000-009-0007	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year			2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No		2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			
BremSLI-2420315		4558-000-026-0206	No	Not evaluated	Non-Lead - Plastic	No		0.75	GIS Mains Year	Visual inspection at the meter pit		2016-2024		Non-Lead - Plastic		0.75	GIS Mains Year	No	Visual inspection at the meter pit	2016-2024		Non-lead	No	Unknown	Unknown	Single Family Residence	Unknown	Unknown			